



Trees to north of site are plotted by eye apart from trees close to eastern end of site.  
 Trees in poor condition should be removed and are the responsibility of the land owner.  
 No roots are expected to spread into site due to trees' location and drainage channel.  
 Trees will not be an issue due to ground sloping down away from site and northern aspect.

Only roads and attenuation basins close to trees, houses removed for clarity.

**KEY:**

- T12 Tree number (T)
- Tree or (G) Group
- Canopy outline
- Root Protection Area (RPA)
- Category U tree centre
- Category A tree centre
- Category B tree centre
- Category C tree centre
- Incursion into root protection area
- Tree to be removed to facilitate development.

**Revisions**

Reva: Layout updated



CLIENT: Obsidian Homes

PROJECT: Land adjacent to Brynheulog St Clears

DRAWING TITLE: Tree Location and Arboricultural Impact Assessment

DRAWING NO: ARW1116:01

DATE: 14/11/2021

SCALE: 1:250@A3