

# Translation of Auction Sheet

Total kms. “\*\*” =Unknown kms. “S” =Total kms from owner records supplied

Make and Model

Doors / Body Type  
5 Door

Year and Month of first registration using Japanese year system (This may be after manufacture date)

Model details- this was base model so only S is stated. If it were a Type SP, the Japanese characters for 'Type' would be written after S, followed by the letters SP in English

Model code. DAA-NHP10

Auction Number

出品番号	初度登録	車名	ドア形状	グレード	評価点
30277	H27	アキア	5ハコ	S	4.5
初出品	年	車歴	排気量	燃料	型式
	6月	レンタ	1500cc	ガソリン	DAA-NHP10
外装	内装				
B	B				

Overall Grade 4.5

Exterior and Interior Grade B and B

走行	車検	録番号	名実期限	セールスポイント
53,696 km	年月	Engine size in cc	月日	★SDナビ 地デジ ★バックカメラ ★ETC ★スマートキー ★プッシュスタート
シフト	エアコン	外装色	乗車定員	最大積載量
FAT	AAC	シロ	5人	kg
カラーNo.	内装色	輸入車	リサイクル標記	系
040				9,130円


Positive features box.

- ★ SD = Navigation
  - ★ Terrestrial Digital.
  - ★ Back Camera.
  - ★ Key Push Start.
- Anything of note will be translated at inspection

保証書	ナビ	Auto Aricon	Color Code

Positive comments box. ETC=Electronic Toll card reader

検査員記入欄
<p>ハンドル傷 室内薄汚れ ホイールカバーA 外装小傷有り 室内内張傷小</p> <p><b>Negative comments box</b></p> <ul style="list-style-type: none"> <li>★ Handle scratches</li> <li>★ Dirty from inside</li> <li>★ Small scratches inside</li> </ul> <p>事務局よりご案内</p> <p>キーケース</p>



Feature such as TV, Airbag, Alloy Wheels, Power Steering, Sunroof, Power Windows and rear spoiler are listed here

Chassis number, combine with model code to get chassis code NHP10-2452575

Vehicle Diagram shows damage type and location

A1 to A3=small to large scratch. A1's are hard to see, A3 is a deep scratch. A is also used for small windscreen chips

U1 to U3= small to large pin dent. U1's are often hard to see

B1 to B3= small to large dent

B1 to B3= Minor to serious paint issue such as fading, acid rain damage etc.

Transmission

FA / FAT = Fully Automatic Transmission

5F / 6F = 5 or 5 speed manual transmission

Y1 to Y3= crack, typically bumpers, side-skirts or light

S=Rust

W1 to W3= Wavy, which means paint surface is uneven usually due to painting.

W1 can be very hard to see if not painted out

AU may be combined to describe a dent and scratch together. AU3 would be a large scrape and dent

Body condition will be inspected by our agent and pictures taken of any damage worth noting. Most vehicle will have some small scratches or pin dents. These are normal things to expect from daily use and generally they don't detract from the overall condition

POSITION