



RINGWOOD MINES/LANDFILL SITE WEEKLY CONSTRUCTION UPDATE RINGWOOD BOROUGH, NEW JERSEY



NOVEMBER 22 – DECEMBER 2, 2021 UPDATE #3

Cleanup Activities The Last Two Weeks

- Completed stabilized construction entrance in the Cannon Mine Pit Area
- Completed tree clearing in the Cannon Mine Pit Area
- Installed temporary fence in the Cannon Mine Pit Area
- Completed stabilized construction entrance at the Peters Mine Pit Area
- Completed silt fence installation in the Peters Mine Pit Area
- Began tree clearing in the Peters Mine Pit Area
- Continued silt fence installation at the O'Connor Disposal Area
- Additional excavation equipment was delivered to the site
- Air and vibration monitoring was performed during the work

Cleanup Activities Next Week

- Continue silt fence installation at the O'Connor Disposal Area
- Continue tree clearing in the Peters Mine Pit Area
- Continue air monitoring during the work
- Continue vibration monitoring during the work

Contact Information:

Joe Gowers
EPA Remedial Project Manager
(212) 637-4413
gowers.joe@epa.gov

Pat Seppi
EPA Community Involvement
Coordinator
(646) 369-0068
seppi.pat@epa.gov

Immediate concerns regarding ongoing construction can also be referred to:

de maximis, inc.
(610) 435-1151 ext. 2

Additional Information:

www.epa.gov/superfund/ringwood-mines

Site Background

The 500-acre Ringwood Mines/Landfill site is in a historic iron mining district in the borough of Ringwood in Passaic County, New Jersey where car parts and paint sludge wastes were dumped on the ground and in abandoned mine pits.

EPA originally placed the site on the Superfund program's National Priorities List (NPL) in September 1983. The site was deleted from the NPL in 1994. EPA placed the site on the NPL in 2006 a second time after discovering more contamination. The selected cleanup action for the Peters Mine Pit Area, Cannon Mine Pit Area and the O'Connor Disposal Area is currently being constructed.