

The Sallade's Bill Sallade
TREC #10276
Inspection Services
(469)667-0923
www.TheSallades.com



To: Super Smart customer

PopShelf

101 America Drive Lake Worth, TX

Draw inspection for 1948 S Hwy 78, Wylie, TX



The foundation has been poured.



Steel girders and other steel framing materials have been delivered.



Storm water drains were being worked on at the time of inspection.



Building sheathing has also been delivered.

Bill Sallade

Professional Real Estate Inspector TREC #10276

469-776-0923

inspections@thesallades.com