

The Sallade's Bill Sallade
TREC #10276
Inspection Services
(469)667-0923
www.TheSallades.com



To: Super Smart Customer

Dollar General July 7th 2023

123 Patriot Street
Springtown TX 76082

Draw inspection for 123 Patriot Street, Springtown TX




- Picture of the front and left side of the building.
- The parking lot has been poured and the control joints for the parking lot have been scored



- The sidewalk near the front and side of the building was formed up and getting ready to be poured.



- Painters were on site Painting the interior walls and caulking.



- Electricians were on site installing breakers, running wires etc...
- Storage room. Fire suppression sprinklers were installed.



- Picture of the buildings interior as viewed from the back wall looking towards the front entry.
- Picture of the manager offices.

Bill Sallade

Professional Real Estate Inspector TREC #10276

469-776-0923

inspections@thesallades.com