

¹**Minutes**
Ida Township Road Review Meeting
April 26, 2019
Ida Township Hall
4700 County Rd 6 NW, Garfield, MN 56332

The Board of Supervisors and Clerk/Treasurer Barbara Kilgore proceeded from the Township Hall at 8:30 a.m. to check on the condition of the roads of the township.

Issues noted on the review:

- **Signs**
 - Mallard Lane - street sign missing by Lake Ida Way.
- **Other**
 - Betsy Ross Road – 3538-3512 may need a new drain pipe through the road.
 - Burr Oak Drive – Deep hole in shoulder on north side of the road, across from driveway.
 - Clear View Road – East of County Road 12, South side - steep drop off.
 - Jack Rabbit Trail – Drainage issues. Diedrich will meet with RBS about them.
 - Oakwood Terrace – Drainage issues. Need to get permission from property owner on corner lot (5672) to put in a ditch and a culvert to divert water under the road
 - Pleasant Grove – North part before Big Chip Trail needs small trees removed before they get too large. South of County Road 22 – check west end of culvert by 4268.

Gravel

1 Load = 1 belly dump truck (17 yards)

See the attached 2019 Gravel Map page 2 for locations and amounts. The load amounts are estimates. Approximately 80 loads are required. There were a few other locations that may need more gravel throughout the season.

Chloride

Will be put down in the same areas as 2018, excluding the roads that were blacktopped in 2018 and the roads that will be blacktopped in 2019. See Chloride Map page 3

The Board will act on the issues noted at the May 6, 2019 Town Board Meeting.


The board returned to the township hall at 12:30 p.m. and the meeting was adjourned.

Barbara D. Kilgore
 Ida Township Clerk/Treasurer

Daniel Diedrich
 Ida Township Chairman

2019 Gravel Map

Page 2



80 loads Gravel

2019 Chloride

Page 3

