## Responding in the cold

A photograph of Denver firefighters working to battle the blaze in freezing temperatures with snow falling around them.

Photograph from DFM Permanent

#### **Helpful Hint!**

Collection

Use your zoom in/out feature on your PDF reader to read the document and make the page larger.





#### **Containing the blaze**

Denver firefighters
bravely try to contain
the fire as the response
escalates over the
course of the evening.
Photograph from
DFM Permanent
Collection



The second Big Hammer edition of the year in 1984 documented the events of the Masonic Lodge fire.

> Photograph from DFM Permanent Collection



show the frozen water clinging to the Masonic Lodge building after the fire had been extinguished.

Photograph from DFM **Permanent Collection** 





### **Devastating Destruction**

The building and contents suffered heavy damage. The roof and all of the floors pancaked in on the basement. After the fire, only the rock face sandstone front wall facing Welton St. and 16th St. stood mostly undamaged. The red sandstone parapet's triangular wall located on the corner of 16th and Welton had fallen into the basement below. The masonry wall facing the CAC on Welton St. and the masonry wall on the alley partially collapsed. The commercial occupancies on the street sides remained intact other than heavy smoke and water damage. *Photograph from DFM Permanent Collection* 

# **Masonic Lodge Building Today**

The insurance company, the developer, Masonic Lodge #5, and the City and County of Denver agreed to support the remaining exterior walls prior to the investigation of the fire scene. Six weeks went by before the Fire Investigators could actually start digging the scene. Such coordination with all parties involved is why the Masonic Lodge building is still able to be occupied to this date.

Photograph from DFM
Permanent Collection

