

## Inspection Information

<b>Inspection Date:</b> 2024-01-01	<b>Inspector:</b> Lenny Carlson	<b>Customer:</b> John Doe
<b>Email:</b> Lenny@valleyautoinspections.com		<b>Phone Number:</b> (000) 000-0000
<b>Dealer/Seller:</b> Dealership	<b>Year:</b> 2018	<b>Make:</b> Dodge
<b>Model:</b> Challenger	<b>Mileage:</b> 42412	<b>VIN:</b> 2C3CDZC92JH121405

P = Pass   N = N/A   C = Needs Attention

P   N   C	P   N   C	P   N   C
<p><b>Exterior</b></p> <p><input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> 1. Body/Paint Work</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 2. Scratches/Chips</p> <p><input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> 3. Dings/Dents</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 4. Paint Condition</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 5. Lights</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 6. Glass/Tint</p> <p><b>Tires and Wheels</b></p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7. Condition of Tires</p> <p><input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> 8. Condition of Wheels</p> <p>9. Tire dates - If applicable</p>	<p><b>Test Drive/ Underbody</b></p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 10. Engine Function</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 11. Transmission Function</p> <p>Y <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 12. Suspension Noise</p> <p>Y <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 13. Brake Noise</p> <p>Y <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 14. Leaks</p> <p>Y <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 15. Rust</p> <p><b>Underhood</b></p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 16. Battery/ Terminals</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 17. Oil Level/ Condition</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 18. Coolant Level/ Condition</p> <p>Y <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 19. Modifications</p>	<p><b>Interior</b></p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 20. Seats/ Wear</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 21. Carpet/ Wear</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 22. Door Panels/ Trim Panels</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 23. Radio/ Navigation</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 24. Window Function</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 25. Sunroof/ Convertible</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 26. Air Conditioning/ Heat</p> <p><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 27. OBDII Scan/If Applicable</p> <p>Y <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 28. Other Accessories Seen</p> <p>29. Number of Keys</p>

### Comments

1. **Body/Paint Work** Rear bumper shows touch up on top. Likely due to wear and tear from loading Andy loading trunk.
2. **Scratches/Chips** Minor misc marks seen around exterior. One notable on roof above passenger door.
3. **Dings/Dents** Line dent on passenger front fender. Small ding in passenger door.
4. **Paint Condition** Vehicle has residue left from a vinyl wrap or plastic dip coating. Spoiler has some fading but could be refreshed.
8. **Condition of Wheels** Small marks seen on wheel edges
9. **Tire dates - If applicable** 2024
20. **Seats/ Wear** Normal wear and tear seen on interior no notable damages.
21. **Carpet/ Wear** Floor mats in trunk
22. **Door Panels/ Trim Panels** Light marks on common touch points. No damages seen.
29. **Number of Keys** One red and one black

Pictures





























