



Inspection Information

Inspection Date: 2026-01-01

Inspector: Lenny Carlson

Customer: Buyer

Email: Support@valleyautoinspections.com

is.com

Phone Number: (000) 000-0000

Dealer/Seller: Seller

Year: 2019

Make: Ram

Model: 1500

Mileage: 44007

VIN: 1C6SRELTXKN914566

P = Pass N = N/A C = Needs Attention

P N C

Exterior

Tires and Wheels

- 7. Condition of Tires
 - 8. Condition of Wheels
 - 9. Tire dates - If applicable

P N C

Test Drive/ Underbody

- | | | | |
|-------------------------------------|----------------------------------|--------------------------|---------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 10. Engine Function |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | 11. Transmission Function |
| Y | <input checked="" type="radio"/> | (N) | 12. Suspension Noise |
| Y | <input checked="" type="radio"/> | (N) | 13. Brake Noise |
| Y | <input checked="" type="radio"/> | (N) | 14. Leaks |
| Y | <input checked="" type="radio"/> | (N) | 15. Rust |

Underhood

- 16. Battery/ Terminals
 - 17. Oil Level/ Condition
 - 18. Coolant Level/ Condition
 - 19. Modifications

P N C

Interior

- INTERIOR

 - 20. Seats/ Wear
 - 21. Carpet/ Wear
 - 22. Door Panels/ Trim Panels
 - 23. Radio/ Navigation
 - 24. Window Function
 - 25. Sunroof/ Convertible
 - 26. Air Conditioning/ Heat
 - 27. OBDII Scan/If Applicable
 - 28. Other Accessories Seen
 -  N
 -  Y
 - 29. Number of Keys

Comments

- 1. Body/Paint Work** Tail gate has been touched up and poorly blended. Runs and can be seen on some spots. Rear bumper has overspray spots from bed liner present.
 - 2. Scratches/Chips** Minor marks around front end. Light marks seen around exterior. Plastics around bed have gouges and scratches present.
 - 3. Dings/Dents** Indent on rear of roof.
 - 4. Paint Condition** Bed liner is worn out
 - 7. Condition of Tires** Tires are showing dryness.
 - 8. Condition of Wheels** Scratches present on every wheel.
 - 9. Tire dates - If applicable** 2023
 - 10. Engine Function** Valvetrain was very noisy on cold start but quieted down after warm
 - 20. Seats/ Wear** Normal wear and tear seen.
 - 22. Door Panels/ Trim Panels** Normal light marks from use. Some trim panels are peeling. Ac vent adjuster drive center broken touch point.
 - 28. Other Accessories Seen** Bed cover needs adjustment to sit properly.
 - 29. Number of Keys** One shown

Pictures

























