

Inspection Information

Inspection Date: 2026-08-22
Phone Number: (000) 000-0000
Make: Nissan
VIN: JN1AZ4EH4GM934281

Customer: Copy
Dealer/Seller: Bell Road Mitsubishi
Model: 370Z

Email: Copy
Year: 2016
Mileage: 56462

P = Pass NA = N/A R = Needs Review

P NA R

Exterior

- | | | | |
|-------------------------------------|--------------------------|-------------------------------------|-----------------------------|
| ☐ | ☐ | ☒ | 1. Body/Paint Work |
| ☐ | ☐ | ☒ | 2. Scratches/Chips |
| ☐ | ☐ | ☒ | 3. Dings/Dents |
| ☐ | ☐ | ☒ | 4. Paint Condition |
| ☐ | ☐ | ☒ | 5. Light Condition/Function |
| ☒ | ☐ | ☐ | 6. Glass/Tint |

Tires and Wheels

- | | | | |
|--------------------------|--------------------------|-------------------------------------|-------------------------------|
| ☐ | ☐ | ☒ | 7. Condition of Tires |
| ☐ | ☐ | ☒ | 8. Condition of Wheels/Rims |
| | | | 9. Tire dates - If applicable |

Interior

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|------------------------------|
| ☒ | ☐ | ☐ | 10. Seats/ Wear |
| ☒ | ☐ | ☐ | 11. Carpet/ Wear |
| ☐ | ☐ | ☒ | 12. Door Panels/ Trim Panels |
| ☒ | ☐ | ☐ | 13. Radio/ Navigation |
| ☒ | ☐ | ☐ | 14. Window Function |
| ☐ | ☒ | ☐ | 15. Sunroof/ Convertible |
| ☒ | ☐ | ☐ | 16. Air Conditioning/ Heat |
| ☒ | ☐ | ☐ | 17. OBDII Scan/If Applicable |

P NA R

Interior

- | | | | |
|---|-------------------------------------|--|----------------------------|
| Y | ☒ | | 18. Smells |
| Y | ☒ | | 19. Other Accessories Seen |
| | | | 20. Number of Keys |

Underhood

- | | | | |
|-------------------------------------|--------------------------|--------------------------|------------------------------|
| ☒ | ☐ | ☐ | 21. Battery/ Terminals |
| ☒ | ☐ | ☐ | 22. Oil Level/ Condition |
| ☒ | ☐ | ☐ | 23. Coolant Level/ Condition |
| ☒ | ☐ | ☐ | 24. Visible Hoses/Belts |

Test Drive

- | | | | |
|-------------------------------------|-------------------------------------|--------------------------|---------------------------|
| ☒ | ☐ | ☐ | 25. Engine Function |
| ☒ | ☐ | ☐ | 26. Transmission Function |
| Y | ☒ | | 27. Suspension Noise |
| Y | ☒ | | 28. Brake Noise |
| Y | ☒ | | 29. Visible Leaks |
| Y | ☒ | | 30. Visible Rust |

P NA R

Disclaimer

31. PLEASE NOTE: The attached report represents the vehicle's condition strictly at the time of inspection. Valley Auto Inspections LLC does not have control over the vehicle before or after the assessment; therefore, we cannot be held responsible for any damages or mechanical failures that occur after the inspection is complete.

For questions or concerns, please contact
support@valleyautoinspections.com.

Comments

1. **Body/Paint Work** Side panels on roof poorly painted.
2. **Scratches/Chips** Excessive marks and scratches seen throughout exterior.
3. **Dings/Dents** Ding in driver rear fender edge.
4. **Paint Condition** Various panels show heavy paint fading.
5. **Light Condition/Function** Headlights and lower brake light foggy and peeling.
6. **Glass/Tint** Miscellaneous small marks
7. **Condition of Tires** Front tires need to be replaced. Rear do not match.
8. **Condition of Wheels/Rims** Rims have chips and have been poorly repainted.
9. **Tire dates - If applicable** Front 2023
Rear 2026
10. **Seats/ Wear** Normal wear and tear seen.
12. **Door Panels/ Trim Panels** Steering wheel shows heavy wear. , Marks and scratches seen throughout cargo areas. Minor marks seen on common touchpoints through interior.
13. **Radio/ Navigation** Aftermarket radio
17. **OBDII Scan/If Applicable** Vehicle would drop idle during inspection and cause ac to get warm and once system idled up it was cold again.
20. **Number of Keys** One shown

Pictures






















← Car health check

Car health check complete: Your vehicle's system has been scanned.

The OBD2 system was scanned for critical faults.

ECU checked

✓ Results: **No issues detected**

The live data parameters were analyzed for potential issues.

Live data checked

✓ Results: **No issues detected**

The engine light status was verified.

Engine light checked

✓ Results: **No issues detected**
Engine light OFF

