


Demo Customer

Solar Thermography Pro

SCHEMATIC REPORT

Inspected 21 September 2023



Legend



Single bypassed (3)	PID (1)
Suspected PID (11)	Hotspot (193)
Multi hotspot (153)	Heated junction box (10)
String (open circuit) (7)	Module (open circuit) (12)
Miscellaneous issue (5)	

Demo Customer

Solar Thermography Pro

SCHEMATIC REPORT

Inspected 21 September 2023



Legend


- Single bypassed (1)
- Hotspot (27)
- Multi hotspot (17)

Demo Customer

Solar Thermography Pro


SCHEMATIC REPORT

Inspected 21 September 2023




Legend

Single bypassed (1)	PID (1)
Suspected PID (11)	Hotspot (36)
Multi hotspot (27)	Heated junction box (2)
String (open circuit) (7)	Module (open circuit) (4)





Solar Thermography Pro

Inspected 21 September 2023



Hotspot (46)	Multi hotspot (50)
Heated junction box (3)	Module (open circuit) (5)
Miscellaneous issue (5)	






Demo Customer

Solar Thermography Pro

SCHEMATIC REPORT

Inspected 21 September 2023



Legend


- Single bypassed (1)
- Hotspot (22)
- Multi hotspot (14)
- Heated junction box (1)
- Module (open circuit) (1)

Demo Customer

Solar Thermography Pro

SCHEMATIC REPORT

Inspected 21 September 2023



Legend



Multi hotspot (1)

Demo Customer

Solar Thermography Pro


SCHEMATIC REPORT

Inspected 21 September 2023



Legend

- | | |
|-------------------------|---------------------------|
| Hotspot (49) | Multi hotspot (25) |
| Heated junction box (3) | Module (open circuit) (2) |




Demo Customer

Solar Thermography Pro

SCHEMATIC REPORT

Inspected 21 September 2023



Legend

- Hotspot (19)
- Multi hotspot (25)
- Heated junction box (1)