

Sanitary Sewer Overflow Summary

SSO Report Log: (Includes basements if caused by public asset problems)

Red = DEQ reported and additional information posted on web site

GRINDER PUMP RELATED - 37th Street and/or Sherman lake pressure sewer - Sh LK grinder system on line late 2007 - early 2008						
Date	Location	(Ground Basement Surface Water) Type	Reported to MDEQ	Gallons Estimated	Grinder Related	Summary remarks
7/21/2014	Clarkson residence: 5201 N 37th Street	Ground	Yes	75	yes	Leaking Grinder pump connection at street - copper connection corroded
3/11/2012	Swaniker: 5204 N 37th Street	Ground	Yes	50	yes	Leaking Grinder basin - seepage out from the lid - failed grinder pump
10/4/2011	N of 6091 Island Drive	Surface Water	Yes	300		Drilling company drilled through improperly marked 3" pressure sewer line
9/14/2011	Clarkson residence: 5201 N 37th Street	Ground	No	minimal	yes	Leaking Grinder pump check valve assembly at street
4/28/2011	Family Living, Inc: 6254 N 37th Street	Ground	No	minimal	yes	Leaking Grinder pump discharge line at basin
7/11/2010	To Luat residence: 5370 N 37th Street	Ground	No	minimal	yes	Leaking Grinder pump discharge line at curb stop
3/1/2009	6347 N 37th Street: edge of road	Ground	Yes	100,000	yes	Leaking Grinder pump connection at street - copper connection corroded
6/10/2008	Dunn residence: 4216 N 37th Street	Basement	No	minimal	yes	Grinder pump check valve at basin failed during extended power outage
5/16/2008	Lager residence: 6091 Island Drive	Ground	No	minimal	yes	Leaking Grinder pump check valve assembly at street

NON-GRINDER PUMP RELATED - Basements + Ground						
Date	Location	(Ground Basement Surface Water) Type	Reported to MDEQ	Gallons Estimated	Grinder Related	Summary remarks
5/26/2016	9228 Pattiwood	Basement	No	minimal		Plugged 8" sanitary- S end of Pattiwood. Pieces of asphalt. Vacated - to be televised
7/1/2015	9820 E M-89	Garage floor	No	200		Plugged 8" drop pipe - vacated out brick and rags + televised
6/23/2015	Lift Station #1 - 7300 N 37th Street	Surface Water	Yes	40,000		4" rain event over 2 hour - flows overwhelmed LS #1 capability
11/18/2014	Lift Station #1 - 7300 N 37th Street	Surface Water	Yes	24,000		See Snake investigation project - cleaning pig plugged end manhole
7/22/2013	Liggett: N of 5201 N 37th Street	Ground	Yes	1,200		Failure of galvanized nipple for a force main air release valve
9/14/2008	Lift Station #1 - 7300 N 37th Street	Surface Water	Yes	80,000		10" rain event - flows overwhelmed LS #1 capability
7/2/2008	Lift Station #1 - 7300 N 37th Street	Surface Water	Yes	9,000		Heavy rain event over 2 hours + 2 days - Power outage - LS #1 generator failed to start
6/2/2008	Rolling Pines apts: 9605 E. D Avenue	Ground	No	minimal		Manhole cover removed and debris deposited plugging pipe
3/18/2005	Lord residence: 8800 Tamarisk Circle	Basement	No	minimal		Manhole plugged from sewer connection debris
10/17/2000	Perrin residence: 10756 M-43	Basement	No	minimal		Manhole plugged, low flow manhole
12/27/2000	7200 Block N 37th Street	Ground	Yes	1,800		Seepage from Air Release south of LS #1
10/19/1999	Shank's + Pew's residences: 574 + 678 EGLD	Basements	No	1,500		Lift Station 18 back up from alarm system malfunction
6/7/1985	Spitters residence: 2163 Idlewild	Basement (2x)	No	100		Lift Station 5 back up from alarm system malfunction
6/7/1985	Marshall residence: 2187 Idlewild	Basement (2x)	No	1,500		Lift Station 5 back up from alarm system malfunction