
	Police Use Only Commonwealth of Massachusetts RMV Document Number										
	Date of Crash Time of Crash		otor Veh	icle Cras	$\mathbf{h}$ $\begin{bmatrix} N_1 \\ V_{\ell} \end{bmatrix}$		howai	Speed l		State Police Local Police MBTA Police Campus Police	1 2
	07/07/2024 1432 Aub	ourn	<b>Police</b>	Report	1	0	·	Latitud Longitu		MBTA Police Campus Police Other:	1
	AT INTERSECT	ΓΙΟN: <	LOCA	TION >		NO				CTION:	┐
											<b>1</b> 10
	Route# Direction	Name of Roadway/Street		Route# Direction	n Addr	ress #	OCH:		E ST	dway/Street	_[-
<sup>1</sup> 1	Kouter Direction	At						ING	inc or Road	away/Succi	-
				Feet N	S E W	of —	— — Iile Mar		— or	Exit Number	- 🖳
	Route# Direction N	Name of Intersecting Roadway/Stree  Also at Intersection with	et	Feet N	SEW		THE IVIAL	KCI			<b>1</b> 11
		Also at Intersection with			S E W	Rou	ite#		Intersectin	g Roadway/Street	
<sup>2</sup> <b>1</b>	Route# Direction N	Name of Intersecting Roadway/Stree	et	Feet	S E W				Landma	-1-	_
	Please Select One		T_,			0.4.	226			ark	┥
<sup>3</sup> 99	of the Following:	#Occupants Hit/Run	Moped	Crash Rep	ort ID#	24-2	23(	) – [	AC		╛
		TX DOB/Age 02/09/19	955 Reg #	# <u>738216J</u>		R	eg Type	AHN	1		- 12
	Sex M Lic. Class D 19 Lic.	. Restrictions CDL CDL	Veh	Year <b>2006</b>	Veh M	ake <b>Tru</b>	ck		V	eh Config. 8	1
	Operator WINKLER, ELMF			er WINKLER	, ELI	MER C	HAR	LES			_
<sup>4</sup> <b>1</b>	Address 17495 OWL CREI			ess <b>17495</b> O	WL C	REEK	RD			Middle	_
	City <b>MOODY</b> Sta	ate <b>TX</b> Zip <b>76557</b>	City	MOODY			Stat	e <b>TX</b>	Zip_	76557	_
	Insurance Company <b>GERMANIA</b>	FIRE & CASUALI	<b>IY</b> Vehic	ele Action Prior to Cra	ash	1 22	Da	maged	Area Code	9 27 27 27	
	Vehicle Travel Direction: N S E	Responding to Emergency? 2	Even	t Sequence 34 23	23	23 23	Tes	st Statu	is:	28	
<sup>5</sup> <b>1</b>	Citation # (If Issued)		Most		34 <sup>24</sup>		-	pe of To		30	
	Viol. 1: Ch/Sec/Sub		Drive	er Contributing Code		<sup>25</sup> 3 <sup>2</sup>	25	AC Test sp. Alco	Result:	31 Susp. Drug: 32	<b>28</b> <sup>13</sup>
	Viol. 3: Ch/Sec/Sub			er Distracted by	26	26	_	•	om scene?	2 33	
<sup>6</sup> 1		erator and all occupants involved		2 2 3 4 4 4 4	34	35 36	37	38	39 40		_
	Name (Last First Middle)	Address		DOB/Age	Sex Seat Pos.	Safety Airba System Statu	s Code	Trap Code	Injury Trans Status Cod		_
	Operator	See Abov	re		X 1	99 99	0	0	10 1		
	Please Select One										┪
<sup>7</sup> 2	of the Following:	#Occupants Hit/Run	Moped	Vulnerable	User Co	mplete the V	ulnerabl	e User	section.		╛
		DOB/Age	Reg #	#		R	eg Type				-
	Sex Lic. Class 19	. Restrictions CDL CDL		Year	Veh Ma	ake			V	eh Config.	
8	Operator	First Middle	Own	er	t .		First			Middle	-
<sup>8</sup> 1	Address	Iddic		ess							-
	City Sta	ate Zip	City_				Stat	е	Zip		_ <b>1</b> 14
	Insurance Company		Vehic	cle Action Prior to Cra	ash	22	Da	maged	Area Code		
	Vehicle Travel Direction: NSEW	Responding to Emergency?	Even	t Sequence 23	23	23 23		st Statu		28	
9 .	Citation # (If Issued)		Most	Harmful Event	24	,		pe of To	est: Result:	30	
<sup>9</sup> <b>1</b>	Viol. 1: Ch/Sec/Sub	Viol. 2: Ch/Sec/Sub	Drive	er Contributing Code		25 2	25	sp. Alco		31 Susp. Drug: 32	
	Viol. 3: Ch/Sec/Sub			er Distracted by	26	26		•	om scene?	33	
		erator and all occupants involved		T -	34 Seat	35 36 Safety Airba	37 g Eject	38 Trap	39 40 Injury Trans	sp.	7
	Name (Last First Middle)	Address		DOB/Age	Sex Pos.	System Statu	Code	Code	Status Cod		$\dashv$
	Operator/Occupants	See Abov	re		X 1						_



V1 was travelling west on Rochdale St. V1 is a tall fifth wheel camper. V1 made contact with a railroad bridge as it passed under it leaving debris in roadway. There are dangerous intersection and a bridge height sign plainly visible before the bridge. V1 could of turned onto Leicester St to avoid bridge. Due to the height of the trailer it should of been readily apparent it was not going to fit underneath the bridge. There was cosmetic damage to the bridge. Providence Worcester Railroad was contacted to check the bridge structure. V1 did not stop to report accident. V1 was stopped in another town.

There was three locations in Auburn the vehicle could have stopped to report the accident. Due to operator being out of state and no obvious signs of structural damage to bridge operator was given verbal warning for leaving the scene of property damage.

Withesses.											
Name (Last,First,Middle)	Address				Phone #	Statement					
					-						
Property Damage:											
Owner (Last,First,Middle)	Address		Phone #	41-Type	Descri	iption of Dan	naged Property				
PROVIDENCE WORCESTER RAILROAD 75 HAMMOND ST WORCE		ESTER MA 01610		97	RAI	LROAD	BRIDGE				
Truck and Bus Information:  Registration #											
Address			City			St	Zip				
US DOT #:	State Number		Issuing State	MC/MX	/ICC #:						
Interstate 43 Cargo Body Typ	e Code	GVWR/GCWR	45				46				
Trailer Reg #:	Reg Type	Reg State	Reg Year	——— Trai	iler Len	gth	40				
Hazmat Information:											
Placard Material 1 digit #	48 Material Name	>		_Material 4 dig	git #		Release code	49			

62AG

ID/Badge #

Patrolman Adam D Gustafson
Police Officer Name (Please Print)

Auburn Police Department

07/07/2024

Signature

Department

Precinct/Barracks

Date