

Date of Crash **03/28/2024** Time of Crash **1852** City/Town **Auburn** **Motor Vehicle Crash Police Report** Number Vehicles **1** Number Injured **0** Speed Limit **30** State Police Local Police MBTA Police Campus Police Other:

AT INTERSECTION: < LOCATION > NOT AT INTERSECTION:

Route# _____ Direction _____ Name of Roadway/Street _____ At _____

Route# _____ Direction _____ Name of Intersecting Roadway/Street _____ Also at Intersection with _____

Route# _____ Direction _____ Name of Intersecting Roadway/Street _____

Route# **44** Direction _____ Address # **BARNES ST** Name of Roadway/Street _____

Feet **N S E W** of _____ or _____ Mile Marker _____ Exit Number _____

Feet **N S E W** of _____ Route# _____ Intersecting Roadway/Street _____

Feet **N S E W** of _____ Landmark _____

Please Select One of the Following: Vehicle **1** #Occupants Hit/Run Moped Crash Report ID# **24-97-AC**

License # **S76109062** St **MA** DOB/Age **07/22/1980** Reg # **S46381** Reg Type **CON** Reg State **MA**

Sex **M** Lic. Class **D 19 19** Lic. Restrictions **20** CDL _____ Veh Year **2016** Veh Make **CHEVROLET** Veh Config. **1 21**

Operator **MCCALL, MATTHEW L** Owner **MCCALL, CHRISTINA M**

Address **65 S OXFORD RD** Address **65 S OXFORD RD**

City **MILLBURY** State **MA** Zip **01527-1034** City **MILLBURY** State **MA** Zip **01527-1034**

Insurance Company **THE COMMERCE INSURANCE CO** Vehicle Action Prior to Crash **1 22** Damaged Area Code: **2 27 27 27**

Vehicle Travel Direction: **N S E W** Responding to Emergency? **2** Event Sequence **21 23 23 23 23** Test Status: **1 28**

Citation # (If Issued) _____ Most Harmful Event **21 24** Type of Test: **29**

Viol. 1: Ch/Sec/Sub _____ Viol. 2: Ch/Sec/Sub _____ Driver Contributing Code **11 25 25** BAC Test Result: **30**

Viol. 3: Ch/Sec/Sub _____ Viol. 4: Ch/Sec/Sub _____ Driver Distracted by **0 26** Susp. Alcohol: **2 31** Susp. Drug: **2 32**

Towed from scene? **1 33**

Please fill out for operator and all occupants involved		DOB/Age	Sex	34 Seat Pos.	35 Safety System	36 Airbag Status	37 Eject Code	38 Trap Code	39 Injury Status	40 Transp. Code	Medical Facility
Operator	See Above	XXXX	XX	1	1	4	0	0	10	1	

Please Select One of the Following: Vehicle **2** #Occupants Non-Motorist A Type **15** Action **16** Location **17** Condition **18** Hit/Run Moped

License # _____ St _____ DOB/Age _____ Reg # _____ Reg Type _____ Reg State _____

Sex _____ Lic. Class **19 19** Lic. Restrictions **20** CDL _____ Veh Year _____ Veh Make _____ Veh Config. **21**

Operator _____ Owner _____

Address _____ Address _____

City _____ State _____ Zip _____ City _____ State _____ Zip _____

Insurance Company _____ Vehicle Action Prior to Crash **22** Damaged Area Code: **27 27 27**

Vehicle Travel Direction: **N S E W** Responding to Emergency? _____ Event Sequence **23 23 23 23** Test Status: **28**

Citation # (If Issued) _____ Most Harmful Event **24** Type of Test: **29**

Viol. 1: Ch/Sec/Sub _____ Viol. 2: Ch/Sec/Sub _____ Driver Contributing Code **25 25** BAC Test Result: **30**

Viol. 3: Ch/Sec/Sub _____ Viol. 4: Ch/Sec/Sub _____ Driver Distracted by **26** Susp. Alcohol: **31** Susp. Drug: **32**


Towed from scene? **33**

Please fill out for operator/non-motorist and all occupants involved		DOB/Age	Sex	34 Seat Pos.	35 Safety System	36 Airbag Status	37 Eject Code	38 Trap Code	39 Injury Status	40 Transp. Code	Medical Facility
Operator/Non-Motorist	See Above	XXXX	XX	1							

→ = Direction 1 = Vehicle 1 2 = Vehicle 2 ○ = Pedestrian 🚲 = Bicycle

Crash Diagram:

ie: → 1 → 2 → ○ → 🚲



If Crash Did Not Occur on a Public Way:

- Off-Street Parking Lot
- Garage
- Mall/Shopping Center
- Other Private Way

↑ Arrow



Crash Narrative:

Vehicle #1 was traveling westbound on Barnes Street. The driver stated that a deer ran out in front of him and he swerved to avoid hitting the deer when he hit a tree roadside. The vehicle was towed from the scene. No injuries to report.

Witnesses:

Name (Last,First,Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last,First,Middle)	Address	Phone #	41-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Bus Use 42

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ MC/MX/ICC #: _____

Interstate 43 Cargo Body Type Code 44 GVWR/GCWR 45

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length 46

Hazmat Information:

Placard 47 Material 1 digit # 48 Material Name _____ Material 4 digit # _____ Release code 49

Patrolman Alex K Myers

Police Officer Name (Please Print)

Signature

89AM

ID/Badge #

Auburn Police Department

Department

Precinct/Barracks

03/28/2024

Date