


Police Use Only			Commonwealth of Massachusetts					RMV Document Number						
Date of Crash 08/10/2026		Time of Crash 0729 24HR		City/Town Auburn		Motor Vehicle Crash Police Report			Number Vehicles 2	Number Injured 0	Speed Limit 40		State Police ☐ Local Police ☒ MBTA Police ☐ Campus Police ☐ Other: ☐	
AT INTERSECTION:				< LOCATION >		NOT AT INTERSECTION:								
11 Route# Direction Name of Roadway/Street At Route# Direction Name of Intersecting Roadway/Street Also at Intersection with Route# Direction Name of Intersecting Roadway/Street						210 Route# Direction Address # Name of Roadway/Street Feet N S E W of or Mile Marker Exit Number Feet N S E W of Route# Intersecting Roadway/Street Feet N S E W of Landmark								
Please Select One of the Following:		☒ Vehicle 11 #Occupants		☐ Hit/Run		☐ Moped		Crash Report ID# 26-307-AC						
License # St. DOB/Age						Reg # 431JG0 Reg Type PC Reg State MA								
Sex F Lic. Class D 19 19 Lic. Restrictions B 20 CDL Endorsement						Veh Year 2016 Veh Make TOYOTA Veh Config. 1 21								
Operator BLAIS, CYNTHIA MARIE Last First Middle						Owner BLAIS, CYNTHIA MARIE Last First Middle								
Address 2 PITCAIRN AVE						Address 2 PITCAIRN AVE								
City LEICESTER State MA Zip 01524-1214						City LEICESTER State MA Zip 01524-1214								
Insurance Company PLYMOUTH ROCK ASSURANCE C						Vehicle Action Prior to Crash 4 22				Damaged Area Code: 4 27 27 27				
Vehicle Travel Direction: N X E W Responding to Emergency? 2						Event Sequence 1 23 23 23 23				Test Status: 1 28				
Citation # (If Issued)						Most Harmful Event 1 24				Type of Test: 0 29				
Viol. 1: Ch/Sec/Sub Viol. 2: Ch/Sec/Sub						Driver Contributing Code 1 25 25				BAC Test Result: 1 30				
Viol. 3: Ch/Sec/Sub Viol. 4: Ch/Sec/Sub						Driver Distracted by 0 26 26				Susp. Alcohol: 2 31 Susp. Drug: 2 32				
Please fill out for operator and all occupants involved						Towed from scene? 99 33								
Name (Last First Middle) Address DOB/Age Sex 34 Seat Pos. 35 Safety System 36 Airbag Status 37 Eject Code 38 Trap Code 39 Injury Status 40 Transp. Code Medical Facility														
Operator See Above						1 1 4 0 0 10 1								
Please Select One of the Following:		☒ Vehicle 21 #Occupants		☐ Hit/Run		☐ Moped		☐ Vulnerable User Complete the Vulnerable User section.						
License # St. DOB/Age						Reg # 4HCK21 Reg Type PC Reg State MA								
Sex F Lic. Class D 19 19 Lic. Restrictions B 20 CDL Endorsement						Veh Year 2018 Veh Make TOYOTA Veh Config. 1 21								
Operator MARDIROSIAN, SHELBY ELIZABETH Last First Middle						Owner MARDIROSIAN, SHELBY ELIZABETH Last First Middle								
Address 152 CENTER DEPOT RD						Address 152 CENTER DEPOT RD								
City CHARLTON State MA Zip 01507-1214						City CHARLTON State MA Zip 01507-1214								
Insurance Company PREFERRED MUTUAL INSURANC						Vehicle Action Prior to Crash 1 22				Damaged Area Code: 1 27 27 27				
Vehicle Travel Direction: X S E W Responding to Emergency? 2						Event Sequence 1 23 23 23 23				Test Status: 1 28				
Citation # (If Issued)						Most Harmful Event 1 24				Type of Test: 0 29				
Viol. 1: Ch/Sec/Sub Viol. 2: Ch/Sec/Sub						Driver Contributing Code 1 25 25				BAC Test Result: 1 30				
Viol. 3: Ch/Sec/Sub Viol. 4: Ch/Sec/Sub						Driver Distracted by 0 26 26				Susp. Alcohol: 2 31 Susp. Drug: 2 32				
Please fill out for operator and all occupants involved						Towed from scene? 2 33								
Name (Last First Middle) Address DOB/Age Sex 34 Seat Pos. 35 Safety System 36 Airbag Status 37 Eject Code 38 Trap Code 39 Injury Status 40 Transp. Code Medical Facility														
Operator/Occupants See Above						1 1 4 0 0 10 1								

→ = Direction 1 = Vehicle 1 2 = Vehicle 2 ○ = Pedestrian ○ = Bicycle

Crash Diagram:

ie: → 1 → 2 → ○ → ○



If Crash Did Not Occur on a Public Way:

- ☐ Off-Street Parking Lot
- ☐ Garage
- ☐ Mall/Shopping Center
- ☐ Other Private Way

North Arrow



Crash Narrative:

Carl was waiting to turn left into 717 Southbridge Street. The vehicle in the left lane of the northbound lane waved carl to go. Carl inched into the right northbound travel lane and car2 was traveling north in the right lane. Car2 struck Carl's rear passenger tire. Car2 had damage to the front and Carl right rear tire had damage. No airbag deployment and neither operator were injured.

Witnesses:

Name (Last,First,Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last,First,Middle)	Address	Phone #	41-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Bus Use ☐ 42

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ MC/MX/ICC #: _____

Interstate ☐ 43 Cargo Body Type Code ☐ 44 GVWR/GCWR ☐ 45

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length ☐ 46

Hazmat Information:

Placard ☐ 47 Material 1 digit # ☐ 48 Material Name _____ Material 4 digit # _____ Release code ☐ 49

Patrolman Grace Griffin

Police Officer Name (Please Print)

Signature

98GG

ID/Badge #

Auburn Police Department

Department

Precinct/Barracks

08/10/2026

Date