


→ = Direction 1 = Vehicle 1 2 = Vehicle 2 ○ = Pedestrian ○ = Bicycle

Crash Diagram:

ie: → 1 → 2 → ○ → ○



Crash Narrative:

Vehicle 1 was traveling Westbound on Route 20 in the right lane. An UNKNOWN vehicle was traveling in the left hand lane. At some point the UNKNOWN vehicle allegedly attempted to merge into the right hand lane. To avoid being struck, Vehicle 1 swerved to avoid the UNKNOWN vehicle. Due to this, Vehicle 1 struck the guardrail damaging the front passenger side. The female passenger was believed to have sustained minor injuries and was transported [REDACTED]. Vehicle 1 was towed by Direccion's.

Witnesses:

Name (Last,First,Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last,First,Middle)	Address	Phone #	41-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Bus Use ☐ 42
 Address _____ City _____ St _____ Zip _____
 US DOT #: _____ State Number _____ Issuing State _____ MC/MX/ICC #: _____
 Interstate ☐ 43 Cargo Body Type Code ☐ 44 GVWR/GCWR ☐ 45
 Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length ☐ 46

Hazmat Information:

Placard ☐ 47 Material 1 digit # ☐ 48 Material Name _____ Material 4 digit # _____ Release code ☐ 49

Patrolman Nathan Lewos

Police Officer Name (Please Print)

Signature

103NL

ID/Badge #

Auburn Police Department

Department

Precinct/Barracks

08/10/2026

Date