

Date of Crash 01/05/2026 Time of Crash 1921 City/Town Auburn

Motor Vehicle Crash Police Report

Number Vehicles 2 Number Injured 0 Speed Limit 30 State Police Local Police MBTA Police Campus Police Other

AT INTERSECTION: < LOCATION > NOT AT INTERSECTION:

Location details for ROCHDALE ST and WEST ST, including route numbers, directions, and intersection names.

Please Select One of the Following: [X] Vehicle 1 Occupants [ ] Hit/Run [ ] Moped Crash Report ID# 26-6-AC

Operator and Owner information for SEAN M LUCIER, including license, address, insurance, and vehicle details.

Table with columns for Name, Address, DOB/Age, Sex, and various vehicle safety features (Seat Pos, Safety System, Airbag Status, Eject Code, Trap Code, Injury Status, Transp. Code, Medical Facility).

Please Select One of the Following: [X] Vehicle 2 Occupants [ ] Hit/Run [ ] Moped [ ] Vulnerable User Complete the Vulnerable User section.


Operator and Owner information for NADIYA A ISGRO, including license, address, insurance, and vehicle details.

Table with columns for Name, Address, DOB/Age, Sex, and various vehicle safety features (Seat Pos, Safety System, Airbag Status, Eject Code, Trap Code, Injury Status, Transp. Code, Medical Facility).

→ = Direction    1 = Vehicle 1    2 = Vehicle 2    ○ = Pedestrian    ○ = Bicycle

**Crash Diagram:**

ie: → 1 → 2 → ○ → ○



**If Crash Did Not Occur on a Public Way:**

- Off-Street Parking Lot
- Garage
- Mall/Shopping Center
- Other Private Way

North Arrow



**Crash Narrative:**

V1 was traveling south on Rochdale Street. V2 stopped at the stop sign. The operator of V1 stated that he flashed their headlights to V2. V2 attempted to take a left onto Rochdale Street. V1 crashed into the passenger side door/ rear drivers side tire.

**Witnesses:**

Name (Last,First,Middle)	Address	Phone #	Statement

**Property Damage:**

Owner (Last,First,Middle)	Address	Phone #	41-Type	Description of Damaged Property

**Truck and Bus Information:**

Registration # \_\_\_\_\_ (From Vehicle Section)

Carrier Name \_\_\_\_\_ Bus Use  42

Address \_\_\_\_\_ City \_\_\_\_\_ St \_\_\_\_\_ Zip \_\_\_\_\_

US DOT #: \_\_\_\_\_ State Number \_\_\_\_\_ Issuing State \_\_\_\_\_ MC/MX/ICC #: \_\_\_\_\_

Interstate  43    Cargo Body Type Code  44    GVWR/GCWR  45

Trailer Reg #: \_\_\_\_\_ Reg Type \_\_\_\_\_ Reg State \_\_\_\_\_ Reg Year \_\_\_\_\_ Trailer Length  46

**Hazmat Information:**

Placard  47    Material 1 digit #  48    Material Name \_\_\_\_\_ Material 4 digit # \_\_\_\_\_ Release code  49

Patrolman David Ljunggren

Police Officer Name (Please Print)

Signature

82DL

ID/Badge #

Auburn Police Department

Department

Precinct/Barracks

01/05/2026

Date