


Police Use Only			Commonwealth of Massachusetts						RMV Document Number								
Date of Crash 12/01/2025		Time of Crash 1709 24HR		City/Town Auburn		Motor Vehicle Crash Police Report			Number Vehicles 2	Number Injured 0	Speed Limit 45 Latitude Longitude		State Police Local Police MBTA Police Campus Police Other:		<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
AT INTERSECTION:						< LOCATION >		NOT AT INTERSECTION:									
Route# Direction Name of Roadway/Street At Route# Direction Name of Intersecting Roadway/Street Also at Intersection with Route# Direction Name of Intersecting Roadway/Street						Route# Direction Address # Name of Roadway/Street Feet N S E W of or Mile Marker Exit Number Feet N S E W of Route# Intersecting Roadway/Street Feet N S E W of Landmark											
Please Select One of the Following:		<input checked="" type="checkbox"/> Vehicle 11 #Occupants		<input type="checkbox"/> Hit/Run		<input type="checkbox"/> Moped		Crash Report ID# 25-428-AC									
License # S58783513 St MA DOB/Age 01/21/1964 Sex M Lic. Class D 19 19 Lic. Restrictions 20 CDL Endorsement Operator LOSAW, DANA MICHAEL Address 1250 W BOYLSTON ST City WORCESTER State MA Zip 01606-1149 Insurance Company CENTURY INSURANCE Vehicle Travel Direction: N S E X Responding to Emergency? 2 Citation # (If Issued) Viol. 1: Ch/Sec/Sub Viol. 2: Ch/Sec/Sub Viol. 3: Ch/Sec/Sub Viol. 4: Ch/Sec/Sub						Reg # 3010499 Reg Type APN Reg State IN Veh Year 2019 Veh Make RAM Veh Config. 6 Owner MEYER LOGISTICS INC Address 306 E 25TH ST City JASPER State IN Zip 47546 Vehicle Action Prior to Crash 1 22 Event Sequence 1 23 23 23 23 Most Harmful Event 1 24 Driver Contributing Code 19 25 25 Driver Distracted by 99 26 26 Damaged Area Code: 2 27 27 27 Test Status: 1 28 Type of Test: 29 BAC Test Result: 30 Susp. Alcohol: 2 31 Susp. Drug: 2 32 Towed from scene? 2 33											
Please fill out for operator and all occupants involved																	
Name (Last First Middle)		Address		DOB/Age		Sex		34 Seat Pos.	35 Safety System	36 Airbag Status	37 Eject Code	38 Trap Code	39 Injury Status	40 Transp. Code	Medical Facility		
Operator		See Above		X		X		1	1	4	0	0	10	1			
Please Select One of the Following:		<input checked="" type="checkbox"/> Vehicle 21 #Occupants		<input type="checkbox"/> Hit/Run		<input type="checkbox"/> Moped		<input type="checkbox"/> Vulnerable User Complete the Vulnerable User section.									
License # 189571952 St CT DOB/Age 06/12/1970 Sex F Lic. Class D 19 19 Lic. Restrictions 20 CDL Endorsement Operator ETZEL, WENDOLYN BARBARA Address 128 POWHATTAN ST City PUTNAM State CT Zip 06260 Insurance Company Progressive Direct Insura Vehicle Travel Direction: N S E X Responding to Emergency? 2 Citation # (If Issued) Viol. 1: Ch/Sec/Sub Viol. 2: Ch/Sec/Sub Viol. 3: Ch/Sec/Sub Viol. 4: Ch/Sec/Sub						Reg # BF86668 Reg Type PAN Reg State CT Veh Year 2015 Veh Make CHEVROLET Veh Config. 1 Owner ETZEL, WENDOLYN BARBARA Address 128 POWHATTAN ST City PUTNAM State CT Zip 06260 Vehicle Action Prior to Crash 2 22 Event Sequence 1 23 23 23 23 Most Harmful Event 1 24 Driver Contributing Code 1 25 25 Driver Distracted by 0 26 26 Damaged Area Code: 4 27 5 27 27 Test Status: 1 28 Type of Test: 29 BAC Test Result: 30 Susp. Alcohol: 2 31 Susp. Drug: 2 32 Towed from scene? 2 33											
Please fill out for operator and all occupants involved																	
Name (Last First Middle)		Address		DOB/Age		Sex		34 Seat Pos.	35 Safety System	36 Airbag Status	37 Eject Code	38 Trap Code	39 Injury Status	40 Transp. Code	Medical Facility		
Operator/Occupants		See Above		X		X		1	1	4	0	0	10	1			

→ = Direction 1 = Vehicle 1 2 = Vehicle 2 ○ = Pedestrian ○ = Bicycle

Crash Diagram:

ie: → 1 → 2 → ○ → ○



If Crash Did Not Occur on a Public Way:

- ☐ Off-Street Parking Lot
- ☐ Garage
- ☐ Mall/Shopping Center
- ☐ Other Private Way

↓ Arrow

Crash Narrative:

Vehicle 2 was slowing down in traffic and traveling westbound on Washington Street (public way). Vehicle 1 was traveling the same direction behind Vehicle 2 when the operator stated that he wasn't paying attention for a moment and that's when vehicle 1 ran into the back of vehicle 2 who was slowing due to traffic. No injuries to report and no vehicles needed to be towed from the scene.

Witnesses:

Name (Last,First,Middle)	Address	Phone #	Statement

Property Damage:

Owner (Last,First,Middle)	Address	Phone #	41-Type	Description of Damaged Property

Truck and Bus Information:

Registration # _____ (From Vehicle Section)

Carrier Name _____ Bus Use ☐ 42

Address _____ City _____ St _____ Zip _____

US DOT #: _____ State Number _____ Issuing State _____ MC/MX/ICC #: _____

Interstate ☐ 43 Cargo Body Type Code ☐ 44 GVWR/GCWR ☐ 45

Trailer Reg #: _____ Reg Type _____ Reg State _____ Reg Year _____ Trailer Length ☐ 46

Hazmat Information:

Placard ☐ 47 Material 1 digit # ☐ 48 Material Name _____ Material 4 digit # _____ Release code ☐ 49

Patrolman Alex K Myers

Police Officer Name (Please Print)

Signature

89AM

ID/Badge #

Auburn Police Department

Department

Precinct/Barracks

12/01/2025

Date