National Indoor RV Centers

498 E State Hwy 121, Lewisville, TX 75055 Phone: (469) 277-1330

FAX: (469) 718-0326

Workfile ID: PartsShare:

Federal ID:

7C7vFx

27-0615910

f5872612

Preliminary Estimate

Customer: MALONE, TONY

Written By: Ricardo Porter

Insured:

MALONE, TONY

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact:

Owner:

MALONE, TONY 914 N MARSALAS AVE. DALLAS, TX 75203 (972) 743-5986 Cell

Inspection Location:

National Indoor RV Centers 498 E State Hwy 121 Lewisville, TX 75055

Repair Facility (469) 277-1330 Business Insurance Company:

VEHICLE

2007 DESTINATION

VIN:

4UZACJBV27CX86351

Interior Color:

Mileage In:

Vehicle Out:

License:

Exterior Color:

Mileage Out:

State:

Production Date:

Condition:

Job #:

Preliminary Estimate

Customer: MALONE, TONY

2007 DESTINATION

Line		Oper	Description	David No				
1	#	Donl		Part Number	Qty	Extended Price \$	Labor	Paint
2		Repl	ENTRY STEP					
_	#	Repl	FILLER PANEL NEXT TO STEP		1	636.63	3.0	
3	#	Refn	SAND, PREP, AND PRIME (.5HR PER PANEL OR 1HR OVERSIZED)		1	44.13	1.0	0.5
4	#	Repl	COVER COACH					0.3
5	#	Refn	TINT TO MATCH WITH SPRAY CARD (X2)		1	20.00	1.0	1000
6	4		BASE COAT (tan)					1.0
7	#		BASE COAT (white)					0.3
8	#		CLEAR REFINSHED AREA					0.3
9	#		EXHAUST VENT ON ROOF					1.0
0	ü		DANIEST VENT ON ROOF		1	21.13	1.1	1.0
_			S	UBTOTALS		721.89	6.1	3.1

ESTIMATE TOTALS

Category					
Parts	Basis	Basis		Cost \$	
Body Labor				721.89	
Paint Labor	6.1 hrs	0	\$ 150.00 /hr	915.00	
Paint Supplies	3.1 hrs	0	\$ 150.00 /hr	465.00	
	3.1 hrs	0	\$ 52.00 /hr	161.20	
Body Supplies Subtotal	6.1 hrs	@	\$ 10.40 /hr	63.44	
				2,326.53	
Sales Tax	\$ 946.53	0	8.2500 %	78.09	
Grand Total				2,404.62	

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.