

From: [Ordway, Nelson](#)
To: samuel.nicolai@casella.com
Cc: marc.morgan@casella.com; [Daun, Mary](#); [Jones, Emily](#); [Davidson, Tyler](#); [Mills, Austin](#)
Subject: North Country Environmental Services, Inc., 581 Trudeau Rd, Bethlehem Permit No DES-SW-SP-03-002 Solid Waste Facility Inspection Report
Date: Friday, September 12, 2025 2:35:24 PM
Attachments: [image001.png](#)
[image003.png](#)
[image004.png](#)
[image005.png](#)
[image006.png](#)
[image007.png](#)
[20250912 Landfill Daily Cover Inspection Report 9-9-2025.pdf](#)

Attached is your copy of correspondence from the New Hampshire Department of Environmental Services dated 09/12/2025 regarding North Country Environmental Services, Inc., 581 Trudeau Rd, Bethlehem Permit No DES-SW-SP-03-002 Solid Waste Facility Inspection Report. If you are unable to open the attached document(s) or require a paper copy, please contact me as shown below. Thank you. Nelson

Nelson E. Ordway, Administrative Secretary
New Hampshire Department of Environmental Services,
Waste Management Division, Solid Waste Management Bureau
29 Hazen Drive, PO Box 95
Concord, NH 03302-0095
phone: 603.271.2925
fax: 603.271.2456

*E-mail: nelson.e.ordway@des.nh.gov



Think Green!

This e-mail and any files transmitted with it may be confidential and are intended solely for the use of the individual or entity to whom they are addressed. This communication may contain material protected by law or regulation. If you are not the intended recipient or the person responsible for delivering the e-mail for the intended recipient, be advised that if you have received this e-mail in error that any use, dissemination, forwarding, printing, or copying of this e-mail is strictly prohibited. If you believe that you have received this e-mail in error, please notify me at the Department of Environmental Services at 603.271.2925.

NHDES would greatly appreciate your feedback and wants to hear from you. Please take a moment to fill out our short (5-question) [NHDES Customer Service Satisfaction Survey](#).



Website: des.nh.gov

[Subscribe to our e-news!](#)





The State of New Hampshire
Department of Environmental Services

Robert R. Scott, Commissioner



VIA EMAIL ONLY

September 12, 2025

North Country Environmental Services, Inc.
Attn: Samuel Nicolai, P.E.
25 Greens Hill Lane
Rutland, VT 05701
Samuel.nicolai@casella.com

Subject Facility: **North Country Environmental Services, Inc., 581 Trudeau Rd, Bethlehem**
Permit No DES-SW-SP-03-002
Solid Waste Facility Inspection Report

Dear Samuel Nicolai,

On September 9, 2025, the New Hampshire Department of Environmental Services conducted a focused landfill cover inspection at the subject solid waste facility. The inspection was conducted to determine compliance with landfill cover requirements in RSA 149-M, the New Hampshire Solid Waste Rules Env-Sw 100-2000, and the facility permit.

Arrived Onsite:	5:25 A.M.	Departed from Site:	6:40 A.M.
NHDES Staff:	Austin Mills, Mary Daun		
Facility Attendees:	Bruce Grover – Casella, Marc Morgan - Casella		
Weather:	Clear, 34F		
Open Enforcement:	<input type="checkbox"/> No <input checked="" type="checkbox"/> Yes, ID #: SWMB 24-006, WMD 21-023, WMD 21-009, WMD 16-015		
Photos Taken?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Camera Used:	iPhone 13

Summary of Findings:

Was cover material placed over all waste at the facility? Yes No Unable to determine
Cover Materials Used: Geosynthetic tarps, soil

The following deficiencies were observed during the inspection:

LANDFILL GENERAL OPERATING REQUIREMENTS – LANDFILL COVER APPLICATION

Env-Sw 806.03(c): At landfills receiving municipal solid waste, Env-Sw 806.03(c) requires cover material to be placed over all exposed waste no less frequently than at the end of each operating day. During the inspection, incomplete cover application was observed at the working face (IMG_1662, IMG_1663, IMG_1666, IMG_1667).

Corrective Action: Immediately place adequate cover material over all waste at the facility and submit photos to NHDES showing cover application. Note: On September 9, 2025, the facility submitted photos to NHDES showing appropriate cover application in the areas noted in this report.

www.des.nh.gov

29 Hazen Drive • PO Box 95 • Concord, NH 03302-0095
(603) 271-2925 • Fax: (603) 271-2456 • TDD Access: Relay NH 1-800-735-2964

As noted above, the permittee submitted documentation showing correction of the deficiency identified in this report. As such, no further actions are required in response to this report. A similar deficiency identified in the future may result in the issuance of an enforcement action in accordance with the NHDES Compliance Assurance Response Policy.

If you have any questions, please contact me at (603) 271-2927.

Sincerely,



Austin Mills
Compliance Assurance Section
Solid Waste Management Bureau

Waste
Management
Division

Digitally signed by Waste
Management Division
Date: 2025.09.12 14:34:14
-04'00'


cc: Marc Morgan, Division Manager, marc.morgan@casella.com
Mary Daun, P.E., Solid Waste Management Bureau, NHDES
Emily Jones, Solid Waste Management Bureau, NHDES
Tyler Davidson, Solid Waste Management Bureau, NHDES

IMG_1662

North Country Environmental Services, Inc.
Solid Waste Facility Inspection Report
Date of Inspection: 9/9/2025



IMG_1663



IMG_1666

North Country Environmental Services, Inc.
Solid Waste Facility Inspection Report
Date of Inspection: 9/9/2025



IMG_1667

