

EARTHSEARCH SOIL CONSULTING, LLC

2000 Mallory Ln.
Suite 130-306
Franklin, TN 37067
(615) 210-5523

01/29/19

To whom it may concern,

This letter is to verify that a preliminary soil evaluation was performed at 7211 Bahne Rd. in Williamson Co. The soil on this tract was evaluated for subsurface sewage disposal possibilities. Two large areas of suitable soil were located on the property. The soil was identified as the Sengtown-Mountview series with estimated absorption rates of 60 minutes per inch. Each area appeared to be about 20,000 sq. ft.+. Depending on final soil mapping results, each area should be adequate for a four to five bedroom septic disposal area. The approximate areas are shown on the satellite image provided and is marked with orange surveyflags onsite. **These findings are based on a preliminary evaluation only. Extra high intensity soil mapping, property line and easement locations will be required for final approvals. Only the Williamson County Department of Sewage Disposal has the authority to determine the number of bedrooms and system approvals.** For any questions please contact me at 615-210-5523.

Sincerely,

J. Michael Haarbauer

