



Digital Vehicle Inspection

Total Performance

502 W Front St
Lillington, NC, 27546, US

910-984-1030

www.nctotalperformance.com



Total Performance Inspection

Customer:	Kicak	License:	GOFAST68
Vehicle:	1968 Ford Mustang GT500	VIN:	-
Inspection date:	11/08/2017	Odometer:	79,500 miles
Repair Order:	N.A.	Technician:	Zach Overby

We have inspected your vehicle with the following results:




Zach Overby, Technician



Lisa Kicak, Service Advisor

Inspection Details

Good		
Road Test	Observation	Action
Walk Around	Image(s):  Click on image for original size	
Engine Performance	Notes: Wow!!!	
Under Car	Observation	Action
Transfer case		Not Applicable

Good		
Road Test		
✓ Engine cranking	✓ Warning Lights/Instrument Panel	✓ Clutch Engagement
✓ Shifting	✓ Alignment	✓ Braking
✓ Nose Dive	✓ Acceleration Squat	✓ Steering
✓ Miscellaneous		
In Car		
✓ Oil Change Sticker	✓ Horn	✓ Turn Signals/Hazards
✓ Windshield Wipers	✓ Air Conditioning/Heater	✓ Headlights
Under Hood		
✓ Engine Oil	✓ Engine Coolant	✓ Power Steering Fluid
✓ Brake Fluid	✓ Clutch Fluid	✓ Drive Belts

Good		
✓ Radiator	✓ Cooling System Hoses	✓ Cooling Fans
✓ Battery		
Under Car		
✓ Front Tires	✓ Rear Tires	✓ Front Brakes
✓ Rear Brakes	✓ Brake Hydraulics	✓ Front Strut/Shock
✓ Rear Strut/Shock	✓ Suspension/Steering	✓ Differential
✓ Sway Bar/Stabilizer Bar	✓ Exhaust System	✓ Fluid Leaks

Needs future Attention		
Road Test	Observation	Action
Chassis		Diagnose
Parking Brake	<i>Notes:</i> Does not hold under load	

Needs Immediate Attention		
In Car	Observation	Action
Brake/Running Lights	<i>Notes:</i> Passenger brake light out will need bulb replacement	Replace Bulb
Under Hood	Observation	Action
Air Filter		Replace