

**Boat Name:** *Eversummer* 

**Cleaning date** 09-05-2024

# Before and After Photos



















## **After Photos**


















## **Cleaning Notes**

Hull was completely covered with white worms and barnacles, lift gear had several clams and a handful of mussels, prop speed is completely ineffective.



# Visual Inspection

#### **Zinc Photos:**





## **Plate Zinc Condition**

70%


## **Other Zinc Condition**

80%

#### **Zinc Notes**

R4 zinc on hydraulic lift gear

#### **Bottom Paint Photo**




#### **Bottom Paint Condition**

Other


#### **Bottom Paint custom note**

Paint is in decent condition, it's very soft, with tons of barnacle feet all over





# **Noticed Damages**





Extra Service No	