

Index of RAIB recommendations



Report Title	Report No	Event Date	Recommendation Number	Recommendation Status	RAIB Concern	End Implementer/s	Recommendation status report
Train striking debris at Yarnton near Hanborough, Oxfordshire	01/2024	10/02/2023	01/2024/01	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f324399d99de001103df3a/01_2024_Yarnton.pdf
Train striking debris at Yarnton near Hanborough, Oxfordshire	01/2024	10/02/2023	01/2024/02	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f324399d99de001103df3a/01_2024_Yarnton.pdf
Train striking debris at Yarnton near Hanborough, Oxfordshire	01/2024	10/02/2023	01/2024/03	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f324399d99de001103df3a/01_2024_Yarnton.pdf
Train striking debris at Yarnton near Hanborough, Oxfordshire	01/2024	10/02/2023	01/2024/04	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f324399d99de001103df3a/01_2024_Yarnton.pdf
Freight train derailment at London Gateway, Essex	14/2023	24/12/2021	14/2023/01	Awaiting Response	None	VTG	https://assets.publishing.service.gov.uk/media/65f323e8fa1851001a011781/14_2023_London_Gateway.pdf
Freight train derailment at London Gateway, Essex	14/2023	24/12/2021	14/2023/02	Awaiting Response	None	GB Railfreight	https://assets.publishing.service.gov.uk/media/65f323e8fa1851001a011781/14_2023_London_Gateway.pdf
Freight train derailment at London Gateway, Essex	14/2023	24/12/2021	14/2023/03	Awaiting Response	None	RSSB	https://assets.publishing.service.gov.uk/media/65f323e8fa1851001a011781/14_2023_London_Gateway.pdf
Serious injury to a passenger alighting from a train at Loughborough Central station	13/2023	14/01/2023	13/2023/01	Awaiting Response	None	Great Central Railway	https://assets.publishing.service.gov.uk/media/65f323b99d99de001d03df36/13_2023_Loughborough.pdf
Serious injury to a passenger alighting from a train at Loughborough Central station	13/2023	14/01/2023	13/2023/02	Awaiting Response	None	Great Central Railway	https://assets.publishing.service.gov.uk/media/65f323b99d99de001d03df36/13_2023_Loughborough.pdf
Serious injury to a passenger alighting from a train at Loughborough Central station	13/2023	14/01/2023	13/2023/03	Awaiting Response	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/65f323b99d99de001d03df36/13_2023_Loughborough.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/01	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/02	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/03	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/04	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/05	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/06	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf

Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/07	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/08	Awaiting Response	None	South Western Railway	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/09	Awaiting Response	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/10	Awaiting Response	None	Angel Trains Limited	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/10	Awaiting Response	None	Eversholt Rail	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Collision between passenger trains at Salisbury Tunnel Junction	12/2023	31/10/2021	12/2023/10	Awaiting Response	None	Porterbrook	https://assets.publishing.service.gov.uk/media/65f322f310cd8e001136c60c/12_2023_Salisbury.pdf
Two trains in the same signal section at South Wingfield	11/2023	26/10/2022	11/2023/01	Awaiting Response	None	Bridgeway Consulting Limited	https://assets.publishing.service.gov.uk/media/65f322affa1851001a011780/11_2023_South_Wingfield.pdf
Two trains in the same signal section at South Wingfield	11/2023	26/10/2022	11/2023/02	Awaiting Response	None	Randstad Solutions Limited	https://assets.publishing.service.gov.uk/media/65f322affa1851001a011780/11_2023_South_Wingfield.pdf
Two trains in the same signal section at South Wingfield	11/2023	26/10/2022	11/2023/03	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322affa1851001a011780/11_2023_South_Wingfield.pdf
Two trains in the same signal section at South Wingfield	11/2023	26/10/2022	11/2023/04	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322affa1851001a011780/11_2023_South_Wingfield.pdf
Two trains in the same signal section at South Wingfield	11/2023	26/10/2022	11/2023/05	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f322affa1851001a011780/11_2023_South_Wingfield.pdf
Freight train derailment at Petteril Bridge Junction	10/2023	19/10/2022	10/2023/01	Awaiting Response	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/65f32251fa1851001a01177c/10_2023_Pettril_Bridge.pdf
Freight train derailment at Petteril Bridge Junction	10/2023	19/10/2022	10/2023/01	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/65f32251fa1851001a01177c/10_2023_Pettril_Bridge.pdf
Freight train derailment at Petteril Bridge Junction	10/2023	19/10/2022	10/2023/02	Awaiting Response	None	RSSB	https://assets.publishing.service.gov.uk/media/65f32251fa1851001a01177c/10_2023_Pettril_Bridge.pdf
Freight train derailment at Petteril Bridge Junction	10/2023	19/10/2022	10/2023/03	Awaiting Response	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/65f32251fa1851001a01177c/10_2023_Pettril_Bridge.pdf
Near miss with two track workers at Penkridge, Staffordshire	09/2023	11/07/2022	09/2023/01	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502ce6b5b07380013029e7e/09_2023_Penkridge.pdf
Near miss with two track workers at Penkridge, Staffordshire	09/2023	11/07/2022	09/2023/02	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502ce6b5b07380013029e7e/09_2023_Penkridge.pdf
Collision between two freight trains at Loversall Carr Junction	08/2023	05/07/2022	08/2023/01	Awaiting Response	None	GB Railfreight	https://assets.publishing.service.gov.uk/media/6502ce0197d396000d482e73/08_2023_Doncaster.pdf
Collision between two freight trains at Loversall Carr Junction	08/2023	05/07/2022	08/2023/02	Awaiting Response	None	RSSB	https://assets.publishing.service.gov.uk/media/6502ce0197d396000d482e73/08_2023_Doncaster.pdf

Embankment washout under a passenger train at Haddiscoe	07/2023	30/01/2022	07/2023/01	Awaiting Response	None	Environment Agency	https://assets.publishing.service.gov.uk/media/6502cc4c702634001389b826/07_2023_Haddiscoe.pdf
Embankment washout under a passenger train at Haddiscoe	07/2023	30/01/2022	07/2023/01	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502cc4c702634001389b826/07_2023_Haddiscoe.pdf
Embankment washout under a passenger train at Haddiscoe	07/2023	30/01/2022	07/2023/02	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502cc4c702634001389b826/07_2023_Haddiscoe.pdf
Embankment washout under a passenger train at Haddiscoe	07/2023	30/01/2022	07/2023/03	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502cc4c702634001389b826/07_2023_Haddiscoe.pdf
Embankment washout under a passenger train at Haddiscoe	07/2023	30/01/2022	07/2023/04	Awaiting Response	None	Environment Agency	https://assets.publishing.service.gov.uk/media/6502cc4c702634001389b826/07_2023_Haddiscoe.pdf
Embankment washout under a passenger train at Haddiscoe	07/2023	30/01/2022	07/2023/04	Awaiting Response	None	Natural Resources Wales	https://assets.publishing.service.gov.uk/media/6502cc4c702634001389b826/07_2023_Haddiscoe.pdf
Embankment washout under a passenger train at Haddiscoe	07/2023	30/01/2022	07/2023/04	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502cc4c702634001389b826/07_2023_Haddiscoe.pdf
Embankment washout under a passenger train at Haddiscoe	07/2023	30/01/2022	07/2023/05	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502cc4c702634001389b826/07_2023_Haddiscoe.pdf
Train overspeeding at Spital Junction, Peterborough	06/2023	17/04/2022	06/2023/01	Awaiting Response	None	Lumo	https://assets.publishing.service.gov.uk/media/6502cb61702634001389b823/06_2023_Peterborough.pdf
Train overspeeding at Spital Junction, Peterborough	06/2023	17/04/2022	06/2023/02	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502cb61702634001389b823/06_2023_Peterborough.pdf
Train overspeeding at Spital Junction, Peterborough	06/2023	17/04/2022	06/2023/03	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502cb61702634001389b823/06_2023_Peterborough.pdf
Train overspeeding at Spital Junction, Peterborough	06/2023	17/04/2022	06/2023/04	Awaiting Response	None	Lumo	https://assets.publishing.service.gov.uk/media/6502cb61702634001389b823/06_2023_Peterborough.pdf
Track worker struck by train near Chalfont & Latimer station	05/2023	15/04/2022	05/2023/01	Awaiting Response	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/6486f21a103ca6000c039cc7/05_2023_Chalfont_and_Latimer.pdf
Track worker struck by train near Chalfont & Latimer station	05/2023	15/04/2022	05/2023/02	Awaiting Response	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/6486f21a103ca6000c039cc7/05_2023_Chalfont_and_Latimer.pdf
Track worker struck by train near Chalfont & Latimer station	05/2023	15/04/2022	05/2023/03	Awaiting Response	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/6486f21a103ca6000c039cc7/05_2023_Chalfont_and_Latimer.pdf
Track worker struck by train near Chalfont & Latimer station	05/2023	15/04/2022	05/2023/04	Awaiting Response	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/6486f21a103ca6000c039cc7/05_2023_Chalfont_and_Latimer.pdf
Near miss at Farnborough North footpath level crossing	04/2023	19/05/2022	04/2023/01	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6486f1c7b32b9e000ca9657f/04_2023_Farnborough_North.pdf
Near miss at Farnborough North footpath level crossing	04/2023	19/05/2022	04/2023/02	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6486f1c7b32b9e000ca9657f/04_2023_Farnborough_North.pdf
Track damage between Pencoed and Llanharan, South Wales	03/2023	06/03/2021	03/2023/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c77ae90e076cd09acd29/03_2023_Pencoed-Llanharan.pdf

Train driver struck by a train near West Worthing Middle Siding, West Sussex	02/2023	01/02/2022	02/2023/01	Closed - I	None	Govia Thameslink Railway	https://assets.publishing.service.gov.uk/media/6409c72e8fa8f556125db9ae/02_2023_West_Worthing.pdf
Train driver struck by a train near West Worthing Middle Siding, West Sussex	02/2023	01/02/2022	02/2023/02	Awaiting Response	None	Department for Transport	https://assets.publishing.service.gov.uk/media/6409c72e8fa8f556125db9ae/02_2023_West_Worthing.pdf
Train driver struck by a train near West Worthing Middle Siding, West Sussex	02/2023	01/02/2022	02/2023/03	Open	None	RSSB	https://assets.publishing.service.gov.uk/media/6409c72e8fa8f556125db9ae/02_2023_West_Worthing.pdf
Pedestrian struck by a train at Lady Howard footpath and bridleway crossing, Surrey	01/2023	21/04/2022	01/2023/01	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c6f2e90e076cc5cc1953/01_2023_Lady_Howard_crossing.pdf
Pedestrian struck by a train at Lady Howard footpath and bridleway crossing, Surrey	01/2023	21/04/2022	01/2023/02	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c6f2e90e076cc5cc1953/01_2023_Lady_Howard_crossing.pdf
Fatal collision between a tram and a pedestrian at Cleveleys, Lancashire	14/2022	24/11/2021	14/2022/01	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/6409c6a1d3bf7f02f7d9db02/14_2022_Cleveleys.pdf
Fatal collision between a tram and a pedestrian at Cleveleys, Lancashire	14/2022	24/11/2021	14/2022/02	Closed - I	None	Blackpool Council	https://assets.publishing.service.gov.uk/media/6409c6a1d3bf7f02f7d9db02/14_2022_Cleveleys.pdf
Fatal collision between a tram and a pedestrian at Cleveleys, Lancashire	14/2022	24/11/2021	14/2022/03	Closed - I	None	Blackpool Council	https://assets.publishing.service.gov.uk/media/6409c6a1d3bf7f02f7d9db02/14_2022_Cleveleys.pdf
Buffer stop collision at Enfield Town station	13/2022	12/10/2021	13/2022/01	Awaiting Response	None	Arriva Rail London	https://assets.publishing.service.gov.uk/media/6502ca7f702634000d89b80b/13_2022_Enfield.pdf
Buffer stop collision at Enfield Town station	13/2022	12/10/2021	13/2022/02	Awaiting Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/6502ca7f702634000d89b80b/13_2022_Enfield.pdf
Collision between a train and agricultural equipment at Kisby user worked crossing, Cambridgeshire	12/2022	19/08/2021	12/2022/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c65f8fa8f55611a84c7d/12_2022_Kisby.pdf
Collision between a train and agricultural equipment at Kisby user worked crossing, Cambridgeshire	12/2022	19/08/2021	12/2022/02	Open	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/6409c65f8fa8f55611a84c7d/12_2022_Kisby.pdf
Collision between a passenger train and a hand trolley at Challow, Oxfordshire	11/2022	21/10/2021	11/2022/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c5e9d3bf7f02f92f2039/11_2022_Challow.pdf
Collision between a passenger train and a hand trolley at Challow, Oxfordshire	11/2022	21/10/2021	11/2022/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c5e9d3bf7f02f92f2039/11_2022_Challow.pdf
Collision between a passenger train and a hand trolley at Challow, Oxfordshire	11/2022	21/10/2021	11/2022/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c5e9d3bf7f02f92f2039/11_2022_Challow.pdf
Collision between a passenger train and a hand trolley at Challow, Oxfordshire	11/2022	21/10/2021	11/2022/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c5e9d3bf7f02f92f2039/11_2022_Challow.pdf
Collision between a passenger train and a hand trolley at Challow, Oxfordshire	11/2022	21/10/2021	11/2022/05	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c5e9d3bf7f02f92f2039/11_2022_Challow.pdf
Wrong side signalling failure and derailment at Dalwhinnie, Badenoch and Strathspey	10/2022	10/04/2021	10/2022/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c596e90e076cc76a8df4/10_2022_Dalwhinnie.pdf
Wrong side signalling failure and derailment at Dalwhinnie, Badenoch and Strathspey	10/2022	10/04/2021	10/2022/02	Open		Network Rail	https://assets.publishing.service.gov.uk/media/6409c596e90e076cc76a8df4/10_2022_Dalwhinnie.pdf

Wrong side signalling failure and derailment at Dalwhinnie, Badenoch and Strathspey	10/2022	10/04/2021	10/2022/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c596e90e076cc76a8df4/10_2022_Dalwhinnie.pdf
Wrong side signalling failure and derailment at Dalwhinnie, Badenoch and Strathspey	10/2022	10/04/2021	10/2022/04	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c596e90e076cc76a8df4/10_2022_Dalwhinnie.pdf
Wrong side signalling failure and derailment at Dalwhinnie, Badenoch and Strathspey	10/2022	10/04/2021	10/2022/05	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6409c596e90e076cc76a8df4/10_2022_Dalwhinnie.pdf
Collision between road-rail vehicles near Ramsden Bellhouse, Essex	09/2022	02/05/2021	09/2022/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e76de90e073725585d60/09_2022_Ramsden_Bellhouse.pdf
Collision between road-rail vehicles near Ramsden Bellhouse, Essex	09/2022	02/05/2021	09/2022/02	Closed - I	None	Readypower	https://assets.publishing.service.gov.uk/media/6329e76de90e073725585d60/09_2022_Ramsden_Bellhouse.pdf
Collision between road-rail vehicles near Ramsden Bellhouse, Essex	09/2022	02/05/2021	09/2022/02	Closed - I	None	SPL Powerlines UK	https://assets.publishing.service.gov.uk/media/6329e76de90e073725585d60/09_2022_Ramsden_Bellhouse.pdf
Collision between road-rail vehicles near Ramsden Bellhouse, Essex	09/2022	02/05/2021	09/2022/03	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/6329e76de90e073725585d60/09_2022_Ramsden_Bellhouse.pdf
Collision between a tram and a cyclist, near Audenshaw tram stop, Manchester	08/2022	01/09/2021	08/2022/01	Closed - I	None	Tameside Council	https://assets.publishing.service.gov.uk/media/6329e729d3bf7f75befbbf22/08_2022_Audenshaw.pdf
Collision between a tram and a cyclist, near Audenshaw tram stop, Manchester	08/2022	01/09/2021	08/2022/01	Closed - I	None	Transport for Greater Manchester	https://assets.publishing.service.gov.uk/media/6329e729d3bf7f75befbbf22/08_2022_Audenshaw.pdf
Collision between a tram and a cyclist, near Audenshaw tram stop, Manchester	08/2022	01/09/2021	08/2022/02	Closed - I	None	Transport for Greater Manchester	https://assets.publishing.service.gov.uk/media/6329e729d3bf7f75befbbf22/08_2022_Audenshaw.pdf
Collision between a tram and a cyclist, near Audenshaw tram stop, Manchester	08/2022	01/09/2021	08/2022/03	Open	None	LRSSB	https://assets.publishing.service.gov.uk/media/6329e729d3bf7f75befbbf22/08_2022_Audenshaw.pdf
Collision between a tram and a cyclist, near Audenshaw tram stop, Manchester	08/2022	01/09/2021	08/2022/04	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/6329e729d3bf7f75befbbf22/08_2022_Audenshaw.pdf
Collision between a tram and a cyclist, near Audenshaw tram stop, Manchester	08/2022	01/09/2021	08/2022/05	Open	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/6329e729d3bf7f75befbbf22/08_2022_Audenshaw.pdf
Collision between a tram and a cyclist, near Audenshaw tram stop, Manchester	08/2022	01/09/2021	08/2022/05	Open	None	Transport for Greater Manchester	https://assets.publishing.service.gov.uk/media/6329e729d3bf7f75befbbf22/08_2022_Audenshaw.pdf
Buffer stop collision at Kirkby, Merseyside	07/2022	13/03/2021	07/2022/01	Open	None	RSSB	https://assets.publishing.service.gov.uk/media/6329e6f6e90e073721b083c2/07_2022_Kirkby.pdf
Buffer stop collision at Kirkby, Merseyside	07/2022	13/03/2021	07/2022/02	Open	None	Merseyrail	https://assets.publishing.service.gov.uk/media/6329e6f6e90e073721b083c2/07_2022_Kirkby.pdf
Buffer stop collision at Kirkby, Merseyside	07/2022	13/03/2021	07/2022/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e6f6e90e073721b083c2/07_2022_Kirkby.pdf
Buffer stop collision at Kirkby, Merseyside	07/2022	13/03/2021	07/2022/03	Open	None	Merseyrail	https://assets.publishing.service.gov.uk/media/6329e6f6e90e073721b083c2/07_2022_Kirkby.pdf
Near miss between a rail grinding train and an empty passenger train at Sileby Junction, Leicestershire	06/2022	05/05/2021	06/2022/01	Closed - I	None	Colas Rail	https://assets.publishing.service.gov.uk/media/6329e6ade90e0737284e3f98/06_2022_Sileby.pdf

Near miss between a rail grinding train and an empty passenger train at Sileby Junction, Leicestershire	06/2022	05/05/2021	06/2022/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e6ade90e0737284e3f98/06_2022_Sileby.pdf
Track worker struck by a train near Surbiton station, south-west London	05/2022	09/02/2021	05/2022/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e65fd3bf7f75c8657c26/05_2022_Surbiton.pdf
Track worker struck by a train near Surbiton station, south-west London	05/2022	09/02/2021	05/2022/02	Open	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/6329e65fd3bf7f75c8657c26/05_2022_Surbiton.pdf
Track worker struck by a train near Surbiton station, south-west London	05/2022	09/02/2021	05/2022/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e65fd3bf7f75c8657c26/05_2022_Surbiton.pdf
Runaway of a road-rail vehicle at Belle Isle Junction	04/2022	16/05/2021	04/2022/01	Closed - I	None	Alan J Hargreaves Plant engineers	https://assets.publishing.service.gov.uk/media/6329e61de90e0737279c012b/04_2022_Belle_Isle_junction.pdf
Runaway of a road-rail vehicle at Belle Isle Junction	04/2022	16/05/2021	04/2022/02	Closed - I	None	Pod-Trak	https://assets.publishing.service.gov.uk/media/6329e61de90e0737279c012b/04_2022_Belle_Isle_junction.pdf
Near miss at Coltishall Lane User Worked Level Crossing, Norfolk	03/2022	21/01/2021	03/2022/01	Closed - I	Red	Network Rail	https://assets.publishing.service.gov.uk/media/6329e5d4e90e07371acca5f3/03_2022_Coltishall.pdf
Near miss at Coltishall Lane User Worked Level Crossing, Norfolk	03/2022	21/01/2021	03/2022/02	Closed - I	Blue	Department for Transport	https://assets.publishing.service.gov.uk/media/6329e5d4e90e07371acca5f3/03_2022_Coltishall.pdf
Near miss at Coltishall Lane User Worked Level Crossing, Norfolk	03/2022	21/01/2021	03/2022/02	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/6329e5d4e90e07371acca5f3/03_2022_Coltishall.pdf
Near miss at Coltishall Lane User Worked Level Crossing, Norfolk	03/2022	21/01/2021	03/2022/02	Closed - I	Blue	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/6329e5d4e90e07371acca5f3/03_2022_Coltishall.pdf
Near miss at Coltishall Lane User Worked Level Crossing, Norfolk	03/2022	21/01/2021	03/2022/03	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/6329e5d4e90e07371acca5f3/03_2022_Coltishall.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/04	Closed - I	None	Amey	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/06	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/07	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf

Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/08	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/09	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/10	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/11	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/12	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/12	Open	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/13	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/14	Open	None	HST Owners	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/15	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/16	Open	None	Angel Trains Limited	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/17	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/18	Open	None	Owners of MK3 coaches and other RV fleets	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/19	Open	None	HST Operators	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment of a passenger train at Carmont, Aberdeenshire	02/2022	12/08/2020	02/2022/20	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/6329e57de90e0737279c012a/02_2022_Carmont.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/01	Open	None	TOUAX Rail Services	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/02	Open	None	TOUAX Rail Services	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/03	Insufficient Response	None	Arlington Fleet Services Ltd	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/04	Insufficient Response	None	Wabtec Faiveley UK	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/05	Awaiting Response	None	BELAC	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf

Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/06	Open	None	RSSB	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/07	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/08	Open	None	Freight Technical Committee	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/08	Open	None	National Freight Safety Group	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/09	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Derailment and fire involving a tanker train at Llangennech, Carmarthenshire	01/2022	26/08/2020	01/2022/09	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/6329e541d3bf7f75c388a77c/01_2022_Morlais.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/01	Open	None	Colas Rail	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/01	Open	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/01	Open	None	DC Rail	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/01	Open	None	Direct Rail Services	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/01	Open	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/01	Open	None	GB Railfreight	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/01	Open	None	Victa Railfreight	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/02	Open	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/03	Insufficient Response	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Runaway and derailment of wagons at Toton, Nottinghamshire	09/2021	17/01/2021	09/2021/04	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e4f1e90e07371e5e5842/09_2021_Toton.pdf
Trains overspeeding between Laurencekirk and Portlethen, Aberdeenshire	08/2021	04/12/2020	08/2021/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/6329e492d3bf7f75c989d8f6/08_2021_Laurencekirk_and_Portlethen.pdf
Trains overspeeding between Laurencekirk and Portlethen, Aberdeenshire	08/2021	04/12/2020	08/2021/02	Open	None	RSSB	https://assets.publishing.service.gov.uk/media/6329e492d3bf7f75c989d8f6/08_2021_Laurencekirk_and_Portlethen.pdf
Freight train derailment at Sheffield station	07/2021	11/11/2020	07/2021/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/619d01d8d3bf7f055eb9b666/07_2021_Sheffield_station.pdf

Freight train derailment at Sheffield station	07/2021	11/11/2020	07/2021/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/619d01d8d3bf7f055eb9b666/07_2021_Sheffield_station.pdf
Freight train derailment at Sheffield station	07/2021	11/11/2020	07/2021/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/619d01d8d3bf7f055eb9b666/07_2021_Sheffield_station.pdf
Freight train derailment at Sheffield station	07/2021	11/11/2020	07/2021/04	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/619d01d8d3bf7f055eb9b666/07_2021_Sheffield_station.pdf
Near miss with a member of staff at Rowlands Castle station, Hampshire	06/2021	19/12/2020	06/2021/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/619d012ae90e070449d49d7c/06_2021_Rowlands_Castle.pdf
Near miss with a member of staff at Rowlands Castle station, Hampshire	06/2021	19/12/2020	06/2021/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/619d012ae90e070449d49d7c/06_2021_Rowlands_Castle.pdf
Near miss with a member of staff at Rowlands Castle station, Hampshire	06/2021	19/12/2020	06/2021/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/619d012ae90e070449d49d7c/06_2021_Rowlands_Castle.pdf
Near miss with a member of staff at Rowlands Castle station, Hampshire	06/2021	19/12/2020	06/2021/04	Open	None	South Western Railway	https://assets.publishing.service.gov.uk/media/619d012ae90e070449d49d7c/06_2021_Rowlands_Castle.pdf
Fatal accident at Waterloo Underground station, London	05/2021	26/05/2020	05/2021/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/619cff89d3bf7f055eb9b664/05_2021_Waterloo.pdf
Fatal accident at Waterloo Underground station, London	05/2021	26/05/2020	05/2021/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/619cff89d3bf7f055eb9b664/05_2021_Waterloo.pdf
Fatal accident at Waterloo Underground station, London	05/2021	26/05/2020	05/2021/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/619cff89d3bf7f055eb9b664/05_2021_Waterloo.pdf
Signal passed at danger and subsequent near miss, Chalfont & Latimer station	04/2021	21/06/2020	04/2021/01	Closed - I	None	Chiltern Railways	https://assets.publishing.service.gov.uk/media/619cfeabd3bf7f0560be634c/04_2021_Chalfont_and_Latimer.pdf
Signal passed at danger and subsequent near miss, Chalfont & Latimer station	04/2021	21/06/2020	04/2021/02	Open	None	Chiltern Railways	https://assets.publishing.service.gov.uk/media/619cfeabd3bf7f0560be634c/04_2021_Chalfont_and_Latimer.pdf
Signal passed at danger and subsequent near miss, Chalfont & Latimer station	04/2021	21/06/2020	04/2021/02	Open	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/619cfeabd3bf7f0560be634c/04_2021_Chalfont_and_Latimer.pdf
Signal passed at danger and subsequent near miss, Chalfont & Latimer station	04/2021	21/06/2020	04/2021/03	Open	None	Chiltern Railways	https://assets.publishing.service.gov.uk/media/619cfeabd3bf7f0560be634c/04_2021_Chalfont_and_Latimer.pdf
Signal passed at danger and subsequent near miss, Chalfont & Latimer station	04/2021	21/06/2020	04/2021/03	Open	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/619cfeabd3bf7f0560be634c/04_2021_Chalfont_and_Latimer.pdf
Track worker struck by train near Roade	03/2021	08/04/2020	03/2021/01	Closed - I	None	Amco Giffen	https://assets.publishing.service.gov.uk/media/619d0241e90e070446653bd6/03_2021_Roade.pdf
Track worker struck by train near Roade	03/2021	08/04/2020	03/2021/02	Closed - I	None	Amco Giffen	https://assets.publishing.service.gov.uk/media/619d0241e90e070446653bd6/03_2021_Roade.pdf
Track worker struck by train near Roade	03/2021	08/04/2020	03/2021/03	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/619d0241e90e070446653bd6/03_2021_Roade.pdf
Freight train derailment at Eastleigh, Hampshire	02/2021	28/01/2020	02/2021/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dcb5dd3bf7f2798db5987/02_2021_Eastleigh.pdf

Freight train derailment at Eastleigh, Hampshire	02/2021	28/01/2020	02/2021/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dcb5dd3bf7f2798db5987/02_2021_Eastleigh.pdf
Person struck by a train at Eden Park station, south-east London	01/2021	26/02/2020	01/2021/01	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/605dcaf0e90e0769a0441781/01_2021_Eden_Park.pdf
Person struck by a train at Eden Park station, south-east London	01/2021	26/02/2020	01/2021/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dcaf0e90e0769a0441781/01_2021_Eden_Park.pdf
Person struck by a train at Eden Park station, south-east London	01/2021	26/02/2020	01/2021/02	Open	None	Department for Transport	https://assets.publishing.service.gov.uk/media/605dcaf0e90e0769a0441781/01_2021_Eden_Park.pdf
Person struck by a train at Eden Park station, south-east London	01/2021	26/02/2020	01/2021/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dcaf0e90e0769a0441781/01_2021_Eden_Park.pdf
Person struck by a train at Eden Park station, south-east London	01/2021	26/02/2020	01/2021/03	Closed - I	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/605dcaf0e90e0769a0441781/01_2021_Eden_Park.pdf
Person struck by a train at Eden Park station, south-east London	01/2021	26/02/2020	01/2021/04	Open	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/605dcaf0e90e0769a0441781/01_2021_Eden_Park.pdf
Person struck by a train at Eden Park station, south-east London	01/2021	26/02/2020	01/2021/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/605dcaf0e90e0769a0441781/01_2021_Eden_Park.pdf
Person struck by a train at Eden Park station, south-east London	01/2021	26/02/2020	01/2021/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dcaf0e90e0769a0441781/01_2021_Eden_Park.pdf
Runaway and derailment of a wagon at Clitheroe, Lancashire	16/2020	09/03/2020	16/2020/01	Open	None	GB Railfreight	https://assets.publishing.service.gov.uk/media/605dca758fa8f50470673edd/16_2020_Clitheroe.pdf
Runaway and derailment of a wagon at Clitheroe, Lancashire	16/2020	09/03/2020	16/2020/02	Open	None	Hanson UK	https://assets.publishing.service.gov.uk/media/605dca758fa8f50470673edd/16_2020_Clitheroe.pdf
Runaway and derailment of a wagon at Clitheroe, Lancashire	16/2020	09/03/2020	16/2020/03	Open	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/605dca758fa8f50470673edd/16_2020_Clitheroe.pdf
Near miss between a passenger train and cars at Norwich Road level crossing, New Rackheath, Norfolk	15/2020	24/11/2019	15/2020/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc9f98fa8f5046b4e4ac6/15_2020_Norwich_Road.pdf
Near miss between a passenger train and cars at Norwich Road level crossing, New Rackheath, Norfolk	15/2020	24/11/2019	15/2020/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc9f98fa8f5046b4e4ac6/15_2020_Norwich_Road.pdf
Near miss between a passenger train and cars at Norwich Road level crossing, New Rackheath, Norfolk	15/2020	24/11/2019	15/2020/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc9f98fa8f5046b4e4ac6/15_2020_Norwich_Road.pdf
Passenger train collision with a derailed locomotive at Bromsgrove	14/2020	23/03/2020	14/2020/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc9858fa8f5047c7f79e0/14_2020_Bromsgrove.pdf
Collision and derailment at Neville Hill	13/2020	13/11/2019	13/2020/01	Closed - I	None	London North Eastern Railway	https://assets.publishing.service.gov.uk/media/605dc8f6e90e07699fadf0ae/13_2020_Neville_Hill.pdf
Collision and derailment at Neville Hill	13/2020	13/11/2019	13/2020/02	Closed - I	None	London North Eastern Railway	https://assets.publishing.service.gov.uk/media/605dc8f6e90e07699fadf0ae/13_2020_Neville_Hill.pdf
Collision and derailment at Neville Hill	13/2020	13/11/2019	13/2020/03	Closed - I	None	Hitachi STS	https://assets.publishing.service.gov.uk/media/605dc8f6e90e07699fadf0ae/13_2020_Neville_Hill.pdf

Collision and derailment at Neville Hill	13/2020	13/11/2019	13/2020/04	Closed - I	None	London North Eastern Railway	https://assets.publishing.service.gov.uk/media/605dc8f6e90e07699fadf0ae/13_2020_Neville_Hill.pdf
Collision and derailment at Neville Hill	13/2020	13/11/2019	13/2020/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/605dc8f6e90e07699fadf0ae/13_2020_Neville_Hill.pdf
Derailment of a freight train near Wanstead Park	12/2020	23/01/2020	12/2020/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc7f08fa8f520ec7b1b99/12_2020_Wanstead_Park.pdf
Derailment of a freight train near Wanstead Park	12/2020	23/01/2020	12/2020/02	Closed - I	None	VTG	https://assets.publishing.service.gov.uk/media/605dc7f08fa8f520ec7b1b99/12_2020_Wanstead_Park.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/02	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/04	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/09	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/10	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Track workers struck by a train at Margam, Neath Port Talbot,	11/2020	03/07/2019	11/2020/11	Open	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/605dc859d3bf7f279e24729d/11_2020_Margam_Neath_Port_Talbot.pdf
Signal passed at danger at Loughborough South Junction, Leicestershire	10/2020	26/03/2020	10/2020/01	Closed - I	None	Rail Operations Group	https://assets.publishing.service.gov.uk/media/605dc70a8fa8f520e0ad7c8e/10_2020_Loughborough_South_Junction_Leicestershire.pdf
Fatal accident at Tyseley depot	09/2020	14/12/2019	09/2020/01	Closed - I	None	West Midlands Trains	https://assets.publishing.service.gov.uk/media/605dc6908fa8f520e6d8bf0a/09_2020_Tyseley_depot.pdf
Fatal accident at Tyseley depot	09/2020	14/12/2019	09/2020/02	Closed - I	None	West Midlands Trains	https://assets.publishing.service.gov.uk/media/605dc6908fa8f520e6d8bf0a/09_2020_Tyseley_depot.pdf
Collision between mobile elevating work platforms at Rochford, Essex	08/2020	25/01/2020	08/2020/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc5ddd3bf7f27a58a87f3/08_2020_Rochford_Essex.pdf

Collision between mobile elevating work platforms at Rochford, Essex	08/2020	25/01/2020	08/2020/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc5ddd3bf7f27a58a87f3/08_2020_Rochford_Essex.pdf
Collision between mobile elevating work platforms at Rochford, Essex	08/2020	25/01/2020	08/2020/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc5ddd3bf7f27a58a87f3/08_2020_Rochford_Essex.pdf
Collision between mobile elevating work platforms at Rochford, Essex	08/2020	25/01/2020	08/2020/04	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/605dc5ddd3bf7f27a58a87f3/08_2020_Rochford_Essex.pdf
Collision between mobile elevating work platforms at Rochford, Essex	08/2020	25/01/2020	08/2020/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc5ddd3bf7f27a58a87f3/08_2020_Rochford_Essex.pdf
Freight train derailment at Willesden High Level Junction, north-west London	07/2020	06/05/2019	07/2020/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc55fe90e07699c378ec/07_2020_Willesden_High_Level_Junction.pdf
Freight train derailment at Willesden High Level Junction, north-west London	07/2020	06/05/2019	07/2020/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc55fe90e07699c378ec/07_2020_Willesden_High_Level_Junction.pdf
Freight train derailment at Willesden High Level Junction, north-west London	07/2020	06/05/2019	07/2020/03	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/605dc55fe90e07699c378ec/07_2020_Willesden_High_Level_Junction.pdf
Freight train derailment at Willesden High Level Junction, north-west London	07/2020	06/05/2019	07/2020/04	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/605dc55fe90e07699c378ec/07_2020_Willesden_High_Level_Junction.pdf
Signal passed at stop and near miss, Deansgate-Castlefield tram stop, Manchester 17 May 2019	06/2020	17/05/2019	06/2020/01	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/605dc34ed3bf7f27a58a87f2/06_2020_Deansgate-Castlefield.pdf
Signal passed at stop and near miss, Deansgate-Castlefield tram stop, Manchester 17 May 2019	06/2020	17/05/2019	06/2020/02	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/605dc34ed3bf7f27a58a87f2/06_2020_Deansgate-Castlefield.pdf
Signal passed at stop and near miss, Deansgate-Castlefield tram stop, Manchester 17 May 2019	06/2020	17/05/2019	06/2020/03	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/605dc34ed3bf7f27a58a87f2/06_2020_Deansgate-Castlefield.pdf
Loss of brake control on a sleeper train approaching Edinburgh	05/2020	01/08/2019	05/2020/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/605cb2f3e90e0724cb471e7a/05_2020_Edinburgh-Loss_of_brake_control.pdf
Loss of brake control on a sleeper train approaching Edinburgh	05/2020	01/08/2019	05/2020/02	Closed - I	None	Caledonian Sleeper	https://assets.publishing.service.gov.uk/media/605cb2f3e90e0724cb471e7a/05_2020_Edinburgh-Loss_of_brake_control.pdf
Train collision with material washed out from a cutting slope at Corby, Northamptonshire	04/2020	13/06/2019	04/2020/01	Open	None	Environment Agency	https://assets.publishing.service.gov.uk/media/605cb1fb8fa8f57ec2557e89/04_2020_Corby_Northamptonshire.pdf
Train collision with material washed out from a cutting slope at Corby, Northamptonshire	04/2020	13/06/2019	04/2020/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605cb1fb8fa8f57ec2557e89/04_2020_Corby_Northamptonshire.pdf
Train collision with material washed out from a cutting slope at Corby, Northamptonshire	04/2020	13/06/2019	04/2020/03	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/605cb1fb8fa8f57ec2557e89/04_2020_Corby_Northamptonshire.pdf
Train collision with material washed out from a cutting slope at Corby, Northamptonshire	04/2020	13/06/2019	04/2020/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605cb1fb8fa8f57ec2557e89/04_2020_Corby_Northamptonshire.pdf
Train collision with material washed out from a cutting slope at Corby, Northamptonshire	04/2020	13/06/2019	04/2020/04	Closed - I	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/605cb1fb8fa8f57ec2557e89/04_2020_Corby_Northamptonshire.pdf
Train collision with material washed out from a cutting slope at Corby, Northamptonshire	04/2020	13/06/2019	04/2020/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605cb1fb8fa8f57ec2557e89/04_2020_Corby_Northamptonshire.pdf

Class investigation into factors affecting safety-critical human performance in signalling operations on the national network	03/2020	31/03/2014	03/2020/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc102e90e076997a72fb4/03_2020_Class_investigation_safety-critical_human_performance_in_signalling_operations.pdf
Class investigation into factors affecting safety-critical human performance in signalling operations on the national network	03/2020	31/03/2014	03/2020/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc102e90e076997a72fb4/03_2020_Class_investigation_safety-critical_human_performance_in_signalling_operations.pdf
Class investigation into factors affecting safety-critical human performance in signalling operations on the national network	03/2020	31/03/2014	03/2020/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc102e90e076997a72fb4/03_2020_Class_investigation_safety-critical_human_performance_in_signalling_operations.pdf
Class investigation into factors affecting safety-critical human performance in signalling operations on the national network	03/2020	31/03/2014	03/2020/04	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc102e90e076997a72fb4/03_2020_Class_investigation_safety-critical_human_performance_in_signalling_operations.pdf
Class investigation into factors affecting safety-critical human performance in signalling operations on the national network	03/2020	31/03/2014	03/2020/05	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc102e90e076997a72fb4/03_2020_Class_investigation_safety-critical_human_performance_in_signalling_operations.pdf
Class investigation into factors affecting safety-critical human performance in signalling operations on the national network	03/2020	31/03/2014	03/2020/06	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605dc102e90e076997a72fb4/03_2020_Class_investigation_safety-critical_human_performance_in_signalling_operations.pdf
Runaway locomotive at Beddgelert, North Wales	02/2020	16/04/2019	02/2020/01	Closed - I	None	Ffestiniog & Welsh Highland Railways	https://assets.publishing.service.gov.uk/media/605caff8fa8f57ec637c5ba/02_2020_Beddgelert.pdf
Runaway locomotive at Beddgelert, North Wales	02/2020	16/04/2019	02/2020/02	Closed - I	None	Ffestiniog & Welsh Highland Railways	https://assets.publishing.service.gov.uk/media/605caff8fa8f57ec637c5ba/02_2020_Beddgelert.pdf
Runaway locomotive at Beddgelert, North Wales	02/2020	16/04/2019	02/2020/03	Closed - I	None	Ffestiniog & Welsh Highland Railways	https://assets.publishing.service.gov.uk/media/605caff8fa8f57ec637c5ba/02_2020_Beddgelert.pdf
Runaway locomotive at Beddgelert, North Wales	02/2020	16/04/2019	02/2020/04	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/605caff8fa8f57ec637c5ba/02_2020_Beddgelert.pdf
Serious operational irregularity at Balham	01/2020	20/04/2019	01/2020/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605c78e7e90e0724c31f7263/01_2020_Balham.pdf
Serious operational irregularity at Balham	01/2020	20/04/2019	01/2020/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605c78e7e90e0724c31f7263/01_2020_Balham.pdf
Serious operational irregularity at Balham	01/2020	20/04/2019	01/2020/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/605c78e7e90e0724c31f7263/01_2020_Balham.pdf
Serious operational irregularity at Balham	01/2020	20/04/2019	01/2020/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/605c78e7e90e0724c31f7263/01_2020_Balham.pdf
Loss of safety critical signalling data on the Cambrian Coast line	17/2019	20/10/2017	17/2019/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2819bce5274a6c3ee68fba/17_2019_Cambrian_Coast_line.pdf
Loss of safety critical signalling data on the Cambrian Coast line	17/2019	20/10/2017	17/2019/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5e2819bce5274a6c3ee68fba/17_2019_Cambrian_Coast_line.pdf
Loss of safety critical signalling data on the Cambrian Coast line	17/2019	20/10/2017	17/2019/02	Closed - I	None	Hitachi STS	https://assets.publishing.service.gov.uk/media/5e2819bce5274a6c3ee68fba/17_2019_Cambrian_Coast_line.pdf
Loss of safety critical signalling data on the Cambrian Coast line	17/2019	20/10/2017	17/2019/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2819bce5274a6c3ee68fba/17_2019_Cambrian_Coast_line.pdf
Loss of safety critical signalling data on the Cambrian Coast line	17/2019	20/10/2017	17/2019/03	Open	None	RSSB	https://assets.publishing.service.gov.uk/media/5e2819bce5274a6c3ee68fba/17_2019_Cambrian_Coast_line.pdf

Loss of safety critical signalling data on the Cambrian Coast line	17/2019	20/10/2017	17/2019/04	Closed - I	None	Hitachi STS	https://assets.publishing.service.gov.uk/media/5e2819bce5274a6c3ee68fba/17_2019_Cambrian_Coast_line.pdf
Loss of safety critical signalling data on the Cambrian Coast line	17/2019	20/10/2017	17/2019/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2819bce5274a6c3ee68fba/17_2019_Cambrian_Coast_line.pdf
Loss of safety critical signalling data on the Cambrian Coast line	17/2019	20/10/2017	17/2019/05	Open	None	Hitachi STS	https://assets.publishing.service.gov.uk/media/5e2819bce5274a6c3ee68fba/17_2019_Cambrian_Coast_line.pdf
Passenger injury at Ashton-under-Lyne tram stop	15/2019	12/03/2019	15/2019/01	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/5e281924ed915d1f19b595c1/15_2019_Ashton-under-Lyne.pdf
Passenger injury at Ashton-under-Lyne tram stop	15/2019	12/03/2019	15/2019/02	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/5e281924ed915d1f19b595c1/15_2019_Ashton-under-Lyne.pdf
Passenger injury at Ashton-under-Lyne tram stop	15/2019	12/03/2019	15/2019/03	Open	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/5e281924ed915d1f19b595c1/15_2019_Ashton-under-Lyne.pdf
Passenger injury at Ashton-under-Lyne tram stop	15/2019	12/03/2019	15/2019/04	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/5e281924ed915d1f19b595c1/15_2019_Ashton-under-Lyne.pdf
Passenger injury at Ashton-under-Lyne tram stop	15/2019	12/03/2019	15/2019/04	Closed - I	None	North West Ambulance Service	https://assets.publishing.service.gov.uk/media/5e281924ed915d1f19b595c1/15_2019_Ashton-under-Lyne.pdf
Fatal accident involving a train passenger at Twerton	14/2019	01/12/2018	14/2019/01	Open	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5e28183b40f0b62c4f345ae3/14_2019_Twerton.pdf
Fatal accident involving a train passenger at Twerton	14/2019	01/12/2018	14/2019/02	Closed - I	White	Heritage Train Operating Companies	https://assets.publishing.service.gov.uk/media/5e28183b40f0b62c4f345ae3/14_2019_Twerton.pdf
Fatal accident involving a train passenger at Twerton	14/2019	01/12/2018	14/2019/03	Closed - I	None	Great Western Railway	https://assets.publishing.service.gov.uk/media/5e28183b40f0b62c4f345ae3/14_2019_Twerton.pdf
Fatal accident involving a train passenger at Twerton	14/2019	01/12/2018	14/2019/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5e28183b40f0b62c4f345ae3/14_2019_Twerton.pdf
Fatal accident at Tibberton No. 8 footpath crossing	13/2019	06/02/2019	13/2019/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2817b240f0b62c49e4dd16/13_2019_Tibberton_No._8_footpath_crossing.pdf
Near miss with a track worker near Gatwick Airport station	12/2019	02/12/2018	12/2019/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2816ebed915d1f1fc94ac8/12_2019_Gatwick_Airport_station.pdf
Near miss with a track worker near Gatwick Airport station	12/2019	02/12/2018	12/2019/02	Closed - I	None	BAM Nuttall	https://assets.publishing.service.gov.uk/media/5e2816ebed915d1f1fc94ac8/12_2019_Gatwick_Airport_station.pdf
Serious operational irregularity at Bagillt user worked crossing, Flintshire, involving an abnormally heavy road vehicle	11/2019	17/08/2018	11/2019/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e28166840f0b62c47c5461b/11_2019_Bagillt_user_worked_crossing_Flintshire.pdf
Overspeed at Sandy South Junction, Bedfordshire	10/2019	19/10/2018	10/2019/01	Open	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5e2815f3e5274a6c44d681a4/10_2019_Sandy_South_Junction_Bedfordshire.pdf
Overspeed at Sandy South Junction, Bedfordshire	10/2019	19/10/2018	10/2019/01	Open	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5e2815f3e5274a6c44d681a4/10_2019_Sandy_South_Junction_Bedfordshire.pdf
Overspeed at Sandy South Junction, Bedfordshire	10/2019	19/10/2018	10/2019/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2815f3e5274a6c44d681a4/10_2019_Sandy_South_Junction_Bedfordshire.pdf

Overspeed at Sandy South Junction, Bedfordshire	10/2019	19/10/2018	10/2019/02	Closed - I	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/5e2815f3e5274a6c44d681a4/10_2019_Sandy_South_Junction_Bedfordshire.pdf
Overspeed at Sandy South Junction, Bedfordshire	10/2019	19/10/2018	10/2019/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5e2815f3e5274a6c44d681a4/10_2019_Sandy_South_Junction_Bedfordshire.pdf
Overspeed at Sandy South Junction, Bedfordshire	10/2019	19/10/2018	10/2019/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2815f3e5274a6c44d681a4/10_2019_Sandy_South_Junction_Bedfordshire.pdf
Overspeed at Sandy South Junction, Bedfordshire	10/2019	19/10/2018	10/2019/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5e2815f3e5274a6c44d681a4/10_2019_Sandy_South_Junction_Bedfordshire.pdf
Overspeed at Sandy South Junction, Bedfordshire	10/2019	19/10/2018	10/2019/04	Closed - I	None	London North Eastern Railway	https://assets.publishing.service.gov.uk/media/5e2815f3e5274a6c44d681a4/10_2019_Sandy_South_Junction_Bedfordshire.pdf
Overspeed at Sandy South Junction, Bedfordshire	10/2019	19/10/2018	10/2019/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5e2815f3e5274a6c44d681a4/10_2019_Sandy_South_Junction_Bedfordshire.pdf
Fatal collision between a tram and a pedestrian, near Saughton tram stop, Edinburgh	09/2019	11/09/2018	09/2019/01	Closed - I	None	Edinburgh Trams Ltd	https://assets.publishing.service.gov.uk/media/5e28153740f0b62c4546008e/09_2019_Saughton.pdf
Fatal collision between a tram and a pedestrian, near Saughton tram stop, Edinburgh	09/2019	11/09/2018	09/2019/02	Closed - I	None	Edinburgh Trams Ltd	https://assets.publishing.service.gov.uk/media/5e28153740f0b62c4546008e/09_2019_Saughton.pdf
Fatal collision between a tram and a pedestrian, near Saughton tram stop, Edinburgh	09/2019	11/09/2018	09/2019/03	Closed - I	None	LRSSB	https://assets.publishing.service.gov.uk/media/5e28153740f0b62c4546008e/09_2019_Saughton.pdf
Fatal collision between a tram and a pedestrian, near Saughton tram stop, Edinburgh	09/2019	11/09/2018	09/2019/04	Closed - I	None	LRSSB	https://assets.publishing.service.gov.uk/media/5e28153740f0b62c4546008e/09_2019_Saughton.pdf
Collision between two road-rail vehicles at Cholmondeston, Cheshire 19 September 2018	08/2019	19/09/2018	08/2019/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5e28149440f0b62c4a0b1360/08_2019_Cholmondeston_Cheshire.pdf
Collision between two road-rail vehicles at Cholmondeston, Cheshire 19 September 2018	08/2019	19/09/2018	08/2019/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e28149440f0b62c4a0b1360/08_2019_Cholmondeston_Cheshire.pdf
Track worker struck by a train at Stoats Nest Junction, near Purley	07/2019	06/11/2018	07/2019/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e281405ed915d1f18948ac6/07_2019_Stoats_Nest_Junction_near_Purley.pdf
Track worker struck by a train at Stoats Nest Junction, near Purley	07/2019	06/11/2018	07/2019/02	Closed - I	None	Vital Rail	https://assets.publishing.service.gov.uk/media/5e281405ed915d1f18948ac6/07_2019_Stoats_Nest_Junction_near_Purley.pdf
Train travelling with doors open on the Jubilee line	06/2019	01/09/2018	06/2019/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5e28135740f0b62c47c54619/06_2019_Jubilee_line.pdf
Train travelling with doors open on the Jubilee line	06/2019	01/09/2018	06/2019/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5e28135740f0b62c47c54619/06_2019_Jubilee_line.pdf
Train travelling with doors open on the Jubilee line	06/2019	01/09/2018	06/2019/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5e28135740f0b62c47c54619/06_2019_Jubilee_line.pdf
Train travelling with doors open on the Jubilee line	06/2019	01/09/2018	06/2019/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5e28135740f0b62c47c54619/06_2019_Jubilee_line.pdf
Collision between a train and utility vehicle at Dollands Moor freight yard, Kent	05/2019	04/09/2018	05/2019/01	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/5e281296ed915d1f217acea0/05_2019_Dollands_Moor.pdf

Collision between a train and utility vehicle at Dollands Moor freight yard, Kent	05/2019	04/09/2018	05/2019/02	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/5e281296ed915d1f217acea0/05_2019_Dollands_Moor.pdf
Near miss between a train and a track worker at Peterborough	04/2019	20/07/2018	04/2019/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e28121d40f0b62c4546008c/04_2019_Peterborough.pdf
Near miss between a train and a track worker at Peterborough	04/2019	20/07/2018	04/2019/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e28121d40f0b62c4546008c/04_2019_Peterborough.pdf
Near miss between a train and a track worker at Peterborough	04/2019	20/07/2018	04/2019/03	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e28121d40f0b62c4546008c/04_2019_Peterborough.pdf
Near miss between a train and a track worker at Peterborough	04/2019	20/07/2018	04/2019/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e28121d40f0b62c4546008c/04_2019_Peterborough.pdf
Near miss between a train and a track worker at Peterborough	04/2019	20/07/2018	04/2019/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e28121d40f0b62c4546008c/04_2019_Peterborough.pdf
Train dispatch accident at Elstree & Borehamwood station	03/2019	07/09/2018	03/2019/01	Open	None	Govia Thameslink Railway	https://assets.publishing.service.gov.uk/media/5e2810da40f0b62c4ccf5aea/03_2019_Elstree_Borehamwood_station.pdf
Train dispatch accident at Elstree & Borehamwood station	03/2019	07/09/2018	03/2019/02	Open	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/5e2810da40f0b62c4ccf5aea/03_2019_Elstree_Borehamwood_station.pdf
Train dispatch accident at Elstree & Borehamwood station	03/2019	07/09/2018	03/2019/02	Open	None	RSSB	https://assets.publishing.service.gov.uk/media/5e2810da40f0b62c4ccf5aea/03_2019_Elstree_Borehamwood_station.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/01	Closed - I	None	Southeastern	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/02	Closed - I	None	Southeastern	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/03	Closed - I	None	Southeastern	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/04	Closed - I	None	Southeastern	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf

Self-detrainment of passengers onto lines that were still open to traffic and electrically live at Lewisham, south-east London	02/2019	02/03/2018	02/2019/05	Closed - I	None	Southeastern	https://assets.publishing.service.gov.uk/media/5e2809e1ed915d1f19b595c0/02_2019_Lewisham_south-east_London.pdf
Runaway of a road-rail vehicle at Bradford Interchange	01/2019	08/06/2018	01/2019/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e280784ed915d1f217ace9e/01_2019_Bradford_Interchange.pdf
Runaway of a road-rail vehicle at Bradford Interchange	01/2019	08/06/2018	01/2019/02	Closed - I	None	Readypower	https://assets.publishing.service.gov.uk/media/5e280784ed915d1f217ace9e/01_2019_Bradford_Interchange.pdf
Runaway of a road-rail vehicle at Bradford Interchange	01/2019	08/06/2018	01/2019/03	Closed - I	None	Readypower	https://assets.publishing.service.gov.uk/media/5e280784ed915d1f217ace9e/01_2019_Bradford_Interchange.pdf
Near miss with track workers and trolleys at South Hampstead, London	20/2018	10/03/2018	20/2018/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5cacbf3940f0b67b6848b42c/20_2018_South_Hampstead_London.pdf
Near miss with track workers and trolleys at South Hampstead, London	20/2018	10/03/2018	20/2018/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5cacbf3940f0b67b6848b42c/20_2018_South_Hampstead_London.pdf
Near miss with track workers and trolleys at South Hampstead, London	20/2018	10/03/2018	20/2018/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5cacbf3940f0b67b6848b42c/20_2018_South_Hampstead_London.pdf
Near miss with track workers and trolleys at South Hampstead, London	20/2018	10/03/2018	20/2018/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5cacbf3940f0b67b6848b42c/20_2018_South_Hampstead_London.pdf
Near miss with track workers and trolleys at South Hampstead, London	20/2018	10/03/2018	20/2018/05	Closed - IA	White	Network Rail	https://assets.publishing.service.gov.uk/media/5cacbf3940f0b67b6848b42c/20_2018_South_Hampstead_London.pdf
Near miss with track workers and trolleys at South Hampstead, London	20/2018	10/03/2018	20/2018/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5cacbf3940f0b67b6848b42c/20_2018_South_Hampstead_London.pdf
Collision at London Waterloo	19/2018	15/08/2017	19/2018/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5cacbf0140f0b67b5959b4b9/19_2018_Waterloo.pdf
Collision at London Waterloo	19/2018	15/08/2017	19/2018/02	Closed - I	None	OSL Rail Limited	https://assets.publishing.service.gov.uk/media/5cacbf0140f0b67b5959b4b9/19_2018_Waterloo.pdf
Collision at London Waterloo	19/2018	15/08/2017	19/2018/03	Closed - I	None	Mott MacDonald Limited	https://assets.publishing.service.gov.uk/media/5cacbf0140f0b67b5959b4b9/19_2018_Waterloo.pdf
Runaway hand trolley at Ramsbottom, East Lancashire Railway	18/2018	16/03/2018	18/2018/01	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/5cacbe69e5274a429f386803/18_2018_Ramsbottom.pdf
Runaway hand trolley at Ramsbottom, East Lancashire Railway	18/2018	16/03/2018	18/2018/02	Closed - I	None	East Lancashire Railway	https://assets.publishing.service.gov.uk/media/5cacbe69e5274a429f386803/18_2018_Ramsbottom.pdf
Runaway hand trolley at Ramsbottom, East Lancashire Railway	18/2018	16/03/2018	18/2018/03	Closed - I	None	East Lancashire Railway	https://assets.publishing.service.gov.uk/media/5cacbe69e5274a429f386803/18_2018_Ramsbottom.pdf
Extensive track damage between Ferryside and Llangennech, Carmarthenshire	17/2018	30/10/2017	17/2018/01	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/5cadc208e5274a5b434ed899/17_2018_Ferryside_and_Llangennech.pdf
Extensive track damage between Ferryside and Llangennech, Carmarthenshire	17/2018	30/10/2017	17/2018/01	Closed - I	None	Puma Energy	https://assets.publishing.service.gov.uk/media/5cadc208e5274a5b434ed899/17_2018_Ferryside_and_Llangennech.pdf
Extensive track damage between Ferryside and Llangennech, Carmarthenshire	17/2018	30/10/2017	17/2018/01	Closed - I	None	TOUAX Rail Services	https://assets.publishing.service.gov.uk/media/5cadc208e5274a5b434ed899/17_2018_Ferryside_and_Llangennech.pdf

Detrainment of passengers onto electrically live track near Peckham Rye station	16/2018	07/11/2017	16/2018/01	Closed - I	None	Arriva Rail London	https://assets.publishing.service.gov.uk/media/5c9de53a40f0b633f6c52aa4/16_2018_Peckham_Rye.pdf
Detrainment of passengers onto electrically live track near Peckham Rye station	16/2018	07/11/2017	16/2018/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9de53a40f0b633f6c52aa4/16_2018_Peckham_Rye.pdf
Detrainment of passengers onto electrically live track near Peckham Rye station	16/2018	07/11/2017	16/2018/02	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5c9de53a40f0b633f6c52aa4/16_2018_Peckham_Rye.pdf
Detrainment of passengers onto electrically live track near Peckham Rye station	16/2018	07/11/2017	16/2018/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9de53a40f0b633f6c52aa4/16_2018_Peckham_Rye.pdf
Detrainment of passengers onto electrically live track near Peckham Rye station	16/2018	07/11/2017	16/2018/03	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5c9de53a40f0b633f6c52aa4/16_2018_Peckham_Rye.pdf
Pushchair trapped in tram doors and dragged, Nottingham	15/2018	15/12/2017	15/2018/01	Open	None	Nottingham Express Transit	https://assets.publishing.service.gov.uk/media/5c9de4f5e274a528752d5b3/15_2018_Pushchair_trap_and_drag_Nottingham.pdf
Pushchair trapped in tram doors and dragged, Nottingham	15/2018	15/12/2017	15/2018/02	Open	None	Nottingham Express Transit	https://assets.publishing.service.gov.uk/media/5c9de4f5e274a528752d5b3/15_2018_Pushchair_trap_and_drag_Nottingham.pdf
Passenger trapped and dragged at Notting Hill Gate station	14/2018	31/01/2018	14/2018/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5c9de4b540f0b633fe11d31b/14_2018_Notting_Hill_Gate_station.pdf
Passenger trapped and dragged at Notting Hill Gate station	14/2018	31/01/2018	14/2018/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5c9de4b540f0b633fe11d31b/14_2018_Notting_Hill_Gate_station.pdf
Passenger trapped and dragged at Notting Hill Gate station	14/2018	31/01/2018	14/2018/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5c9de4b540f0b633fe11d31b/14_2018_Notting_Hill_Gate_station.pdf
Passenger trapped and dragged at Notting Hill Gate station	14/2018	31/01/2018	14/2018/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5c9de4b540f0b633fe11d31b/14_2018_Notting_Hill_Gate_station.pdf
Passenger trapped and dragged at Notting Hill Gate station	14/2018	31/01/2018	14/2018/05	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5c9de4b540f0b633fe11d31b/14_2018_Notting_Hill_Gate_station.pdf
Near miss with track workers at Pelaw North Junction	13/2018	21/02/2018	13/2018/01	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/5e25e81b40f0b62c522480af/13_2018_Pelaw_North_Junction.pdf
Near miss with track workers at Pelaw North Junction	13/2018	21/02/2018	13/2018/02	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/5e25e81b40f0b62c522480af/13_2018_Pelaw_North_Junction.pdf
Near miss with track workers at Pelaw North Junction	13/2018	21/02/2018	13/2018/03	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/5e25e81b40f0b62c522480af/13_2018_Pelaw_North_Junction.pdf
Near miss with track workers at Pelaw North Junction	13/2018	21/02/2018	13/2018/04	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/5e25e81b40f0b62c522480af/13_2018_Pelaw_North_Junction.pdf
Near miss with track workers at Pelaw North Junction	13/2018	21/02/2018	13/2018/05	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/5e25e81b40f0b62c522480af/13_2018_Pelaw_North_Junction.pdf
Collision at Frogmal Farm User Worked Crossing	12/2018	23/10/2017	12/2018/01	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/5c9de3d840f0b633f48c860a/12_2018_Frogmal_Farm_User_Worked_Crossing.pdf
Collision at Frogmal Farm User Worked Crossing	12/2018	23/10/2017	12/2018/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9de3d840f0b633f48c860a/12_2018_Frogmal_Farm_User_Worked_Crossing.pdf

Collision at Frogmal Farm User Worked Crossing	12/2018	23/10/2017	12/2018/01	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5c9de3d840f0b633f48c860a/12_2018_Frogmal_Farm_User_Worked_Crossing.pdf
Collision at Frogmal Farm User Worked Crossing	12/2018	23/10/2017	12/2018/02	Open	None	Department for Transport	https://assets.publishing.service.gov.uk/media/5c9de3d840f0b633f48c860a/12_2018_Frogmal_Farm_User_Worked_Crossing.pdf
Collision at Frogmal Farm User Worked Crossing	12/2018	23/10/2017	12/2018/02	Open	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5c9de3d840f0b633f48c860a/12_2018_Frogmal_Farm_User_Worked_Crossing.pdf
Collision at Frogmal Farm User Worked Crossing	12/2018	23/10/2017	12/2018/03	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/5c9de3d840f0b633f48c860a/12_2018_Frogmal_Farm_User_Worked_Crossing.pdf
Collision at Frogmal Farm User Worked Crossing	12/2018	23/10/2017	12/2018/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9de3d840f0b633f48c860a/12_2018_Frogmal_Farm_User_Worked_Crossing.pdf
Near miss with a group of track workers at Egmonton level crossing, Nottinghamshire	11/2018	05/10/2017	11/2018/01	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/5c9ce6eb40f0b633f3d4b757/11_2018_Egmonton_level_crossing_Nottinghamshire.pdf
Near miss with a group of track workers at Egmonton level crossing, Nottinghamshire	11/2018	05/10/2017	11/2018/02	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/5c9ce6eb40f0b633f3d4b757/11_2018_Egmonton_level_crossing_Nottinghamshire.pdf
Near miss with a group of track workers at Egmonton level crossing, Nottinghamshire	11/2018	05/10/2017	11/2018/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9ce6eb40f0b633f3d4b757/11_2018_Egmonton_level_crossing_Nottinghamshire.pdf
Landslip and derailment at Loch Eilt, north-west Scotland	10/2018	22/01/2018	10/2018/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9ce684ed915d07adf5c2c8/10_2018_Loch_Eilt.pdf
Freight train derailment at Ely West Junction	09/2018	14/08/2017	09/2018/01	Closed - I	None	GB Railfreight	https://assets.publishing.service.gov.uk/media/5c9ce59240f0b633f95f7c8/09-2018-Ely.pdf
Collision at Stainforth Road level crossing	08/2018	11/01/2018	08/2018/01	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/547c9070e5274a42900001db/01_2006_Stainforth_Road.pdf
Collision at Stainforth Road level crossing	08/2018	11/01/2018	08/2018/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9070e5274a42900001db/01_2006_Stainforth_Road.pdf
Fatal accident at Trenos footpath crossing near Llanharan, Rhondda Cynon Taf, South Wales	07/2018	01/06/2017	07/2018/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9ce451e5274a527c259bd/07/07_2018_Trenos.pdf
Passengers struck by a flying cable at Abergavenny (Y Fenni) station	06/2018	28/07/2017	06/2018/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9ce3eae915d07b0af3e4c/06_2018_Abergavenny.pdf
Passengers struck by a flying cable at Abergavenny (Y Fenni) station	06/2018	28/07/2017	06/2018/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9ce3eae915d07b0af3e4c/06_2018_Abergavenny.pdf
Passengers struck by a flying cable at Abergavenny (Y Fenni) station	06/2018	28/07/2017	06/2018/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5c9ce3eae915d07b0af3e4c/06_2018_Abergavenny.pdf
Explosion inside an underframe equipment case at Guildford	05/2018	07/07/2017	05/2018/01	Open	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5ae72193ed915d42f42b5fd3/05_2018_Guildford.pdf
Explosion inside an underframe equipment case at Guildford	05/2018	07/07/2017	05/2018/01	Open	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5ae72193ed915d42f42b5fd3/05_2018_Guildford.pdf
Explosion inside an underframe equipment case at Guildford	05/2018	07/07/2017	05/2018/01	Open	None	Rolling Stock Contracting Entities	https://assets.publishing.service.gov.uk/media/5ae72193ed915d42f42b5fd3/05_2018_Guildford.pdf

Explosion inside an underframe equipment case at Guildford	05/2018	07/07/2017	05/2018/01	Open	None	Rolling Stock Leasing Companies	https://assets.publishing.service.gov.uk/media/5ae72193ed915d42f42b5fd3/05_2018_Guildford.pdf
Freight train derailment at Lewisham, south-east London	04/2018	24/01/2017	04/2018/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ae7214de5274a7024fd6f2c/04_2018_Lewisham_south-east_London.pdf
Freight train derailment at Lewisham, south-east London	04/2018	24/01/2017	04/2018/02	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/5ae7214de5274a7024fd6f2c/04_2018_Lewisham_south-east_London.pdf
Freight train derailment at Lewisham, south-east London	04/2018	24/01/2017	04/2018/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ae7214de5274a7024fd6f2c/04_2018_Lewisham_south-east_London.pdf
Freight train derailment at Lewisham, south-east London	04/2018	24/01/2017	04/2018/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ae7214de5274a7024fd6f2c/04_2018_Lewisham_south-east_London.pdf
Freight train derailment at Lewisham, south-east London	04/2018	24/01/2017	04/2018/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5ae7214de5274a7024fd6f2c/04_2018_Lewisham_south-east_London.pdf
Trailer runaway near Hope, Derbyshire	03/2018	28/05/2017	03/2018/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ae72108ed915d42f42b5fd2/03_2018_Hope_Derbyshire.pdf
Trailer runaway near Hope, Derbyshire	03/2018	28/05/2017	03/2018/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ae72108ed915d42f42b5fd2/03_2018_Hope_Derbyshire.pdf
Trailer runaway near Hope, Derbyshire	03/2018	28/05/2017	03/2018/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ae72108ed915d42f42b5fd2/03_2018_Hope_Derbyshire.pdf
Child nearly falling through a missing toilet floor, South Devon Railway	02/2018	22/06/2017	02/2018/01	Open	None	South Devon Railway	https://assets.publishing.service.gov.uk/media/5ae72091ed915d42f7c6bc2f/02_2018_South_Devon_Railway.pdf
Runaway of a maintenance train near Markinch, Fife	01/2018	17/10/2017	01/2018/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ae71ff9ed915d42f42b5fd0/01_2018_Markinch.pdf
Runaway of a maintenance train near Markinch, Fife	01/2018	17/10/2017	01/2018/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ae71ff9ed915d42f42b5fd0/01_2018_Markinch.pdf
Freight train derailment at East Somerset Junction	19/2017	20/03/2017	19/2017/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bd6eed915d32a3a70fbd/19_2017_East_Somerset_Junction.pdf
Freight train derailment at East Somerset Junction	19/2017	20/03/2017	19/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bd6eed915d32a3a70fbd/19_2017_East_Somerset_Junction.pdf
Freight train derailment at East Somerset Junction	19/2017	20/03/2017	19/2017/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bd6eed915d32a3a70fbd/19_2017_East_Somerset_Junction.pdf
Freight train derailment at East Somerset Junction	19/2017	20/03/2017	19/2017/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bd6eed915d32a3a70fbd/19_2017_East_Somerset_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/01	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/01	Closed - I	None	UK Tram Industry	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/02	Closed - I	None	UK Tram Infrastructure Managers	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf

Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/10	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/11	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/12	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/13	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/13	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/13	Closed - I	None	Transport for London (TfL)	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/14	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Overturning of a tram at Sandilands junction, Croydon	18/2017	09/11/2016	18/2017/15	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/5e25e6b740f0b62c4a0b1340/18_2017_Sandilands_Junction.pdf
Partial collapse of a wall onto open railway lines, Liverpool	17/2017	28/02/2017	17/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bc8de5274a76be66c7f3/17_2017_Liverpool.pdf
Partial collapse of a wall onto open railway lines, Liverpool	17/2017	28/02/2017	17/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bc8de5274a76be66c7f3/17_2017_Liverpool.pdf
Track worker near miss incidents at Camden Junction South, London	16/2017	28/02/2017	16/2017/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bc3240f0b617df335f27/16_2017_Camden_Junction_South.pdf
Track worker near miss incidents at Camden Junction South, London	16/2017	28/02/2017	16/2017/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bc3240f0b617df335f27/16_2017_Camden_Junction_South.pdf
Track worker near miss incidents at Camden Junction South, London	16/2017	28/02/2017	16/2017/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bc3240f0b617df335f27/16_2017_Camden_Junction_South.pdf
Serious irregularity at Cardiff East Junction	15/2017	29/12/2016	15/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bc0140f0b617df335f24/15_2017_Cardiff_East_Junction.pdf
Serious irregularity at Cardiff East Junction	15/2017	29/12/2016	15/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bc0140f0b617df335f24/15_2017_Cardiff_East_Junction.pdf
Serious irregularity at Cardiff East Junction	15/2017	29/12/2016	15/2017/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bc0140f0b617df335f24/15_2017_Cardiff_East_Junction.pdf
Fatal accident at Alice Holt footpath crossing, Hampshire	14/2017	05/10/2016	14/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bbc7e5274a76be66c7ee/14_2017_Alice_Holt_footpath_crossing_Hampshire.pdf
Fatal collision between a tram and pedestrian at Woodbourn Road, Sheffield	13/2017	22/12/2016	13/2017/01	Closed - I	None	Stagecoach Supertram	https://assets.publishing.service.gov.uk/media/5ad9bb98e5274a76be66c7ed/13_2017_Woodbourn_Road_Sheffield.pdf
Fatal collision between a tram and pedestrian at Woodbourn Road, Sheffield	13/2017	22/12/2016	13/2017/02	Closed - I	None	UK Tram	https://assets.publishing.service.gov.uk/media/5ad9bb98e5274a76be66c7ed/13_2017_Woodbourn_Road_Sheffield.pdf

Fatal collision between a tram and pedestrian at Woodbourn Road, Sheffield	13/2017	22/12/2016	13/2017/02	Closed - I	None	UK Tram Operators	https://assets.publishing.service.gov.uk/media/5ad9bb98e5274a76be66c7ed/13_2017_Woodbourn_Road_Sheffield.pdf
Dangerous train door incident at Bank station on the Docklands Light Railway	12/2017	06/02/2017	12/2017/01	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/5ad9bb66ed915d32a65dbfe9/12_2017_Bank_station.pdf
Dangerous train door incident at Bank station on the Docklands Light Railway	12/2017	06/02/2017	12/2017/01	Closed - I	None	Keolis Amey Docklands	https://assets.publishing.service.gov.uk/media/5ad9bb66ed915d32a65dbfe9/12_2017_Bank_station.pdf
Dangerous train door incident at Bank station on the Docklands Light Railway	12/2017	06/02/2017	12/2017/02	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/5ad9bb66ed915d32a65dbfe9/12_2017_Bank_station.pdf
Dangerous train door incident at Bank station on the Docklands Light Railway	12/2017	06/02/2017	12/2017/03	Closed - I	None	Keolis Amey Docklands	https://assets.publishing.service.gov.uk/media/5ad9bb66ed915d32a65dbfe9/12_2017_Bank_station.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/03	Closed - I	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/04	Closed - I	None	Angel Trains Limited	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/04	Closed - I	None	Eversholt Rail UK (Ltd)	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/04	Closed - I	None	South Western Railway	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/04	Closed - I	None	Siemens AG	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Derailment due to a landslip, and subsequent collision, Watford	11/2017	16/09/2016	11/2017/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9bb35e5274a76c13dff98/11_2017_Watford_tunnel.pdf
Partial collapse of a bridge onto open railway lines at Barrow upon Soar, Leicestershire	10/2017	01/08/2016	10/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9ba7ded915d32a65dbfe3/10_2017_Barrow_upon_Soar_Leicestershire.pdf
Partial collapse of a bridge onto open railway lines at Barrow upon Soar, Leicestershire	10/2017	01/08/2016	10/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9ba7ded915d32a65dbfe3/10_2017_Barrow_upon_Soar_Leicestershire.pdf
Partial collapse of a bridge onto open railway lines at Barrow upon Soar, Leicestershire	10/2017	01/08/2016	10/2017/03	Closed - I	None	Construction Marine Limited (CML)	https://assets.publishing.service.gov.uk/media/5ad9ba7ded915d32a65dbfe3/10_2017_Barrow_upon_Soar_Leicestershire.pdf
Fatal accident involving a train passenger near Balham	09/2017	07/08/2016	09/2017/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5ad9ba23ed915d32a3a70fac/09_2017_Balham.pdf

Fatal accident involving a train passenger near Balham	09/2017	07/08/2016	09/2017/02	Open	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5ad9ba23ed915d32a3a70fac/09_2017_Balham.pdf
Near miss between a train and a level crossing user at Dock Lane, Melton, Suffolk	08/2017	14/06/2016	08/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/591590d4ed915d5a3c00003c/08_2017_Dock_Lane.pdf
Near miss between a train and a level crossing user at Dock Lane, Melton, Suffolk	08/2017	14/06/2016	08/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/591590d4ed915d5a3c00003c/08_2017_Dock_Lane.pdf
Near miss between a train and a level crossing user at Dock Lane, Melton, Suffolk	08/2017	14/06/2016	08/2017/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/591590d4ed915d5a3c00003c/08_2017_Dock_Lane.pdf
Near miss between a train and a level crossing user at Dock Lane, Melton, Suffolk	08/2017	14/06/2016	08/2017/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/591590d4ed915d5a3c00003c/08_2017_Dock_Lane.pdf
Class investigation into accidents and near misses involving trains and track workers outside possessions	07/2017	02/02/2016	07/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5d3af766e5274a4012298f15/07_2017_Class_investigation_into_accidents_nr_misses_involving_trackworkers.pdf
Class investigation into accidents and near misses involving trains and track workers outside possessions	07/2017	02/02/2016	07/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5d3af766e5274a4012298f15/07_2017_Class_investigation_into_accidents_nr_misses_involving_trackworkers.pdf
Class investigation into accidents and near misses involving trains and track workers outside possessions	07/2017	02/02/2016	07/2017/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5d3af766e5274a4012298f15/07_2017_Class_investigation_into_accidents_nr_misses_involving_trackworkers.pdf
Class investigation into accidents and near misses involving trains and track workers outside possessions	07/2017	02/02/2016	07/2017/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5d3af766e5274a4012298f15/07_2017_Class_investigation_into_accidents_nr_misses_involving_trackworkers.pdf
Class investigation into accidents and near misses involving trains and track workers outside possessions	07/2017	02/02/2016	07/2017/05	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/5d3af766e5274a4012298f15/07_2017_Class_investigation_into_accidents_nr_misses_involving_trackworkers.pdf
Fatal accident near David Lane tram stop	06/2017	15/08/2016	06/2017/01	Closed - I	None	Nottingham Express Transit	https://assets.publishing.service.gov.uk/media/59159006ed915d59de000040/06_2017_David_Lane.pdf
Near miss between a train and a track worker at Shawford	05/2017	24/06/2016	05/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158f9de5274a44cd00004e/05_2017_Shawford.pdf
Near miss between a train and a track worker at Shawford	05/2017	24/06/2016	05/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158f9de5274a44cd00004e/05_2017_Shawford.pdf
Near miss between a train and a track worker at Shawford	05/2017	24/06/2016	05/2017/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158f9de5274a44cd00004e/05_2017_Shawford.pdf
Collision between a train and tractor at Hockham Road user worked crossing, near Thetford	04/2017	10/04/2016	04/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158f3b40f0b638b000005d/04_2017_Hockham_Road.pdf
Collision between a train and tractor at Hockham Road user worked crossing, near Thetford	04/2017	10/04/2016	04/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158f3b40f0b638b000005d/04_2017_Hockham_Road.pdf
Collision between a train and tractor at Hockham Road user worked crossing, near Thetford	04/2017	10/04/2016	04/2017/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158f3b40f0b638b000005d/04_2017_Hockham_Road.pdf
Trains passed over washed out track at Baildon, West Yorkshire	03/2017	07/06/2016	03/2017/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158e5aed915d59de00003e/03_2017_Baildon.pdf
Trains passed over washed out track at Baildon, West Yorkshire	03/2017	07/06/2016	03/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158e5aed915d59de00003e/03_2017_Baildon.pdf

Trains passed over washed out track at Baildon, West Yorkshire	03/2017	07/06/2016	03/2017/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158e5aed915d59de00003e/03_2017_Baildon.pdf
Collision at Plymouth station	02/2017	03/04/2016	02/2017/01	Closed - I	None	Great Western Railway	https://assets.publishing.service.gov.uk/media/59158dbee5274a44cd00004c/02_2017_Plymouth.pdf
Collision at Plymouth station	02/2017	03/04/2016	02/2017/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/59158dbee5274a44cd00004c/02_2017_Plymouth.pdf
Collision at Plymouth station	02/2017	03/04/2016	02/2017/03	Closed - I	None	Great Western Railway	https://assets.publishing.service.gov.uk/media/59158dbee5274a44cd00004c/02_2017_Plymouth.pdf
Occupied wheelchair contacting a passing train at Twyford station	01/2017	07/04/2016	01/2017/01	Closed - I	None	Rail Delivery Group	https://assets.publishing.service.gov.uk/media/59158cc3e5274a455000004d/01_2017_Twyford_station.pdf
Occupied wheelchair contacting a passing train at Twyford station	01/2017	07/04/2016	01/2017/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/59158cc3e5274a455000004d/01_2017_Twyford_station.pdf
Occupied wheelchair contacting a passing train at Twyford station	01/2017	07/04/2016	01/2017/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/59158cc3e5274a455000004d/01_2017_Twyford_station.pdf
Occupied wheelchair contacting a passing train at Twyford station	01/2017	07/04/2016	01/2017/04	Closed - I	None	Great Western Railway	https://assets.publishing.service.gov.uk/media/59158cc3e5274a455000004d/01_2017_Twyford_station.pdf
Occupied wheelchair contacting a passing train at Twyford station	01/2017	07/04/2016	01/2017/05	Closed - I	None	Great Western Railway	https://assets.publishing.service.gov.uk/media/59158cc3e5274a455000004d/01_2017_Twyford_station.pdf
Derailment of a passenger train at Ealing Broadway	24/2016	01/03/2016	24/2016/01	Closed - IA	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/58ecef80e5274a06b300015e/24_2016_Ealing_Broadway.pdf
Derailment of a passenger train at Ealing Broadway	24/2016	01/03/2016	24/2016/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/58ecef80e5274a06b300015e/24_2016_Ealing_Broadway.pdf
Derailment of a passenger train at Ealing Broadway	24/2016	01/03/2016	24/2016/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/58ecef80e5274a06b300015e/24_2016_Ealing_Broadway.pdf
Fatal accident at Grimston Lane footpath crossing, Suffolk	23/2016	23/02/2016	23/2016/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/58ecef10ed915d06b0000141/23_2016_Grimston_Lane.pdf
Fatal accident at Grimston Lane footpath crossing, Suffolk	23/2016	23/02/2016	23/2016/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/58ecef10ed915d06b0000141/23_2016_Grimston_Lane.pdf
Structural failure caused by scour at Lamington viaduct, South Lanarkshire	22/2016	31/12/2015	22/2016/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/58ecee1eed915d06ac000176/21_2016_Barrow_upon_Soar.pdf
Structural failure caused by scour at Lamington viaduct, South Lanarkshire	22/2016	31/12/2015	22/2016/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/58ecee1eed915d06ac000176/21_2016_Barrow_upon_Soar.pdf
Structural failure caused by scour at Lamington viaduct, South Lanarkshire	22/2016	31/12/2015	22/2016/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/58ecee1eed915d06ac000176/21_2016_Barrow_upon_Soar.pdf
Collision between a train and a piece of equipment at Barrow-upon-Soar, Leicestershire,	21/2016	14/02/2016	21/2016/01	Open	None	Tarmac Aggregates	https://assets.publishing.service.gov.uk/media/58ecee1eed915d06ac000176/21_2016_Barrow_upon_Soar.pdf
Collision between a train and a piece of equipment at Barrow-upon-Soar, Leicestershire,	21/2016	14/02/2016	21/2016/01	Open	None	Wabtec Rail Limited	https://assets.publishing.service.gov.uk/media/58ecee1eed915d06ac000176/21_2016_Barrow_upon_Soar.pdf

Collision between a train and a piece of equipment at Barrow-upon-Soar, Leicestershire,	21/2016	14/02/2016	21/2016/02	Open	None	Wabtec Rail Limited	https://assets.publishing.service.gov.uk/media/58ecee1eed915d06ac000176/21_2016_Barrow_upon_Soar.pdf
Collision between a train and a piece of equipment at Barrow-upon-Soar, Leicestershire,	21/2016	14/02/2016	21/2016/03	Closed - NI	None	Tarmac Aggregates	https://assets.publishing.service.gov.uk/media/58ecee1eed915d06ac000176/21_2016_Barrow_upon_Soar.pdf
Collision between a train and a piece of equipment at Barrow-upon-Soar, Leicestershire,	21/2016	14/02/2016	21/2016/04	Closed - NI	None	Tarmac Aggregates	https://assets.publishing.service.gov.uk/media/58ecee1eed915d06ac000176/21_2016_Barrow_upon_Soar.pdf
Collision at Knockmore Junction, Northern Ireland	20/2016	04/02/2016	20/2016/01	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/58ececfaed915d06ac000174/20_2016_Knockmore.pdf
Collision at Knockmore Junction, Northern Ireland	20/2016	04/02/2016	20/2016/02	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/58ececfaed915d06ac000174/20_2016_Knockmore.pdf
Overspeed at Queen's Park, London	19/2016	05/01/2016	19/2016/01	Closed - I	None	London Midland	https://assets.publishing.service.gov.uk/media/58ecec42e5274a06b300015c/19_2016_Queens_Park.pdf
Overspeed at Queen's Park, London	19/2016	05/01/2016	19/2016/02	Closed - I	None	London Midland	https://assets.publishing.service.gov.uk/media/58ecec42e5274a06b300015c/19_2016_Queens_Park.pdf
Overspeed at Queen's Park, London	19/2016	05/01/2016	19/2016/03	Closed - I	None	London Midland	https://assets.publishing.service.gov.uk/media/58ecec42e5274a06b300015c/19_2016_Queens_Park.pdf
Two signal passed at danger incidents, at Reading Westbury Line Junction and Ruscombe Junction	18/2016	03/11/2015	18/2016/01	Open	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/5ad9b4c9e5274a76be66c7d3/18_2016_Reading_Ruscombe.pdf
Two signal passed at danger incidents, at Reading Westbury Line Junction and Ruscombe Junction	18/2016	03/11/2015	18/2016/02	Open	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5ad9b4c9e5274a76be66c7d3/18_2016_Reading_Ruscombe.pdf
Two signal passed at danger incidents, at Reading Westbury Line Junction and Ruscombe Junction	18/2016	03/11/2015	18/2016/03	Open	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/5ad9b4c9e5274a76be66c7d3/18_2016_Reading_Ruscombe.pdf
Collision between two trams at Shalesmoor, Sheffield	17/2016	22/10/2015	17/2016/01	Closed - I	None	UK Tram Operators	https://assets.publishing.service.gov.uk/media/57d91095e5274a34fb000038/17_2016_Shalesmoor.pdf
Derailment at Knaresborough	16/2016	07/11/2015	16/2016/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/57d9112f40f0b6533a00004c/16_2016_Knaresborough.pdf
Collision with buffer stops at King's Cross	15/2016	17/09/2015	15/2016/01	Closed - I	None	Govia Thameslink Railway	https://assets.publishing.service.gov.uk/media/57d91055e5274a34fb000036/15_2016_King_s_Cross.pdf
Collision with buffer stops at King's Cross	15/2016	17/09/2015	15/2016/02	Closed - I	None	Govia Thameslink Railway	https://assets.publishing.service.gov.uk/media/57d91055e5274a34fb000036/15_2016_King_s_Cross.pdf
Overspeed at Fletton Junction, Peterborough	14/2016	11/09/2015	14/2016/01	Closed - I	None	Virgin Trains	https://assets.publishing.service.gov.uk/media/57d910dc40f0b65264000037/14_2016_Fletton_Junction_Peterborough.pdf
Overspeed at Fletton Junction, Peterborough	14/2016	11/09/2015	14/2016/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/57d910dc40f0b65264000037/14_2016_Fletton_Junction_Peterborough.pdf
Overspeed at Fletton Junction, Peterborough	14/2016	11/09/2015	14/2016/02	Closed - I	None	Virgin Trains	https://assets.publishing.service.gov.uk/media/57d910dc40f0b65264000037/14_2016_Fletton_Junction_Peterborough.pdf
Overspeed at Fletton Junction, Peterborough	14/2016	11/09/2015	14/2016/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/57d910dc40f0b65264000037/14_2016_Fletton_Junction_Peterborough.pdf

Overspeed at Fletton Junction, Peterborough	14/2016	11/09/2015	14/2016/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/57d910dc40f0b65264000037/14_2016_Fletton_Junction_Peterborough.pdf
Overspeed at Fletton Junction, Peterborough	14/2016	11/09/2015	14/2016/05	Closed - I	None	Virgin Trains	https://assets.publishing.service.gov.uk/media/57d910dc40f0b65264000037/14_2016_Fletton_Junction_Peterborough.pdf
Freight train collision near Logan, East Ayrshire	13/2016	01/08/2015	13/2016/01	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5795e2dded915d622c000160/13_2016_Logan.pdf
Freight train collision near Logan, East Ayrshire	13/2016	01/08/2015	13/2016/02	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5795e2dded915d622c000160/13_2016_Logan.pdf
Freight train collision near Logan, East Ayrshire	13/2016	01/08/2015	13/2016/03	Open	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5795e2dded915d622c000160/13_2016_Logan.pdf
Freight train collision near Logan, East Ayrshire	13/2016	01/08/2015	13/2016/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5795e2dded915d622c000160/13_2016_Logan.pdf
Freight train collision near Logan, East Ayrshire	13/2016	01/08/2015	13/2016/04	Open	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5795e2dded915d622c000160/13_2016_Logan.pdf
Freight train collision near Logan, East Ayrshire	13/2016	01/08/2015	13/2016/04	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5795e2dded915d622c000160/13_2016_Logan.pdf
Passenger trapped and dragged by a train at Hayes & Harlington station	12/2016	25/07/2015	12/2016/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5795e3b240f0b64974000000/12_2016_Hayes_and_Harlington.pdf
Passenger trapped and dragged by a train at Hayes & Harlington station	12/2016	25/07/2015	12/2016/02	Open	None	Angel Trains Limited	https://assets.publishing.service.gov.uk/media/5795e3b240f0b64974000000/12_2016_Hayes_and_Harlington.pdf
Passenger trapped and dragged by a train at Hayes & Harlington station	12/2016	25/07/2015	12/2016/02	Open	None	Eversholt Rail UK (Ltd)	https://assets.publishing.service.gov.uk/media/5795e3b240f0b64974000000/12_2016_Hayes_and_Harlington.pdf
Derailment of a freight train near Langworth, Lincolnshire	11/2016	30/06/2015	11/2016/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5795e482ed915d3cfd0001a1/11_2016_Langworth_Lincolnshire.pdf
Derailment of a freight train near Langworth, Lincolnshire	11/2016	30/06/2015	11/2016/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5795e482ed915d3cfd0001a1/11_2016_Langworth_Lincolnshire.pdf
Derailment of a freight train near Langworth, Lincolnshire	11/2016	30/06/2015	11/2016/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5795e482ed915d3cfd0001a1/11_2016_Langworth_Lincolnshire.pdf
Derailment of a freight train near Langworth, Lincolnshire	11/2016	30/06/2015	11/2016/04	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/5795e482ed915d3cfd0001a1/11_2016_Langworth_Lincolnshire.pdf
Freight train derailment at Angerstein Junction	10/2016	03/06/2015	10/2016/01	Closed - I	None	VTG	https://assets.publishing.service.gov.uk/media/5795d4da40f0b652dd000174/10_2016_Angerstein_Junction.pdf
Freight train derailment at Angerstein Junction	10/2016	03/06/2015	10/2016/02	Closed - I	None	VTG	https://assets.publishing.service.gov.uk/media/5795d4da40f0b652dd000174/10_2016_Angerstein_Junction.pdf
Freight train derailment at Angerstein Junction	10/2016	03/06/2015	10/2016/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5795d4da40f0b652dd000174/10_2016_Angerstein_Junction.pdf
Runaway and collision at Bryn station, Wigan	09/2016	27/11/2014	09/2016/01	Closed - I	None	Balfour Beatty	https://assets.publishing.service.gov.uk/media/5795d14bed915d622c00015e/09_2016_Bryn_station_Wigan.pdf

Runaway and collision at Bryn station, Wigan	09/2016	27/11/2014	09/2016/02	Closed - I	None	Balfour Beatty	https://assets.publishing.service.gov.uk/media/5795d14bed915d622c00015e/09_2016_Bryn_station_Wigan.pdf
Runaway and collision at Bryn station, Wigan	09/2016	27/11/2014	09/2016/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5795d14bed915d622c00015e/09_2016_Bryn_station_Wigan.pdf
Runaway and collision at Bryn station, Wigan	09/2016	27/11/2014	09/2016/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5795d14bed915d622c00015e/09_2016_Bryn_station_Wigan.pdf
Runaway and collision at Bryn station, Wigan	09/2016	27/11/2014	09/2016/05	Closed - I	None	Balfour Beatty	https://assets.publishing.service.gov.uk/media/5795d14bed915d622c00015e/09_2016_Bryn_station_Wigan.pdf
Signal passed at danger on approach to Wootton Bassett Junction, Wiltshire	08/2016	07/03/2015	08/2016/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5756d5d5ed915d1692000000/08_2016_Wootton_Bassett.pdf
Signal passed at danger on approach to Wootton Bassett Junction, Wiltshire	08/2016	07/03/2015	08/2016/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5756d5d5ed915d1692000000/08_2016_Wootton_Bassett.pdf
Signal passed at danger on approach to Wootton Bassett Junction, Wiltshire	08/2016	07/03/2015	08/2016/02	Closed - I	None	West Coast Railway Company	https://assets.publishing.service.gov.uk/media/5756d5d5ed915d1692000000/08_2016_Wootton_Bassett.pdf
Signal passed at danger on approach to Wootton Bassett Junction, Wiltshire	08/2016	07/03/2015	08/2016/03	Closed - I	None	West Coast Railway Company	https://assets.publishing.service.gov.uk/media/5756d5d5ed915d1692000000/08_2016_Wootton_Bassett.pdf
Signal passed at danger on approach to Wootton Bassett Junction, Wiltshire	08/2016	07/03/2015	08/2016/04	Closed - I	None	West Coast Railway Company	https://assets.publishing.service.gov.uk/media/5756d5d5ed915d1692000000/08_2016_Wootton_Bassett.pdf
Signal passed at danger on approach to Wootton Bassett Junction, Wiltshire	08/2016	07/03/2015	08/2016/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5756d5d5ed915d1692000000/08_2016_Wootton_Bassett.pdf
Collision between a train and a tractor at Oakwood Farm User Worked Crossing, Knaresborough	07/2016	14/05/2015	07/2016/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/572322cc40f0b61584000013/07_2016_Oakwood_Farm.pdf
Collision between a train and a tractor at Oakwood Farm User Worked Crossing, Knaresborough	07/2016	14/05/2015	07/2016/02	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/572322cc40f0b61584000013/07_2016_Oakwood_Farm.pdf
Collision between a train and a tractor at Oakwood Farm User Worked Crossing, Knaresborough	07/2016	14/05/2015	07/2016/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/572322cc40f0b61584000013/07_2016_Oakwood_Farm.pdf
Tram collision with pedestrian near Market Street tram stop, Manchester	06/2016	12/05/2015	06/2016/01	Closed - I	White	Metrolink RAPT Dev limited (MRDL)	https://assets.publishing.service.gov.uk/media/571636c8ed915d160400000f/06_2016_Market-Street.pdf
Tram collision with pedestrian near Market Street tram stop, Manchester	06/2016	12/05/2015	06/2016/02	Open	None	Metrolink RAPT Dev limited (MRDL)	https://assets.publishing.service.gov.uk/media/571636c8ed915d160400000f/06_2016_Market-Street.pdf
Tram collision with pedestrian near Market Street tram stop, Manchester	06/2016	12/05/2015	06/2016/02	Open	None	Transport for Greater Manchester	https://assets.publishing.service.gov.uk/media/571636c8ed915d160400000f/06_2016_Market-Street.pdf
Tram collision with pedestrian near Market Street tram stop, Manchester	06/2016	12/05/2015	06/2016/03	Closed - I	Blue	UK Tram	https://assets.publishing.service.gov.uk/media/571636c8ed915d160400000f/06_2016_Market-Street.pdf
Derailment at Godmersham, Kent	05/2016	26/07/2015	05/2016/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5716367fed915d160400000d/05_2016_Godmersham.pdf
Derailment at Godmersham, Kent	05/2016	26/07/2015	05/2016/02	Closed - IA	White	Network Rail	https://assets.publishing.service.gov.uk/media/5716367fed915d160400000d/05_2016_Godmersham.pdf

Derailment at Godmersham, Kent	05/2016	26/07/2015	05/2016/03	Closed - I	None	Govia Thameslink Railway	https://assets.publishing.service.gov.uk/media/5716367fed915d16040000/0d/05_2016_Godmersham.pdf
Derailment at Godmersham, Kent	05/2016	26/07/2015	05/2016/03	Closed - I	None	London & South Eastern Railway Ltd	https://assets.publishing.service.gov.uk/media/5716367fed915d16040000/0d/05_2016_Godmersham.pdf
Derailment at Godmersham, Kent	05/2016	26/07/2015	05/2016/03	Closed - I	None	South Western Railway	https://assets.publishing.service.gov.uk/media/5716367fed915d16040000/0d/05_2016_Godmersham.pdf
Derailment at Godmersham, Kent	05/2016	26/07/2015	05/2016/04	Open	None	RSSB	https://assets.publishing.service.gov.uk/media/5716367fed915d16040000/0d/05_2016_Godmersham.pdf
Derailment at Godmersham, Kent	05/2016	26/07/2015	05/2016/05	Closed - I	None	London & South Eastern Railway Ltd	https://assets.publishing.service.gov.uk/media/5716367fed915d16040000/0d/05_2016_Godmersham.pdf
Derailment at Godmersham, Kent	05/2016	26/07/2015	05/2016/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5716367fed915d16040000/0d/05_2016_Godmersham.pdf
Derailment at Godmersham, Kent	05/2016	26/07/2015	05/2016/05	Closed - I	None	Siemens AG	https://assets.publishing.service.gov.uk/media/5716367fed915d16040000/0d/05_2016_Godmersham.pdf
Passenger trapped in train doors and dragged at Clapham South station	04/2016	12/03/2015	04/2016/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56f13eebed915d117a0000/20/04_2016_Clapham_South.pdf
Passenger trapped and dragged under a train at West Wickham	03/2016	10/04/2015	03/2016/01	Open	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/56f13e5ced915d117a0000/1e/03_2016_West_Wickham.pdf
Passenger trapped and dragged under a train at West Wickham	03/2016	10/04/2015	03/2016/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56f13e5ced915d117a0000/1e/03_2016_West_Wickham.pdf
Collision between a train and a fallen bridge parapet at Froxfield, Wiltshire	02/2016	22/02/2015	02/2016/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56f13dbee5274a14d90000/12/02_2016_Froxfield.pdf
Collision between a train and a fallen bridge parapet at Froxfield, Wiltshire	02/2016	22/02/2015	02/2016/02	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/56f13dbee5274a14d90000/12/02_2016_Froxfield.pdf
Collision between a train and a fallen bridge parapet at Froxfield, Wiltshire	02/2016	22/02/2015	02/2016/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56f13dbee5274a14d90000/12/02_2016_Froxfield.pdf
Collision between a train and a fallen bridge parapet at Froxfield, Wiltshire	02/2016	22/02/2015	02/2016/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56f13dbee5274a14d90000/12/02_2016_Froxfield.pdf
Derailment at Washwood Heath West Junction, Birmingham	01/2016	23/03/2015	01/2016/01	Closed - I	None	VTG	https://assets.publishing.service.gov.uk/media/56f13d39ed915d117a0000/1c/01_2016_Washwood_Heath_West_Junction_Birmingham.pdf
Derailment at Washwood Heath West Junction, Birmingham	01/2016	23/03/2015	01/2016/02	Closed - I	None	VTG	https://assets.publishing.service.gov.uk/media/56f13d39ed915d117a0000/1c/01_2016_Washwood_Heath_West_Junction_Birmingham.pdf
Derailment at Washwood Heath West Junction, Birmingham	01/2016	23/03/2015	01/2016/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56f13d39ed915d117a0000/1c/01_2016_Washwood_Heath_West_Junction_Birmingham.pdf
Unsafe events at Heathrow Tunnel Junction	20/2015	28/12/2014	20/2015/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56f13be5ed915d117a0000/1a/20_2015_Heathrow.pdf
Unsafe events at Heathrow Tunnel Junction	20/2015	28/12/2014	20/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56f13be5ed915d117a0000/1a/20_2015_Heathrow.pdf

Unsafe events at Heathrow Tunnel Junction	20/2015	28/12/2014	20/2015/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56f13be5ed915d117a00001a/20_2015_Heathrow.pdf
Unsafe events at Heathrow Tunnel Junction	20/2015	28/12/2014	20/2015/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56f13be5ed915d117a00001a/20_2015_Heathrow.pdf
Electrical arcing and fire under a train near Windsor & Eton Riverside	18/2015	30/01/2015	18/2015/01	Closed - I	None	Wabtec Rail Limited	https://assets.publishing.service.gov.uk/media/56ab85ade5274a24e9000015/17_2015_Moston.pdf
Electrical arcing and fire under a train near Windsor & Eton Riverside	18/2015	30/01/2015	18/2015/02	Open	None	Alstom	https://assets.publishing.service.gov.uk/media/56ab85ade5274a24e9000015/17_2015_Moston.pdf
Electrical arcing and fire under a train near Windsor & Eton Riverside	18/2015	30/01/2015	18/2015/02	Open	None	South Western Railway	https://assets.publishing.service.gov.uk/media/56ab85ade5274a24e9000015/17_2015_Moston.pdf
Electrical arcing and fire under a train near Windsor & Eton Riverside	18/2015	30/01/2015	18/2015/02	Open	None	South West Trains	https://assets.publishing.service.gov.uk/media/56ab85ade5274a24e9000015/17_2015_Moston.pdf
Electrical arcing and fire under a train near Windsor & Eton Riverside	18/2015	30/01/2015	18/2015/03	Closed - I	None	South West Trains	https://assets.publishing.service.gov.uk/media/56ab85ade5274a24e9000015/17_2015_Moston.pdf
Electrical arcing and fire under a train near Windsor & Eton Riverside	18/2015	30/01/2015	18/2015/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56ab85ade5274a24e9000015/17_2015_Moston.pdf
Electrical arcing and fire under a train near Windsor & Eton Riverside	18/2015	30/01/2015	18/2015/04	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/56ab85ade5274a24e9000015/17_2015_Moston.pdf
Trains struck platform at Moston, Manchester	17/2015	28/01/2015	17/2015/01	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/56ab85ade5274a24e9000015/17_2015_Moston.pdf
Trains struck platform at Moston, Manchester	17/2015	28/01/2015	17/2015/02	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/56ab85ade5274a24e9000015/17_2015_Moston.pdf
Freight train derailment at Heworth, Tyne and Wear	16/2015	23/10/2014	16/2015/01	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/56a8d880ed915d6275000001/16_2015_Heworth_Tyne_and_Wear.pdf
Freight train derailment at Heworth, Tyne and Wear	16/2015	23/10/2014	16/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d880ed915d6275000001/16_2015_Heworth_Tyne_and_Wear.pdf
Freight train derailment at Heworth, Tyne and Wear	16/2015	23/10/2014	16/2015/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d880ed915d6275000001/16_2015_Heworth_Tyne_and_Wear.pdf
Freight train derailment at Heworth, Tyne and Wear	16/2015	23/10/2014	16/2015/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d880ed915d6275000001/16_2015_Heworth_Tyne_and_Wear.pdf
Freight train derailment at Heworth, Tyne and Wear	16/2015	23/10/2014	16/2015/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d880ed915d6275000001/16_2015_Heworth_Tyne_and_Wear.pdf
Collision between a train and a collapsed signal post at Newbury	15/2015	17/11/2014	15/2015/01	Insufficient Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d9b9ed915d6319000004/15_2015_Newbury.pdf
Collision between a train and a collapsed signal post at Newbury	15/2015	17/11/2014	15/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d9b9ed915d6319000004/15_2015_Newbury.pdf
Collision between a train and a collapsed signal post at Newbury	15/2015	17/11/2014	15/2015/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d9b9ed915d6319000004/15_2015_Newbury.pdf

Collision between a train and a collapsed signal post at Newbury	15/2015	17/11/2014	15/2015/04	Closed - I	None	Amey	https://assets.publishing.service.gov.uk/media/56a8d9b9ed915d63190000/04/15_2015_Newbury.pdf
Collision between a train and a collapsed signal post at Newbury	15/2015	17/11/2014	15/2015/05	Insufficient Response	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d9b9ed915d63190000/04/15_2015_Newbury.pdf
Class investigation into irregularities with protection arrangements during infrastructure engineering work	14/2015	17/12/2012	14/2015/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dc27e5274a24e90000/01/14_2015_Class_investigation_into_irregularities_with_protection_arrangements.pdf
Class investigation into irregularities with protection arrangements during infrastructure engineering work	14/2015	17/12/2012	14/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dc27e5274a24e90000/01/14_2015_Class_investigation_into_irregularities_with_protection_arrangements.pdf
Runaway of 'ironmen' trolleys and subsequent near miss at Raven level crossing, Garnant, Carmarthenshire	13/2015	01/11/2014	13/2015/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dd73e5274a24e90000/03/13_2015_Raven_level_crossing_Garnant_Carmarthenshire.pdf
Runaway of 'ironmen' trolleys and subsequent near miss at Raven level crossing, Garnant, Carmarthenshire	13/2015	01/11/2014	13/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dd73e5274a24e90000/03/13_2015_Raven_level_crossing_Garnant_Carmarthenshire.pdf
Runaway of 'ironmen' trolleys and subsequent near miss at Raven level crossing, Garnant, Carmarthenshire	13/2015	01/11/2014	13/2015/03	Open	None	Permaquip Limited	https://assets.publishing.service.gov.uk/media/56a8dd73e5274a24e90000/03/13_2015_Raven_level_crossing_Garnant_Carmarthenshire.pdf
Runaway of 'ironmen' trolleys and subsequent near miss at Raven level crossing, Garnant, Carmarthenshire	13/2015	01/11/2014	13/2015/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dd73e5274a24e90000/03/13_2015_Raven_level_crossing_Garnant_Carmarthenshire.pdf
Runaway of 'ironmen' trolleys and subsequent near miss at Raven level crossing, Garnant, Carmarthenshire	13/2015	01/11/2014	13/2015/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a8dd73e5274a24e90000/03/13_2015_Raven_level_crossing_Garnant_Carmarthenshire.pdf
Runaway of 'ironmen' trolleys and subsequent near miss at Raven level crossing, Garnant, Carmarthenshire	13/2015	01/11/2014	13/2015/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dd73e5274a24e90000/03/13_2015_Raven_level_crossing_Garnant_Carmarthenshire.pdf
Runaway of 'ironmen' trolleys and subsequent near miss at Raven level crossing, Garnant, Carmarthenshire	13/2015	01/11/2014	13/2015/06	Closed - I	None	Torrent Trackside Limited	https://assets.publishing.service.gov.uk/media/56a8dd73e5274a24e90000/03/13_2015_Raven_level_crossing_Garnant_Carmarthenshire.pdf
Train struck and damaged by equipment cabinet door in Watford Tunnel	12/2015	26/10/2014	12/2015/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8ddefed915d63190000/06/12_2015_Watford_Tunnel.pdf
Train struck and damaged by equipment cabinet door in Watford Tunnel	12/2015	26/10/2014	12/2015/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8ddefed915d63190000/06/12_2015_Watford_Tunnel.pdf
Train struck and damaged by equipment cabinet door in Watford Tunnel	12/2015	26/10/2014	12/2015/03	Closed - I	None	Siemens AG	https://assets.publishing.service.gov.uk/media/56a8ddefed915d63190000/06/12_2015_Watford_Tunnel.pdf
Train struck and damaged by equipment cabinet door in Watford Tunnel	12/2015	26/10/2014	12/2015/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8ddefed915d63190000/06/12_2015_Watford_Tunnel.pdf
Train struck and damaged by equipment cabinet door in Watford Tunnel	12/2015	26/10/2014	12/2015/05	Closed - I	None	Henry Williams Limited	https://assets.publishing.service.gov.uk/media/56a8ddefed915d63190000/06/12_2015_Watford_Tunnel.pdf
Train struck and damaged by equipment cabinet door in Watford Tunnel	12/2015	26/10/2014	12/2015/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8ddefed915d63190000/06/12_2015_Watford_Tunnel.pdf
Train struck and damaged by equipment cabinet door in Watford Tunnel	12/2015	26/10/2014	12/2015/06	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8ddefed915d63190000/06/12_2015_Watford_Tunnel.pdf
Freight train derailment at Angerstein Junction	11/2015	02/04/2014	11/2015/01	Closed - I	None	Aggregate Industries	https://assets.publishing.service.gov.uk/media/56a8e1ffed915d631900000/8/11_2015_Angerstein_Junction.pdf

Freight train derailment at Angerstein Junction	11/2015	02/04/2014	11/2015/02	Closed - I	None	Freight maintainers	https://assets.publishing.service.gov.uk/media/56a8e1ffed915d6319000008/11_2015_Angerstein_Junction.pdf
Freight train derailment at Angerstein Junction	11/2015	02/04/2014	11/2015/02	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/56a8e1ffed915d6319000008/11_2015_Angerstein_Junction.pdf
Freight train derailment at Angerstein Junction	11/2015	02/04/2014	11/2015/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a8e1ffed915d6319000008/11_2015_Angerstein_Junction.pdf
Freight train derailment at Angerstein Junction	11/2015	02/04/2014	11/2015/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e1ffed915d6319000008/11_2015_Angerstein_Junction.pdf
Freight train derailment at Angerstein Junction	11/2015	02/04/2014	11/2015/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e1ffed915d6319000008/11_2015_Angerstein_Junction.pdf
Freight train derailment at Angerstein Junction	11/2015	02/04/2014	11/2015/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a8e1ffed915d6319000008/11_2015_Angerstein_Junction.pdf
Freight train derailment at Angerstein Junction	11/2015	02/04/2014	11/2015/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e1ffed915d6319000008/11_2015_Angerstein_Junction.pdf
Freight train derailment at Angerstein Junction	11/2015	02/04/2014	11/2015/06	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a8e1ffed915d6319000008/11_2015_Angerstein_Junction.pdf
Derailment at Porthkerry, South Wales	10/2015	02/10/2014	10/2015/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e317ed915d631900000a/10_2015_Porthkerry_South_Wales.pdf
Derailment at Porthkerry, South Wales	10/2015	02/10/2014	10/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e317ed915d631900000a/10_2015_Porthkerry_South_Wales.pdf
Derailment at Porthkerry, South Wales	10/2015	02/10/2014	10/2015/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e317ed915d631900000a/10_2015_Porthkerry_South_Wales.pdf
Parting of the live overhead wire at Walkergate station, Tyne and Wear Metro	09/2015	11/08/2014	09/2015/01	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/56a8e440e5274a24e9000007/09_2015_Walkergate_station_Tyne_and_Wear.pdf
Parting of the live overhead wire at Walkergate station, Tyne and Wear Metro	09/2015	11/08/2014	09/2015/02	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/56a8e440e5274a24e9000007/09_2015_Walkergate_station_Tyne_and_Wear.pdf
Parting of the live overhead wire at Walkergate station, Tyne and Wear Metro	09/2015	11/08/2014	09/2015/02	Closed - I	None	Tyne & Wear Metro	https://assets.publishing.service.gov.uk/media/56a8e440e5274a24e9000007/09_2015_Walkergate_station_Tyne_and_Wear.pdf
Parting of the live overhead wire at Walkergate station, Tyne and Wear Metro	09/2015	11/08/2014	09/2015/03	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/56a8e440e5274a24e9000007/09_2015_Walkergate_station_Tyne_and_Wear.pdf
Parting of the live overhead wire at Walkergate station, Tyne and Wear Metro	09/2015	11/08/2014	09/2015/03	Closed - I	None	Tyne & Wear Metro	https://assets.publishing.service.gov.uk/media/56a8e440e5274a24e9000007/09_2015_Walkergate_station_Tyne_and_Wear.pdf
Near miss involving track workers near Hest Bank, Lancashire	08/2015	22/09/2014	08/2015/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e4eaed915d631900000c/08_2015_Hest_Bank_Lancashire.pdf
Near miss involving track workers near Hest Bank, Lancashire	08/2015	22/09/2014	08/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e4eaed915d631900000c/08_2015_Hest_Bank_Lancashire.pdf
Train driver receiving a severe electric shock at Sutton Weaver, Cheshire	07/2015	23/09/2014	07/2015/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e30340f0b61628000006/07_2015_Sutton_Weaver.pdf

Train driver receiving a severe electric shock at Sutton Weaver, Cheshire	07/2015	23/09/2014	07/2015/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a8e30340f0b616280000/06/07_2015_Sutton_Weaver.pdf
Accident to a track worker near Redhill	06/2015	24/06/2014	06/2015/01	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e19140f0b616140000/00/06_2015_Redhill.pdf
Accident to a track worker near Redhill	06/2015	24/06/2014	06/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e19140f0b616140000/00/06_2015_Redhill.pdf
Accident to a track worker near Redhill	06/2015	24/06/2014	06/2015/03	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56a8e19140f0b616140000/00/06_2015_Redhill.pdf
Fatal accident at Frampton level crossing	05/2015	11/05/2014	05/2015/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dfe1e5274a24e90000/05/05_2015_Frampton_level_crossing.pdf
Fatal accident at Frampton level crossing	05/2015	11/05/2014	05/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dfe1e5274a24e90000/05/05_2015_Frampton_level_crossing.pdf
Fatal accident at Frampton level crossing	05/2015	11/05/2014	05/2015/03	Closed - IA	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a8dfe1e5274a24e90000/05/05_2015_Frampton_level_crossing.pdf
Fatal accident at Frampton level crossing	05/2015	11/05/2014	05/2015/04	Open	None	Department for Transport	https://assets.publishing.service.gov.uk/media/56a8dfe1e5274a24e90000/05/05_2015_Frampton_level_crossing.pdf
Fatal accident at Frampton level crossing	05/2015	11/05/2014	05/2015/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dfe1e5274a24e90000/05/05_2015_Frampton_level_crossing.pdf
Fatal accident at Frampton level crossing	05/2015	11/05/2014	05/2015/06	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56a8dfe1e5274a24e90000/05/05_2015_Frampton_level_crossing.pdf
Runaway and subsequent collision near to Loughborough Central station, Great Central Railway	04/2015	12/05/2014	04/2015/01	Closed - I	None	Great Central Railway	https://assets.publishing.service.gov.uk/media/56a8de9a40f0b616280000/04/04_2015_Loughborough_Central_station.pdf
Runaway and subsequent collision near to Loughborough Central station, Great Central Railway	04/2015	12/05/2014	04/2015/02	Closed - I	Blue	Great Central Railway	https://assets.publishing.service.gov.uk/media/56a8de9a40f0b616280000/04/04_2015_Loughborough_Central_station.pdf
Runaway and subsequent collision near to Loughborough Central station, Great Central Railway	04/2015	12/05/2014	04/2015/03	Closed - I	None	Great Central Railway	https://assets.publishing.service.gov.uk/media/56a8de9a40f0b616280000/04/04_2015_Loughborough_Central_station.pdf
Runaway and subsequent collision near to Loughborough Central station, Great Central Railway	04/2015	12/05/2014	04/2015/04	Closed - I	None	Great Central Railway	https://assets.publishing.service.gov.uk/media/56a8de9a40f0b616280000/04/04_2015_Loughborough_Central_station.pdf
Derailment of an empty passenger train at Paddington station	03/2015	25/05/2014	03/2015/01	Closed - I	None	Siemens AG	https://assets.publishing.service.gov.uk/media/56a8da75ed915d62750000/03/03_2015_Paddington_station.pdf
Derailment of an empty passenger train at Paddington station	03/2015	25/05/2014	03/2015/02	Closed - I	None	Siemens AG	https://assets.publishing.service.gov.uk/media/56a8da75ed915d62750000/03/03_2015_Paddington_station.pdf
Derailment of an empty passenger train at Paddington station	03/2015	25/05/2014	03/2015/03	Closed - I	None	Siemens AG	https://assets.publishing.service.gov.uk/media/56a8da75ed915d62750000/03/03_2015_Paddington_station.pdf
Derailment of an empty passenger train at Paddington station	03/2015	25/05/2014	03/2015/04	Closed - I	None	Siemens AG	https://assets.publishing.service.gov.uk/media/56a8da75ed915d62750000/03/03_2015_Paddington_station.pdf
Derailment of an empty passenger train at Paddington station	03/2015	25/05/2014	03/2015/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8da75ed915d62750000/03/03_2015_Paddington_station.pdf

Derailment of a freight train at Stoke Lane Level Crossing, near Nottingham	02/2015	27/08/2013	02/2015/01	Closed - I	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/56a8d8ff40f0b6162800000/2/02_2015_Stoke_Lane.pdf
Derailment of a freight train at Stoke Lane Level Crossing, near Nottingham	02/2015	27/08/2013	02/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d8ff40f0b6162800000/2/02_2015_Stoke_Lane.pdf
Derailment of a freight train at Stoke Lane Level Crossing, near Nottingham	02/2015	27/08/2013	02/2015/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d8ff40f0b6162800000/2/02_2015_Stoke_Lane.pdf
Derailment of a freight train at Stoke Lane Level Crossing, near Nottingham	02/2015	27/08/2013	02/2015/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d8ff40f0b6162800000/2/02_2015_Stoke_Lane.pdf
Fatal accident involving a track worker near Newark North Gate station	01/2015	22/01/2014	01/2015/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d7aaed915d63190000/02/01_2015_Newark.pdf
Fatal accident involving a track worker near Newark North Gate station	01/2015	22/01/2014	01/2015/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a8d7aaed915d63190000/02/01_2015_Newark.pdf
Unauthorised entry of a train onto a single line at Greenford	29/2014	20/03/2014	29/2014/01	Closed - I	None	Chiltern Railways	https://assets.publishing.service.gov.uk/media/56a7916ced915d6cc90000/03/29_2014_Greenford.pdf
Unauthorised entry of a train onto a single line at Greenford	29/2014	20/03/2014	29/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a7916ced915d6cc90000/03/29_2014_Greenford.pdf
Unauthorised entry of a train onto a single line at Greenford	29/2014	20/03/2014	29/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a7916ced915d6cc90000/03/29_2014_Greenford.pdf
Collision between a train and a car at Jetty Avenue level crossing, Woodbridge, Suffolk	28/2014	14/07/2013	28/2014/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78d92ed915d6ccc0000/08/28_2014_Jetty_Avenue_level_crossing.pdf
Collision between a train and a car at Jetty Avenue level crossing, Woodbridge, Suffolk	28/2014	14/07/2013	28/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78d92ed915d6ccc0000/08/28_2014_Jetty_Avenue_level_crossing.pdf
Collision between a train and a car at Jetty Avenue level crossing, Woodbridge, Suffolk	28/2014	14/07/2013	28/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78d92ed915d6ccc0000/08/28_2014_Jetty_Avenue_level_crossing.pdf
Collision between a train and a car at Jetty Avenue level crossing, Woodbridge, Suffolk	28/2014	14/07/2013	28/2014/04	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78d92ed915d6ccc0000/08/28_2014_Jetty_Avenue_level_crossing.pdf
Collision between a train and a car at Jetty Avenue level crossing, Woodbridge, Suffolk	28/2014	14/07/2013	28/2014/05	Closed - IA	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a78d92ed915d6ccc0000/08/28_2014_Jetty_Avenue_level_crossing.pdf
Derailment at Liverpool Street station, London	27/2014	23/01/2013	27/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78c8ce5274a28480000/0b/27_2014_Liverpool_Street_station.pdf
Derailment at Liverpool Street station, London	27/2014	23/01/2013	27/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78c8ce5274a28480000/0b/27_2014_Liverpool_Street_station.pdf
Derailment at Liverpool Street station, London	27/2014	23/01/2013	27/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78c8ce5274a28480000/0b/27_2014_Liverpool_Street_station.pdf
Buffer stop collision at Chester station	26/2014	20/11/2013	26/2014/01	Closed - I	None	Operators of Class 220 and 221 units	https://assets.publishing.service.gov.uk/media/56a78bcde5274a28480000/09/26_2014_Chester_station.pdf
Buffer stop collision at Chester station	26/2014	20/11/2013	26/2014/02	Closed - I	None	Virgin Trains	https://assets.publishing.service.gov.uk/media/56a78bcde5274a28480000/09/26_2014_Chester_station.pdf

Buffer stop collision at Chester station	26/2014	20/11/2013	26/2014/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a78bcde5274a28480000/09/26_2014_Chester_station.pdf
Passenger train collision with trolley at Bridgeway User Worked Crossing, near Shrewsbury	25/2014	16/01/2014	25/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78acee5274a28480000/06/25_2014_Bridgeway_UWC_near_Shrewsbury.pdf
Passenger train collision with trolley at Bridgeway User Worked Crossing, near Shrewsbury	25/2014	16/01/2014	25/2014/02	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56a78acee5274a28480000/06/25_2014_Bridgeway_UWC_near_Shrewsbury.pdf
Passenger train collision with trolley at Bridgeway User Worked Crossing, near Shrewsbury	25/2014	16/01/2014	25/2014/03	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56a78acee5274a28480000/06/25_2014_Bridgeway_UWC_near_Shrewsbury.pdf
Class investigation into rail breaks on the East Coast Main Line	24/2014	14/09/2012	24/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e25dd6fe5274a6c3f52a50/3/24_2014_Class_investigation_into_rail_breaks_on_the_East_Coast_Main_Line.pdf
Class investigation into rail breaks on the East Coast Main Line	24/2014	14/09/2012	24/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e25dd6fe5274a6c3f52a50/3/24_2014_Class_investigation_into_rail_breaks_on_the_East_Coast_Main_Line.pdf
Class investigation into rail breaks on the East Coast Main Line	24/2014	14/09/2012	24/2014/03	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e25dd6fe5274a6c3f52a50/3/24_2014_Class_investigation_into_rail_breaks_on_the_East_Coast_Main_Line.pdf
Class investigation into rail breaks on the East Coast Main Line	24/2014	14/09/2012	24/2014/04	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e25dd6fe5274a6c3f52a50/3/24_2014_Class_investigation_into_rail_breaks_on_the_East_Coast_Main_Line.pdf
Class investigation into rail breaks on the East Coast Main Line	24/2014	14/09/2012	24/2014/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5e25dd6fe5274a6c3f52a50/3/24_2014_Class_investigation_into_rail_breaks_on_the_East_Coast_Main_Line.pdf
Dangerous occurrence at Denmark Hill station	23/2014	01/08/2013	23/2014/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a788da40f0b628110000/01/23_2014_Denmark_Hill_station.pdf
Passenger dragged a short distance by a train at Holborn station	22/2014	03/02/2014	22/2014/01	Closed - NI	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56a787a4e5274a28480000/01/22_2014_Holborn_station.pdf
Derailment at Primrose Hill / Camden Road West Junction	21/2014	15/10/2013	21/2014/01	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56a7870ced915d6ccc0000/03/21_2014_Primrose_Hill.pdf
Derailment at Primrose Hill / Camden Road West Junction	21/2014	15/10/2013	21/2014/02	Closed - I	Blue	Freightliner Group	https://assets.publishing.service.gov.uk/media/56a7870ced915d6ccc0000/03/21_2014_Primrose_Hill.pdf
Derailment at Primrose Hill / Camden Road West Junction	21/2014	15/10/2013	21/2014/02	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56a7870ced915d6ccc0000/03/21_2014_Primrose_Hill.pdf
Derailment at Primrose Hill / Camden Road West Junction	21/2014	15/10/2013	21/2014/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a7870ced915d6ccc0000/03/21_2014_Primrose_Hill.pdf
Freight train derailment near Gloucester	20/2014	15/10/2013	20/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78604ed915d6cc90000/00/20_2014_Gloucester.pdf
Freight train derailment near Gloucester	20/2014	15/10/2013	20/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78604ed915d6cc90000/00/20_2014_Gloucester.pdf
Freight train derailment near Gloucester	20/2014	15/10/2013	20/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78604ed915d6cc90000/00/20_2014_Gloucester.pdf
Freight train derailment near Gloucester	20/2014	15/10/2013	20/2014/04	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a78604ed915d6cc90000/00/20_2014_Gloucester.pdf

Freight train derailment near Gloucester	20/2014	15/10/2013	20/2014/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a78604ed915d6cc90000/00/20_2014_Gloucester.pdf
Freight train derailment near Gloucester	20/2014	15/10/2013	20/2014/06	Closed - I	None	Direct Rail Services	https://assets.publishing.service.gov.uk/media/56a78604ed915d6cc90000/00/20_2014_Gloucester.pdf
Freight train derailment near Gloucester	20/2014	15/10/2013	20/2014/07	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a78604ed915d6cc90000/00/20_2014_Gloucester.pdf
Passenger trapped in a train door and dragged a short distance at Newcastle Central station	19/2014	05/06/2013	19/2014/01	Closed - I	None	Operators of Siemens UK Desiro trains fitted with electrically operated	https://assets.publishing.service.gov.uk/media/56a7841bed915d6ccc0000/00/19_2014_Newcastle_Central_station.pdf
Passenger trapped in a train door and dragged a short distance at Newcastle Central station	19/2014	05/06/2013	19/2014/02	Closed - IA	None	Siemens AG	https://assets.publishing.service.gov.uk/media/56a7841bed915d6ccc0000/00/19_2014_Newcastle_Central_station.pdf
Passenger trapped in a train door and dragged a short distance at Newcastle Central station	19/2014	05/06/2013	19/2014/03	Closed - I	None	Siemens AG	https://assets.publishing.service.gov.uk/media/56a7841bed915d6ccc0000/00/19_2014_Newcastle_Central_station.pdf
Passenger trapped in a train door and dragged a short distance at Newcastle Central station	19/2014	05/06/2013	19/2014/04	Closed - I	None	First TransPennine Express (FTPE)	https://assets.publishing.service.gov.uk/media/56a7841bed915d6ccc0000/00/19_2014_Newcastle_Central_station.pdf
Passenger trapped in a train door and dragged a short distance at Newcastle Central station	19/2014	05/06/2013	19/2014/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a7841bed915d6ccc0000/00/19_2014_Newcastle_Central_station.pdf
Passenger trapped in a train door and dragged a short distance at Newcastle Central station	19/2014	05/06/2013	19/2014/06	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a7841bed915d6ccc0000/00/19_2014_Newcastle_Central_station.pdf
Accidents involving a wheelchair rolling onto the track at Southend Central and a pushchair rolling onto the track at Whyteleafe	17/2014	28/08/2013	17/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a7852140f0b628140000/00/17_2014_Southend_Central_and_Whyteleafe.pdf
Accidents involving a wheelchair rolling onto the track at Southend Central and a pushchair rolling onto the track at Whyteleafe	17/2014	28/08/2013	17/2014/02	Closed - I	None	Association of Train Operating Companies (ATOC)	https://assets.publishing.service.gov.uk/media/56a7852140f0b628140000/00/17_2014_Southend_Central_and_Whyteleafe.pdf
Accidents involving a wheelchair rolling onto the track at Southend Central and a pushchair rolling onto the track at Whyteleafe	17/2014	28/08/2013	17/2014/02	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/56a7852140f0b628140000/00/17_2014_Southend_Central_and_Whyteleafe.pdf
Accidents involving a wheelchair rolling onto the track at Southend Central and a pushchair rolling onto the track at Whyteleafe	17/2014	28/08/2013	17/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a7852140f0b628140000/00/17_2014_Southend_Central_and_Whyteleafe.pdf
Accidents involving a wheelchair rolling onto the track at Southend Central and a pushchair rolling onto the track at Whyteleafe	17/2014	28/08/2013	17/2014/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a7852140f0b628140000/00/17_2014_Southend_Central_and_Whyteleafe.pdf
Accidents involving a wheelchair rolling onto the track at Southend Central and a pushchair rolling onto the track at Whyteleafe	17/2014	28/08/2013	17/2014/03	Closed - I	None	Association of Train Operating Companies (ATOC)	https://assets.publishing.service.gov.uk/media/56a7852140f0b628140000/00/17_2014_Southend_Central_and_Whyteleafe.pdf
Accidents involving a wheelchair rolling onto the track at Southend Central and a pushchair rolling onto the track at Whyteleafe	17/2014	28/08/2013	17/2014/04	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a7852140f0b628140000/00/17_2014_Southend_Central_and_Whyteleafe.pdf
Accidents involving a wheelchair rolling onto the track at Southend Central and a pushchair rolling onto the track at Whyteleafe	17/2014	28/08/2013	17/2014/04	Closed - IA	None	RSSB	https://assets.publishing.service.gov.uk/media/56a7852140f0b628140000/00/17_2014_Southend_Central_and_Whyteleafe.pdf
Uncontrolled evacuation of a London Underground train at Holland Park station	16/2014	25/08/2013	16/2014/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56a8e674ed915d62750000/05/16_2014_Holland_Park.pdf
Uncontrolled evacuation of a London Underground train at Holland Park station	16/2014	25/08/2013	16/2014/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56a8e674ed915d62750000/05/16_2014_Holland_Park.pdf

Uncontrolled evacuation of a London Underground train at Holland Park station	16/2014	25/08/2013	16/2014/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56a8e674ed915d62750000/05/16_2014_Holland_Park.pdf
Uncontrolled evacuation of a London Underground train at Holland Park station	16/2014	25/08/2013	16/2014/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56a8e674ed915d62750000/05/16_2014_Holland_Park.pdf
Uncontrolled evacuation of a London Underground train at Holland Park station	16/2014	25/08/2013	16/2014/05	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56a8e674ed915d62750000/05/16_2014_Holland_Park.pdf
Uncontrolled evacuation of a London Underground train at Holland Park station	16/2014	25/08/2013	16/2014/06	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56a8e674ed915d62750000/05/16_2014_Holland_Park.pdf
Runaway of a road rail vehicle and the resulting collision in Queen Street High Level Tunnel, Glasgow	15/2014	21/04/2013	15/2014/01	Closed - IA	None	Rexquote Ltd	https://assets.publishing.service.gov.uk/media/56a77b34ed915d14350000/07/15_2014_Queen_Street_Tunnel_Glasgow.pdf
Runaway of a road rail vehicle and the resulting collision in Queen Street High Level Tunnel, Glasgow	15/2014	21/04/2013	15/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a77b34ed915d14350000/07/15_2014_Queen_Street_Tunnel_Glasgow.pdf
Runaway of a road rail vehicle and the resulting collision in Queen Street High Level Tunnel, Glasgow	15/2014	21/04/2013	15/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a77b34ed915d14350000/07/15_2014_Queen_Street_Tunnel_Glasgow.pdf
Runaway of a road rail vehicle and the resulting collision in Queen Street High Level Tunnel, Glasgow	15/2014	21/04/2013	15/2014/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a77b34ed915d14350000/07/15_2014_Queen_Street_Tunnel_Glasgow.pdf
Runaway of a road rail vehicle and the resulting collision in Queen Street High Level Tunnel, Glasgow	15/2014	21/04/2013	15/2014/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a77b34ed915d14350000/07/15_2014_Queen_Street_Tunnel_Glasgow.pdf
Road vehicle incursion onto the railway at Aspatria, Cumbria	14/2014	26/10/2013	14/2014/01	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/56a77a7ded915d14350000/05/14_2014_Aspatria_Cumbria.pdf
Road vehicle incursion onto the railway at Aspatria, Cumbria	14/2014	26/10/2013	14/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a77a7ded915d14350000/05/14_2014_Aspatria_Cumbria.pdf
Road vehicle incursion onto the railway at Aspatria, Cumbria	14/2014	26/10/2013	14/2014/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a77a7ded915d14350000/05/14_2014_Aspatria_Cumbria.pdf
Near-miss at Butterswood level crossing, North Lincolnshire	12/2014	25/06/2013	12/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a76f17ed915d14350000/00/12_2014_Butterswood_North_Lincolnshire.pdf
Near-miss at Butterswood level crossing, North Lincolnshire	12/2014	25/06/2013	12/2014/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a76f17ed915d14350000/00/12_2014_Butterswood_North_Lincolnshire.pdf
Near-miss at Butterswood level crossing, North Lincolnshire	12/2014	25/06/2013	12/2014/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a76f17ed915d14350000/00/12_2014_Butterswood_North_Lincolnshire.pdf
Near-miss at Butterswood level crossing, North Lincolnshire	12/2014	25/06/2013	12/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a76f17ed915d14350000/00/12_2014_Butterswood_North_Lincolnshire.pdf
Near-miss at Butterswood level crossing, North Lincolnshire	12/2014	25/06/2013	12/2014/04	Closed - I	None	First TransPennine Express (FTPE)	https://assets.publishing.service.gov.uk/media/56a76f17ed915d14350000/00/12_2014_Butterswood_North_Lincolnshire.pdf
Locomotive failure near Winchfield	13/2014	23/11/2013	13/2014/01	Closed - IA	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/56a774e0ed915d14350000/03/13_2014_Winchfield.pdf
Locomotive failure near Winchfield	13/2014	23/11/2013	13/2014/01	Closed - IA	None	West Coast Railway Company	https://assets.publishing.service.gov.uk/media/56a774e0ed915d14350000/03/13_2014_Winchfield.pdf

Locomotive failure near Winchfield	13/2014	23/11/2013	13/2014/02	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/56a774e0ed915d14350000/03/13_2014_Winchfield.pdf
Locomotive failure near Winchfield	13/2014	23/11/2013	13/2014/02	Closed - I	None	Main Line Steam Locomotive Operators Association	https://assets.publishing.service.gov.uk/media/56a774e0ed915d14350000/03/13_2014_Winchfield.pdf
Locomotive failure near Winchfield	13/2014	23/11/2013	13/2014/03	Closed - I	None	West Coast Railway Company	https://assets.publishing.service.gov.uk/media/56a774e0ed915d14350000/03/13_2014_Winchfield.pdf
Locomotive failure near Winchfield	13/2014	23/11/2013	13/2014/04	Closed - IA	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/56a774e0ed915d14350000/03/13_2014_Winchfield.pdf
Locomotive failure near Winchfield	13/2014	23/11/2013	13/2014/04	Closed - IA	None	Main Line Steam Locomotive Operators Association	https://assets.publishing.service.gov.uk/media/56a774e0ed915d14350000/03/13_2014_Winchfield.pdf
Near-miss at Llandovery level crossing, Carmarthenshire	11/2014	06/06/2013	11/2014/01	Closed - I	None	Arriva Trains Wales	https://assets.publishing.service.gov.uk/media/56a76dd940f0b613ee0000/0e/11_2014_Llandovery_level_crossing.pdf
Near-miss at Llandovery level crossing, Carmarthenshire	11/2014	06/06/2013	11/2014/02	Closed - I	None	Arriva Trains Wales	https://assets.publishing.service.gov.uk/media/56a76dd940f0b613ee0000/0e/11_2014_Llandovery_level_crossing.pdf
Near-miss at Llandovery level crossing, Carmarthenshire	11/2014	06/06/2013	11/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a76dd940f0b613ee0000/0e/11_2014_Llandovery_level_crossing.pdf
Near-miss at Llandovery level crossing, Carmarthenshire	11/2014	06/06/2013	11/2014/04	Closed - I	None	Arriva Trains Wales	https://assets.publishing.service.gov.uk/media/56a76dd940f0b613ee0000/0e/11_2014_Llandovery_level_crossing.pdf
Near-miss at Llandovery level crossing, Carmarthenshire	11/2014	06/06/2013	11/2014/05	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a76dd940f0b613ee0000/0e/11_2014_Llandovery_level_crossing.pdf
Near-miss at Llandovery level crossing, Carmarthenshire	11/2014	06/06/2013	11/2014/06	Closed - I	None	Arriva Trains Wales	https://assets.publishing.service.gov.uk/media/56a76dd940f0b613ee0000/0e/11_2014_Llandovery_level_crossing.pdf
Accident at Balnamore level crossing, Ballymoney, Northern Ireland	10/2014	31/05/2013	10/2014/01	Closed - I	White	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a63e9f40f0b613f400000/5/10_2014_Balnamore_Ballymoney_NI.pdf
Accident at Balnamore level crossing, Ballymoney, Northern Ireland	10/2014	31/05/2013	10/2014/02	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a63e9f40f0b613f400000/5/10_2014_Balnamore_Ballymoney_NI.pdf
Accident at Balnamore level crossing, Ballymoney, Northern Ireland	10/2014	31/05/2013	10/2014/03	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a63e9f40f0b613f400000/5/10_2014_Balnamore_Ballymoney_NI.pdf
Passenger train collision at Norwich	09/2014	21/07/2013	09/2014/01	Closed - I	None	Greater Anglia	https://assets.publishing.service.gov.uk/media/56a63d45e5274a13ca0000/07/09_2014_Norwich.pdf
Passenger train collision at Norwich	09/2014	21/07/2013	09/2014/02	Closed - I	None	Greater Anglia	https://assets.publishing.service.gov.uk/media/56a63d45e5274a13ca0000/07/09_2014_Norwich.pdf
Passenger train collision at Norwich	09/2014	21/07/2013	09/2014/03	Closed - I	Blue	Greater Anglia	https://assets.publishing.service.gov.uk/media/56a63d45e5274a13ca0000/07/09_2014_Norwich.pdf
Passenger train collision at Norwich	09/2014	21/07/2013	09/2014/04	Closed - I	None	Greater Anglia	https://assets.publishing.service.gov.uk/media/56a63d45e5274a13ca0000/07/09_2014_Norwich.pdf
Passenger train collision at Norwich	09/2014	21/07/2013	09/2014/05	Open	None	Greater Anglia	https://assets.publishing.service.gov.uk/media/56a63d45e5274a13ca0000/07/09_2014_Norwich.pdf

Passenger train collision at Norwich	09/2014	21/07/2013	09/2014/05	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a63d45e5274a13ca0000/07/09_2014_Norwich.pdf
Class investigation into landslips affecting Network Rail infrastructure	08/2014	28/06/2012	08/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62f1140f0b613ee00000/3/08_2014_Class_Investigation_into_Landslips.pdf
Class investigation into landslips affecting Network Rail infrastructure	08/2014	28/06/2012	08/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62f1140f0b613ee00000/3/08_2014_Class_Investigation_into_Landslips.pdf
Class investigation into landslips affecting Network Rail infrastructure	08/2014	28/06/2012	08/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62f1140f0b613ee00000/3/08_2014_Class_Investigation_into_Landslips.pdf
Class investigation into landslips affecting Network Rail infrastructure	08/2014	28/06/2012	08/2014/04	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62f1140f0b613ee00000/3/08_2014_Class_Investigation_into_Landslips.pdf
Class investigation into landslips affecting Network Rail infrastructure	08/2014	28/06/2012	08/2014/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62f1140f0b613ee00000/3/08_2014_Class_Investigation_into_Landslips.pdf
Locomotive derailment at Ordsall Lane Junction, Salford	07/2014	23/01/2013	07/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62db240f0b613f400000/2/07_2014_Ordsall_Lane_Junction_Salford.pdf
Locomotive derailment at Ordsall Lane Junction, Salford	07/2014	23/01/2013	07/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62db240f0b613f400000/2/07_2014_Ordsall_Lane_Junction_Salford.pdf
Locomotive derailment at Ordsall Lane Junction, Salford	07/2014	23/01/2013	07/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62db240f0b613f400000/2/07_2014_Ordsall_Lane_Junction_Salford.pdf
Collision at Buttington Hall user worked crossing, Welshpool	06/2014	16/07/2013	06/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62c46ed915d6d2a0000/1b/06_2014_Buttington_Hall.pdf
Collision at Buttington Hall user worked crossing, Welshpool	06/2014	16/07/2013	06/2014/01	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a62c46ed915d6d2a0000/1b/06_2014_Buttington_Hall.pdf
Collision at Buttington Hall user worked crossing, Welshpool	06/2014	16/07/2013	06/2014/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a62c46ed915d6d2a0000/1b/06_2014_Buttington_Hall.pdf
Collision at Buttington Hall user worked crossing, Welshpool	06/2014	16/07/2013	06/2014/02	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a62c46ed915d6d2a0000/1b/06_2014_Buttington_Hall.pdf
Collision at Buttington Hall user worked crossing, Welshpool	06/2014	16/07/2013	06/2014/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a62c46ed915d6d2a0000/1b/06_2014_Buttington_Hall.pdf
Tram running with doors open on London Tramlink, Croydon	05/2014	13/04/2013	05/2014/01	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/56a62b12e5274a13d10000/01/05_2014_London_Tramlink_Croydon.pdf
Tram running with doors open on London Tramlink, Croydon	05/2014	13/04/2013	05/2014/02	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/56a62b12e5274a13d10000/01/05_2014_London_Tramlink_Croydon.pdf
Tram running with doors open on London Tramlink, Croydon	05/2014	13/04/2013	05/2014/03	Closed - IA	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/56a62b12e5274a13d10000/01/05_2014_London_Tramlink_Croydon.pdf
Tram running with doors open on London Tramlink, Croydon	05/2014	13/04/2013	05/2014/03	Closed - IA	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/56a62b12e5274a13d10000/01/05_2014_London_Tramlink_Croydon.pdf
Tram running with doors open on London Tramlink, Croydon	05/2014	13/04/2013	05/2014/04	Closed - I	None	UK Tram Operators	https://assets.publishing.service.gov.uk/media/56a62b12e5274a13d10000/01/05_2014_London_Tramlink_Croydon.pdf

Tram running with doors open on London Tramlink, Croydon	05/2014	13/04/2013	05/2014/05	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a62b12e5274a13d10000/01/05_2014_London_Tramlink_Croydon.pdf
Tram running with doors open on London Tramlink, Croydon	05/2014	13/04/2013	05/2014/06	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/56a62b12e5274a13d10000/01/05_2014_London_Tramlink_Croydon.pdf
Tram running with doors open on London Tramlink, Croydon	05/2014	13/04/2013	05/2014/07	Closed - I	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/56a62b12e5274a13d10000/01/05_2014_London_Tramlink_Croydon.pdf
Tram running with doors open on London Tramlink, Croydon	05/2014	13/04/2013	05/2014/08	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/56a62b12e5274a13d10000/01/05_2014_London_Tramlink_Croydon.pdf
Fatal accident at Athelney level crossing, near Taunton, Somerset	04/2014	21/03/2013	04/2014/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a6298840f0b613ee0000/00/04_2014_Athelney_near_Taunton.pdf
Fatal accident at Athelney level crossing, near Taunton, Somerset	04/2014	21/03/2013	04/2014/02	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56a6298840f0b613ee0000/00/04_2014_Athelney_near_Taunton.pdf
Fatal accident at Athelney level crossing, near Taunton, Somerset	04/2014	21/03/2013	04/2014/02	Closed - I	Blue	RSSB	https://assets.publishing.service.gov.uk/media/56a6298840f0b613ee0000/00/04_2014_Athelney_near_Taunton.pdf
Fatal accident at Athelney level crossing, near Taunton, Somerset	04/2014	21/03/2013	04/2014/03	Closed - NI	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a6298840f0b613ee0000/00/04_2014_Athelney_near_Taunton.pdf
Fatal accident at Athelney level crossing, near Taunton, Somerset	04/2014	21/03/2013	04/2014/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a6298840f0b613ee0000/00/04_2014_Athelney_near_Taunton.pdf
Penetration and obstruction of a tunnel between Old Street and Essex Road stations, London	03/2014	08/03/2013	03/2014/01	Closed - I	None	Railway Infrastructure Managers	https://assets.publishing.service.gov.uk/media/56a623b2ed915d6d2a0000/18/03_2014_Old_Street_and_Essex_Road_stations.pdf
Penetration and obstruction of a tunnel between Old Street and Essex Road stations, London	03/2014	08/03/2013	03/2014/02	Closed - I	None	Railway Infrastructure Managers	https://assets.publishing.service.gov.uk/media/56a623b2ed915d6d2a0000/18/03_2014_Old_Street_and_Essex_Road_stations.pdf
Penetration and obstruction of a tunnel between Old Street and Essex Road stations, London	03/2014	08/03/2013	03/2014/03	Closed - I	None	Railway Infrastructure Managers	https://assets.publishing.service.gov.uk/media/56a623b2ed915d6d2a0000/18/03_2014_Old_Street_and_Essex_Road_stations.pdf
Penetration and obstruction of a tunnel between Old Street and Essex Road stations, London	03/2014	08/03/2013	03/2014/04	Closed - I	None	The British Standards Institution	https://assets.publishing.service.gov.uk/media/56a623b2ed915d6d2a0000/18/03_2014_Old_Street_and_Essex_Road_stations.pdf
Penetration and obstruction of a tunnel between Old Street and Essex Road stations, London	03/2014	08/03/2013	03/2014/05	Closed - I	None	Department for Communities and Local Government	https://assets.publishing.service.gov.uk/media/56a623b2ed915d6d2a0000/18/03_2014_Old_Street_and_Essex_Road_stations.pdf
Derailment at Castle Donington, Leicestershire	02/2014	21/01/2013	02/2014/01	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56a6221a40f0b613f400000/0/02_2014_Castle_Donington.pdf
Derailment at Castle Donington, Leicestershire	02/2014	21/01/2013	02/2014/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a6221a40f0b613f400000/0/02_2014_Castle_Donington.pdf
Fatal accident at Motts Lane level crossing, Witham, Essex	01/2014	24/01/2013	01/2014/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a620b5ed915d6d2a0000/14/01_2014_Motts_Lane_Witham_Essex.pdf
Fatal accident at Motts Lane level crossing, Witham, Essex	01/2014	24/01/2013	01/2014/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a620b5ed915d6d2a0000/14/01_2014_Motts_Lane_Witham_Essex.pdf
Fatal accident at Motts Lane level crossing, Witham, Essex	01/2014	24/01/2013	01/2014/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a620b5ed915d6d2a0000/14/01_2014_Motts_Lane_Witham_Essex.pdf

Fatal accident at Motts Lane level crossing, Witham, Essex	01/2014	24/01/2013	01/2014/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a620b5ed915d6d2a000014/01_2014_Motts_Lane_Witham_Essex.pdf
Derailment of a freight train at Barrow upon Soar, Leicestershire	22/2013	27/12/2012	22/2013/01	Closed - IA	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56a242b640f0b613a4000009/22_2013_Barrow_upon_Soar.pdf
Derailment of a freight train at Barrow upon Soar, Leicestershire	22/2013	27/12/2012	22/2013/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a242b640f0b613a4000009/22_2013_Barrow_upon_Soar.pdf
Derailment of a freight train at Barrow upon Soar, Leicestershire	22/2013	27/12/2012	22/2013/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a242b640f0b613a4000009/22_2013_Barrow_upon_Soar.pdf
Fatal accident involving a track worker at Saxilby	21/2013	04/12/2012	21/2013/01	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56a240c740f0b613a700000b/21_2013_Saxilby.pdf
Fatal accident involving a track worker at Saxilby	21/2013	04/12/2012	21/2013/02	Superseded	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a240c740f0b613a700000b/21_2013_Saxilby.pdf
Fatal accident involving a track worker at Saxilby	21/2013	04/12/2012	21/2013/03	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/56a240c740f0b613a700000b/21_2013_Saxilby.pdf
Fatal accident involving a track worker at Saxilby	21/2013	04/12/2012	21/2013/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a240c740f0b613a700000b/21_2013_Saxilby.pdf
Track worker struck by a train at Bulwell, Nottingham	20/2013	06/08/2012	20/2013/01	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56a23f92ed915d6d2700000a/20_2013_Bulwell.pdf
Track worker struck by a train at Bulwell, Nottingham	20/2013	06/08/2012	20/2013/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a23f92ed915d6d2700000a/20_2013_Bulwell.pdf
Track worker struck by a train at Bulwell, Nottingham	20/2013	06/08/2012	20/2013/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a23f92ed915d6d2700000a/20_2013_Bulwell.pdf
Track worker struck by a train at Bulwell, Nottingham	20/2013	06/08/2012	20/2013/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a23f92ed915d6d2700000a/20_2013_Bulwell.pdf
Track worker struck by a train at Bulwell, Nottingham	20/2013	06/08/2012	20/2013/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a23f92ed915d6d2700000a/20_2013_Bulwell.pdf
Track worker struck by a train at Bulwell, Nottingham	20/2013	06/08/2012	20/2013/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a23f92ed915d6d2700000a/20_2013_Bulwell.pdf
Fatal accident at Bayles and Wylies footpath crossing, Bestwood, Nottingham	19/2013	28/11/2012	19/2013/01	Closed - IA	None	UK Tram Operators	https://assets.publishing.service.gov.uk/media/56a23bd540f0b613a7000008/19_2013_Bayles_and_Wylies.pdf
Fatal accident at Bayles and Wylies footpath crossing, Bestwood, Nottingham	19/2013	28/11/2012	19/2013/02	Closed - I	White	UK Tram Operators	https://assets.publishing.service.gov.uk/media/56a23bd540f0b613a7000008/19_2013_Bayles_and_Wylies.pdf
Fatal accident at Bayles and Wylies footpath crossing, Bestwood, Nottingham	19/2013	28/11/2012	19/2013/03	Closed - I	Blue	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a23bd540f0b613a7000008/19_2013_Bayles_and_Wylies.pdf
Fatal accident at Bayles and Wylies footpath crossing, Bestwood, Nottingham	19/2013	28/11/2012	19/2013/03	Closed - I	Blue	UK Tram Industry	https://assets.publishing.service.gov.uk/media/56a23bd540f0b613a7000008/19_2013_Bayles_and_Wylies.pdf
Fatal accident at Bayles and Wylies footpath crossing, Bestwood, Nottingham	19/2013	28/11/2012	19/2013/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a23bd540f0b613a7000008/19_2013_Bayles_and_Wylies.pdf

Fatal accident at Bayles and Wylies footpath crossing, Bestwood, Nottingham	19/2013	28/11/2012	19/2013/04	Closed - I	None	UK Tram Operators	https://assets.publishing.service.gov.uk/media/56a23bd540f0b613a7000008/19_2013_Bayles_and_Wylies.pdf
Train fire at South Gosforth	18/2013	08/01/2013	18/2013/01	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/56a23948ed915d6d2a000008/18_2013_South_Gosforth.pdf
Train fire at South Gosforth	18/2013	08/01/2013	18/2013/02	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/56a23948ed915d6d2a000008/18_2013_South_Gosforth.pdf
Train fire at South Gosforth	18/2013	08/01/2013	18/2013/02	Closed - I	None	Tyne & Wear Metro	https://assets.publishing.service.gov.uk/media/56a23948ed915d6d2a000008/18_2013_South_Gosforth.pdf
Train fire at South Gosforth	18/2013	08/01/2013	18/2013/03	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/56a23948ed915d6d2a000008/18_2013_South_Gosforth.pdf
Collision between a train and a car at Beech Hill level crossing, near Finningley	17/2013	04/12/2012	17/2013/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a236afe5274a6212000003/16_2013_Stafford.pdf
Collision between a train and a car at Beech Hill level crossing, near Finningley	17/2013	04/12/2012	17/2013/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a236afe5274a6212000003/16_2013_Stafford.pdf
Collision between a train and a car at Beech Hill level crossing, near Finningley	17/2013	04/12/2012	17/2013/03	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56a236afe5274a6212000003/16_2013_Stafford.pdf
Collision between a train and a car at Beech Hill level crossing, near Finningley	17/2013	04/12/2012	17/2013/04	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56a236afe5274a6212000003/16_2013_Stafford.pdf
Signal passed at danger at Stafford	16/2013	26/04/2012	16/2013/01	Closed - I	None	Devon & Cornwall Railways	https://assets.publishing.service.gov.uk/media/56a236afe5274a6212000003/16_2013_Stafford.pdf
Signal passed at danger at Stafford	16/2013	26/04/2012	16/2013/02	Closed - I	None	Devon & Cornwall Railways	https://assets.publishing.service.gov.uk/media/56a236afe5274a6212000003/16_2013_Stafford.pdf
Signal passed at danger at Stafford	16/2013	26/04/2012	16/2013/03	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a236afe5274a6212000003/16_2013_Stafford.pdf
Signal passed at danger at Stafford	16/2013	26/04/2012	16/2013/04	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a236afe5274a6212000003/16_2013_Stafford.pdf
Signal passed at danger at Stafford	16/2013	26/04/2012	16/2013/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a236afe5274a6212000003/16_2013_Stafford.pdf
Dangerous occurrence involving an engineering train at Blatchbridge Junction, near Frome	15/2013	19/03/2012	15/2013/01	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a234bfd915d6d2a000004/15_2013_Blatchbridge_Junction.pdf
Dangerous occurrence involving an engineering train at Blatchbridge Junction, near Frome	15/2013	19/03/2012	15/2013/02	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a234bfd915d6d2a000004/15_2013_Blatchbridge_Junction.pdf
Dangerous occurrence involving an engineering train at Blatchbridge Junction, near Frome	15/2013	19/03/2012	15/2013/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a234bfd915d6d2a000004/15_2013_Blatchbridge_Junction.pdf
Dangerous occurrence involving an engineering train at Blatchbridge Junction, near Frome	15/2013	19/03/2012	15/2013/04	Open	None	Matisa (UK) Ltd	https://assets.publishing.service.gov.uk/media/56a234bfd915d6d2a000004/15_2013_Blatchbridge_Junction.pdf
Dangerous occurrence involving an engineering train at Blatchbridge Junction, near Frome	15/2013	19/03/2012	15/2013/05	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a234bfd915d6d2a000004/15_2013_Blatchbridge_Junction.pdf

Dangerous occurrence involving an engineering train at Blatchbridge Junction, near Frome	15/2013	19/03/2012	15/2013/06	Open	None	Matisa (UK) Ltd	https://assets.publishing.service.gov.uk/media/56a234bfed915d6d2a000004/15_2013_Blatchbridge_Junction.pdf
Dangerous occurrence involving an engineering train at Blatchbridge Junction, near Frome	15/2013	19/03/2012	15/2013/07	Closed - I	None	Matisa (UK) Ltd	https://assets.publishing.service.gov.uk/media/56a234bfed915d6d2a000004/15_2013_Blatchbridge_Junction.pdf
Train ran onto a washed-out embankment near Knockmore, Northern Ireland	14/2013	28/06/2012	14/2013/01	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a22eaf40f0b613a4000005/14_2013_Knockmore_Northern_Ireland.pdf
Train ran onto a washed-out embankment near Knockmore, Northern Ireland	14/2013	28/06/2012	14/2013/02	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a22eaf40f0b613a4000005/14_2013_Knockmore_Northern_Ireland.pdf
Train ran onto a washed-out embankment near Knockmore, Northern Ireland	14/2013	28/06/2012	14/2013/03	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a22eaf40f0b613a4000005/14_2013_Knockmore_Northern_Ireland.pdf
Train ran onto a washed-out embankment near Knockmore, Northern Ireland	14/2013	28/06/2012	14/2013/04	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a22eaf40f0b613a4000005/14_2013_Knockmore_Northern_Ireland.pdf
Train ran onto a washed-out embankment near Knockmore, Northern Ireland	14/2013	28/06/2012	14/2013/05	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56a22eaf40f0b613a4000005/14_2013_Knockmore_Northern_Ireland.pdf
Partial failure of a structure inside Balcombe Tunnel, West Sussex	13/2013	23/09/2011	13/2013/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22d52ed915d6d27000002/13_2013_Balcombe.pdf
Partial failure of a structure inside Balcombe Tunnel, West Sussex	13/2013	23/09/2011	13/2013/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22d52ed915d6d27000002/13_2013_Balcombe.pdf
Partial failure of a structure inside Balcombe Tunnel, West Sussex	13/2013	23/09/2011	13/2013/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22d52ed915d6d27000002/13_2013_Balcombe.pdf
Partial failure of a structure inside Balcombe Tunnel, West Sussex	13/2013	23/09/2011	13/2013/04	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56a22d52ed915d6d27000002/13_2013_Balcombe.pdf
Partial failure of a structure inside Balcombe Tunnel, West Sussex	13/2013	23/09/2011	13/2013/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22d52ed915d6d27000002/13_2013_Balcombe.pdf
Partial failure of a structure inside Balcombe Tunnel, West Sussex	13/2013	23/09/2011	13/2013/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22d52ed915d6d27000002/13_2013_Balcombe.pdf
Partial failure of a structure inside Balcombe Tunnel, West Sussex	13/2013	23/09/2011	13/2013/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22d52ed915d6d27000002/13_2013_Balcombe.pdf
Partial failure of a structure inside Balcombe Tunnel, West Sussex	13/2013	23/09/2011	13/2013/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22d52ed915d6d27000002/13_2013_Balcombe.pdf
Partial failure of a structure inside Balcombe Tunnel, West Sussex	13/2013	23/09/2011	13/2013/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22d52ed915d6d27000002/13_2013_Balcombe.pdf
Collision between a stoneblower and ballast regulator near Arley, Warwickshire	12/2013	10/08/2012	12/2013/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22bd640f0b613a4000003/12_2013_Arley.pdf
Collision between a stoneblower and ballast regulator near Arley, Warwickshire	12/2013	10/08/2012	12/2013/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22bd640f0b613a4000003/12_2013_Arley.pdf
Collision between a stoneblower and ballast regulator near Arley, Warwickshire	12/2013	10/08/2012	12/2013/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a22bd640f0b613a4000003/12_2013_Arley.pdf

Dangerous occurrence at Lindridge Farm user worked crossing, near Bagworth, Leicestershire	11/2013	22/03/2012	11/2013/01	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56a228e740f0b613a7000003/11_2013_Lindridge_Farm_UWC.pdf
Dangerous occurrence at Lindridge Farm user worked crossing, near Bagworth, Leicestershire	11/2013	22/03/2012	11/2013/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a228e740f0b613a7000003/11_2013_Lindridge_Farm_UWC.pdf
Dangerous occurrence at Lindridge Farm user worked crossing, near Bagworth, Leicestershire	11/2013	22/03/2012	11/2013/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a228e740f0b613a7000003/11_2013_Lindridge_Farm_UWC.pdf
Dangerous occurrence at Lindridge Farm user worked crossing, near Bagworth, Leicestershire	11/2013	22/03/2012	11/2013/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a228e740f0b613a7000003/11_2013_Lindridge_Farm_UWC.pdf
Dangerous occurrence at Lindridge Farm user worked crossing, near Bagworth, Leicestershire	11/2013	22/03/2012	11/2013/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a228e740f0b613a7000003/11_2013_Lindridge_Farm_UWC.pdf
Collision of a road-rail vehicle with a buffer stop at Bradford Interchange station	09/2013	25/03/2012	09/2013/01	Closed - I	None	Quattro Plant Limited (Quattro)	https://assets.publishing.service.gov.uk/media/56a2276340f0b613a7000001/09_2013_Bradford_Interchange_station.pdf
Collision of a road-rail vehicle with a buffer stop at Bradford Interchange station	09/2013	25/03/2012	09/2013/02	Closed - I	None	Quattro Plant Limited (Quattro)	https://assets.publishing.service.gov.uk/media/56a2276340f0b613a7000001/09_2013_Bradford_Interchange_station.pdf
Collision of a road-rail vehicle with a buffer stop at Bradford Interchange station	09/2013	25/03/2012	09/2013/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a2276340f0b613a7000001/09_2013_Bradford_Interchange_station.pdf
Collision of a road-rail vehicle with a buffer stop at Bradford Interchange station	09/2013	25/03/2012	09/2013/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a2276340f0b613a7000001/09_2013_Bradford_Interchange_station.pdf
Collision of a road-rail vehicle with a buffer stop at Bradford Interchange station	09/2013	25/03/2012	09/2013/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a2276340f0b613a7000001/09_2013_Bradford_Interchange_station.pdf
Derailment of a freight train at Shrewsbury station	08/2013	07/07/2012	08/2013/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a225c3e5274a6212000000/08_2013_Shrewsbury_station.pdf
Derailment of a freight train at Shrewsbury station	08/2013	07/07/2012	08/2013/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a225c3e5274a6212000000/08_2013_Shrewsbury_station.pdf
Derailment of a freight train at Shrewsbury station	08/2013	07/07/2012	08/2013/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a225c3e5274a6212000000/08_2013_Shrewsbury_station.pdf
Derailment of a freight train at Shrewsbury station	08/2013	07/07/2012	08/2013/04	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/56a225c3e5274a6212000000/08_2013_Shrewsbury_station.pdf
Dangerous occurrence involving track workers, near Roydon station, Essex	07/2013	16/07/2012	07/2013/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a218a0ed915d6d2a000000/07_2013_Roydon_station_Essex.pdf
Dangerous occurrence involving track workers, near Roydon station, Essex	07/2013	16/07/2012	07/2013/02	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56a218a0ed915d6d2a000000/07_2013_Roydon_station_Essex.pdf
Accident involving a pantograph and the overhead line near Littleport, Cambridgeshire	06/2013	05/01/2012	06/2013/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a2150fed915d468c000039/06_2013_Littleport_Cambs.pdf
Accident involving a pantograph and the overhead line near Littleport, Cambridgeshire	06/2013	05/01/2012	06/2013/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a2150fed915d468c000039/06_2013_Littleport_Cambs.pdf
Derailment of a tram at East Croydon	04/2013	17/02/2012	04/2013/01	Closed - IA	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/56a21238e5274a117500001e/04_2013_East_Croydon.pdf

Derailment of a tram at East Croydon	04/2013	17/02/2012	04/2013/02	Closed - I	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/56a21238e5274a117500001e/04_2013_East_Croydon.pdf
Derailment of a tram at East Croydon	04/2013	17/02/2012	04/2013/03	Closed - I	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/56a21238e5274a117500001e/04_2013_East_Croydon.pdf
Pedestrian struck by a tram at Sandilands tram stop, Croydon	03/2013	16/05/2012	03/2013/01	Closed - I	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/56a210a9e5274a112c00003e/03_2013_Sandilands_Croydon.pdf
Pedestrian struck by a tram at Sandilands tram stop, Croydon	03/2013	16/05/2012	03/2013/01	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/56a210a9e5274a112c00003e/03_2013_Sandilands_Croydon.pdf
Pedestrian struck by a tram at Sandilands tram stop, Croydon	03/2013	16/05/2012	03/2013/02	Closed - I	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/56a210a9e5274a112c00003e/03_2013_Sandilands_Croydon.pdf
Pedestrian struck by a tram at Sandilands tram stop, Croydon	03/2013	16/05/2012	03/2013/03	Closed - I	Blue	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a210a9e5274a112c00003e/03_2013_Sandilands_Croydon.pdf
Pedestrian struck by a tram at Sandilands tram stop, Croydon	03/2013	16/05/2012	03/2013/04	Closed - I	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/56a210a9e5274a112c00003e/03_2013_Sandilands_Croydon.pdf
Pedestrian struck by a tram at Sandilands tram stop, Croydon	03/2013	16/05/2012	03/2013/04	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/56a210a9e5274a112c00003e/03_2013_Sandilands_Croydon.pdf
Pedestrian struck by a tram at Sandilands tram stop, Croydon	03/2013	16/05/2012	03/2013/05	Closed - I	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/56a210a9e5274a112c00003e/03_2013_Sandilands_Croydon.pdf
Freight train derailment at Reading West Junction	02/2013	28/01/2012	02/2013/01	Closed - I	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/56a20b8640f0b667f300002e/02_2013_Reading_West_Junction.pdf
Freight train derailment at Reading West Junction	02/2013	28/01/2012	02/2013/02	Closed - I	White	Freightliner Group	https://assets.publishing.service.gov.uk/media/56a20b8640f0b667f300002e/02_2013_Reading_West_Junction.pdf
Freight train derailment at Reading West Junction	02/2013	28/01/2012	02/2013/03	Closed - I	White	Freightliner Group	https://assets.publishing.service.gov.uk/media/56a20b8640f0b667f300002e/02_2013_Reading_West_Junction.pdf
Freight train derailment at Reading West Junction	02/2013	28/01/2012	02/2013/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a20b8640f0b667f300002e/02_2013_Reading_West_Junction.pdf
Freight train derailment at Reading West Junction	02/2013	28/01/2012	02/2013/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a20b8640f0b667f300002e/02_2013_Reading_West_Junction.pdf
Fatal accident at Kings Mill No.1 level crossing, Mansfield	01/2013	02/05/2012	01/2013/01	Closed - I	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/56a209b540f0b667ce000029/01_2013_Kings_Mill_No_1_level_crossing_Mansfield.pdf
Fatal accident at Kings Mill No.1 level crossing, Mansfield	01/2013	02/05/2012	01/2013/01	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a209b540f0b667ce000029/01_2013_Kings_Mill_No_1_level_crossing_Mansfield.pdf
Near miss incident at Ufton Automatic Half Barrier Crossing, Berkshire	28/2012	04/09/2011	28/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21731ed915d4747000040/28_2012_Ufton_Berkshire.pdf
Near miss incident at Ufton Automatic Half Barrier Crossing, Berkshire	28/2012	04/09/2011	28/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21731ed915d4747000040/28_2012_Ufton_Berkshire.pdf
Near miss incident at Ufton Automatic Half Barrier Crossing, Berkshire	28/2012	04/09/2011	28/2012/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21731ed915d4747000040/28_2012_Ufton_Berkshire.pdf

Near miss incident at Ufton Automatic Half Barrier Crossing, Berkshire	28/2012	04/09/2011	28/2012/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21731ed915d47470000/40/28_2012_Ufton_Berkshire.pdf
Near miss incident at Ufton Automatic Half Barrier Crossing, Berkshire	28/2012	04/09/2011	28/2012/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21731ed915d47470000/40/28_2012_Ufton_Berkshire.pdf
Near miss incident at Ufton Automatic Half Barrier Crossing, Berkshire	28/2012	04/09/2011	28/2012/06	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21731ed915d47470000/40/28_2012_Ufton_Berkshire.pdf
Near miss incident at Ufton Automatic Half Barrier Crossing, Berkshire	28/2012	04/09/2011	28/2012/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21731ed915d47470000/40/28_2012_Ufton_Berkshire.pdf
Fatality at Johnson's footpath crossing near Bishop's Stortford, Hertfordshire	27/2012	28/01/2012	27/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21696ed915d468c0000/3b/27_2012_Johnson_s_FPC_Bishops_Stortford.pdf
Fatality at Johnson's footpath crossing near Bishop's Stortford, Hertfordshire	27/2012	28/01/2012	27/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21696ed915d468c0000/3b/27_2012_Johnson_s_FPC_Bishops_Stortford.pdf
Fatality at Johnson's footpath crossing near Bishop's Stortford, Hertfordshire	27/2012	28/01/2012	27/2012/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a21696ed915d468c0000/3b/27_2012_Johnson_s_FPC_Bishops_Stortford.pdf
Person trapped in a train door and dragged at Jarrow station, Tyne and Wear Metro	26/2012	12/04/2012	26/2012/01	Closed - I	None	Tyne & Wear Metro	https://assets.publishing.service.gov.uk/media/56a20005e5274a112c0000/3a/26_2012_Jarrow_station_Tyne_and_Wear.pdf
Person trapped in a train door and dragged at Jarrow station, Tyne and Wear Metro	26/2012	12/04/2012	26/2012/02	Closed - I	None	Tyne & Wear Metro	https://assets.publishing.service.gov.uk/media/56a20005e5274a112c0000/3a/26_2012_Jarrow_station_Tyne_and_Wear.pdf
Person trapped in a train door and dragged at Jarrow station, Tyne and Wear Metro	26/2012	12/04/2012	26/2012/03	Closed - I	None	Tyne & Wear Metro	https://assets.publishing.service.gov.uk/media/56a20005e5274a112c0000/3a/26_2012_Jarrow_station_Tyne_and_Wear.pdf
Person trapped in a train door and dragged at Jarrow station, Tyne and Wear Metro	26/2012	12/04/2012	26/2012/04	Closed - I	None	Tyne & Wear Metro	https://assets.publishing.service.gov.uk/media/56a20005e5274a112c0000/3a/26_2012_Jarrow_station_Tyne_and_Wear.pdf
Person trapped in a train door and dragged at Jarrow station, Tyne and Wear Metro	26/2012	12/04/2012	26/2012/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56a20005e5274a112c0000/3a/26_2012_Jarrow_station_Tyne_and_Wear.pdf
Derailment at Bletchley Junction, Bletchley	24/2012	03/02/2012	24/2012/01	Closed - I	None	Virgin Trains	https://assets.publishing.service.gov.uk/media/56a0fb6be5274a11750000/18/24_2012_Bletchley_Junction.pdf
Derailment at Bletchley Junction, Bletchley	24/2012	03/02/2012	24/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a0fb6be5274a11750000/18/24_2012_Bletchley_Junction.pdf
Derailment at Bletchley Junction, Bletchley	24/2012	03/02/2012	24/2012/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a0fb6be5274a11750000/18/24_2012_Bletchley_Junction.pdf
Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/01	Closed - I	None	Suffolk County Council (SCC)	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf
Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf
Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf
Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/04	Closed - I	None	Suffolk County Council (SCC)	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf

Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/05	Closed - I	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf
Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/05	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf
Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/06	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf
Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/07	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf
Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/08	Open	None	Department for Transport	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf
Road vehicle incursion and subsequent collision with a train at Stowmarket Road	25/2012	30/11/2011	25/2012/09	Open	None	Department for Transport	https://assets.publishing.service.gov.uk/media/56a0ff4f40f0b667ce000027/25_2012_Stowmarket_Road.pdf
Fatal accident at Grosmont, North Yorkshire Moors Railway	23/2012	21/05/2012	23/2012/01	Closed - I	None	North Yorkshire Moors Railway	https://assets.publishing.service.gov.uk/media/569faf73ed915d4747000036/23_2012_Grosmont_North_Yorkshire.pdf
Fatal accident at James Street station, Liverpool	22/2012	22/10/2011	22/2012/01	Closed - I	None	Merseyrail	https://assets.publishing.service.gov.uk/media/569faddbe5274a112c000036/22_2012_James_Street_Liverpool.pdf
Fatal accident at James Street station, Liverpool	22/2012	22/10/2011	22/2012/02	Closed - I	None	Merseyrail	https://assets.publishing.service.gov.uk/media/569faddbe5274a112c000036/22_2012_James_Street_Liverpool.pdf
Fatal accident at James Street station, Liverpool	22/2012	22/10/2011	22/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569faddbe5274a112c000036/22_2012_James_Street_Liverpool.pdf
Fatal accident at James Street station, Liverpool	22/2012	22/10/2011	22/2012/03	Closed - I	White	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/569faddbe5274a112c000036/22_2012_James_Street_Liverpool.pdf
Collision between a train and a lorry and trailer on Llanboidy automatic half barrier level crossing	20/2012	19/12/2011	20/2012/01	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/569faa5640f0b667f3000027/20_2012_Llanboidy.pdf
Collision between a train and a lorry and trailer on Llanboidy automatic half barrier level crossing	20/2012	19/12/2011	20/2012/02	Closed - NI	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/569faa5640f0b667f3000027/20_2012_Llanboidy.pdf
Collision between a train and a lorry and trailer on Llanboidy automatic half barrier level crossing	20/2012	19/12/2011	20/2012/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569faa5640f0b667f3000027/20_2012_Llanboidy.pdf
Collision between a train and a lorry and trailer on Llanboidy automatic half barrier level crossing	20/2012	19/12/2011	20/2012/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569faa5640f0b667f3000027/20_2012_Llanboidy.pdf
Collision between a train and a lorry and trailer on Llanboidy automatic half barrier level crossing	20/2012	19/12/2011	20/2012/05	Closed - I	None	Angel Trains Limited	https://assets.publishing.service.gov.uk/media/569faa5640f0b667f3000027/20_2012_Llanboidy.pdf
Collision between a train and a lorry and trailer on Llanboidy automatic half barrier level crossing	20/2012	19/12/2011	20/2012/06	Closed - I	None	Alstom	https://assets.publishing.service.gov.uk/media/569faa5640f0b667f3000027/20_2012_Llanboidy.pdf
Collision between a train and a lorry and trailer on Llanboidy automatic half barrier level crossing	20/2012	19/12/2011	20/2012/06	Closed - I	None	Angel Trains Limited	https://assets.publishing.service.gov.uk/media/569faa5640f0b667f3000027/20_2012_Llanboidy.pdf
Collapse of the overhead line near to Jewellery Quarter Tram Stop, Midland Metro	21/2012	20/04/2011	21/2012/01	Closed - I	None	National Express Midland Metro	https://assets.publishing.service.gov.uk/media/569fac79e5274a1175000016/21_2012_Jewellery_Quarter.pdf

Collapse of the overhead line near to Jewellery Quarter Tram Stop, Midland Metro	21/2012	20/04/2011	21/2012/02	Closed - I	None	National Express Midland Metro	https://assets.publishing.service.gov.uk/media/569fac79e5274a11750000/16/21_2012_Jewellery_Quarter.pdf
Collapse of the overhead line near to Jewellery Quarter Tram Stop, Midland Metro	21/2012	20/04/2011	21/2012/03	Closed - IA	None	National Express Midland Metro	https://assets.publishing.service.gov.uk/media/569fac79e5274a11750000/16/21_2012_Jewellery_Quarter.pdf
Collapse of the overhead line near to Jewellery Quarter Tram Stop, Midland Metro	21/2012	20/04/2011	21/2012/04	Closed - I	None	National Express Midland Metro	https://assets.publishing.service.gov.uk/media/569fac79e5274a11750000/16/21_2012_Jewellery_Quarter.pdf
Collapse of the overhead line near to Jewellery Quarter Tram Stop, Midland Metro	21/2012	20/04/2011	21/2012/05	Closed - I	None	National Express Midland Metro	https://assets.publishing.service.gov.uk/media/569fac79e5274a11750000/16/21_2012_Jewellery_Quarter.pdf
Collapse of the overhead line near to Jewellery Quarter Tram Stop, Midland Metro	21/2012	20/04/2011	21/2012/06	Closed - I	None	National Express Midland Metro	https://assets.publishing.service.gov.uk/media/569fac79e5274a11750000/16/21_2012_Jewellery_Quarter.pdf
Collapse of the overhead line near to Jewellery Quarter Tram Stop, Midland Metro	21/2012	20/04/2011	21/2012/07	Closed - I	None	National Express Midland Metro	https://assets.publishing.service.gov.uk/media/569fac79e5274a11750000/16/21_2012_Jewellery_Quarter.pdf
Derailment at Bordesley Junction, Birmingham	19/2012	26/08/2011	19/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569fa8f1e5274a112c00003/4/19_2012_Bordesley_Junction.pdf
Derailment at Bordesley Junction, Birmingham	19/2012	26/08/2011	19/2012/02	Closed - I	None	Lafarge Aggregates Ltd	https://assets.publishing.service.gov.uk/media/569fa8f1e5274a112c00003/4/19_2012_Bordesley_Junction.pdf
Derailment at Bordesley Junction, Birmingham	19/2012	26/08/2011	19/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569fa8f1e5274a112c00003/4/19_2012_Bordesley_Junction.pdf
Derailment at Bordesley Junction, Birmingham	19/2012	26/08/2011	19/2012/02	Closed - I	None	Wabtec Rail Limited	https://assets.publishing.service.gov.uk/media/569fa8f1e5274a112c00003/4/19_2012_Bordesley_Junction.pdf
Derailment at Bordesley Junction, Birmingham	19/2012	26/08/2011	19/2012/03	Closed - I	None	Lafarge Aggregates Ltd	https://assets.publishing.service.gov.uk/media/569fa8f1e5274a112c00003/4/19_2012_Bordesley_Junction.pdf
Derailment at Bordesley Junction, Birmingham	19/2012	26/08/2011	19/2012/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569fa8f1e5274a112c00003/4/19_2012_Bordesley_Junction.pdf
Derailment at Princes Street Gardens, Edinburgh	18/2012	27/07/2011	18/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569fa3aced915d47470000/34/18_2012_Princes_Street_Gardens_Edinburgh.pdf
Derailment at Princes Street Gardens, Edinburgh	18/2012	27/07/2011	18/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569fa3aced915d47470000/34/18_2012_Princes_Street_Gardens_Edinburgh.pdf
Derailment at Princes Street Gardens, Edinburgh	18/2012	27/07/2011	18/2012/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/569fa3aced915d47470000/34/18_2012_Princes_Street_Gardens_Edinburgh.pdf
Derailment at Princes Street Gardens, Edinburgh	18/2012	27/07/2011	18/2012/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569fa3aced915d47470000/34/18_2012_Princes_Street_Gardens_Edinburgh.pdf
Derailment at Princes Street Gardens, Edinburgh	18/2012	27/07/2011	18/2012/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/569fa3aced915d47470000/34/18_2012_Princes_Street_Gardens_Edinburgh.pdf
Container train accident near Althorpe Park, Northamptonshire	17/2012	18/07/2011	17/2012/01	Closed - I	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/568e8d97e5274a112c0000/11/17_2012_Althorpe_Park.pdf
Container train accident near Althorpe Park, Northamptonshire	17/2012	18/07/2011	17/2012/02	Open	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/568e8d97e5274a112c0000/11/17_2012_Althorpe_Park.pdf

Container train accident near Althorpe Park, Northamptonshire	17/2012	18/07/2011	17/2012/03	Open	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/568e8d97e5274a112c000011/17_2012_Althorpe_Park.pdf
Container train accident near Althorpe Park, Northamptonshire	17/2012	18/07/2011	17/2012/04	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/568e8d97e5274a112c000011/17_2012_Althorpe_Park.pdf
Container train accident near Althorpe Park, Northamptonshire	17/2012	18/07/2011	17/2012/04	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/568e8d97e5274a112c000011/17_2012_Althorpe_Park.pdf
Track worker struck by a train at Stoats Nest Junction	16/2012	12/06/2011	16/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e8ae040f0b667f300000d/16_2012_Stoats_Nest_Junction.pdf
Fatal accident at Gipsy Lane footpath crossing, Needham Market, Suffolk	15/2012	24/08/2011	15/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e8a57e5274a112c00000f/15_2012_Gipsy_Lane_Needham_Market.pdf
Fatal accident at Gipsy Lane footpath crossing, Needham Market, Suffolk	15/2012	24/08/2011	15/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e8a57e5274a112c00000f/15_2012_Gipsy_Lane_Needham_Market.pdf
Fatal accident at Gipsy Lane footpath crossing, Needham Market, Suffolk	15/2012	24/08/2011	15/2012/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e8a57e5274a112c00000f/15_2012_Gipsy_Lane_Needham_Market.pdf
Fatal accident at Gipsy Lane footpath crossing, Needham Market, Suffolk	15/2012	24/08/2011	15/2012/04	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e8a57e5274a112c00000f/15_2012_Gipsy_Lane_Needham_Market.pdf
Incident involving a runaway track maintenance trolley near Haslemere, Surrey	14/2012	10/09/2011	14/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e86bfe5274a112c00000d/14_2012_Haslemere.pdf
Incident involving a runaway track maintenance trolley near Haslemere, Surrey	14/2012	10/09/2011	14/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e86bfe5274a112c00000d/14_2012_Haslemere.pdf
Incident involving a runaway track maintenance trolley near Haslemere, Surrey	14/2012	10/09/2011	14/2012/03	Closed - I	None	Torrent Trackside Limited	https://assets.publishing.service.gov.uk/media/568e86bfe5274a112c00000d/14_2012_Haslemere.pdf
Incident involving a runaway track maintenance trolley near Haslemere, Surrey	14/2012	10/09/2011	14/2012/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e86bfe5274a112c00000d/14_2012_Haslemere.pdf
Incident involving a runaway track maintenance trolley near Haslemere, Surrey	14/2012	10/09/2011	14/2012/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e86bfe5274a112c00000d/14_2012_Haslemere.pdf
Incident involving a runaway track maintenance trolley near Haslemere, Surrey	14/2012	10/09/2011	14/2012/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e86bfe5274a112c00000d/14_2012_Haslemere.pdf
Train departed with doors open, Warren Street, Victoria Line, London Underground	13/2012	11/07/2011	13/2012/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/568e83f6ed915d474700000e/13_2012_Warren_Street.pdf
Train departed with doors open, Warren Street, Victoria Line, London Underground	13/2012	11/07/2011	13/2012/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/568e83f6ed915d474700000e/13_2012_Warren_Street.pdf
Train departed with doors open, Warren Street, Victoria Line, London Underground	13/2012	11/07/2011	13/2012/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/568e83f6ed915d474700000e/13_2012_Warren_Street.pdf
Train departed with doors open, Warren Street, Victoria Line, London Underground	13/2012	11/07/2011	13/2012/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/568e83f6ed915d474700000e/13_2012_Warren_Street.pdf
Detachment of a cardan shaft at Durham station	12/2012	10/04/2011	12/2012/01	Closed - I	None	The owners of class 14x vehicles	https://assets.publishing.service.gov.uk/media/568e8106e5274a112c00000b/12_2007_Durham_station.pdf

Detachment of a cardan shaft at Durham station	12/2012	10/04/2011	12/2012/02	Closed - I	None	The owners of class 14x vehicles	https://assets.publishing.service.gov.uk/media/568e8106e5274a112c00000b/12_2007_Durham_station.pdf
Detachment of a cardan shaft at Durham station	12/2012	10/04/2011	12/2012/03	Closed - I	None	Northern Rail	https://assets.publishing.service.gov.uk/media/568e8106e5274a112c00000b/12_2007_Durham_station.pdf
Detachment of a cardan shaft at Durham station	12/2012	10/04/2011	12/2012/04	Closed - I	None	The owners of class 14x vehicles	https://assets.publishing.service.gov.uk/media/568e8106e5274a112c00000b/12_2007_Durham_station.pdf
Detachment of a cardan shaft at Durham station	12/2012	10/04/2011	12/2012/05	Closed - I	None	The owners of class 14x vehicles	https://assets.publishing.service.gov.uk/media/568e8106e5274a112c00000b/12_2007_Durham_station.pdf
Detachment of a cardan shaft at Durham station	12/2012	10/04/2011	12/2012/06	Closed - I	None	Northern Rail	https://assets.publishing.service.gov.uk/media/568e8106e5274a112c00000b/12_2007_Durham_station.pdf
Incident at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	11/2012	19/06/2011	11/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e779ee5274a1175000009/11_2012_Llanbadarn.pdf
Incident at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	11/2012	19/06/2011	11/2012/02	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e779ee5274a1175000009/11_2012_Llanbadarn.pdf
Incident at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	11/2012	19/06/2011	11/2012/03	Closed - IA	None	Arriva Trains Wales	https://assets.publishing.service.gov.uk/media/568e779ee5274a1175000009/11_2012_Llanbadarn.pdf
Incident at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	11/2012	19/06/2011	11/2012/04	Closed - IA	None	Arriva Trains Wales	https://assets.publishing.service.gov.uk/media/568e779ee5274a1175000009/11_2012_Llanbadarn.pdf
Incident at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	11/2012	19/06/2011	11/2012/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e779ee5274a1175000009/11_2012_Llanbadarn.pdf
Incident at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	11/2012	19/06/2011	11/2012/06	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/568e779ee5274a1175000009/11_2012_Llanbadarn.pdf
Fatal accident at Mexico footpath crossing (near Penzance)	10/2012	03/10/2011	10/2012/01	Closed - I	None	Network Rail	https://www.gov.uk/raib-reports/fatal-accident-at-mexico-footpath-crossing-near-penzance
Fatal accident at Mexico footpath crossing (near Penzance)	10/2012	03/10/2011	10/2012/02	Closed - I	None	RSSB	https://www.gov.uk/raib-reports/fatal-accident-at-mexico-footpath-crossing-near-penzance
Fatal accident at Mexico footpath crossing (near Penzance)	10/2012	03/10/2011	10/2012/03	Closed - I	White	Network Rail	https://www.gov.uk/raib-reports/fatal-accident-at-mexico-footpath-crossing-near-penzance
Fatal accident at Mexico footpath crossing (near Penzance)	10/2012	03/10/2011	10/2012/03	Closed - I	White	RSSB	https://www.gov.uk/raib-reports/fatal-accident-at-mexico-footpath-crossing-near-penzance
Fatal accident at Mexico footpath crossing (near Penzance)	10/2012	03/10/2011	10/2012/04	Closed - I	None	First Great Western	https://www.gov.uk/raib-reports/fatal-accident-at-mexico-footpath-crossing-near-penzance
Fatal accident at Mexico footpath crossing (near Penzance)	10/2012	03/10/2011	10/2012/04	Closed - I	None	RSSB	https://www.gov.uk/raib-reports/fatal-accident-at-mexico-footpath-crossing-near-penzance
Fatal accident at Mexico footpath crossing (near Penzance)	10/2012	03/10/2011	10/2012/05	Closed - I	None	Network Rail	https://www.gov.uk/raib-reports/fatal-accident-at-mexico-footpath-crossing-near-penzance
Fatal accident at Piccadilly Gardens, Manchester	08/2012	05/06/2011	08/2012/01	Closed - I	None	UK Tram Operators	https://assets.publishing.service.gov.uk/media/568e6b9aed915d468c00000f/08_2012_Piccadilly_Gardens.pdf

Fatal accident at Piccadilly Gardens, Manchester	08/2012	05/06/2011	08/2012/02	Closed - NI	None	UK Tram	https://assets.publishing.service.gov.uk/media/568e6b9aed915d468c0000/0f/08_2012_Piccadilly_Gardens.pdf
Fatal accident at Piccadilly Gardens, Manchester	08/2012	05/06/2011	08/2012/02	Closed - NI	None	UK Tram Operators	https://assets.publishing.service.gov.uk/media/568e6b9aed915d468c0000/0f/08_2012_Piccadilly_Gardens.pdf
Person trapped in doors and pulled along platform at King's Cross station, London	09/2012	10/10/2011	09/2012/01	Closed - I	None	Eversholt Rail UK (Ltd)	https://assets.publishing.service.gov.uk/media/568e6ddd40f0b667ce0000/0f/09_2012_King_s_Cross_station.pdf
Safety incident between Dock Junction and Kentish Town	07/2012	26/05/2011	07/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e68d3e5274a11750000/06/07_2012_Kentish_Town.pdf
Safety incident between Dock Junction and Kentish Town	07/2012	26/05/2011	07/2012/01	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/568e68d3e5274a11750000/06/07_2012_Kentish_Town.pdf
Safety incident between Dock Junction and Kentish Town	07/2012	26/05/2011	07/2012/02	Closed - I	None	First Capital Connect	https://assets.publishing.service.gov.uk/media/568e68d3e5274a11750000/06/07_2012_Kentish_Town.pdf
Safety incident between Dock Junction and Kentish Town	07/2012	26/05/2011	07/2012/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e68d3e5274a11750000/06/07_2012_Kentish_Town.pdf
Safety incident between Dock Junction and Kentish Town	07/2012	26/05/2011	07/2012/03	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/568e68d3e5274a11750000/06/07_2012_Kentish_Town.pdf
Partial failure of Bridge 94, near Bromsgrove	05/2012	06/04/2011	05/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e62dde5274a11750000/04/05_2012_Bromsgrove.pdf
Partial failure of Bridge 94, near Bromsgrove	05/2012	06/04/2011	05/2012/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e62dde5274a11750000/04/05_2012_Bromsgrove.pdf
Partial failure of Bridge 94, near Bromsgrove	05/2012	06/04/2011	05/2012/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e62dde5274a11750000/04/05_2012_Bromsgrove.pdf
Boiler incident on the Kirklees Light Railway	04/2012	03/07/2011	04/2012/01	Closed - I	None	Kirklees Light Railway	https://assets.publishing.service.gov.uk/media/568e61c540f0b667f300000/a/04_2012_Kirklees.pdf
Boiler incident on the Kirklees Light Railway	04/2012	03/07/2011	04/2012/02	Closed - I	None	Kirklees Light Railway	https://assets.publishing.service.gov.uk/media/568e61c540f0b667f300000/a/04_2012_Kirklees.pdf
Two incidents involving track workers between Clapham Junction and Earlsfield	03/2012	08/03/2011	03/2012/01	Closed - IA	White	Network Rail	https://assets.publishing.service.gov.uk/media/568e60e9ed915d47470000/07/03_2012_Clapham_Earlsfield.pdf
Two incidents involving track workers between Clapham Junction and Earlsfield	03/2012	08/03/2011	03/2012/02	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e60e9ed915d47470000/07/03_2012_Clapham_Earlsfield.pdf
Two incidents involving track workers between Clapham Junction and Earlsfield	03/2012	08/03/2011	03/2012/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e60e9ed915d47470000/07/03_2012_Clapham_Earlsfield.pdf
Two incidents involving track workers between Clapham Junction and Earlsfield	03/2012	08/03/2011	03/2012/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e60e9ed915d47470000/07/03_2012_Clapham_Earlsfield.pdf
Two incidents involving track workers between Clapham Junction and Earlsfield	03/2012	08/03/2011	03/2012/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e60e9ed915d47470000/07/03_2012_Clapham_Earlsfield.pdf
Tamper driver struck by a train at Torworth level crossing	02/2012	08/01/2011	02/2012/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568e5fc0e5274a112c0000/08/02_2012_Torworth.pdf

Tamper driver struck by a train at Torworth level crossing	02/2012	08/01/2011	02/2012/01	Closed - I	None	Railway Contractors	https://assets.publishing.service.gov.uk/media/568e5fc0e5274a112c0000/08/02_2012_Torworth.pdf
Passenger train derailment near East Langton, Leicestershire	01/2012	20/02/2010	01/2012/01	Closed - I	None	Bombardier Transportation	https://assets.publishing.service.gov.uk/media/568e5ca740f0b667ce0000/0b/01_2012_East_Langton.pdf
Passenger train derailment near East Langton, Leicestershire	01/2012	20/02/2010	01/2012/01	Closed - I	None	Voith	https://assets.publishing.service.gov.uk/media/568e5ca740f0b667ce0000/0b/01_2012_East_Langton.pdf
Passenger train derailment near East Langton, Leicestershire	01/2012	20/02/2010	01/2012/02	Closed - I	None	Rolling Stock Maintainers	https://assets.publishing.service.gov.uk/media/568e5ca740f0b667ce0000/0b/01_2012_East_Langton.pdf
Passenger train derailment near East Langton, Leicestershire	01/2012	20/02/2010	01/2012/02	Closed - I	None	Rolling Stock Leasing Companies	https://assets.publishing.service.gov.uk/media/568e5ca740f0b667ce0000/0b/01_2012_East_Langton.pdf
Passenger train derailment near East Langton, Leicestershire	01/2012	20/02/2010	01/2012/03	Closed - I	None	Bombardier Transportation	https://assets.publishing.service.gov.uk/media/568e5ca740f0b667ce0000/0b/01_2012_East_Langton.pdf
Passenger train derailment near East Langton, Leicestershire	01/2012	20/02/2010	01/2012/04	Closed - I	None	East Midlands Trains	https://assets.publishing.service.gov.uk/media/568e5ca740f0b667ce0000/0b/01_2012_East_Langton.pdf
Train passed over Lydney level crossing with crossing barriers raised	20/2011	23/03/2011	20/2011/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683b556ed915d03640000/05/20_2011_Lydney.pdf
Train passed over Lydney level crossing with crossing barriers raised	20/2011	23/03/2011	20/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683b556ed915d03640000/05/20_2011_Lydney.pdf
Train passed over Lydney level crossing with crossing barriers raised	20/2011	23/03/2011	20/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683b556ed915d03640000/05/20_2011_Lydney.pdf
Passenger accident at Brentwood station	19/2011	28/01/2011	19/2011/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683b28840f0b603580000/05/19_2011_Brentwood.pdf
Passenger accident at Brentwood station	19/2011	28/01/2011	19/2011/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5683b28840f0b603580000/05/19_2011_Brentwood.pdf
Passenger accident at Brentwood station	19/2011	28/01/2011	19/2011/03	Closed - I	None	Abellio Greater Anglia	https://assets.publishing.service.gov.uk/media/5683b28840f0b603580000/05/19_2011_Brentwood.pdf
Passenger accident at Brentwood station	19/2011	28/01/2011	19/2011/04	Closed - I	None	Abellio Greater Anglia	https://assets.publishing.service.gov.uk/media/5683b28840f0b603580000/05/19_2011_Brentwood.pdf
Passenger accident at Brentwood station	19/2011	28/01/2011	19/2011/05	Closed - I	None	Abellio Greater Anglia	https://assets.publishing.service.gov.uk/media/5683b28840f0b603580000/05/19_2011_Brentwood.pdf
Station overrun at Stonegate, East Sussex	18/2011	08/11/2010	18/2011/01	Closed - I	None	London & South Eastern Railway Ltd	https://assets.publishing.service.gov.uk/media/5683b1d140f0b603580000/03/18_2011_Stonegate.pdf
Station overrun at Stonegate, East Sussex	18/2011	08/11/2010	18/2011/02	Closed - I	None	London & South Eastern Railway Ltd	https://assets.publishing.service.gov.uk/media/5683b1d140f0b603580000/03/18_2011_Stonegate.pdf
Station overrun at Stonegate, East Sussex	18/2011	08/11/2010	18/2011/03	Closed - I	None	London & South Eastern Railway Ltd	https://assets.publishing.service.gov.uk/media/5683b1d140f0b603580000/03/18_2011_Stonegate.pdf
Derailment of a passenger train near Dryclough Junction, Halifax	17/2011	05/02/2011	17/2011/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683b099ed915d03640000/02/17_2011_Dryclough_Junction_Halifax.pdf

Derailment of a passenger train near Dryclough Junction, Halifax	17/2011	05/02/2011	17/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683b099ed915d03640000/02/17_2011_Dryclough_Junction_Halifax.pdf
Derailment of a passenger train near Dryclough Junction, Halifax	17/2011	05/02/2011	17/2011/03	Closed - I	None	Amey	https://assets.publishing.service.gov.uk/media/5683b099ed915d03640000/02/17_2011_Dryclough_Junction_Halifax.pdf
Derailment of a passenger train near Dryclough Junction, Halifax	17/2011	05/02/2011	17/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683b099ed915d03640000/02/17_2011_Dryclough_Junction_Halifax.pdf
Derailment of a passenger train near Dryclough Junction, Halifax	17/2011	05/02/2011	17/2011/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683b099ed915d03640000/02/17_2011_Dryclough_Junction_Halifax.pdf
Derailment of a passenger train near Dryclough Junction, Halifax	17/2011	05/02/2011	17/2011/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683b099ed915d03640000/02/17_2011_Dryclough_Junction_Halifax.pdf
Derailment in Summit tunnel, near Todmorden, West Yorkshire	16/2011	28/12/2010	16/2011/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683afca40f0b6035800000/1/16_2011_Summit_tunnel_Todmorden.pdf
Derailment in Summit tunnel, near Todmorden, West Yorkshire	16/2011	28/12/2010	16/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683afca40f0b6035800000/1/16_2011_Summit_tunnel_Todmorden.pdf
Derailment in Summit tunnel, near Todmorden, West Yorkshire	16/2011	28/12/2010	16/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683afca40f0b6035800000/1/16_2011_Summit_tunnel_Todmorden.pdf
Derailment in Summit tunnel, near Todmorden, West Yorkshire	16/2011	28/12/2010	16/2011/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683afca40f0b6035800000/1/16_2011_Summit_tunnel_Todmorden.pdf
Derailment in Summit tunnel, near Todmorden, West Yorkshire	16/2011	28/12/2010	16/2011/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683afca40f0b6035800000/1/16_2011_Summit_tunnel_Todmorden.pdf
Uncontrolled freight train run-back between Shap and Tebay, Cumbria	15/2011	17/08/2010	15/2011/01	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/5683a8a0ed915d03640000/00/15_2011_Shap_and_Tebay.pdf
Uncontrolled freight train run-back between Shap and Tebay, Cumbria	15/2011	17/08/2010	15/2011/02	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5683a8a0ed915d03640000/00/15_2011_Shap_and_Tebay.pdf
Uncontrolled freight train run-back between Shap and Tebay, Cumbria	15/2011	17/08/2010	15/2011/03	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5683a8a0ed915d03640000/00/15_2011_Shap_and_Tebay.pdf
Uncontrolled freight train run-back between Shap and Tebay, Cumbria	15/2011	17/08/2010	15/2011/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5683a8a0ed915d03640000/00/15_2011_Shap_and_Tebay.pdf
Collision between an articulated tanker and a passenger train at Sewage Works Lane user worked crossing, near Sudbury, Suffolk	14/2011	17/08/2010	14/2011/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683ada6e5274a036a0000/00/14_2011_Sewage_Works_Lane.pdf
Collision between an articulated tanker and a passenger train at Sewage Works Lane user worked crossing, near Sudbury, Suffolk	14/2011	17/08/2010	14/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683ada6e5274a036a0000/00/14_2011_Sewage_Works_Lane.pdf
Collision between an articulated tanker and a passenger train at Sewage Works Lane user worked crossing, near Sudbury, Suffolk	14/2011	17/08/2010	14/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683ada6e5274a036a0000/00/14_2011_Sewage_Works_Lane.pdf
Collision between an articulated tanker and a passenger train at Sewage Works Lane user worked crossing, near Sudbury, Suffolk	14/2011	17/08/2010	14/2011/04	Closed - I	None	Anglian Water	https://assets.publishing.service.gov.uk/media/5683ada6e5274a036a0000/00/14_2011_Sewage_Works_Lane.pdf
Collision between an articulated tanker and a passenger train at Sewage Works Lane user worked crossing, near Sudbury, Suffolk	14/2011	17/08/2010	14/2011/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683ada6e5274a036a0000/00/14_2011_Sewage_Works_Lane.pdf

Collision between an articulated tanker and a passenger train at Sewage Works Lane user worked crossing, near Sudbury, Suffolk	14/2011	17/08/2010	14/2011/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683ada6e5274a036a000000/14_2011_Sewage_Works_Lane.pdf
Collision between an articulated tanker and a passenger train at Sewage Works Lane user worked crossing, near Sudbury, Suffolk	14/2011	17/08/2010	14/2011/06	Closed - I	None	Owners and Operators of Class 156 units	https://assets.publishing.service.gov.uk/media/5683ada6e5274a036a000000/14_2011_Sewage_Works_Lane.pdf
Bridge strike and road vehicle incursion onto the roof of a passing train near Oxshott Station	13/2011	05/11/2010	13/2011/01	Closed - I	None	Surrey County Council	https://assets.publishing.service.gov.uk/media/5683a7cbed915d0361000001/13_2011_Oxshott_Station.pdf
Bridge strike and road vehicle incursion onto the roof of a passing train near Oxshott Station	13/2011	05/11/2010	13/2011/02	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/5683a7cbed915d0361000001/13_2011_Oxshott_Station.pdf
Bridge strike and road vehicle incursion onto the roof of a passing train near Oxshott Station	13/2011	05/11/2010	13/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5683a7cbed915d0361000001/13_2011_Oxshott_Station.pdf
Bridge strike and road vehicle incursion onto the roof of a passing train near Oxshott Station	13/2011	05/11/2010	13/2011/04	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/5683a7cbed915d0361000001/13_2011_Oxshott_Station.pdf
Bridge strike and road vehicle incursion onto the roof of a passing train near Oxshott Station	13/2011	05/11/2010	13/2011/05	Closed - I	None	Surrey County Council	https://assets.publishing.service.gov.uk/media/5683a7cbed915d0361000001/13_2011_Oxshott_Station.pdf
Investigation into the safety of automatic open level crossings on Network Rail's managed infrastructure	12/2011	02/02/2010	12/2011/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5682a9b6e5274a7a98000002/12_2011_Safety_of_AOCLs.pdf
Investigation into the safety of automatic open level crossings on Network Rail's managed infrastructure	12/2011	02/02/2010	12/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5682a9b6e5274a7a98000002/12_2011_Safety_of_AOCLs.pdf
Investigation into the safety of automatic open level crossings on Network Rail's managed infrastructure	12/2011	02/02/2010	12/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5682a9b6e5274a7a98000002/12_2011_Safety_of_AOCLs.pdf
Investigation into the safety of automatic open level crossings on Network Rail's managed infrastructure	12/2011	02/02/2010	12/2011/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5682a9b6e5274a7a98000002/12_2011_Safety_of_AOCLs.pdf
Accident at Falls of Cruachan, Argyll	11/2011	06/06/2010	11/2011/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5682a6f2ed915d31b8000000/11_2011_Falls_of_Cruachan.pdf
Accident at Falls of Cruachan, Argyll	11/2011	06/06/2010	11/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5682a6f2ed915d31b8000000/11_2011_Falls_of_Cruachan.pdf
Accident at Falls of Cruachan, Argyll	11/2011	06/06/2010	11/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5682a6f2ed915d31b8000000/11_2011_Falls_of_Cruachan.pdf
Accident at Falls of Cruachan, Argyll	11/2011	06/06/2010	11/2011/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5682a6f2ed915d31b8000000/11_2011_Falls_of_Cruachan.pdf
Accident at Falls of Cruachan, Argyll	11/2011	06/06/2010	11/2011/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5682a6f2ed915d31b8000000/11_2011_Falls_of_Cruachan.pdf
Accident at Falls of Cruachan, Argyll	11/2011	06/06/2010	11/2011/06	Closed - I	None	First ScotRail	https://assets.publishing.service.gov.uk/media/5682a6f2ed915d31b8000000/11_2011_Falls_of_Cruachan.pdf
Runaway and collision of a road-rail vehicle near Raigmore, Inverness	10/2011	20/07/2010	10/2011/01	Closed - I	Blue	Liebherr-Great Britain Ltd	https://assets.publishing.service.gov.uk/media/56829d8eed915d144f00002c/10_2011_Raigmore_Inverness.pdf
Runaway and collision of a road-rail vehicle near Raigmore, Inverness	10/2011	20/07/2010	10/2011/02	Closed - I	None	Liebherr-Great Britain Ltd	https://assets.publishing.service.gov.uk/media/56829d8eed915d144f00002c/10_2011_Raigmore_Inverness.pdf

Runaway and collision of a road-rail vehicle near Raigmore, Inverness	10/2011	20/07/2010	10/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56829d8eed915d144f00002c/10_2011_Raigmore_Inverness.pdf
Runaway and collision of a road-rail vehicle near Raigmore, Inverness	10/2011	20/07/2010	10/2011/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56829d8eed915d144f00002c/10_2011_Raigmore_Inverness.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/01	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/02	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/03	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/04	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/05	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/05	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/06	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Runaway of an engineering train from Highgate	09/2011	13/08/2010	09/2011/07	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56829c50ed915d144c000024/09_2011_Highgate.pdf
Collision between train 1C84 and a tree at Lavington, Wiltshire	08/2011	10/07/2010	08/2011/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56829987ed915d144c000021/08_2011_Lavington_Wiltshire.pdf
Collision between train 1C84 and a tree at Lavington, Wiltshire	08/2011	10/07/2010	08/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56829987ed915d144c000021/08_2011_Lavington_Wiltshire.pdf
Collision between train 1C84 and a tree at Lavington, Wiltshire	08/2011	10/07/2010	08/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56829987ed915d144c000021/08_2011_Lavington_Wiltshire.pdf
Collision between train 1C84 and a tree at Lavington, Wiltshire	08/2011	10/07/2010	08/2011/04	Closed - I	None	First Great Western	https://assets.publishing.service.gov.uk/media/56829987ed915d144c000021/08_2011_Lavington_Wiltshire.pdf
Runaway and derailment of wagons at Ashburys	07/2011	04/05/2010	07/2011/01	Closed - NI	Red	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/568298e2ed915d144c00001f/07_2011_Ashburys.pdf

Runaway and derailment of wagons at Ashburys	07/2011	04/05/2010	07/2011/02	Closed - I	None	VTG	https://assets.publishing.service.gov.uk/media/568298e2ed915d144c00001f/07_2011_Ashburys.pdf
Runaway and derailment of wagons at Ashburys	07/2011	04/05/2010	07/2011/03	Closed - I	None	Operators, Maintainers & Owners of wagons fitted with	https://assets.publishing.service.gov.uk/media/568298e2ed915d144c00001f/07_2011_Ashburys.pdf
Runaway and derailment of wagons at Ashburys	07/2011	04/05/2010	07/2011/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/568298e2ed915d144c00001f/07_2011_Ashburys.pdf
Runaway and derailment of wagons at Ashburys	07/2011	04/05/2010	07/2011/05	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/568298e2ed915d144c00001f/07_2011_Ashburys.pdf
Runaway and derailment of wagons at Ashburys	07/2011	04/05/2010	07/2011/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/568298e2ed915d144c00001f/07_2011_Ashburys.pdf
Runaway and derailment of wagons at Ashburys	07/2011	04/05/2010	07/2011/06	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/568298e2ed915d144c00001f/07_2011_Ashburys.pdf
Track worker struck by a train at Cheshunt Junction	06/2011	30/03/2010	06/2011/01	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56828c27ed915d144f00002a/06_2011_Cheshunt_Junction.pdf
Track worker struck by a train at Cheshunt Junction	06/2011	30/03/2010	06/2011/02	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56828c27ed915d144f00002a/06_2011_Cheshunt_Junction.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/01	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/02	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/03	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/04	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/05	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/06	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/07	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/08	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf
Derailment of an engineering train between Gloucester Road and Earl's Court stations on London Underground	05/2011	12/05/2010	05/2011/09	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/568287d1ed915d144c00001a/05_2011_Gloucester_Road_and_Earl_s_Court.pdf

Fatal accident at Moreton-on-Lugg, near Hereford	04/2011	16/01/2010	04/2011/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567abfdb40f0b672b4000017/04_2011_Moreton-on-Lugg.pdf
Fatal accident at Moreton-on-Lugg, near Hereford	04/2011	16/01/2010	04/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567abfdb40f0b672b4000017/04_2011_Moreton-on-Lugg.pdf
Fatal accident at Moreton-on-Lugg, near Hereford	04/2011	16/01/2010	04/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567abfdb40f0b672b4000017/04_2011_Moreton-on-Lugg.pdf
Fatal accident at Moreton-on-Lugg, near Hereford	04/2011	16/01/2010	04/2011/04	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/567abfdb40f0b672b4000017/04_2011_Moreton-on-Lugg.pdf
Derailment of a freight train at Carrbridge, Badenoch and Strathspey	03/2011	04/01/2010	03/2011/01	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/567ab109e5274a1385000017/03_2011_Carrbridge_Badenoch_Strathspey.pdf
Derailment of a freight train at Carrbridge, Badenoch and Strathspey	03/2011	04/01/2010	03/2011/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/567ab109e5274a1385000017/03_2011_Carrbridge_Badenoch_Strathspey.pdf
Derailment of a freight train at Carrbridge, Badenoch and Strathspey	03/2011	04/01/2010	03/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567ab109e5274a1385000017/03_2011_Carrbridge_Badenoch_Strathspey.pdf
Derailment of a freight train at Carrbridge, Badenoch and Strathspey	03/2011	04/01/2010	03/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567ab109e5274a1385000017/03_2011_Carrbridge_Badenoch_Strathspey.pdf
Derailment of a freight train at Carrbridge, Badenoch and Strathspey	03/2011	04/01/2010	03/2011/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567ab109e5274a1385000017/03_2011_Carrbridge_Badenoch_Strathspey.pdf
Near miss involving a freight train and two passenger trains, Carstairs	02/2011	22/12/2009	02/2011/01	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/567aa51ce5274a1385000015/02_2011_Carstairs.pdf
Near miss involving a freight train and two passenger trains, Carstairs	02/2011	22/12/2009	02/2011/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/567aa51ce5274a1385000015/02_2011_Carstairs.pdf
Near miss involving a freight train and two passenger trains, Carstairs	02/2011	22/12/2009	02/2011/02	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/567aa51ce5274a1385000015/02_2011_Carstairs.pdf
Near miss involving a freight train and two passenger trains, Carstairs	02/2011	22/12/2009	02/2011/03	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/567aa51ce5274a1385000015/02_2011_Carstairs.pdf
Near miss involving a freight train and two passenger trains, Carstairs	02/2011	22/12/2009	02/2011/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/567aa51ce5274a1385000015/02_2011_Carstairs.pdf
Passenger train struck by object at Washwood Heath	01/2011	06/03/2010	01/2011/01	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/567aa44aed915d144c000014/01_2011_Washwood_Heath.pdf
Passenger train struck by object at Washwood Heath	01/2011	06/03/2010	01/2011/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567aa44aed915d144c000014/01_2011_Washwood_Heath.pdf
Passenger train struck by object at Washwood Heath	01/2011	06/03/2010	01/2011/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567aa44aed915d144c000014/01_2011_Washwood_Heath.pdf
Passenger train struck by object at Washwood Heath	01/2011	06/03/2010	01/2011/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567aa44aed915d144c000014/01_2011_Washwood_Heath.pdf
Incident at Romford station	20/2010	04/02/2010	20/2010/01	Closed - I	Blue	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/567a981ced915d144f000021/20_2010_Romford_station.pdf

Incident at Romford station	20/2010	04/02/2010	20/2010/02	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/567a981ced915d144f000021/20_2010_Romford_station.pdf
Incident at Romford station	20/2010	04/02/2010	20/2010/03	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/567a981ced915d144f000021/20_2010_Romford_station.pdf
Incident at Romford station	20/2010	04/02/2010	20/2010/04	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/567a981ced915d144f000021/20_2010_Romford_station.pdf
Incident at Romford station	20/2010	04/02/2010	20/2010/05	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/567a981ced915d144f000021/20_2010_Romford_station.pdf
Derailment near Gillingham tunnel, Dorset	19/2010	28/11/2009	19/2010/01	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/567a8e01e5274a138800001d/19_2010_Gillingham_tunnel_Dorset.pdf
Derailment near Gillingham tunnel, Dorset	19/2010	28/11/2009	19/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a8e01e5274a138800001d/19_2010_Gillingham_tunnel_Dorset.pdf
Derailment near Gillingham tunnel, Dorset	19/2010	28/11/2009	19/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a8e01e5274a138800001d/19_2010_Gillingham_tunnel_Dorset.pdf
Derailment near Gillingham tunnel, Dorset	19/2010	28/11/2009	19/2010/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a8e01e5274a138800001d/19_2010_Gillingham_tunnel_Dorset.pdf
Derailment near Gillingham tunnel, Dorset	19/2010	28/11/2009	19/2010/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a8e01e5274a138800001d/19_2010_Gillingham_tunnel_Dorset.pdf
Near-miss on Victory level crossing, near Taunton, Somerset	18/2010	19/12/2009	18/2010/01	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a8b18e5274a138800001b/18_2010_Victory_Level_Crossing_near_Taunton.pdf
Near-miss on Victory level crossing, near Taunton, Somerset	18/2010	19/12/2009	18/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a8b18e5274a138800001b/18_2010_Victory_Level_Crossing_near_Taunton.pdf
Near-miss on Victory level crossing, near Taunton, Somerset	18/2010	19/12/2009	18/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a8b18e5274a138800001b/18_2010_Victory_Level_Crossing_near_Taunton.pdf
Near-miss on Victory level crossing, near Taunton, Somerset	18/2010	19/12/2009	18/2010/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a8b18e5274a138800001b/18_2010_Victory_Level_Crossing_near_Taunton.pdf
Fatal accident at Halkirk level crossing, Caithness	16/2010	29/09/2009	16/2010/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a6ed5e5274a1388000017/16_2010_Halkirk_Caithness.pdf
Fatal accident at Halkirk level crossing, Caithness	16/2010	29/09/2009	16/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a6ed5e5274a1388000017/16_2010_Halkirk_Caithness.pdf
Fatal accident at Halkirk level crossing, Caithness	16/2010	29/09/2009	16/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a6ed5e5274a1388000017/16_2010_Halkirk_Caithness.pdf
Fatal accident at Halkirk level crossing, Caithness	16/2010	29/09/2009	16/2010/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a6ed5e5274a1388000017/16_2010_Halkirk_Caithness.pdf
Fatal accident at Halkirk level crossing, Caithness	16/2010	29/09/2009	16/2010/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a6ed5e5274a1388000017/16_2010_Halkirk_Caithness.pdf
Fatal accident at Halkirk level crossing, Caithness	16/2010	29/09/2009	16/2010/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a6ed5e5274a1388000017/16_2010_Halkirk_Caithness.pdf

Failure of Bridge RDG1 48 (River Crane) between Whitton and Feltham	17/2010	15/11/2009	17/2010/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a700640f0b61417000023/17_2010_Bridge_RDG1_48_Whitton_and_Feltham.pdf
Failure of Bridge RDG1 48 (River Crane) between Whitton and Feltham	17/2010	15/11/2009	17/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a700640f0b61417000023/17_2010_Bridge_RDG1_48_Whitton_and_Feltham.pdf
Failure of Bridge RDG1 48 (River Crane) between Whitton and Feltham	17/2010	15/11/2009	17/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a700640f0b61417000023/17_2010_Bridge_RDG1_48_Whitton_and_Feltham.pdf
Failure of Bridge RDG1 48 (River Crane) between Whitton and Feltham	17/2010	15/11/2009	17/2010/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a700640f0b61417000023/17_2010_Bridge_RDG1_48_Whitton_and_Feltham.pdf
Failure of Bridge RDG1 48 (River Crane) between Whitton and Feltham	17/2010	15/11/2009	17/2010/05	Closed - I	None	Environment Agency	https://assets.publishing.service.gov.uk/media/567a700640f0b61417000023/17_2010_Bridge_RDG1_48_Whitton_and_Feltham.pdf
Failure of Bridge RDG1 48 (River Crane) between Whitton and Feltham	17/2010	15/11/2009	17/2010/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a700640f0b61417000023/17_2010_Bridge_RDG1_48_Whitton_and_Feltham.pdf
Fatal accident at Whitehall West junction, Leeds	15/2010	02/12/2009	15/2010/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567a6d82ed915d144f00001e/15_2010_Whitehall_West_Junction.pdf
Fatal accident at Whitehall West junction, Leeds	15/2010	02/12/2009	15/2010/02	Closed - I	None	Ambulance Services	https://assets.publishing.service.gov.uk/media/567a6d82ed915d144f00001e/15_2010_Whitehall_West_Junction.pdf
Derailment at Wigan North Western station	14/2010	25/08/2009	14/2010/01	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/567974b140f0b61417000021/14_2010_Wigan_North_Western.pdf
Derailment at Wigan North Western station	14/2010	25/08/2009	14/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567974b140f0b61417000021/14_2010_Wigan_North_Western.pdf
Derailment at Wigan North Western station	14/2010	25/08/2009	14/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567974b140f0b61417000021/14_2010_Wigan_North_Western.pdf
Derailment at Wigan North Western station	14/2010	25/08/2009	14/2010/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567974b140f0b61417000021/14_2010_Wigan_North_Western.pdf
Collision on the Great Orme Tramway	13/2010	15/09/2009	13/2010/01	Closed - I	None	Conwy County Borough Council	https://assets.publishing.service.gov.uk/media/5679739740f0b672b4000010/13_2010_Great_Orme.pdf
Collision on the Great Orme Tramway	13/2010	15/09/2009	13/2010/02	Closed - I	None	Conwy County Borough Council	https://assets.publishing.service.gov.uk/media/5679739740f0b672b4000010/13_2010_Great_Orme.pdf
Derailment at Windsor and Eton Riverside station	11/2010	11/10/2009	11/2010/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567971b240f0b6141700001f/11_2010_Windsor_and_Eton.pdf
Derailment at Windsor and Eton Riverside station	11/2010	11/10/2009	11/2010/02	Closed - IA	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/567971b240f0b6141700001f/11_2010_Windsor_and_Eton.pdf
Derailment at Windsor and Eton Riverside station	11/2010	11/10/2009	11/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567971b240f0b6141700001f/11_2010_Windsor_and_Eton.pdf
Overhead line failure, St Pancras International	12/2010	23/09/2009	12/2010/01	Closed - I	None	Eurostar International Ltd	https://assets.publishing.service.gov.uk/media/56797286e5274a1388000013/12_2010_St_Pancras_International.pdf
Overhead line failure, St Pancras International	12/2010	23/09/2009	12/2010/02	Closed - I	None	ABB Power	https://assets.publishing.service.gov.uk/media/56797286e5274a1388000013/12_2010_St_Pancras_International.pdf

Overhead line failure, St Pancras International	12/2010	23/09/2009	12/2010/03	Closed - I	None	EDF Energy Services Limited (EDF)	https://assets.publishing.service.gov.uk/media/56797286e5274a13880000/13/12_2010_St_Pancras_International.pdf
Overhead line failure, St Pancras International	12/2010	23/09/2009	12/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56797286e5274a13880000/13/12_2010_St_Pancras_International.pdf
Overhead line failure, St Pancras International	12/2010	23/09/2009	12/2010/04	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56797286e5274a13880000/13/12_2010_St_Pancras_International.pdf
Overhead line failure, St Pancras International	12/2010	23/09/2009	12/2010/05	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56797286e5274a13880000/13/12_2010_St_Pancras_International.pdf
Overhead line failure, St Pancras International	12/2010	23/09/2009	12/2010/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56797286e5274a13880000/13/12_2010_St_Pancras_International.pdf
Overhead line failure, St Pancras International	12/2010	23/09/2009	12/2010/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56797286e5274a13880000/13/12_2010_St_Pancras_International.pdf
Collision at Exeter St Davids station	10/2010	04/01/2010	10/2010/01	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5679700d40f0b614170000/1d/10_2010_Exeter_St_Davids_station.pdf
Fatal accident at Norbreck, Blackpool	09/2010	05/08/2009	09/2010/01	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/56796ed2ed915d144f0000/1c/09_2010_Norbreck_Blackpool.pdf
Fatal accident at Norbreck, Blackpool	09/2010	05/08/2009	09/2010/02	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/56796ed2ed915d144f0000/1c/09_2010_Norbreck_Blackpool.pdf
Fatal accident at Fairfield crossing, Bedwyn	08/2010	06/05/2009	08/2010/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56796defe5274a13850000/0f/08_2010_Fairfield_crossing_Bedwyn.pdf
Fatal accident at Fairfield crossing, Bedwyn	08/2010	06/05/2009	08/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56796defe5274a13850000/0f/08_2010_Fairfield_crossing_Bedwyn.pdf
Fatal accident at Fairfield crossing, Bedwyn	08/2010	06/05/2009	08/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56796defe5274a13850000/0f/08_2010_Fairfield_crossing_Bedwyn.pdf
Derailment at Hampton Loade, Severn Valley Railway	07/2010	28/09/2009	07/2010/01	Closed - I	None	Severn Valley Railway	https://assets.publishing.service.gov.uk/media/56796c12e5274a13880000/11/07_2010_Hampton_Loade_Severn_Valley_Railway.pdf
Derailment at Hampton Loade, Severn Valley Railway	07/2010	28/09/2009	07/2010/02	Closed - I	None	Severn Valley Railway	https://assets.publishing.service.gov.uk/media/56796c12e5274a13880000/11/07_2010_Hampton_Loade_Severn_Valley_Railway.pdf
Derailment at Hampton Loade, Severn Valley Railway	07/2010	28/09/2009	07/2010/03	Closed - I	None	Severn Valley Railway	https://assets.publishing.service.gov.uk/media/56796c12e5274a13880000/11/07_2010_Hampton_Loade_Severn_Valley_Railway.pdf
Derailment at Hampton Loade, Severn Valley Railway	07/2010	28/09/2009	07/2010/04	Closed - I	None	Severn Valley Railway	https://assets.publishing.service.gov.uk/media/56796c12e5274a13880000/11/07_2010_Hampton_Loade_Severn_Valley_Railway.pdf
Derailment at Hampton Loade, Severn Valley Railway	07/2010	28/09/2009	07/2010/05	Closed - I	None	Severn Valley Railway	https://assets.publishing.service.gov.uk/media/56796c12e5274a13880000/11/07_2010_Hampton_Loade_Severn_Valley_Railway.pdf
Derailment of a passenger train near Cummersdale, Cumbria	06/2010	01/06/2009	06/2010/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56796905ed915d144f0000/1a/06_2010_Cummersdale.pdf
Derailment of a passenger train near Cummersdale, Cumbria	06/2010	01/06/2009	06/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56796905ed915d144f0000/1a/06_2010_Cummersdale.pdf

Derailment of a passenger train near Cummersdale, Cumbria	06/2010	01/06/2009	06/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56796905ed915d144f00001a/06_2010_Cummersdale.pdf
Derailment of a passenger train near Cummersdale, Cumbria	06/2010	01/06/2009	06/2010/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56796905ed915d144f00001a/06_2010_Cummersdale.pdf
Derailment of a passenger train near Cummersdale, Cumbria	06/2010	01/06/2009	06/2010/05	Closed - I	None	Northern Rail	https://assets.publishing.service.gov.uk/media/56796905ed915d144f00001a/06_2010_Cummersdale.pdf
Near-miss at Hanger Lane junction	05/2010	27/03/2009	05/2010/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5679655ce5274a138800000d/05_2010_Hanger_Lane.pdf
Near-miss at Hanger Lane junction	05/2010	27/03/2009	05/2010/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5679655ce5274a138800000d/05_2010_Hanger_Lane.pdf
Near-miss at Hanger Lane junction	05/2010	27/03/2009	05/2010/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5679655ce5274a138800000d/05_2010_Hanger_Lane.pdf
Near-miss at Hanger Lane junction	05/2010	27/03/2009	05/2010/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5679655ce5274a138800000d/05_2010_Hanger_Lane.pdf
Near-miss at Hanger Lane junction	05/2010	27/03/2009	05/2010/05	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5679655ce5274a138800000d/05_2010_Hanger_Lane.pdf
Near-miss at Hanger Lane junction	05/2010	27/03/2009	05/2010/06	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5679655ce5274a138800000d/05_2010_Hanger_Lane.pdf
Incident at Greenhill Upper Junction, near Falkirk	04/2010	22/03/2009	04/2010/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567962faed915d144f000017/04_2010_Greenhill_Upper_Junction.pdf
Incident at Greenhill Upper Junction, near Falkirk	04/2010	22/03/2009	04/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567962faed915d144f000017/04_2010_Greenhill_Upper_Junction.pdf
Incident at Greenhill Upper Junction, near Falkirk	04/2010	22/03/2009	04/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567962faed915d144f000017/04_2010_Greenhill_Upper_Junction.pdf
Incident at Greenhill Upper Junction, near Falkirk	04/2010	22/03/2009	04/2010/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567962faed915d144f000017/04_2010_Greenhill_Upper_Junction.pdf
Incident at Greenhill Upper Junction, near Falkirk	04/2010	22/03/2009	04/2010/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567962faed915d144f000017/04_2010_Greenhill_Upper_Junction.pdf
Incident at Greenhill Upper Junction, near Falkirk	04/2010	22/03/2009	04/2010/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567962faed915d144f000017/04_2010_Greenhill_Upper_Junction.pdf
Derailment of a Docklands Light Railway train near West India Quay station, London	03/2010	10/03/2009	03/2010/01	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/56795ff2e5274a138800000b/03_2010_West_India_Quay.pdf
Derailment of a Docklands Light Railway train near West India Quay station, London	03/2010	10/03/2009	03/2010/02	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/56795ff2e5274a138800000b/03_2010_West_India_Quay.pdf
Derailment of a Docklands Light Railway train near West India Quay station, London	03/2010	10/03/2009	03/2010/03	Closed - I	None	Serco Docklands	https://assets.publishing.service.gov.uk/media/56795ff2e5274a138800000b/03_2010_West_India_Quay.pdf
Derailment of a Docklands Light Railway train near West India Quay station, London	03/2010	10/03/2009	03/2010/04	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/56795ff2e5274a138800000b/03_2010_West_India_Quay.pdf

Derailment of a Docklands Light Railway train near West India Quay station, London	03/2010	10/03/2009	03/2010/05	Closed - I	None	Serco Docklands	https://assets.publishing.service.gov.uk/media/56795ff2e5274a138800000b/03_2010_West_India_Quay.pdf
Derailment of a Docklands Light Railway train near West India Quay station, London	03/2010	10/03/2009	03/2010/06	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/56795ff2e5274a138800000b/03_2010_West_India_Quay.pdf
Derailment of a Docklands Light Railway train near West India Quay station, London	03/2010	10/03/2009	03/2010/07	Closed - I	None	Serco Docklands	https://assets.publishing.service.gov.uk/media/56795ff2e5274a138800000b/03_2010_West_India_Quay.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/10	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/11	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/11	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/11	Closed - I	None	Private Wagon Groups (inc PWRA)	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train near Stewarton, Ayrshire	02/2010	27/01/2009	02/2010/12	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/56795edeed915d144f000015/02_2010_Stewarton.pdf
Derailment of a freight train at Marks Tey, Essex	01/2010	12/06/2008	01/2010/01	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/56795d1ee5274a138500000c/01_2010_Marks_Tey.pdf
Derailment of a freight train at Marks Tey, Essex	01/2010	12/06/2008	01/2010/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795d1ee5274a138500000c/01_2010_Marks_Tey.pdf

Derailment of a freight train at Marks Tey, Essex	01/2010	12/06/2008	01/2010/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795d1ee5274a13850000/0c/01_2010_Marks_Tey.pdf
Derailment of a freight train at Marks Tey, Essex	01/2010	12/06/2008	01/2010/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795d1ee5274a13850000/0c/01_2010_Marks_Tey.pdf
Derailment of a freight train at Marks Tey, Essex	01/2010	12/06/2008	01/2010/05	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795d1ee5274a13850000/0c/01_2010_Marks_Tey.pdf
Derailment of a freight train at Marks Tey, Essex	01/2010	12/06/2008	01/2010/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56795d1ee5274a13850000/0c/01_2010_Marks_Tey.pdf
Derailment of a freight train at Marks Tey, Essex	01/2010	12/06/2008	01/2010/07	Closed - IA	White	Network Rail	https://assets.publishing.service.gov.uk/media/56795d1ee5274a13850000/0c/01_2010_Marks_Tey.pdf
Collision and derailment of a passenger train at North Rode, between Macclesfield and Congleton,	33/2009	18/12/2008	33/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679327bed915d144c0000/0d/33_2009_North_Rode.pdf
Collision and derailment of a passenger train at North Rode, between Macclesfield and Congleton,	33/2009	18/12/2008	33/2009/02	Closed - I	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/5679327bed915d144c0000/0d/33_2009_North_Rode.pdf
Collision and derailment of a passenger train at North Rode, between Macclesfield and Congleton,	33/2009	18/12/2008	33/2009/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679327bed915d144c0000/0d/33_2009_North_Rode.pdf
Accident at Dalston Junction	30/2009	30/03/2009	30/2009/01	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/56792d5440f0b614170000/18/30_2009_Dalston_Junction.pdf
Accident at Dalston Junction	30/2009	30/03/2009	30/2009/02	Closed - I	Blue	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/56792d5440f0b614170000/18/30_2009_Dalston_Junction.pdf
Accident at Dalston Junction	30/2009	30/03/2009	30/2009/03	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/56792d5440f0b614170000/18/30_2009_Dalston_Junction.pdf
Container doors hit passenger trains, Penrith Station and Eden Valley Loop, Cumbria	31/2009	04/07/2009	31/2009/01	Closed - I	Blue	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/56792f0fed915d144c00000b/31_2009_Penrith_and_Eden_Valley.pdf
Container doors hit passenger trains, Penrith Station and Eden Valley Loop, Cumbria	31/2009	04/07/2009	31/2009/01	Closed - I	Blue	Direct Rail Services	https://assets.publishing.service.gov.uk/media/56792f0fed915d144c00000b/31_2009_Penrith_and_Eden_Valley.pdf
Container doors hit passenger trains, Penrith Station and Eden Valley Loop, Cumbria	31/2009	04/07/2009	31/2009/02	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/56792f0fed915d144c00000b/31_2009_Penrith_and_Eden_Valley.pdf
Container doors hit passenger trains, Penrith Station and Eden Valley Loop, Cumbria	31/2009	04/07/2009	31/2009/03	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/56792f0fed915d144c00000b/31_2009_Penrith_and_Eden_Valley.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56793149e5274a1388000006/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/01	Closed - I	None	Nottingham Express Transit	https://assets.publishing.service.gov.uk/media/56793149e5274a1388000006/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56793149e5274a1388000006/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/02	Closed - I	None	Nottinghamshire County Council	https://assets.publishing.service.gov.uk/media/56793149e5274a1388000006/32_2009_Bayles_and_Wylies_Bestwood.pdf

Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/03	Closed - I	Red	Network Rail	https://assets.publishing.service.gov.uk/media/56793149e5274a13880000/06/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/03	Closed - I	Red	Nottingham Express Transit	https://assets.publishing.service.gov.uk/media/56793149e5274a13880000/06/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56793149e5274a13880000/06/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56793149e5274a13880000/06/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56793149e5274a13880000/06/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/07	Closed - I	Blue	RSSB	https://assets.publishing.service.gov.uk/media/56793149e5274a13880000/06/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56793149e5274a13880000/06/32_2009_Bayles_and_Wylies_Bestwood.pdf
Double fatality at Bayles & Wylies footpath crossing, Bestwood, Nottingham	32/2009	22/11/2008	32/2009/08	Closed - I	None	NEXUS	https://assets.publishing.service.gov.uk/media/56793149e5274a13880000/06/32_2009_Bayles_and_Wylies_Bestwood.pdf
Serious injury sustained by a signal technician at Kennington Junction	29/2009	23/05/2008	29/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679274640f0b672b40000/0a/29_2009_Kennington_Junction.pdf
Serious injury sustained by a signal technician at Kennington Junction	29/2009	23/05/2008	29/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679274640f0b672b40000/0a/29_2009_Kennington_Junction.pdf
Serious injury sustained by a signal technician at Kennington Junction	29/2009	23/05/2008	29/2009/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679274640f0b672b40000/0a/29_2009_Kennington_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b614170000/16/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b614170000/16/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/03	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b614170000/16/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/04	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b614170000/16/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b614170000/16/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/05	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5679262640f0b614170000/16/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b614170000/16/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b614170000/16/28_2009_East_Somerset_Junction.pdf

Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b61417000016/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b61417000016/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/10	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b61417000016/28_2009_East_Somerset_Junction.pdf
Derailment of two locomotives at East Somerset Junction	28/2009	10/11/2008	28/2009/11	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679262640f0b61417000016/28_2009_East_Somerset_Junction.pdf
Investigation into runaways of road-rail vehicles and their trailers on Network Rail	27/2009	23/05/2008	27/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679252eed915d144f00000f/27_2009_Investigation_into_runaways_of_RRV_and_trailers.pdf
Investigation into runaways of road-rail vehicles and their trailers on Network Rail	27/2009	23/05/2008	27/2009/02	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/5679252eed915d144f00000f/27_2009_Investigation_into_runaways_of_RRV_and_trailers.pdf
Investigation into runaways of road-rail vehicles and their trailers on Network Rail	27/2009	23/05/2008	27/2009/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679252eed915d144f00000f/27_2009_Investigation_into_runaways_of_RRV_and_trailers.pdf
Fatal accident at Wraysholme crossing, Flookburgh, Cumbria	26/2009	03/11/2008	26/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679239940f0b672b4000006/26_2009_Wraysholme.pdf
Fatal accident at Wraysholme crossing, Flookburgh, Cumbria	26/2009	03/11/2008	26/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679239940f0b672b4000006/26_2009_Wraysholme.pdf
Fatal accident at Wraysholme crossing, Flookburgh, Cumbria	26/2009	03/11/2008	26/2009/03	Closed - I	None	Cumbria County Council	https://assets.publishing.service.gov.uk/media/5679239940f0b672b4000006/26_2009_Wraysholme.pdf
Fatal accident at Wraysholme crossing, Flookburgh, Cumbria	26/2009	03/11/2008	26/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5679239940f0b672b4000006/26_2009_Wraysholme.pdf
Fatal accident at Wraysholme crossing, Flookburgh, Cumbria	26/2009	03/11/2008	26/2009/05	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5679239940f0b672b4000006/26_2009_Wraysholme.pdf
Derailment at St Peter's Square, Manchester	25/2009	29/06/2008	25/2009/01	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/567921abed915d144c000009/25_2009_St_Peters_Square_Manchester.pdf
Derailment at St Peter's Square, Manchester	25/2009	29/06/2008	25/2009/01	Closed - I	None	Stagecoach Metrolink	https://assets.publishing.service.gov.uk/media/567921abed915d144c000009/25_2009_St_Peters_Square_Manchester.pdf
Derailment at St Peter's Square, Manchester	25/2009	29/06/2008	25/2009/02	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/567921abed915d144c000009/25_2009_St_Peters_Square_Manchester.pdf
Derailment at St Peter's Square, Manchester	25/2009	29/06/2008	25/2009/03	Closed - I	None	Stagecoach Metrolink	https://assets.publishing.service.gov.uk/media/567921abed915d144c000009/25_2009_St_Peters_Square_Manchester.pdf
Derailment at St Peter's Square, Manchester	25/2009	29/06/2008	25/2009/04	Closed - I	None	Stagecoach Metrolink	https://assets.publishing.service.gov.uk/media/567921abed915d144c000009/25_2009_St_Peters_Square_Manchester.pdf
Derailment at St Peter's Square, Manchester	25/2009	29/06/2008	25/2009/05	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/567921abed915d144c000009/25_2009_St_Peters_Square_Manchester.pdf
Freight train collision at Leigh-on-Sea	24/2009	26/04/2008	24/2009/01	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/56791f1fed915d144c000007/24_2009_Leigh-on-Sea.pdf

Freight train collision at Leigh-on-Sea	24/2009	26/04/2008	24/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56791f1fed915d144c00000/7/24_2009_Leigh-on-Sea.pdf
Freight train collision at Leigh-on-Sea	24/2009	26/04/2008	24/2009/03	Open	None	Network Rail	https://assets.publishing.service.gov.uk/media/56791f1fed915d144c00000/7/24_2009_Leigh-on-Sea.pdf
Freight train collision at Leigh-on-Sea	24/2009	26/04/2008	24/2009/04	Closed - I	None	Balfour Beatty	https://assets.publishing.service.gov.uk/media/56791f1fed915d144c00000/7/24_2009_Leigh-on-Sea.pdf
Freight train collision at Leigh-on-Sea	24/2009	26/04/2008	24/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56791f1fed915d144c00000/7/24_2009_Leigh-on-Sea.pdf
Freight train collision at Leigh-on-Sea	24/2009	26/04/2008	24/2009/06	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56791f1fed915d144c00000/7/24_2009_Leigh-on-Sea.pdf
Freight train collision at Leigh-on-Sea	24/2009	26/04/2008	24/2009/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56791f1fed915d144c00000/7/24_2009_Leigh-on-Sea.pdf
Trackworker struck by train, Stevenage	23/2009	07/12/2008	23/2009/01	Closed - I	None	Jarvis Rail Limited	https://assets.publishing.service.gov.uk/media/567919eed915d144c00000/05/23_2009_Stevenage.pdf
Trackworker struck by train, Stevenage	23/2009	07/12/2008	23/2009/02	Closed - I	None	Jarvis Rail Limited	https://assets.publishing.service.gov.uk/media/567919eed915d144c00000/05/23_2009_Stevenage.pdf
Trackworker struck by train, Stevenage	23/2009	07/12/2008	23/2009/03	Closed - I	None	Jarvis Rail Limited	https://assets.publishing.service.gov.uk/media/567919eed915d144c00000/05/23_2009_Stevenage.pdf
Trackworker struck by train, Stevenage	23/2009	07/12/2008	23/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567919eed915d144c00000/05/23_2009_Stevenage.pdf
Trackworker struck by train, Stevenage	23/2009	07/12/2008	23/2009/05	Closed - I	None	Jarvis Rail Limited	https://assets.publishing.service.gov.uk/media/567919eed915d144c00000/05/23_2009_Stevenage.pdf
Trackworker struck by train, Stevenage	23/2009	07/12/2008	23/2009/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567919eed915d144c00000/05/23_2009_Stevenage.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567918e240f0b614170000/14/22_2009_London_Liverpool_Street.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/02	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/567918e240f0b614170000/14/22_2009_London_Liverpool_Street.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/02	Closed - I	None	Light Rail Engineering Group	https://assets.publishing.service.gov.uk/media/567918e240f0b614170000/14/22_2009_London_Liverpool_Street.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/567918e240f0b614170000/14/22_2009_London_Liverpool_Street.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/02	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/567918e240f0b614170000/14/22_2009_London_Liverpool_Street.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/02	Closed - I	None	Rail for London	https://assets.publishing.service.gov.uk/media/567918e240f0b614170000/14/22_2009_London_Liverpool_Street.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567918e240f0b614170000/14/22_2009_London_Liverpool_Street.pdf

Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/04	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/567918e240f0b61417000014/22_2009_London_Liverpool_Street.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567918e240f0b61417000014/22_2009_London_Liverpool_Street.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/06	Open	None	Health and Safety Executive	https://assets.publishing.service.gov.uk/media/567918e240f0b61417000014/22_2009_London_Liverpool_Street.pdf
Collision with debris from bridge GE19 near London Liverpool Street	22/2009	28/05/2008	22/2009/07	Closed - I	None	National Express East Anglia	https://assets.publishing.service.gov.uk/media/567918e240f0b61417000014/22_2009_London_Liverpool_Street.pdf
Incident involving a container train at Basingstoke station	21/2009	19/12/2008	21/2009/01	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/56791662ed915d144f00000a/21_2009_Basingstoke.pdf
Incident involving a container train at Basingstoke station	21/2009	19/12/2008	21/2009/02	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/56791662ed915d144f00000a/21_2009_Basingstoke.pdf
Incident involving a container train at Basingstoke station	21/2009	19/12/2008	21/2009/03	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/56791662ed915d144f00000a/21_2009_Basingstoke.pdf
Near miss at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	20/2009	21/10/2008	20/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567913f440f0b61417000012/20_2009_Llanbadarn.pdf
Near miss at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	20/2009	21/10/2008	20/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567913f440f0b61417000012/20_2009_Llanbadarn.pdf
Near miss at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	20/2009	21/10/2008	20/2009/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/567913f440f0b61417000012/20_2009_Llanbadarn.pdf
Near miss at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	20/2009	21/10/2008	20/2009/04	Closed - I	None	Arriva Trains Wales	https://assets.publishing.service.gov.uk/media/567913f440f0b61417000012/20_2009_Llanbadarn.pdf
Near miss at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	20/2009	21/10/2008	20/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567913f440f0b61417000012/20_2009_Llanbadarn.pdf
Near miss at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	20/2009	21/10/2008	20/2009/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567913f440f0b61417000012/20_2009_Llanbadarn.pdf
Near miss at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	20/2009	21/10/2008	20/2009/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567913f440f0b61417000012/20_2009_Llanbadarn.pdf
Near miss at Llanbadarn Automatic Barrier Crossing (Locally Monitored), near Aberystwyth	20/2009	21/10/2008	20/2009/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567913f440f0b61417000012/20_2009_Llanbadarn.pdf
Track worker struck by a train on Grosvenor Bridge, London Victoria	19/2009	13/11/2007	19/2009/01	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/56790efa40f0b6141700000f/19_2009_Grosvenor_Bridge.pdf
Track worker struck by a train on Grosvenor Bridge, London Victoria	19/2009	13/11/2007	19/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56790efa40f0b6141700000f/19_2009_Grosvenor_Bridge.pdf
Track worker struck by a train on Grosvenor Bridge, London Victoria	19/2009	13/11/2007	19/2009/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56790efa40f0b6141700000f/19_2009_Grosvenor_Bridge.pdf
Track worker struck by a train on Grosvenor Bridge, London Victoria	19/2009	13/11/2007	19/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56790efa40f0b6141700000f/19_2009_Grosvenor_Bridge.pdf

Track worker struck by a train on Grosvenor Bridge, London Victoria	19/2009	13/11/2007	19/2009/05	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/56790efa40f0b6141700000f/19_2009_Grosvenor_Bridge.pdf
Track worker struck by a train on Grosvenor Bridge, London Victoria	19/2009	13/11/2007	19/2009/06	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/56790efa40f0b6141700000f/19_2009_Grosvenor_Bridge.pdf
Track worker struck by a train on Grosvenor Bridge, London Victoria	19/2009	13/11/2007	19/2009/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56790efa40f0b6141700000f/19_2009_Grosvenor_Bridge.pdf
Track worker struck by a train on Grosvenor Bridge, London Victoria	19/2009	13/11/2007	19/2009/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56790efa40f0b6141700000f/19_2009_Grosvenor_Bridge.pdf
Track worker struck by a train on Grosvenor Bridge, London Victoria	19/2009	13/11/2007	19/2009/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56790efa40f0b6141700000f/19_2009_Grosvenor_Bridge.pdf
Derailment of a passenger train at Gysgfa, Ffestiniog Railway	18/2009	03/05/2008	18/2009/01	Closed - I	None	Ffestiniog & Welsh Highland Railways	https://assets.publishing.service.gov.uk/media/567822a9e5274a138800002/18_2009_Gysgfa.pdf
Derailment of a passenger train at Gysgfa, Ffestiniog Railway	18/2009	03/05/2008	18/2009/02	Closed - I	None	Ffestiniog & Welsh Highland Railways	https://assets.publishing.service.gov.uk/media/567822a9e5274a138800002/18_2009_Gysgfa.pdf
Derailment of a passenger train at Gysgfa, Ffestiniog Railway	18/2009	03/05/2008	18/2009/03	Closed - I	None	Ffestiniog & Welsh Highland Railways	https://assets.publishing.service.gov.uk/media/567822a9e5274a138800002/18_2009_Gysgfa.pdf
Derailment of a passenger train at Gysgfa, Ffestiniog Railway	18/2009	03/05/2008	18/2009/04	Closed - I	None	Ffestiniog & Welsh Highland Railways	https://assets.publishing.service.gov.uk/media/567822a9e5274a138800002/18_2009_Gysgfa.pdf
Derailment of a passenger train at Gysgfa, Ffestiniog Railway	18/2009	03/05/2008	18/2009/05	Closed - I	None	Ffestiniog & Welsh Highland Railways	https://assets.publishing.service.gov.uk/media/567822a9e5274a138800002/18_2009_Gysgfa.pdf
Collision near New Southgate	17/2009	27/07/2008	17/2009/01	Closed - I	None	HST Operators	https://assets.publishing.service.gov.uk/media/5678200740f0b6141700000c/17_2009_New_Southgate.pdf
Collision near New Southgate	17/2009	27/07/2008	17/2009/01	Closed - I	None	HST Owners	https://assets.publishing.service.gov.uk/media/5678200740f0b6141700000c/17_2009_New_Southgate.pdf
Collision near New Southgate	17/2009	27/07/2008	17/2009/01	Closed - I	None	National Express East Coast	https://assets.publishing.service.gov.uk/media/5678200740f0b6141700000c/17_2009_New_Southgate.pdf
Collision near New Southgate	17/2009	27/07/2008	17/2009/02	Closed - I	None	HST Operators	https://assets.publishing.service.gov.uk/media/5678200740f0b6141700000c/17_2009_New_Southgate.pdf
Collision near New Southgate	17/2009	27/07/2008	17/2009/02	Closed - I	None	HST Owners	https://assets.publishing.service.gov.uk/media/5678200740f0b6141700000c/17_2009_New_Southgate.pdf
Collision near New Southgate	17/2009	27/07/2008	17/2009/03	Closed - I	None	National Express East Coast	https://assets.publishing.service.gov.uk/media/5678200740f0b6141700000c/17_2009_New_Southgate.pdf
Collision near New Southgate	17/2009	27/07/2008	17/2009/04	Closed - I	None	National Express East Coast	https://assets.publishing.service.gov.uk/media/5678200740f0b6141700000c/17_2009_New_Southgate.pdf
Collision near New Southgate	17/2009	27/07/2008	17/2009/05	Closed - I	None	HST Operators	https://assets.publishing.service.gov.uk/media/5678200740f0b6141700000c/17_2009_New_Southgate.pdf
Collision near New Southgate	17/2009	27/07/2008	17/2009/05	Closed - I	None	HST Owners	https://assets.publishing.service.gov.uk/media/5678200740f0b6141700000c/17_2009_New_Southgate.pdf

Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/01	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/02	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/03	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/03	Closed - I	None	Serco Docklands	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/04	Closed - I	None	Serco Docklands	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/05	Closed - I	None	Serco Docklands	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/06	Closed - I	None	Serco Docklands	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/07	Closed - I	None	Serco Docklands	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/08	Closed - I	None	Serco Docklands	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/09	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/10	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Derailment of a Docklands Light Railway train, near Deptford Bridge station, London	16/2009	04/04/2008	16/2009/11	Closed - I	None	Docklands Light Railway Ltd	https://assets.publishing.service.gov.uk/media/56781e35ed915d144c000003/16_2009_Deptford_Bridge.pdf
Collision between a passenger train and two rail-mounted grinding machines at Acton West	15/2009	24/06/2008	15/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781d6740f0b6141700000a/15_2009_Acton_West.pdf
Collision between a passenger train and two rail-mounted grinding machines at Acton West	15/2009	24/06/2008	15/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781d6740f0b6141700000a/15_2009_Acton_West.pdf
Collision between a passenger train and two rail-mounted grinding machines at Acton West	15/2009	24/06/2008	15/2009/03	Superseded	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781d6740f0b6141700000a/15_2009_Acton_West.pdf
Collision between a passenger train and two rail-mounted grinding machines at Acton West	15/2009	24/06/2008	15/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781d6740f0b6141700000a/15_2009_Acton_West.pdf
Collision between a passenger train and two rail-mounted grinding machines at Acton West	15/2009	24/06/2008	15/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781d6740f0b6141700000a/15_2009_Acton_West.pdf
Collision between a passenger train and two rail-mounted grinding machines at Acton West	15/2009	24/06/2008	15/2009/06	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781d6740f0b6141700000a/15_2009_Acton_West.pdf
Collision between a passenger train and two rail-mounted grinding machines at Acton West	15/2009	24/06/2008	15/2009/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781d6740f0b6141700000a/15_2009_Acton_West.pdf

Collision between a passenger train and two rail-mounted grinding machines at Acton West	15/2009	24/06/2008	15/2009/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781d6740f0b6141700000a/15_2009_Acton_West.pdf
Near miss at Poplar Farm level crossing, Attleborough, Norfolk	14/2009	01/07/2008	14/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781b5f40f0b61417000007/14_2009_Poplar_Farm.pdf
Near miss at Poplar Farm level crossing, Attleborough, Norfolk	14/2009	01/07/2008	14/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56781b5f40f0b61417000007/14_2009_Poplar_Farm.pdf
Investigation into safety at user worked crossings	13/2009	13/06/2008	13/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567817b840f0b61417000004/13_2009_Investigation_into_UWC.pdf
Investigation into safety at user worked crossings	13/2009	13/06/2008	13/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567817b840f0b61417000004/13_2009_Investigation_into_UWC.pdf
Investigation into safety at user worked crossings	13/2009	13/06/2008	13/2009/03	Closed - NI	Red	Network Rail	https://assets.publishing.service.gov.uk/media/567817b840f0b61417000004/13_2009_Investigation_into_UWC.pdf
Investigation into safety at user worked crossings	13/2009	13/06/2008	13/2009/04	Closed - NI	Red	Network Rail	https://assets.publishing.service.gov.uk/media/567817b840f0b61417000004/13_2009_Investigation_into_UWC.pdf
Investigation into safety at user worked crossings	13/2009	13/06/2008	13/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567817b840f0b61417000004/13_2009_Investigation_into_UWC.pdf
Investigation into safety at user worked crossings	13/2009	13/06/2008	13/2009/06	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/567817b840f0b61417000004/13_2009_Investigation_into_UWC.pdf
Investigation into safety at user worked crossings	13/2009	13/06/2008	13/2009/07	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/567817b840f0b61417000004/13_2009_Investigation_into_UWC.pdf
Investigation into safety at user worked crossings	13/2009	13/06/2008	13/2009/08	Open	None	Department for Transport	https://assets.publishing.service.gov.uk/media/567817b840f0b61417000004/13_2009_Investigation_into_UWC.pdf
Road-rail vehicle runaway incidents at Brentwood, Essex and at Birmingham Snow Hill	11/2009	04/11/2007	11/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56780d3a40f0b61417000002/11_2009_Snow_Hill_Brentwood.pdf
Road-rail vehicle runaway incidents at Brentwood, Essex and at Birmingham Snow Hill	11/2009	04/11/2007	11/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56780d3a40f0b61417000002/11_2009_Snow_Hill_Brentwood.pdf
Road-rail vehicle runaway incidents at Brentwood, Essex and at Birmingham Snow Hill	11/2009	04/11/2007	11/2009/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56780d3a40f0b61417000002/11_2009_Snow_Hill_Brentwood.pdf
Road-rail vehicle runaway incidents at Brentwood, Essex and at Birmingham Snow Hill	11/2009	04/11/2007	11/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56780d3a40f0b61417000002/11_2009_Snow_Hill_Brentwood.pdf
Road-rail vehicle runaway incidents at Brentwood, Essex and at Birmingham Snow Hill	11/2009	04/11/2007	11/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56780d3a40f0b61417000002/11_2009_Snow_Hill_Brentwood.pdf
Road-rail vehicle runaway incidents at Brentwood, Essex and at Birmingham Snow Hill	11/2009	04/11/2007	11/2009/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56780d3a40f0b61417000002/11_2009_Snow_Hill_Brentwood.pdf
Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/01	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5678141ce5274a1385000005/12_2009_Hardendale_Cheddington.pdf
Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/02	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5678141ce5274a1385000005/12_2009_Hardendale_Cheddington.pdf

Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/03	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5678141ce5274a13850000/05/12_2009_Hardendale_Cheddington.pdf
Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/04	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5678141ce5274a13850000/05/12_2009_Hardendale_Cheddington.pdf
Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/05	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5678141ce5274a13850000/05/12_2009_Hardendale_Cheddington.pdf
Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/06	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5678141ce5274a13850000/05/12_2009_Hardendale_Cheddington.pdf
Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/07	Closed - I	Blue	RSSB	https://assets.publishing.service.gov.uk/media/5678141ce5274a13850000/05/12_2009_Hardendale_Cheddington.pdf
Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5678141ce5274a13850000/05/12_2009_Hardendale_Cheddington.pdf
Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/09	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5678141ce5274a13850000/05/12_2009_Hardendale_Cheddington.pdf
Detachment of containers from freight wagons near Cheddington and Hardendale	12/2009	01/03/2008	12/2009/10	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5678141ce5274a13850000/05/12_2009_Hardendale_Cheddington.pdf
Derailment at Santon near Foreign Ore Branch Junction, Scunthorpe	10/2009	25/01/2008	10/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567804ffed915d144f00000/4/10_2009_Santon_Foreign_Ore.pdf
Derailment at Santon near Foreign Ore Branch Junction, Scunthorpe	10/2009	25/01/2008	10/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567804ffed915d144f00000/4/10_2009_Santon_Foreign_Ore.pdf
Derailment at Santon near Foreign Ore Branch Junction, Scunthorpe	10/2009	25/01/2008	10/2009/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567804ffed915d144f00000/4/10_2009_Santon_Foreign_Ore.pdf
Derailment at Santon near Foreign Ore Branch Junction, Scunthorpe	10/2009	25/01/2008	10/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567804ffed915d144f00000/4/10_2009_Santon_Foreign_Ore.pdf
Derailment at Santon near Foreign Ore Branch Junction, Scunthorpe	10/2009	25/01/2008	10/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567804ffed915d144f00000/4/10_2009_Santon_Foreign_Ore.pdf
Derailment at Santon near Foreign Ore Branch Junction, Scunthorpe	10/2009	25/01/2008	10/2009/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567804ffed915d144f00000/4/10_2009_Santon_Foreign_Ore.pdf
Derailment at Santon near Foreign Ore Branch Junction, Scunthorpe	10/2009	25/01/2008	10/2009/07	Closed - I	White	Network Rail	https://assets.publishing.service.gov.uk/media/567804ffed915d144f00000/4/10_2009_Santon_Foreign_Ore.pdf
Derailment at Santon near Foreign Ore Branch Junction, Scunthorpe	10/2009	25/01/2008	10/2009/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567804ffed915d144f00000/4/10_2009_Santon_Foreign_Ore.pdf
Derailment at Santon near Foreign Ore Branch Junction, Scunthorpe	10/2009	25/01/2008	10/2009/09	Closed - NI	Red	Freightliner Group	https://assets.publishing.service.gov.uk/media/567804ffed915d144f00000/4/10_2009_Santon_Foreign_Ore.pdf
Fatal accident at Tackley station level crossing, Oxfordshire	09/2009	31/03/2008	09/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56742d18e5274a12c00000/19/09_2009_Tackley_station.pdf
Fatal accident at Tackley station level crossing, Oxfordshire	09/2009	31/03/2008	09/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56742d18e5274a12c00000/19/09_2009_Tackley_station.pdf

Fatal accident at Tackley station level crossing, Oxfordshire	09/2009	31/03/2008	09/2009/03	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/56742d18e5274a12c00000/19/09_2009_Tackley_station.pdf
Fatal accident at Tackley station level crossing, Oxfordshire	09/2009	31/03/2008	09/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56742d18e5274a12c00000/19/09_2009_Tackley_station.pdf
Fatal accident at Tackley station level crossing, Oxfordshire	09/2009	31/03/2008	09/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56742d18e5274a12c00000/19/09_2009_Tackley_station.pdf
Fatal accident at Tackley station level crossing, Oxfordshire	09/2009	31/03/2008	09/2009/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56742d18e5274a12c00000/19/09_2009_Tackley_station.pdf
Uncontrolled movement of a road vehicle in a Channel Tunnel passenger shuttle train in transit from the UK to France	08/2008	04/04/2008	08/2009/01	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/5674275f40f0b6104500000/4/08_2009_Channel_Tunnel.pdf
Uncontrolled movement of a road vehicle in a Channel Tunnel passenger shuttle train in transit from the UK to France	08/2008	04/04/2008	08/2009/02	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/5674275f40f0b6104500000/4/08_2009_Channel_Tunnel.pdf
Uncontrolled movement of a road vehicle in a Channel Tunnel passenger shuttle train in transit from the UK to France	08/2008	04/04/2008	08/2009/03	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/5674275f40f0b6104500000/4/08_2009_Channel_Tunnel.pdf
Derailment of a freight train near Moor Street station, Birmingham	07/2009	25/03/2008	07/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5674257a40f0b6472f00001/2/07_2009_Moor_Street.pdf
Derailment of a freight train near Moor Street station, Birmingham	07/2009	25/03/2008	07/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5674257a40f0b6472f00001/2/07_2009_Moor_Street.pdf
Derailment of a freight train near Moor Street station, Birmingham	07/2009	25/03/2008	07/2009/03	Closed - I	None	DB Cargo (UK) Ltd	https://assets.publishing.service.gov.uk/media/5674257a40f0b6472f00001/2/07_2009_Moor_Street.pdf
Fatal accident at Morden Hall Park footpath crossing	06/2009	13/09/2008	06/2009/01	Closed - I	None	Tramtrack Croydon Ltd	https://assets.publishing.service.gov.uk/media/5671961c40f0b647320000/05/06_2009_Morden_Hall_Park.pdf
Runaway of a road-rail vehicle at Glen Garry	05/2009	05/12/2007	05/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5671942840f0b6472f00000/f/05_2009_Glen_Garry.pdf
Runaway of a road-rail vehicle at Glen Garry	05/2009	05/12/2007	05/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5671942840f0b6472f00000/f/05_2009_Glen_Garry.pdf
Runaway of a road-rail vehicle at Glen Garry	05/2009	05/12/2007	05/2009/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5671942840f0b6472f00000/f/05_2009_Glen_Garry.pdf
Runaway of a road-rail vehicle at Glen Garry	05/2009	05/12/2007	05/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5671942840f0b6472f00000/f/05_2009_Glen_Garry.pdf
Runaway of a road-rail vehicle at Glen Garry	05/2009	05/12/2007	05/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5671942840f0b6472f00000/f/05_2009_Glen_Garry.pdf
Runaway of a road-rail vehicle at Glen Garry	05/2009	05/12/2007	05/2009/06	Closed - I	None	All RRV owners/manufacturers/maintainers/hirers	https://assets.publishing.service.gov.uk/media/5671942840f0b6472f00000/f/05_2009_Glen_Garry.pdf
Runaway of a road-rail vehicle at Glen Garry	05/2009	05/12/2007	05/2009/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5671942840f0b6472f00000/f/05_2009_Glen_Garry.pdf
Derailment near Exhibition Centre station, Glasgow	04/2009	03/09/2007	04/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567191a240f0b6472f00000/d/04_2009_Glasgow_Exhibition_Centre.pdf

Derailment near Exhibition Centre station, Glasgow	04/2009	03/09/2007	04/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567191a240f0b6472f00000d/04_2009_Glasgow_Exhibition_Centre.pdf
Derailment near Exhibition Centre station, Glasgow	04/2009	03/09/2007	04/2009/03	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/567191a240f0b6472f00000d/04_2009_Glasgow_Exhibition_Centre.pdf
Derailment near Exhibition Centre station, Glasgow	04/2009	03/09/2007	04/2009/04	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/567191a240f0b6472f00000d/04_2009_Glasgow_Exhibition_Centre.pdf
Derailment of a road rail vehicle at Terryhoogan, near Scarva, Northern Ireland	03/2009	09/03/2008	03/2009/01	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56718fd6ed915d1c5300000c/03_2009_Terryhoogan.pdf
Derailment of a road rail vehicle at Terryhoogan, near Scarva, Northern Ireland	03/2009	09/03/2008	03/2009/02	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56718fd6ed915d1c5300000c/03_2009_Terryhoogan.pdf
Derailment of a road rail vehicle at Terryhoogan, near Scarva, Northern Ireland	03/2009	09/03/2008	03/2009/03	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56718fd6ed915d1c5300000c/03_2009_Terryhoogan.pdf
Derailment of a road rail vehicle at Terryhoogan, near Scarva, Northern Ireland	03/2009	09/03/2008	03/2009/04	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56718fd6ed915d1c5300000c/03_2009_Terryhoogan.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/02	Closed - I	None	Lafarge Aggregates Ltd	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/03	Closed - I	Blue	Freight maintainers	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/03	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/10	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/11	Closed - I	None	Rolling Stock Maintainers	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c300000b/02_2009_Ely_Dock_Junction.pdf

Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/11	Closed - I	None	Wabtec Rail Limited	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c30000/0b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/12	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c30000/0b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/13	Closed - I	None	Lafarge Aggregates Ltd	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c30000/0b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/14	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c30000/0b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/15	Closed - I	None	Lafarge Aggregates Ltd	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c30000/0b/02_2009_Ely_Dock_Junction.pdf
Derailment at Ely Dock junction	02/2009	22/06/2007	02/2009/16	Closed - I	None	Lafarge Aggregates Ltd	https://assets.publishing.service.gov.uk/media/56718bc7e5274a12c30000/0b/02_2009_Ely_Dock_Junction.pdf
Fatal accident at West Lodge crossing, Haltwhistle	01/2009	22/01/2008	01/2009/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718a37e5274a12c30000/09/01_2009_West_Lodge.pdf
Fatal accident at West Lodge crossing, Haltwhistle	01/2009	22/01/2008	01/2009/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718a37e5274a12c30000/09/01_2009_West_Lodge.pdf
Fatal accident at West Lodge crossing, Haltwhistle	01/2009	22/01/2008	01/2009/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718a37e5274a12c30000/09/01_2009_West_Lodge.pdf
Fatal accident at West Lodge crossing, Haltwhistle	01/2009	22/01/2008	01/2009/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56718a37e5274a12c30000/09/01_2009_West_Lodge.pdf
Network Rail's Management of Existing Earthworks	25/2008	28/02/2008	25/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5670166fe5274a12c30000/00/25_2008_Earthworks.pdf
Network Rail's Management of Existing Earthworks	25/2008	28/02/2008	25/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5670166fe5274a12c30000/00/25_2008_Earthworks.pdf
Network Rail's Management of Existing Earthworks	25/2008	28/02/2008	25/2008/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5670166fe5274a12c30000/00/25_2008_Earthworks.pdf
Network Rail's Management of Existing Earthworks	25/2008	28/02/2008	25/2008/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5670166fe5274a12c30000/00/25_2008_Earthworks.pdf
Network Rail's Management of Existing Earthworks	25/2008	28/02/2008	25/2008/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5670166fe5274a12c30000/00/25_2008_Earthworks.pdf
Network Rail's Management of Existing Earthworks	25/2008	28/02/2008	25/2008/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5670166fe5274a12c30000/00/25_2008_Earthworks.pdf
Near miss involving railway staff and a train between Bishop's Stortford and Stansted Mountfitchet, Essex	26/2008	20/01/2008	26/2008/01	Closed - I	None	National Express East Anglia	https://assets.publishing.service.gov.uk/media/567017deed915d1c560000/05/26_2008_Bishops_Stortford.pdf
Near miss involving railway staff and a train between Bishop's Stortford and Stansted Mountfitchet, Essex	26/2008	20/01/2008	26/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567017deed915d1c560000/05/26_2008_Bishops_Stortford.pdf
Near miss involving railway staff and a train between Bishop's Stortford and Stansted Mountfitchet, Essex	26/2008	20/01/2008	26/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/567017deed915d1c560000/05/26_2008_Bishops_Stortford.pdf

Near miss involving railway staff and a train between Bishop's Stortford and Stansted Mountfitchet, Essex	26/2008	20/01/2008	26/2008/02	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/567017deed915d1c560000/05/26_2008_Bishops_Stortford.pdf
Near miss involving railway staff and a train between Bishop's Stortford and Stansted Mountfitchet, Essex	26/2008	20/01/2008	26/2008/03	Closed - I	None	National Express East Anglia	https://assets.publishing.service.gov.uk/media/567017deed915d1c560000/05/26_2008_Bishops_Stortford.pdf
Near miss involving railway staff and a train between Bishop's Stortford and Stansted Mountfitchet, Essex	26/2008	20/01/2008	26/2008/04	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/567017deed915d1c560000/05/26_2008_Bishops_Stortford.pdf
Near miss involving railway staff and a train between Bishop's Stortford and Stansted Mountfitchet, Essex	26/2008	20/01/2008	26/2008/05	Closed - I	None	National Express East Anglia	https://assets.publishing.service.gov.uk/media/567017deed915d1c560000/05/26_2008_Bishops_Stortford.pdf
Fatal accident at Moor Lane footpath crossing, Staines	27/2008	16/04/2008	27/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56701b93ed915d1c560000/07/27_2008_Staines.pdf
Fatal accident at Moor Lane footpath crossing, Staines	27/2008	16/04/2008	27/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56701b93ed915d1c560000/07/27_2008_Staines.pdf
Fatal accident at Moor Lane footpath crossing, Staines	27/2008	16/04/2008	27/2008/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56701b93ed915d1c560000/07/27_2008_Staines.pdf
Fatal accident at Moor Lane footpath crossing, Staines	27/2008	16/04/2008	27/2008/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56701b93ed915d1c560000/07/27_2008_Staines.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/01	Closed - I	None	Consillia Limited	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/02	Closed - I	None	Tubelines	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/03	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/04	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/05	Closed - I	None	Consillia Limited	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/06	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/07	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/08	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/09	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf

Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/10	Closed - I	None	Consillia Limited	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/11	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/12	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/13	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/13	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/14	Closed - I	None	Consillia Limited	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Minor collision between an engineering unit and two manual trolleys near St. John's Wood	24/2008	25/10/2007	24/2008/14	Closed - I	None	Tube Lines	https://assets.publishing.service.gov.uk/media/567009c140f0b647320000/00/24_2008_St_Johns_Wood.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/01	Closed - I	None	First Great Western	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/03	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/03	Closed - IA	None	RSSB	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/04	Closed - IA	None	RSSB	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/06	Closed - NI	None	Association of Train Operating Companies (ATOC)	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/07	Closed - I	None	First Great Western	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/08	Closed - I	None	Association of Train Operating Companies (ATOC)	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/08	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Signal passed at danger and subsequent near miss at Didcot North junction	23/2008	22/08/2007	23/2008/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ed0dd40f0b603690000/25/23_2008_Didcot_North.pdf
Train overspeeding through an emergency speed restriction at Ty Mawr Farm Crossing	22/2008	29/08/2007	22/2008/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/566ed06fed915d035f00002e/22_2008_Ty_Mawr.pdf

Train overspeeding through an emergency speed restriction at Ty Mawr Farm Crossing	22/2008	29/08/2007	22/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ed06fed915d035f00002e/22_2008_Ty_Mawr.pdf
Train overspeeding through an emergency speed restriction at Ty Mawr Farm Crossing	22/2008	29/08/2007	22/2008/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ed06fed915d035f00002e/22_2008_Ty_Mawr.pdf
Train overspeeding through an emergency speed restriction at Ty Mawr Farm Crossing	22/2008	29/08/2007	22/2008/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ed06fed915d035f00002e/22_2008_Ty_Mawr.pdf
Train overspeeding through an emergency speed restriction at Ty Mawr Farm Crossing	22/2008	29/08/2007	22/2008/05	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ed06fed915d035f00002e/22_2008_Ty_Mawr.pdf
Train overspeeding through an emergency speed restriction at Ty Mawr Farm Crossing	22/2008	29/08/2007	22/2008/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ed06fed915d035f00002e/22_2008_Ty_Mawr.pdf
Train overspeeding through an emergency speed restriction at Ty Mawr Farm Crossing	22/2008	29/08/2007	22/2008/07	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/566ed06fed915d035f00002e/22_2008_Ty_Mawr.pdf
Fatal accident to a track worker east of Reading station	21/2008	29/11/2007	21/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ec706e5274a105e000027/21_2008_Reading.pdf
Fatal accident to a track worker east of Reading station	21/2008	29/11/2007	21/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ec706e5274a105e000027/21_2008_Reading.pdf
Fatal accident to a track worker east of Reading station	21/2008	29/11/2007	21/2008/03	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/566ec706e5274a105e000027/21_2008_Reading.pdf
Fatal accident to a track worker east of Reading station	21/2008	29/11/2007	21/2008/04	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ec706e5274a105e000027/21_2008_Reading.pdf
Fatal accident to a track worker east of Reading station	21/2008	29/11/2007	21/2008/05	Closed - NI	White	Network Rail	https://assets.publishing.service.gov.uk/media/566ec706e5274a105e000027/21_2008_Reading.pdf
Accident at Leatherhead	19/2008	29/08/2007	19/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ebe6d40f0b60366000032/19_2008_Leatherhead.pdf
Accident at Leatherhead	19/2008	29/08/2007	19/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ebe6d40f0b60366000032/19_2008_Leatherhead.pdf
Accident at Leatherhead	19/2008	29/08/2007	19/2008/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ebe6d40f0b60366000032/19_2008_Leatherhead.pdf
Accident at Leatherhead	19/2008	29/08/2007	19/2008/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ebe6d40f0b60366000032/19_2008_Leatherhead.pdf
Accident at Leatherhead	19/2008	29/08/2007	19/2008/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ebe6d40f0b60366000032/19_2008_Leatherhead.pdf
Accident at Leatherhead	19/2008	29/08/2007	19/2008/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ebe6d40f0b60366000032/19_2008_Leatherhead.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e000025/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e000025/20_2008_Grayrigg.pdf

Derailment at Grayrigg	20/2008	23/02/2007	20/2008/22	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/23	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/24	Closed - I	Blue	Angel Trains Limited	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/24	Closed - I	Blue	Virgin Trains	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/25	Closed - I	Blue	RSSB	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/26	Closed - I	None	Cumbria Police	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/27	Closed - I	None	Ambulance Services	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/27	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/28	Closed - I	None	Ministry of Defence	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Derailment at Grayrigg	20/2008	23/02/2007	20/2008/29	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/566ec44ae5274a105e0000/25/20_2008_Grayrigg.pdf
Collision of a train with a demolished footbridge, Barrow upon Soar	18/2008	01/02/2008	18/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ebd11ed915d03620000/26/18_2008_Barrow_upon_Soar.pdf
Collision of a train with a demolished footbridge, Barrow upon Soar	18/2008	01/02/2008	18/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ebd11ed915d03620000/26/18_2008_Barrow_upon_Soar.pdf
Collision of a train with a demolished footbridge, Barrow upon Soar	18/2008	01/02/2008	18/2008/03	Closed - I	Blue	RSSB	https://assets.publishing.service.gov.uk/media/566ebd11ed915d03620000/26/18_2008_Barrow_upon_Soar.pdf
Collision of a train with a demolished footbridge, Barrow upon Soar	18/2008	01/02/2008	18/2008/04	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/566ebd11ed915d03620000/26/18_2008_Barrow_upon_Soar.pdf
Passenger trapped in a closed train door, Tooting Broadway, Northern Line, London Underground	17/2008	01/11/2007	17/2008/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/566ebacde5274a105e0000/23/17_2008_Tooting_Broadway.pdf
Derailment at Duddeston Junction, Birmingham	16/2008	10/08/2007	16/2008/01	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/566eb9a140f0b603690000/23/16_2008_Duddeston_Junction.pdf
Derailment at Duddeston Junction, Birmingham	16/2008	10/08/2007	16/2008/02	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/566eb9a140f0b603690000/23/16_2008_Duddeston_Junction.pdf
Derailment at Duddeston Junction, Birmingham	16/2008	10/08/2007	16/2008/03	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/566eb9a140f0b603690000/23/16_2008_Duddeston_Junction.pdf
Derailment at Duddeston Junction, Birmingham	16/2008	10/08/2007	16/2008/04	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/566eb9a140f0b603690000/23/16_2008_Duddeston_Junction.pdf

Derailment at Duddeston Junction, Birmingham	16/2008	10/08/2007	16/2008/05	Closed - NI	Blue	Freightliner Group	https://assets.publishing.service.gov.uk/media/566eb9a140f0b60369000023/16_2008_Duddeston_Junction.pdf
Derailment at Duddeston Junction, Birmingham	16/2008	10/08/2007	16/2008/06	Closed - I	Blue	Freightliner Group	https://assets.publishing.service.gov.uk/media/566eb9a140f0b60369000023/16_2008_Duddeston_Junction.pdf
Derailment at Duddeston Junction, Birmingham	16/2008	10/08/2007	16/2008/07	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/566eb9a140f0b60369000023/16_2008_Duddeston_Junction.pdf
Derailment at Duddeston Junction, Birmingham	16/2008	10/08/2007	16/2008/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566eb9a140f0b60369000023/16_2008_Duddeston_Junction.pdf
Child fell from train on the Nene Valley Railway	15/2008	16/02/2008	15/2008/01	Closed - I	None	Nene Valley Railway	https://assets.publishing.service.gov.uk/media/566aa4e2e5274a105b00001b/15_2008_Nene_Valley_Railway.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/01	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/02	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/03	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/04	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/05	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/06	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/07	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/08	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/09	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Collision with the gates at Lydney Town level crossing	14/2008	15/08/2007	14/2008/10	Closed - I	None	Dean Forest Railway	https://assets.publishing.service.gov.uk/media/566aa038ed915d036200001a/14_2008_Lydney_Town_level_crossing.pdf
Two trains in the same section at Aylesbury	13/2008	27/08/2007	13/2008/01	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/566a9edae5274a105b000019/13_2008_Aylesbury.pdf
Two trains in the same section at Aylesbury	13/2008	27/08/2007	13/2008/02	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/566a9edae5274a105b000019/13_2008_Aylesbury.pdf
Two trains in the same section at Aylesbury	13/2008	27/08/2007	13/2008/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/566a9edae5274a105b000019/13_2008_Aylesbury.pdf
Two trains in the same section at Aylesbury	13/2008	27/08/2007	13/2008/04	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/566a9edae5274a105b000019/13_2008_Aylesbury.pdf

Two trains in the same section at Aylesbury	13/2008	27/08/2007	13/2008/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9edae5274a105b0000/19/13_2008_Aylesbury.pdf
Runaway of two wagons from Camden Road Tunnel	12/2008	19/07/2007	12/2008/01	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/566a9d84e5274a105b0000/17/12_2008_Camden_Road.pdf
Runaway of two wagons from Camden Road Tunnel	12/2008	19/07/2007	12/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9d84e5274a105b0000/17/12_2008_Camden_Road.pdf
Runaway of two wagons from Camden Road Tunnel	12/2008	19/07/2007	12/2008/03	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/566a9d84e5274a105b0000/17/12_2008_Camden_Road.pdf
Runaway of two wagons from Camden Road Tunnel	12/2008	19/07/2007	12/2008/04	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/566a9d84e5274a105b0000/17/12_2008_Camden_Road.pdf
Runaway of two wagons from Camden Road Tunnel	12/2008	19/07/2007	12/2008/05	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/566a9d84e5274a105b0000/17/12_2008_Camden_Road.pdf
Runaway of two wagons from Camden Road Tunnel	12/2008	19/07/2007	12/2008/06	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/566a9d84e5274a105b0000/17/12_2008_Camden_Road.pdf
Runaway of two wagons from Camden Road Tunnel	12/2008	19/07/2007	12/2008/07	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/566a9d84e5274a105b0000/17/12_2008_Camden_Road.pdf
Runaway of two wagons from Camden Road Tunnel	12/2008	19/07/2007	12/2008/08	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/566a9d84e5274a105b0000/17/12_2008_Camden_Road.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/03	Closed - IA	None	Holdfast Level Crossings Ltd	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/03	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/04	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/07	Closed - I	None	Holdfast Level Crossings Ltd	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f0000/1e/11_2008_Croxton_level_crossing.pdf

Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f00001e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/10	Closed - I	None	Holdfast Level Crossings Ltd	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f00001e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/11	Closed - I	None	Holdfast Level Crossings Ltd	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f00001e/11_2008_Croxton_level_crossing.pdf
Derailment of a train at Croxton Level Crossing	11/2008	12/09/2006	11/2008/11	Closed - I	None	Rosehill Polymers Ltd	https://assets.publishing.service.gov.uk/media/566a9ad7ed915d035f00001e/11_2008_Croxton_level_crossing.pdf
Runaway and collision at Armathwaite	08/2008	28/01/2007	08/2008/01	Closed - I	None	First Engineering	https://assets.publishing.service.gov.uk/media/5669b4a340f0b60369000012/08_2008_Armathwaite.pdf
Runaway and collision at Armathwaite	08/2008	28/01/2007	08/2008/02	Closed - I	None	First Engineering	https://assets.publishing.service.gov.uk/media/5669b4a340f0b60369000012/08_2008_Armathwaite.pdf
Runaway and collision at Armathwaite	08/2008	28/01/2007	08/2008/03	Closed - I	None	First Engineering	https://assets.publishing.service.gov.uk/media/5669b4a340f0b60369000012/08_2008_Armathwaite.pdf
Derailment of a tram at Pomona, Manchester	09/2008	17/01/2007	09/2008/01	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/566a9098e5274a105e000016/09_2008_Pomona.pdf
Derailment of a tram at Pomona, Manchester	09/2008	17/01/2007	09/2008/02	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/566a9098e5274a105e000016/09_2008_Pomona.pdf
Derailment of a tram at Pomona, Manchester	09/2008	17/01/2007	09/2008/03	Closed - I	None	Stagecoach Metrolink	https://assets.publishing.service.gov.uk/media/566a9098e5274a105e000016/09_2008_Pomona.pdf
Derailment of a tram at Pomona, Manchester	09/2008	17/01/2007	09/2008/04	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/566a9098e5274a105e000016/09_2008_Pomona.pdf
Derailment of a tram at Pomona, Manchester	09/2008	17/01/2007	09/2008/04	Closed - I	None	Stagecoach Metrolink	https://assets.publishing.service.gov.uk/media/566a9098e5274a105e000016/09_2008_Pomona.pdf
Derailment of a tram at Pomona, Manchester	09/2008	17/01/2007	09/2008/05	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/566a9098e5274a105e000016/09_2008_Pomona.pdf
Derailment of a tram at Pomona, Manchester	09/2008	17/01/2007	09/2008/05	Closed - I	None	Stagecoach Metrolink	https://assets.publishing.service.gov.uk/media/566a9098e5274a105e000016/09_2008_Pomona.pdf
Collision between a train and tractor on crossing XL202 near Limavady Junction, Northern Ireland	10/2008	02/08/2007	10/2008/01	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/566a951240f0b60366000029/10_2008_Limavady_NI.pdf
Collision between a train and tractor on crossing XL202 near Limavady Junction, Northern Ireland	10/2008	02/08/2007	10/2008/02	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/566a951240f0b60366000029/10_2008_Limavady_NI.pdf
Collision between a train and tractor on crossing XL202 near Limavady Junction, Northern Ireland	10/2008	02/08/2007	10/2008/03	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/566a951240f0b60366000029/10_2008_Limavady_NI.pdf
Collision between a train and tractor on crossing XL202 near Limavady Junction, Northern Ireland	10/2008	02/08/2007	10/2008/04	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/566a951240f0b60366000029/10_2008_Limavady_NI.pdf
Collision between a train and tractor on crossing XL202 near Limavady Junction, Northern Ireland	10/2008	02/08/2007	10/2008/05	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/566a951240f0b60366000029/10_2008_Limavady_NI.pdf

Collision between a train and tractor on crossing XL202 near Limavady Junction, Northern Ireland	10/2008	02/08/2007	10/2008/06	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/566a951240f0b603660000/29/10_2008_Limavady_NI.pdf
Derailment of a passenger train near Kemble	07/2009	15/01/2007	07/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669ac0240f0b603690000/0f/07_2008_Kemble.pdf
Derailment of a passenger train near Kemble	07/2009	15/01/2007	07/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669ac0240f0b603690000/0f/07_2008_Kemble.pdf
Tube train driven in the wrong direction, Camden Town, Northern Line	06/2008	10/06/2007	06/2008/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5669aa7bed915d035f0000/1c/06_2008_Camden_Town.pdf
Tube train driven in the wrong direction, Camden Town, Northern Line	06/2008	10/06/2007	06/2008/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5669aa7bed915d035f0000/1c/06_2008_Camden_Town.pdf
Tube train driven in the wrong direction, Camden Town, Northern Line	06/2008	10/06/2007	06/2008/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5669aa7bed915d035f0000/1c/06_2008_Camden_Town.pdf
Tube train driven in the wrong direction, Camden Town, Northern Line	06/2008	10/06/2007	06/2008/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5669aa7bed915d035f0000/1c/06_2008_Camden_Town.pdf
Track worker fatality at Ruscombe Junction	04/2008	29/04/2007	04/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669830140f0b603690000/0d/04_2008_Ruscombe_Junction.pdf
Track worker fatality at Ruscombe Junction	04/2008	29/04/2007	04/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669830140f0b603690000/0d/04_2008_Ruscombe_Junction.pdf
Track worker fatality at Ruscombe Junction	04/2008	29/04/2007	04/2008/03	Closed - I	None	First Great Western	https://assets.publishing.service.gov.uk/media/5669830140f0b603690000/0d/04_2008_Ruscombe_Junction.pdf
Track worker fatality at Ruscombe Junction	04/2008	29/04/2007	04/2008/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5669830140f0b603690000/0d/04_2008_Ruscombe_Junction.pdf
Track worker fatality at Ruscombe Junction	04/2008	29/04/2007	04/2008/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669830140f0b603690000/0d/04_2008_Ruscombe_Junction.pdf
Track worker fatality at Ruscombe Junction	04/2008	29/04/2007	04/2008/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669830140f0b603690000/0d/04_2008_Ruscombe_Junction.pdf
Track worker fatality at Ruscombe Junction	04/2008	29/04/2007	04/2008/07	Closed - I	None	National Health Service	https://assets.publishing.service.gov.uk/media/5669830140f0b603690000/0d/04_2008_Ruscombe_Junction.pdf
Track worker fatality at Ruscombe Junction	04/2008	29/04/2007	04/2008/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669830140f0b603690000/0d/04_2008_Ruscombe_Junction.pdf
Derailment in Hooley Cutting, near Merstham, Surrey	05/2008	13/01/2007	05/2008/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669842f40f0b6036600002/1/05_2008_Hooley_Cutting.pdf
Derailment in Hooley Cutting, near Merstham, Surrey	05/2008	13/01/2007	05/2008/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669842f40f0b6036600002/1/05_2008_Hooley_Cutting.pdf
Derailment in Hooley Cutting, near Merstham, Surrey	05/2008	13/01/2007	05/2008/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669842f40f0b6036600002/1/05_2008_Hooley_Cutting.pdf
Derailment in Hooley Cutting, near Merstham, Surrey	05/2008	13/01/2007	05/2008/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669842f40f0b6036600002/1/05_2008_Hooley_Cutting.pdf

Derailment in Hooley Cutting, near Merstham, Surrey	05/2008	13/01/2007	05/2008/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669842f40f0b60366000021/05_2008_Hooley_Cutting.pdf
Derailment in Hooley Cutting, near Merstham, Surrey	05/2008	13/01/2007	05/2008/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669842f40f0b60366000021/05_2008_Hooley_Cutting.pdf
Derailment in Hooley Cutting, near Merstham, Surrey	05/2008	13/01/2007	05/2008/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669842f40f0b60366000021/05_2008_Hooley_Cutting.pdf
Derailment in Hooley Cutting, near Merstham, Surrey	05/2008	13/01/2007	05/2008/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669842f40f0b60366000021/05_2008_Hooley_Cutting.pdf
Derailment in Hooley Cutting, near Merstham, Surrey	05/2008	13/01/2007	05/2008/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669842f40f0b60366000021/05_2008_Hooley_Cutting.pdf
The derailment of a freight train at King Edward Bridge, Newcastle	02/2008	10/05/2007	02/2008/01	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5669800240f0b6036900000b/02_2008_King_Edward_Bridge.pdf
The derailment of a freight train at King Edward Bridge, Newcastle	02/2008	10/05/2007	02/2008/01	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/5669800240f0b6036900000b/02_2008_King_Edward_Bridge.pdf
The derailment of a freight train at King Edward Bridge, Newcastle	02/2008	10/05/2007	02/2008/02	Closed - IA	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669800240f0b6036900000b/02_2008_King_Edward_Bridge.pdf
The derailment of a freight train at King Edward Bridge, Newcastle	02/2008	10/05/2007	02/2008/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669800240f0b6036900000b/02_2008_King_Edward_Bridge.pdf
The derailment of a freight train at King Edward Bridge, Newcastle	02/2008	10/05/2007	02/2008/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669800240f0b6036900000b/02_2008_King_Edward_Bridge.pdf
Derailment of a London Underground Central Line train near Mile End station	03/2008	05/07/2007	03/2008/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56698150ed915d0362000013/03_2008_Mile_End.pdf
Derailment of a London Underground Central Line train near Mile End station	03/2008	05/07/2007	03/2008/02	Closed - I	None	Infrastructure Companies (London Underground Only)	https://assets.publishing.service.gov.uk/media/56698150ed915d0362000013/03_2008_Mile_End.pdf
Derailment of a London Underground Central Line train near Mile End station	03/2008	05/07/2007	03/2008/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56698150ed915d0362000013/03_2008_Mile_End.pdf
Derailment of a London Underground Central Line train near Mile End station	03/2008	05/07/2007	03/2008/04	Closed - I	None	Infrastructure Companies (London Underground Only)	https://assets.publishing.service.gov.uk/media/56698150ed915d0362000013/03_2008_Mile_End.pdf
Derailment of a London Underground Central Line train near Mile End station	03/2008	05/07/2007	03/2008/05	Closed - I	None	Infrastructure Companies (London Underground Only)	https://assets.publishing.service.gov.uk/media/56698150ed915d0362000013/03_2008_Mile_End.pdf
Collision near Burton on Trent	01/2008	01/08/2007	01/2008/01	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56697d4340f0b6036600001c/01_2008_Burton_on_Trent.pdf
Collision near Burton on Trent	01/2008	01/08/2007	01/2008/02	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56697d4340f0b6036600001c/01_2008_Burton_on_Trent.pdf
Collision near Burton on Trent	01/2008	01/08/2007	01/2008/03	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56697d4340f0b6036600001c/01_2008_Burton_on_Trent.pdf
Collision near Burton on Trent	01/2008	01/08/2007	01/2008/04	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56697d4340f0b6036600001c/01_2008_Burton_on_Trent.pdf

Train/vehicle collision on the Leighton Buzzard Narrow Gauge Railway	45/2007	25/03/2007	45/2007/01	Closed - I	None	Leighton Buzzard Railway	https://assets.publishing.service.gov.uk/media/5669760840f0b603660000/16/45_2007_Train_and_Road_Vehicle_collision_Leighton_Buzzard.pdf
Train/vehicle collision on the Leighton Buzzard Narrow Gauge Railway	45/2007	25/03/2007	45/2007/02	Closed - I	None	Bedfordshire County Council	https://assets.publishing.service.gov.uk/media/5669760840f0b603660000/16/45_2007_Train_and_Road_Vehicle_collision_Leighton_Buzzard.pdf
Train/vehicle collision on the Leighton Buzzard Narrow Gauge Railway	45/2007	25/03/2007	45/2007/03	Closed - I	None	Bedfordshire County Council	https://assets.publishing.service.gov.uk/media/5669760840f0b603660000/16/45_2007_Train_and_Road_Vehicle_collision_Leighton_Buzzard.pdf
Train/vehicle collision on the Leighton Buzzard Narrow Gauge Railway	45/2007	25/03/2007	45/2007/03	Closed - I	None	Leighton Buzzard Railway	https://assets.publishing.service.gov.uk/media/5669760840f0b603660000/16/45_2007_Train_and_Road_Vehicle_collision_Leighton_Buzzard.pdf
Collision between a train and a road vehicle on the Leighton Buzzard narrow gauge railway	46/2007	25/08/2007	46/2007/01	Closed - I	None	Leighton Buzzard Railway	https://assets.publishing.service.gov.uk/media/5669760840f0b603660000/16/45_2007_Train_and_Road_Vehicle_collision_Leighton_Buzzard.pdf
Collision between a train and a road vehicle on the Leighton Buzzard narrow gauge railway	46/2007	25/08/2007	46/2007/02	Closed - I	None	Leighton Buzzard Railway	https://assets.publishing.service.gov.uk/media/5669760840f0b603660000/16/45_2007_Train_and_Road_Vehicle_collision_Leighton_Buzzard.pdf
Near miss involving a track worker at Tinsley Green Junction	43/2007	17/03/2007	43/2007/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669719b40f0b603660000/13/43_2007_Tinsley_Junction.pdf
Near miss involving a track worker at Tinsley Green Junction	43/2007	17/03/2007	43/2007/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669719b40f0b603660000/13/43_2007_Tinsley_Junction.pdf
Near miss involving a track worker at Tinsley Green Junction	43/2007	17/03/2007	43/2007/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669719b40f0b603660000/13/43_2007_Tinsley_Junction.pdf
Near miss involving a track worker at Tinsley Green Junction	43/2007	17/03/2007	43/2007/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669719b40f0b603660000/13/43_2007_Tinsley_Junction.pdf
Near miss involving a track worker at Tinsley Green Junction	43/2007	17/03/2007	43/2007/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669719b40f0b603660000/13/43_2007_Tinsley_Junction.pdf
Near miss involving a track worker at Tinsley Green Junction	43/2007	17/03/2007	43/2007/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669719b40f0b603660000/13/43_2007_Tinsley_Junction.pdf
Near miss involving a track worker at Tinsley Green Junction	43/2007	17/03/2007	43/2007/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669719b40f0b603660000/13/43_2007_Tinsley_Junction.pdf
Near miss involving a track worker at Tinsley Green Junction	43/2007	17/03/2007	43/2007/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5669719b40f0b603660000/13/43_2007_Tinsley_Junction.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/01	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f0000/14/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f0000/14/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f0000/14/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f0000/14/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f0000/14/44_2007_London_Waterloo.pdf

Derailments at London Waterloo	44/2007	11/09/2006	44/2007/06	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/08	Closed - I	None	South West Trains	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/10	Closed - I	None	KCI Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/11	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/12	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/13	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailments at London Waterloo	44/2007	11/09/2006	44/2007/14	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566972beed915d035f000014/44_2007_London_Waterloo.pdf
Derailment at Cromore, Northern Ireland	42/2007	14/04/2007	42/2007/01	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56696f67ed915d036200000a/42_2007_Cromore.pdf
Derailment at Cromore, Northern Ireland	42/2007	14/04/2007	42/2007/02	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56696f67ed915d036200000a/42_2007_Cromore.pdf
Derailment at Cromore, Northern Ireland	42/2007	14/04/2007	42/2007/03	Closed - I	None	Sperry Rail International	https://assets.publishing.service.gov.uk/media/56696f67ed915d036200000a/42_2007_Cromore.pdf
Derailment at Cromore, Northern Ireland	42/2007	14/04/2007	42/2007/04	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56696f67ed915d036200000a/42_2007_Cromore.pdf
Derailment at Cromore, Northern Ireland	42/2007	14/04/2007	42/2007/05	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56696f67ed915d036200000a/42_2007_Cromore.pdf
Derailment at Cromore, Northern Ireland	42/2007	14/04/2007	42/2007/06	Closed - I	None	Sperry Rail International	https://assets.publishing.service.gov.uk/media/56696f67ed915d036200000a/42_2007_Cromore.pdf
Derailment at Cromore, Northern Ireland	42/2007	14/04/2007	42/2007/07	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/56696f67ed915d036200000a/42_2007_Cromore.pdf
Fire on prototype tram 611 at Blackpool	41/2007	24/01/2007	41/2007/01	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/56696b0de5274a105e00000a/41_2007_Blackpool_Tram.pdf
Fire on prototype tram 611 at Blackpool	41/2007	24/01/2007	41/2007/02	Closed - I	None	Trampower	https://assets.publishing.service.gov.uk/media/56696b0de5274a105e00000a/41_2007_Blackpool_Tram.pdf

The derailment of a freight train at Washwood Heath	39/2007	08/09/2006	39/2007/01	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56696182ed915d035f000012/39_2007_Washwood_Heath.pdf
The derailment of a freight train at Washwood Heath	39/2007	08/09/2006	39/2007/02	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56696182ed915d035f000012/39_2007_Washwood_Heath.pdf
The derailment of a freight train at Washwood Heath	39/2007	08/09/2006	39/2007/03	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56696182ed915d035f000012/39_2007_Washwood_Heath.pdf
The derailment of a freight train at Washwood Heath	39/2007	08/09/2006	39/2007/04	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56696182ed915d035f000012/39_2007_Washwood_Heath.pdf
Derailment at Birmingham Snow Hill, Midland Metro	38/2007	29/01/2007	38/2007/01	Closed - I	None	West Midlands Metro	https://assets.publishing.service.gov.uk/media/56695fe940f0b60369000006/38_2007_Birmingham_Snow_Hill.pdf
Derailment at Birmingham Snow Hill, Midland Metro	38/2007	29/01/2007	38/2007/02	Closed - I	None	West Midlands Metro	https://assets.publishing.service.gov.uk/media/56695fe940f0b60369000006/38_2007_Birmingham_Snow_Hill.pdf
Derailment at Birmingham Snow Hill, Midland Metro	38/2007	29/01/2007	38/2007/03	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/56695fe940f0b60369000006/38_2007_Birmingham_Snow_Hill.pdf
Derailment at Birmingham Snow Hill, Midland Metro	38/2007	29/01/2007	38/2007/04	Closed - I	None	West Midlands Metro	https://assets.publishing.service.gov.uk/media/56695fe940f0b60369000006/38_2007_Birmingham_Snow_Hill.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/01	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/02	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/03	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/04	Closed - NI	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/05	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/06	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/07	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/08	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/09	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/10	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/11	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b60366000010/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf

Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/12	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b603660000/10/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/13	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b603660000/10/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/14	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b603660000/10/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/15	Closed - I	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b603660000/10/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Fire on HGV shuttle in the Channel Tunnel	37/2007	21/08/2006	37/2007/16	Closed - NI	None	Eurotunnel	https://assets.publishing.service.gov.uk/media/566951ea40f0b603660000/10/37_2007_HGV_shuttle_in_the_Channel_Tunnel.pdf
Collision between a train and a road vehicle, M20 overline bridge, Aylesford	36/2007	05/02/2007	36/2007/01	Closed - I	None	Intergroup	https://assets.publishing.service.gov.uk/media/566830e140f0b603670000/23/36_2007_M20_Bridge_Aylesford.pdf
Collision between a train and a road vehicle, M20 overline bridge, Aylesford	36/2007	05/02/2007	36/2007/02	Closed - I	None	Intergroup	https://assets.publishing.service.gov.uk/media/566830e140f0b603670000/23/36_2007_M20_Bridge_Aylesford.pdf
Collision between a train and a road vehicle, M20 overline bridge, Aylesford	36/2007	05/02/2007	36/2007/03	Closed - I	None	Intergroup	https://assets.publishing.service.gov.uk/media/566830e140f0b603670000/23/36_2007_M20_Bridge_Aylesford.pdf
Collision between a train and a road vehicle, M20 overline bridge, Aylesford	36/2007	05/02/2007	36/2007/04	Closed - I	None	E.S. Access Platforms (NE) Ltd	https://assets.publishing.service.gov.uk/media/566830e140f0b603670000/23/36_2007_M20_Bridge_Aylesford.pdf
Collision between a train and a road vehicle, M20 overline bridge, Aylesford	36/2007	05/02/2007	36/2007/05	Closed - I	None	E.S. Access Platforms (NE) Ltd	https://assets.publishing.service.gov.uk/media/566830e140f0b603670000/23/36_2007_M20_Bridge_Aylesford.pdf
Collision between a train and a road vehicle, M20 overline bridge, Aylesford	36/2007	05/02/2007	36/2007/06	Closed - I	None	Intergroup	https://assets.publishing.service.gov.uk/media/566830e140f0b603670000/23/36_2007_M20_Bridge_Aylesford.pdf
Derailment at Epsom	34/2007	12/09/2006	34/2007/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56670f50e5274a03670000/2a/34_2007_Epsom.pdf
Derailment at Epsom	34/2007	12/09/2006	34/2007/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56670f50e5274a03670000/2a/34_2007_Epsom.pdf
Derailment at Epsom	34/2007	12/09/2006	34/2007/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56670f50e5274a03670000/2a/34_2007_Epsom.pdf
Collision at Swanage station	35/2007	16/11/2006	35/2007/01	Closed - I	None	Swanage Railway Co	https://assets.publishing.service.gov.uk/media/56682eb040f0b6036a0000/1e/35_2007_Swanage_station.pdf
Collision at Swanage station	35/2007	16/11/2006	35/2007/02	Closed - I	None	Swanage Railway Co	https://assets.publishing.service.gov.uk/media/56682eb040f0b6036a0000/1e/35_2007_Swanage_station.pdf
Collision at Swanage station	35/2007	16/11/2006	35/2007/03	Closed - I	None	Swanage Railway Co	https://assets.publishing.service.gov.uk/media/56682eb040f0b6036a0000/1e/35_2007_Swanage_station.pdf
Collision at Swanage station	35/2007	16/11/2006	35/2007/04	Closed - I	None	Swanage Railway Co	https://assets.publishing.service.gov.uk/media/56682eb040f0b6036a0000/1e/35_2007_Swanage_station.pdf
Collision at Swanage station	35/2007	16/11/2006	35/2007/05	Closed - I	None	Swanage Railway Co	https://assets.publishing.service.gov.uk/media/56682eb040f0b6036a0000/1e/35_2007_Swanage_station.pdf

Fatal collision between a Super Voyager train and a car on the line at Copmanthorpe	33/2007	25/09/2006	33/2007/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566703f1e5274a0364000029/33_2007_Copmanthorpe.pdf
Fatal collision between a Super Voyager train and a car on the line at Copmanthorpe	33/2007	25/09/2006	33/2007/03	Closed - I	None	Angel Trains Limited	https://assets.publishing.service.gov.uk/media/566703f1e5274a0364000029/33_2007_Copmanthorpe.pdf
Fatal collision between a Super Voyager train and a car on the line at Copmanthorpe	33/2007	25/09/2006	33/2007/03	Closed - I	None	Bombardier Transportation	https://assets.publishing.service.gov.uk/media/566703f1e5274a0364000029/33_2007_Copmanthorpe.pdf
Fatal collision between a Super Voyager train and a car on the line at Copmanthorpe	33/2007	25/09/2006	33/2007/03	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/566703f1e5274a0364000029/33_2007_Copmanthorpe.pdf
Fatal collision between a Super Voyager train and a car on the line at Copmanthorpe	33/2007	25/09/2006	33/2007/03	Closed - I	None	Voyager Leasing	https://assets.publishing.service.gov.uk/media/566703f1e5274a0364000029/33_2007_Copmanthorpe.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/01	Closed - I	None	Bombardier Transportation	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/01	Closed - I	None	Faiveley Transport	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/01	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/02	Closed - I	None	Bombardier Transportation	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/02	Closed - I	None	Faiveley Transport	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/03	Closed - I	None	Bombardier Transportation	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/03	Closed - I	None	Faiveley Transport	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/04	Closed - I	None	Bombardier Transportation	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/04	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/04	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/05	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/05	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/06	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/06	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf

Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/07	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/08	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/08	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger door open on a moving train near Desborough	31/2007	10/06/2006	31/2007/09	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5666ff1d40f0b6036700001d/31_2007_Desborough.pdf
Passenger train derailment near Fisherground on the Ravenglass & Eskdale Railway	32/2007	12/05/2007	32/2007/01	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56670216ed915d0359000014/32_2007_Fisherground.pdf
Passenger train derailment near Fisherground on the Ravenglass & Eskdale Railway	32/2007	12/05/2007	32/2007/02	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56670216ed915d0359000014/32_2007_Fisherground.pdf
Collision at Badminton	30/2007	31/10/2006	30/2007/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5666feac40f0b6036a00001c/30_2007_Badminton.pdf
Collision at Badminton	30/2007	31/10/2006	30/2007/02	Closed - I	None	First Engineering	https://assets.publishing.service.gov.uk/media/5666feac40f0b6036a00001c/30_2007_Badminton.pdf
Collision at Badminton	30/2007	31/10/2006	30/2007/03	Closed - NI	Red	RSSB	https://assets.publishing.service.gov.uk/media/5666feac40f0b6036a00001c/30_2007_Badminton.pdf
Collision at Badminton	30/2007	31/10/2006	30/2007/04	Closed - I	None	Equipment Suppliers	https://assets.publishing.service.gov.uk/media/5666feac40f0b6036a00001c/30_2007_Badminton.pdf
Collision at Badminton	30/2007	31/10/2006	30/2007/04	Closed - I	None	Railway Contractors	https://assets.publishing.service.gov.uk/media/5666feac40f0b6036a00001c/30_2007_Badminton.pdf
Signal T172 passed at danger at Purley station, Surrey	27/2007	18/08/2006	27/2007/01	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5666ddd5e5274a0367000022/27_2007_Purley.pdf
Signal T172 passed at danger at Purley station, Surrey	27/2007	18/08/2006	27/2007/02	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5666ddd5e5274a0367000022/27_2007_Purley.pdf
Signal T172 passed at danger at Purley station, Surrey	27/2007	18/08/2006	27/2007/03	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5666ddd5e5274a0367000022/27_2007_Purley.pdf
Signal T172 passed at danger at Purley station, Surrey	27/2007	18/08/2006	27/2007/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5666ddd5e5274a0367000022/27_2007_Purley.pdf
Signal T172 passed at danger at Purley station, Surrey	27/2007	18/08/2006	27/2007/05	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5666ddd5e5274a0367000022/27_2007_Purley.pdf
Derailment at Phipps Bridge on Croydon Tramlink	28/2007	25/05/2006	28/2007/01	Closed - I	None	Tramtrack Croydon Ltd	https://assets.publishing.service.gov.uk/media/547c907340f0b602410001bd/04_2006_Phipps_Bridge.pdf
Derailment at Phipps Bridge on Croydon Tramlink	28/2007	25/05/2006	28/2007/02	Closed - I	None	Tramtrack Croydon Ltd	https://assets.publishing.service.gov.uk/media/547c907340f0b602410001bd/04_2006_Phipps_Bridge.pdf
Collision at Pickering station North Yorkshire Moors Railway	29/2007	05/05/2007	29/2007/01	Closed - I	None	North Yorkshire Moors Railway	https://assets.publishing.service.gov.uk/media/5666fc9de5274a0367000026/29_2007_Pickering.pdf

Collision at Pickering station North Yorkshire Moors Railway	29/2007	05/05/2007	29/2007/02	Closed - I	None	North Yorkshire Moors Railway	https://assets.publishing.service.gov.uk/media/5666fc9de5274a03670000/26/29_2007_Pickering.pdf
Possession irregularity near Manor Park	26/2007	19/03/2006	26/2007/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5665b35540f0b6036a0000/0e/26_2007_Manor_Park.pdf
Possession irregularity near Manor Park	26/2007	19/03/2006	26/2007/02	Closed - I	None	Kier Rail Limited	https://assets.publishing.service.gov.uk/media/5665b35540f0b6036a0000/0e/26_2007_Manor_Park.pdf
Possession irregularity near Manor Park	26/2007	19/03/2006	26/2007/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5665b35540f0b6036a0000/0e/26_2007_Manor_Park.pdf
Derailment of a freight train at Maltby North	24/2007	28/06/2006	24/2007/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5665b09a40f0b603670000/05/24_2007_Maltby_North.pdf
Derailment of a freight train at Maltby North	24/2007	28/06/2006	24/2007/02	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/5665b09a40f0b603670000/05/24_2007_Maltby_North.pdf
Derailment of a freight train at Maltby North	24/2007	28/06/2006	24/2007/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5665b09a40f0b603670000/05/24_2007_Maltby_North.pdf
Derailment of a freight train at Maltby North	24/2007	28/06/2006	24/2007/04	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/5665b09a40f0b603670000/05/24_2007_Maltby_North.pdf
Derailment at Trooperslane near Carrickfergus, Northern Ireland	25/2007	23/04/2006	25/2007/01	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/5665b214e5274a03670000/12/25_2007_Trooperslane.pdf
Derailment at Trooperslane near Carrickfergus, Northern Ireland	25/2007	23/04/2006	25/2007/02	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/5665b214e5274a03670000/12/25_2007_Trooperslane.pdf
Derailment at Trooperslane near Carrickfergus, Northern Ireland	25/2007	23/04/2006	25/2007/03	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/5665b214e5274a03670000/12/25_2007_Trooperslane.pdf
Derailment at Trooperslane near Carrickfergus, Northern Ireland	25/2007	23/04/2006	25/2007/04	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/5665b214e5274a03670000/12/25_2007_Trooperslane.pdf
Derailment at Trooperslane near Carrickfergus, Northern Ireland	25/2007	23/04/2006	25/2007/05	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/5665b214e5274a03670000/12/25_2007_Trooperslane.pdf
Derailment at Trooperslane near Carrickfergus, Northern Ireland	25/2007	23/04/2006	25/2007/06	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/5665b214e5274a03670000/12/25_2007_Trooperslane.pdf
Derailment at Trooperslane near Carrickfergus, Northern Ireland	25/2007	23/04/2006	25/2007/07	Closed - I	None	Northern Ireland Railways (Translink)	https://assets.publishing.service.gov.uk/media/5665b214e5274a03670000/12/25_2007_Trooperslane.pdf
Derailment at Trooperslane near Carrickfergus, Northern Ireland	25/2007	23/04/2006	25/2007/08	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5665b214e5274a03670000/12/25_2007_Trooperslane.pdf
Fatal accident to Shunter, Dagenham Dock	23/2007	17/07/2006	23/2007/01	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/5665ad87e5274a03640000/12/23_2007_Dagenham_Dock.pdf
Fatal accident to Shunter, Dagenham Dock	23/2007	17/07/2006	23/2007/02	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/5665ad87e5274a03640000/12/23_2007_Dagenham_Dock.pdf
Fatal accident to Shunter, Dagenham Dock	23/2007	17/07/2006	23/2007/03	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/5665ad87e5274a03640000/12/23_2007_Dagenham_Dock.pdf

Fatal accident to Shunter, Dagenham Dock	23/2007	17/07/2006	23/2007/04	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/5665ad87e5274a03640000/12/23_2007_Dagenham_Dock.pdf
Fatal accident to Shunter, Dagenham Dock	23/2007	17/07/2006	23/2007/05	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/5665ad87e5274a03640000/12/23_2007_Dagenham_Dock.pdf
Fatal accident to Shunter, Dagenham Dock	23/2007	17/07/2006	23/2007/06	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/5665ad87e5274a03640000/12/23_2007_Dagenham_Dock.pdf
Fatal accident to Shunter, Dagenham Dock	23/2007	17/07/2006	23/2007/07	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/5665ad87e5274a03640000/12/23_2007_Dagenham_Dock.pdf
Derailment of a tram on the Seaton Tramway	21/2007	18/03/2007	21/2007/01	Closed - I	None	Seaton & District Electric Tramway	https://assets.publishing.service.gov.uk/media/5661b733e5274a03640000/0a/21_2007_Seaton_Tramway.pdf
Derailment of a tram on the Seaton Tramway	21/2007	18/03/2007	21/2007/02	Closed - I	None	Seaton & District Electric Tramway	https://assets.publishing.service.gov.uk/media/5661b733e5274a03640000/0a/21_2007_Seaton_Tramway.pdf
Fatal accident at Bronwydd Arms station, Gwili Railway	22/2007	19/07/2006	22/2007/01	Closed - I	None	Gwili Railway Co	https://assets.publishing.service.gov.uk/media/5661b68340f0b6036a0000/04/22_2007_Bronwydd_Arms_station.pdf
Fatal accident at Bronwydd Arms station, Gwili Railway	22/2007	19/07/2006	22/2007/02	Closed - I	None	Gwili Railway Co	https://assets.publishing.service.gov.uk/media/5661b68340f0b6036a0000/04/22_2007_Bronwydd_Arms_station.pdf
Fatal accident at Bronwydd Arms station, Gwili Railway	22/2007	19/07/2006	22/2007/03	Closed - I	None	Gwili Railway Co	https://assets.publishing.service.gov.uk/media/5661b68340f0b6036a0000/04/22_2007_Bronwydd_Arms_station.pdf
Fatal accident at Bronwydd Arms station, Gwili Railway	22/2007	19/07/2006	22/2007/04	Closed - I	None	Gwili Railway Co	https://assets.publishing.service.gov.uk/media/5661b68340f0b6036a0000/04/22_2007_Bronwydd_Arms_station.pdf
Fatal accident at Bronwydd Arms station, Gwili Railway	22/2007	19/07/2006	22/2007/05	Closed - I	None	Gwili Railway Co	https://assets.publishing.service.gov.uk/media/5661b68340f0b6036a0000/04/22_2007_Bronwydd_Arms_station.pdf
Fatal accident at Bronwydd Arms station, Gwili Railway	22/2007	19/07/2006	22/2007/06	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/5661b68340f0b6036a0000/04/22_2007_Bronwydd_Arms_station.pdf
Fatal accident at Bronwydd Arms station, Gwili Railway	22/2007	19/07/2006	22/2007/07	Closed - I	None	Gwili Railway Co	https://assets.publishing.service.gov.uk/media/5661b68340f0b6036a0000/04/22_2007_Bronwydd_Arms_station.pdf
Fatal accident at Bronwydd Arms station, Gwili Railway	22/2007	19/07/2006	22/2007/08	Closed - I	None	Gwili Railway Co	https://assets.publishing.service.gov.uk/media/5661b68340f0b6036a0000/04/22_2007_Bronwydd_Arms_station.pdf
Fatal accident at Bronwydd Arms station, Gwili Railway	22/2007	19/07/2006	22/2007/09	Closed - I	None	Gwili Railway Co	https://assets.publishing.service.gov.uk/media/5661b68340f0b6036a0000/04/22_2007_Bronwydd_Arms_station.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf

Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/05	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/06	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/07	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/08	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/09	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/10	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/11	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/12	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/13	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Unauthorised train movement at High Street Kensington	19/2007	29/04/2006	19/2007/14	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/5661a96240f0b603670000/03/19_2007_High_Street_Kensington.pdf
Derailment at Ropley (Mid Hants Railway)	20/2007	25/07/2006	20/2007/01	Closed - I	None	Mid Hants Railway Ltd	https://assets.publishing.service.gov.uk/media/5661aa73e5274a03670000/02/20_2007_Ropley.pdf
Derailment at Ropley (Mid Hants Railway)	20/2007	25/07/2006	20/2007/02	Closed - I	None	Mid Hants Railway Ltd	https://assets.publishing.service.gov.uk/media/5661aa73e5274a03670000/02/20_2007_Ropley.pdf
Derailment at Ropley (Mid Hants Railway)	20/2007	25/07/2006	20/2007/03	Closed - I	None	Mid Hants Railway Ltd	https://assets.publishing.service.gov.uk/media/5661aa73e5274a03670000/02/20_2007_Ropley.pdf
Derailment at Ropley (Mid Hants Railway)	20/2007	25/07/2006	20/2007/04	Closed - I	None	Mid Hants Railway Ltd	https://assets.publishing.service.gov.uk/media/5661aa73e5274a03670000/02/20_2007_Ropley.pdf
Derailment at Ropley (Mid Hants Railway)	20/2007	25/07/2006	20/2007/05	Closed - I	None	Mid Hants Railway Ltd	https://assets.publishing.service.gov.uk/media/5661aa73e5274a03670000/02/20_2007_Ropley.pdf
Derailment at Ropley (Mid Hants Railway)	20/2007	25/07/2006	20/2007/06	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/5661aa73e5274a03670000/02/20_2007_Ropley.pdf
Tram collision at Soho Benson Road, Midland Metro	17/2007	19/12/2006	17/2007/01	Closed - I	None	Travel Midland Metro (TMM)	https://assets.publishing.service.gov.uk/media/5661a341ed915d03590000/06/17_2007_Soho_Benson_Road.pdf
Tram collision at Soho Benson Road, Midland Metro	17/2007	19/12/2006	17/2007/02	Closed - I	None	Travel Midland Metro (TMM)	https://assets.publishing.service.gov.uk/media/5661a341ed915d03590000/06/17_2007_Soho_Benson_Road.pdf
Tram collision at Soho Benson Road, Midland Metro	17/2007	19/12/2006	17/2007/03	Closed - I	None	Travel Midland Metro (TMM)	https://assets.publishing.service.gov.uk/media/5661a341ed915d03590000/06/17_2007_Soho_Benson_Road.pdf

Collision between a tram and road vehicle at New Swan Lane Level Crossing on Midland Metro	18/2007	08/06/2006	18/2007/01	Closed - I	None	West Midlands Metro	https://assets.publishing.service.gov.uk/media/5661a82de5274a03640000/06/18_2007_New_Swan_Lane.pdf
Collision between a tram and road vehicle at New Swan Lane Level Crossing on Midland Metro	18/2007	08/06/2006	18/2007/02	Closed - I	None	West Midlands Metro	https://assets.publishing.service.gov.uk/media/5661a82de5274a03640000/06/18_2007_New_Swan_Lane.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/02	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/03	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/06	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/07	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/08	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Fatal accident involving a train driver, Deal	14/2007	29/07/2006	14/2007/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56619e01ed915d035c0000/04/14_2007_Deal.pdf
Derailment at Starr Gate, Blackpool	15/2007	30/05/2006	15/2007/01	Closed - I	None	Blackpool Borough Council (BBC)	https://assets.publishing.service.gov.uk/media/5661a028ed915d035c0000/06/15_2007_Starr_Gate.pdf
Derailment at Starr Gate, Blackpool	15/2007	30/05/2006	15/2007/01	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/5661a028ed915d035c0000/06/15_2007_Starr_Gate.pdf
Derailment at Starr Gate, Blackpool	15/2007	30/05/2006	15/2007/01	Closed - I	None	Tram Power Limited	https://assets.publishing.service.gov.uk/media/5661a028ed915d035c0000/06/15_2007_Starr_Gate.pdf
Derailment at Starr Gate, Blackpool	15/2007	30/05/2006	15/2007/02	Closed - I	None	Blackpool Borough Council (BBC)	https://assets.publishing.service.gov.uk/media/5661a028ed915d035c0000/06/15_2007_Starr_Gate.pdf
Two near misses at Crofton Old Station No.1 Level Crossing, near Wakefield, West Yorkshire	16/2007	18/05/2006	16/2007/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5661a18e40f0b6036a0000/00/16_2007_Crofton_Old_Station.pdf
Two near misses at Crofton Old Station No.1 Level Crossing, near Wakefield, West Yorkshire	16/2007	18/05/2006	16/2007/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5661a18e40f0b6036a0000/00/16_2007_Crofton_Old_Station.pdf
Two near misses at Crofton Old Station No.1 Level Crossing, near Wakefield, West Yorkshire	16/2007	18/05/2006	16/2007/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5661a18e40f0b6036a0000/00/16_2007_Crofton_Old_Station.pdf

Two near misses at Crofton Old Station No.1 Level Crossing, near Wakefield, West Yorkshire	16/2007	18/05/2006	16/2007/04	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5661a18e40f0b6036a0000/00/16_2007_Crofton_Old_Station.pdf
Two near misses at Crofton Old Station No.1 Level Crossing, near Wakefield, West Yorkshire	16/2007	18/05/2006	16/2007/05	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/5661a18e40f0b6036a0000/00/16_2007_Crofton_Old_Station.pdf
Two near misses at Crofton Old Station No.1 Level Crossing, near Wakefield, West Yorkshire	16/2007	18/05/2006	16/2007/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/5661a18e40f0b6036a0000/00/16_2007_Crofton_Old_Station.pdf
Locomotive runaway near East Didsbury	13/2007	27/08/2006	13/2007/01	Closed - I	None	Freight Train Operating Company (FOC)	https://assets.publishing.service.gov.uk/media/567abf2b40f0b6141700002d/13_2007_East_Didsbury.pdf
Locomotive runaway near East Didsbury	13/2007	27/08/2006	13/2007/02	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/567abf2b40f0b6141700002d/13_2007_East_Didsbury.pdf
Locomotive runaway near East Didsbury	13/2007	27/08/2006	13/2007/03	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/567abf2b40f0b6141700002d/13_2007_East_Didsbury.pdf
Locomotive runaway near East Didsbury	13/2007	27/08/2006	13/2007/04	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/567abf2b40f0b6141700002d/13_2007_East_Didsbury.pdf
Locomotive runaway near East Didsbury	13/2007	27/08/2006	13/2007/05	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/567abf2b40f0b6141700002d/13_2007_East_Didsbury.pdf
Locomotive runaway near East Didsbury	13/2007	27/08/2006	13/2007/06	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/567abf2b40f0b6141700002d/13_2007_East_Didsbury.pdf
Locomotive runaway near East Didsbury	13/2007	27/08/2006	13/2007/07	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/567abf2b40f0b6141700002d/13_2007_East_Didsbury.pdf
Locomotive runaway near East Didsbury	13/2007	27/08/2006	13/2007/08	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/567abf2b40f0b6141700002d/13_2007_East_Didsbury.pdf
Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf
Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf
Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/03	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf
Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/04	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf
Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf
Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/05	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf
Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/06	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf
Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/07	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf

Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/08	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf
Runaway permanent way trolley at Notting Hill Gate	12/2007	24/05/2006	12/2007/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56619a6340f0b603670000/00/12_2007_Notting_Hill_Gate.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/01	Closed - I	None	Railcare	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/02	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/02	Closed - I	None	Silverlink Train Services	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/03	Closed - I	None	Railcare	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/04	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/05	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/05	Closed - I	None	Silverlink Train Services	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/06	Closed - I	None	Railcare	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/07	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/07	Closed - I	None	Silverlink Train Services	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/08	Closed - I	None	Railcare	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/09	Closed - I	None	Railcare	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Traction control failure causing a signal to be passed at danger, Camden Road	10/2007	07/04/2006	10/2007/09	Closed - I	None	West Coast Traincare Ltd	https://assets.publishing.service.gov.uk/media/566065b5ed915d1fdb0000/0f/10_2007_Camden_Road.pdf
Huntingdon train door incident	11/2007	15/02/2006	11/2007/01	Closed - I	None	First Capital Connect	https://assets.publishing.service.gov.uk/media/566197dbed915d03590000/02/11_2007_Huntingdon.pdf
Huntingdon train door incident	11/2007	15/02/2006	11/2007/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566197dbed915d03590000/02/11_2007_Huntingdon.pdf
Huntingdon train door incident	11/2007	15/02/2006	11/2007/03	Closed - I	None	HSBC Rail (UK) Ltd	https://assets.publishing.service.gov.uk/media/566197dbed915d03590000/02/11_2007_Huntingdon.pdf
Huntingdon train door incident	11/2007	15/02/2006	11/2007/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566197dbed915d03590000/02/11_2007_Huntingdon.pdf

Huntingdon train door incident	11/2007	15/02/2006	11/2007/05	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/566197dbed915d03590000/02/11_2007_Huntingdon.pdf
Huntingdon train door incident	11/2007	15/02/2006	11/2007/06	Closed - I	None	First Capital Connect	https://assets.publishing.service.gov.uk/media/566197dbed915d03590000/02/11_2007_Huntingdon.pdf
Train collision with a road vehicle at Bratts Blackhouse No 1 User Worked Crossing, near Sizewell, Suffolk	09/2007	22/05/2006	09/2007/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566062d6ed915d036a0000/1e/09_2007_Bratts_Blackhouse.pdf
Train collision with a road vehicle at Bratts Blackhouse No 1 User Worked Crossing, near Sizewell, Suffolk	09/2007	22/05/2006	09/2007/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566062d6ed915d036a0000/1e/09_2007_Bratts_Blackhouse.pdf
Train collision with a road vehicle at Bratts Blackhouse No 1 User Worked Crossing, near Sizewell, Suffolk	09/2007	22/05/2006	09/2007/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566062d6ed915d036a0000/1e/09_2007_Bratts_Blackhouse.pdf
Train collision with a road vehicle at Bratts Blackhouse No 1 User Worked Crossing, near Sizewell, Suffolk	09/2007	22/05/2006	09/2007/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566062d6ed915d036a0000/1e/09_2007_Bratts_Blackhouse.pdf
Train collision with a road vehicle at Bratts Blackhouse No 1 User Worked Crossing, near Sizewell, Suffolk	09/2007	22/05/2006	09/2007/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566062d6ed915d036a0000/1e/09_2007_Bratts_Blackhouse.pdf
Train collision with a road vehicle at Bratts Blackhouse No 1 User Worked Crossing, near Sizewell, Suffolk	09/2007	22/05/2006	09/2007/06	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/566062d6ed915d036a0000/1e/09_2007_Bratts_Blackhouse.pdf
Train collision with a road vehicle at Bratts Blackhouse No 1 User Worked Crossing, near Sizewell, Suffolk	09/2007	22/05/2006	09/2007/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566062d6ed915d036a0000/1e/09_2007_Bratts_Blackhouse.pdf
Train collision with a road vehicle at Bratts Blackhouse No 1 User Worked Crossing, near Sizewell, Suffolk	09/2007	22/05/2006	09/2007/08	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/566062d6ed915d036a0000/1e/09_2007_Bratts_Blackhouse.pdf
Derailment at Long Millgate, Manchester	08/2007	22/03/2006	08/2007/01	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/56606171ed915d036a0000/1c/08_2007_Long_Millgate.pdf
Derailment at Long Millgate, Manchester	08/2007	22/03/2006	08/2007/02	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/56606171ed915d036a0000/1c/08_2007_Long_Millgate.pdf
Derailment at Long Millgate, Manchester	08/2007	22/03/2006	08/2007/03	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/56606171ed915d036a0000/1c/08_2007_Long_Millgate.pdf
Derailment at Long Millgate, Manchester	08/2007	22/03/2006	08/2007/03	Closed - I	None	Manchester Metrolink	https://assets.publishing.service.gov.uk/media/56606171ed915d036a0000/1c/08_2007_Long_Millgate.pdf
Derailment at Long Millgate, Manchester	08/2007	22/03/2006	08/2007/04	Closed - I	None	Greater Manchester Passenger Transport Executive (GMPTE)	https://assets.publishing.service.gov.uk/media/56606171ed915d036a0000/1c/08_2007_Long_Millgate.pdf
Passenger train derailments on the Ravenglass & Eskdale Railway	07/2007	29/05/2006	07/2007/01	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56604f0d40f0b62ad100000/d/07_2007_Ravenglass_Eskdale.pdf
Passenger train derailments on the Ravenglass & Eskdale Railway	07/2007	29/05/2006	07/2007/02	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56604f0d40f0b62ad100000/d/07_2007_Ravenglass_Eskdale.pdf
Passenger train derailments on the Ravenglass & Eskdale Railway	07/2007	29/05/2006	07/2007/03	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56604f0d40f0b62ad100000/d/07_2007_Ravenglass_Eskdale.pdf
Passenger train derailments on the Ravenglass & Eskdale Railway	07/2007	29/05/2006	07/2007/04	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56604f0d40f0b62ad100000/d/07_2007_Ravenglass_Eskdale.pdf

Passenger train derailments on the Ravenglass & Eskdale Railway	07/2007	29/05/2006	07/2007/05	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56604f0d40f0b62ad100000d/07_2007_Ravenglass_Eskdale.pdf
Passenger train derailments on the Ravenglass & Eskdale Railway	07/2007	29/05/2006	07/2007/06	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56604f0d40f0b62ad100000d/07_2007_Ravenglass_Eskdale.pdf
Passenger train derailments on the Ravenglass & Eskdale Railway	07/2007	29/05/2006	07/2007/07	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56604f0d40f0b62ad100000d/07_2007_Ravenglass_Eskdale.pdf
Passenger train derailments on the Ravenglass & Eskdale Railway	07/2007	29/05/2006	07/2007/08	Closed - I	None	Ravenglass & Eskdale Railway	https://assets.publishing.service.gov.uk/media/56604f0d40f0b62ad100000d/07_2007_Ravenglass_Eskdale.pdf
Dispatch of a train with an unsecured load, Basford Hall Yard, Crewe	06/2007	21/02/2006	06/2007/01	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/56604da5e5274a74e000000f/06_2007_Basford_Hall.pdf
Dispatch of a train with an unsecured load, Basford Hall Yard, Crewe	06/2007	21/02/2006	06/2007/02	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/56604da5e5274a74e000000f/06_2007_Basford_Hall.pdf
Dispatch of a train with an unsecured load, Basford Hall Yard, Crewe	06/2007	21/02/2006	06/2007/03	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/56604da5e5274a74e000000f/06_2007_Basford_Hall.pdf
Dispatch of a train with an unsecured load, Basford Hall Yard, Crewe	06/2007	21/02/2006	06/2007/04	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/56604da5e5274a74e000000f/06_2007_Basford_Hall.pdf
Dispatch of a train with an unsecured load, Basford Hall Yard, Crewe	06/2007	21/02/2006	06/2007/05	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/56604da5e5274a74e000000f/06_2007_Basford_Hall.pdf
Unauthorised train movement and subsequent derailment at Haymarket, Edinburgh	03/2007	14/01/2006	03/2007/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/566047d140f0b60367000042/03_2007_Haymarket.pdf
Unauthorised train movement and subsequent derailment at Haymarket, Edinburgh	03/2007	14/01/2006	03/2007/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566047d140f0b60367000042/03_2007_Haymarket.pdf
Unauthorised train movement and subsequent derailment at Haymarket, Edinburgh	03/2007	14/01/2006	03/2007/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566047d140f0b60367000042/03_2007_Haymarket.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/01	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/02	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/02	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/03	Closed - NI	None	Steam Powered Services Limited	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/04	Closed - I	None	North Yorkshire Moors Railway	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/05	Closed - I	None	North Yorkshire Moors Railway	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/06	Closed - I	None	Heritage Railway Association	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf

The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/06	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/07	Closed - I	None	North Yorkshire Moors Railway	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/08	Closed - I	None	North Yorkshire Moors Railway	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
The blowback of a locomotive fire at Grosmont on the North Yorkshire Moors Railway	04/2007	16/04/2006	04/2007/09	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/566049e2ed915d036a00001a/04_2007_Grosmont.pdf
Derailment near Waterside, East Ayrshire	05/2007	21/01/2006	05/2007/01	Closed - I	None	Scottish Coal Company Limited	https://assets.publishing.service.gov.uk/media/56604c96ed915d1fdb00000d/05_2007_Waterside.pdf
Derailment near Waterside, East Ayrshire	05/2007	21/01/2006	05/2007/02	Closed - I	None	Scottish Coal Company Limited	https://assets.publishing.service.gov.uk/media/56604c96ed915d1fdb00000d/05_2007_Waterside.pdf
Derailment near Waterside, East Ayrshire	05/2007	21/01/2006	05/2007/03	Closed - I	None	Scottish Coal Company Limited	https://assets.publishing.service.gov.uk/media/56604c96ed915d1fdb00000d/05_2007_Waterside.pdf
Derailment near Waterside, East Ayrshire	05/2007	21/01/2006	05/2007/04	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56604c96ed915d1fdb00000d/05_2007_Waterside.pdf
Derailment near Waterside, East Ayrshire	05/2007	21/01/2006	05/2007/05	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56604c96ed915d1fdb00000d/05_2007_Waterside.pdf
Derailment near Waterside, East Ayrshire	05/2007	21/01/2006	05/2007/06	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/56604c96ed915d1fdb00000d/05_2007_Waterside.pdf
Derailment near Waterside, East Ayrshire	05/2007	21/01/2006	05/2007/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/56604c96ed915d1fdb00000d/05_2007_Waterside.pdf
Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/01	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf
Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/02	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf
Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/03	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf
Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf
Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/05	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf
Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/06	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf
Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/07	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf
Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/08	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf

Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/09	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf
Derailment of a freight train at Brentingby Junction, near Melton Mowbray	01/2007	09/02/2006	01/2007/10	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/5660446d40f0b6036700003e/01_2007_Brentingby.pdf
Derailment of a freight train at Cricklewood Curve	02/2007	31/01/2006	02/2007/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566045a640f0b60367000040/02_2007_Cricklewood.pdf
Derailment of a freight train at Cricklewood Curve	02/2007	31/01/2006	02/2007/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566045a640f0b60367000040/02_2007_Cricklewood.pdf
Derailment of a freight train at Cricklewood Curve	02/2007	31/01/2006	02/2007/03	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/566045a640f0b60367000040/02_2007_Cricklewood.pdf
Derailment of a freight train at Cricklewood Curve	02/2007	31/01/2006	02/2007/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566045a640f0b60367000040/02_2007_Cricklewood.pdf
Derailment of a freight train at Cricklewood Curve	02/2007	31/01/2006	02/2007/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566045a640f0b60367000040/02_2007_Cricklewood.pdf
Derailment of a freight train at Cricklewood Curve	02/2007	31/01/2006	02/2007/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/566045a640f0b60367000040/02_2007_Cricklewood.pdf
Autumn Adhesion Investigation Part 2: Signal LW9 Passed at Danger at Lewes	25/2006(2)	30/11/2005	25/2006 Pt 2/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/565f0e98e5274a74e0000007/25_2006_Pt2_Autumn_Adhesion_Lewes.pdf
Autumn Adhesion Investigation Part 2: Signal LW9 Passed at Danger at Lewes	25/2006(2)	30/11/2005	25/2006 Pt 2/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/565f0e98e5274a74e0000007/25_2006_Pt2_Autumn_Adhesion_Lewes.pdf
Autumn Adhesion Investigation Part 2: Signal LW9 Passed at Danger at Lewes	25/2006(2)	30/11/2005	25/2006 Pt 2/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/565f0e98e5274a74e0000007/25_2006_Pt2_Autumn_Adhesion_Lewes.pdf
Autumn Adhesion Investigation Part 2: Signal LW9 Passed at Danger at Lewes	25/2006(2)	30/11/2005	25/2006 Pt 2/03	Closed - I	None	Southern Railway	https://assets.publishing.service.gov.uk/media/565f0e98e5274a74e0000007/25_2006_Pt2_Autumn_Adhesion_Lewes.pdf
Autumn Adhesion Investigation Part 1: Signals WK338 and WK336 Passed at Danger at Esher	25/2006(1)	25/11/2005	25/2006 pt1/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/565f0e5940f0b603670000031/25_2006_pt1_Autumn_Adhesion.pdf
Autumn Adhesion Investigation Part 1: Signals WK338 and WK336 Passed at Danger at Esher	25/2006(1)	25/11/2005	25/2006 pt1/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/565f0e5940f0b603670000031/25_2006_pt1_Autumn_Adhesion.pdf
Autumn Adhesion Investigation Part 1: Signals WK338 and WK336 Passed at Danger at Esher	25/2006(1)	25/11/2005	25/2006 pt1/02	Closed - I	None	South West Trains	https://assets.publishing.service.gov.uk/media/565f0e5940f0b603670000031/25_2006_pt1_Autumn_Adhesion.pdf
Autumn Adhesion Investigation Part 1: Signals WK338 and WK336 Passed at Danger at Esher	25/2006(1)	25/11/2005	25/2006 pt1/03	Closed - I	None	South West Trains	https://assets.publishing.service.gov.uk/media/565f0e5940f0b603670000031/25_2006_pt1_Autumn_Adhesion.pdf
Autumn Adhesion Investigation Part 3: Review of adhesion-related incidents	25/2006(3)	30/11/2005	25/2006 pt3/01	Closed - I	Blue	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/565f0f54ed915d036a000000f/25_2006_Pt3_Class_investigation_Autumn_Adhesion_incidents_at_Esher_and_Lewes.pdf
Autumn Adhesion Investigation Part 3: Review of adhesion-related incidents	25/2006(3)	30/11/2005	25/2006 pt3/02	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/565f0f54ed915d036a000000f/25_2006_Pt3_Class_investigation_Autumn_Adhesion_incidents_at_Esher_and_Lewes.pdf
Autumn Adhesion Investigation Part 3: Review of adhesion-related incidents	25/2006(3)	30/11/2005	25/2006 pt3/03	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/565f0f54ed915d036a000000f/25_2006_Pt3_Class_investigation_Autumn_Adhesion_incidents_at_Esher_and_Lewes.pdf

Collision between train and buffer stops at Sudbury	26/2006	27/01/2006	26/2006/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905be5274a42900001cd/26_2006_Sudbury.pdf
Broken Rails at Urchfont and Kennington following the passage of a freight train	27/2006	05/01/2006	27/2006/01	Closed - I	None	DRC	https://assets.publishing.service.gov.uk/media/547c9061ed915d4c10000197/27_2006_Urchfont_Kennington.pdf
Broken Rails at Urchfont and Kennington following the passage of a freight train	27/2006	05/01/2006	27/2006/02	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/547c9061ed915d4c10000197/27_2006_Urchfont_Kennington.pdf
Broken Rails at Urchfont and Kennington following the passage of a freight train	27/2006	05/01/2006	27/2006/03	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/547c9061ed915d4c10000197/27_2006_Urchfont_Kennington.pdf
Broken Rails at Urchfont and Kennington following the passage of a freight train	27/2006	05/01/2006	27/2006/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9061ed915d4c10000197/27_2006_Urchfont_Kennington.pdf
Broken Rails at Urchfont and Kennington following the passage of a freight train	27/2006	05/01/2006	27/2006/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9061ed915d4c10000197/27_2006_Urchfont_Kennington.pdf
Broken Rails at Urchfont and Kennington following the passage of a freight train	27/2006	05/01/2006	27/2006/06	Closed - I	None	DRC	https://assets.publishing.service.gov.uk/media/547c9061ed915d4c10000197/27_2006_Urchfont_Kennington.pdf
Broken Rails at Urchfont and Kennington following the passage of a freight train	27/2006	05/01/2006	27/2006/06	Closed - I	None	Freightliner Group	https://assets.publishing.service.gov.uk/media/547c9061ed915d4c10000197/27_2006_Urchfont_Kennington.pdf
Broken Rails at Urchfont and Kennington following the passage of a freight train	27/2006	05/01/2006	27/2006/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9061ed915d4c10000197/27_2006_Urchfont_Kennington.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/02	Closed - I	None	Mainline Infrastructure Owners	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/04	Closed - I	Blue	Department for Transport	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/04	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/04	Closed - I	Blue	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/05	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/06	Closed - NI	Red	Network Rail	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/06	Closed - NI	Red	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf

Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/08	Closed - I	None	Mainline Infrastructure Owners	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/09	Closed - I	None	Mainline Infrastructure Owners	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/09	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Investigation into station pedestrian crossings (including pedestrian gates at highway level crossings); with reference to the fat	23/2006	03/12/2005	23/2006/10	Closed - I	None	Mainline Infrastructure Owners	https://assets.publishing.service.gov.uk/media/547c9062ed915d4c0d0001b3/23_2006_Elsenham.pdf
Derailment at Archway	24/2006	02/06/2006	24/2006/01	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/547c904e40f0b602410001a5/24_2006_Archway.pdf
Derailment at Archway	24/2006	02/06/2006	24/2006/02	Closed - I	None	London Underground Ltd	https://assets.publishing.service.gov.uk/media/547c904e40f0b602410001a5/24_2006_Archway.pdf
Derailment at Archway	24/2006	02/06/2006	24/2006/03	Closed - I	None	Tubelines	https://assets.publishing.service.gov.uk/media/547c904e40f0b602410001a5/24_2006_Archway.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/04	Closed - I	None	Department for Communities and Local Government	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/04	Closed - I	None	The Scottish Executive	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/08	Closed - I	None	Bombardier Transportation	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/09	Closed - I	Blue	Rolling Stock Leasing Companies	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf
Derailment near Moy, Inverness-shire	22/2006	26/11/2005	22/2006/10	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/547c9066e5274a42900001d5/22_2006_Moy.pdf

Wagon derailment at York station	21/2006	18/01/2006	21/2006/01	Closed - I	None	GE Rail Services	https://assets.publishing.service.gov.uk/media/547c905d40f0b602440001a9/21_2006_York.pdf
Wagon derailment at York station	21/2006	18/01/2006	21/2006/02	Closed - I	None	GE Rail Services	https://assets.publishing.service.gov.uk/media/547c905d40f0b602440001a9/21_2006_York.pdf
Wagon derailment at York station	21/2006	18/01/2006	21/2006/03	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/547c905d40f0b602440001a9/21_2006_York.pdf
Wagon derailment at York station	21/2006	18/01/2006	21/2006/04	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/547c905d40f0b602440001a9/21_2006_York.pdf
Derailment at Oubeck North near Lancaster	19/2006	04/11/2005	19/2006/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906d40f0b602440001af/19_2006_Oubeck.pdf
Derailment at Oubeck North near Lancaster	19/2006	04/11/2005	19/2006/02	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906d40f0b602440001af/19_2006_Oubeck.pdf
Derailment at Oubeck North near Lancaster	19/2006	04/11/2005	19/2006/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906d40f0b602440001af/19_2006_Oubeck.pdf
Derailment at Oubeck North near Lancaster	19/2006	04/11/2005	19/2006/04	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/547c906d40f0b602440001af/19_2006_Oubeck.pdf
Derailment at Oubeck North near Lancaster	19/2006	04/11/2005	19/2006/05	Closed - NI	None	Alstom	https://assets.publishing.service.gov.uk/media/547c906d40f0b602440001af/19_2006_Oubeck.pdf
Derailment at Oubeck North near Lancaster	19/2006	04/11/2005	19/2006/06	Closed - NI	None	Angel Trains Limited	https://assets.publishing.service.gov.uk/media/547c906d40f0b602440001af/19_2006_Oubeck.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/01	Closed - I	None	Harsco Rail	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/02	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/03	Closed - I	None	Harsco Rail	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/04	Closed - I	None	Harsco Rail	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/05	Closed - I	None	Torrent Trackside Limited	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/06	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/07	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/08	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/08	Closed - I	None	Railway Contractors	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf

Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/09	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/10	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/11	Closed - I	None	Harsco Rail	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/12	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/13	Closed - I	None	Mainline Infrastructure Owners	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/14	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/15	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/15	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Report on the runaway manually propelled trolley between Larkhall and Barncluith Tunnel	20/2006	02/11/2005	20/2006/16	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906e40f0b602410001b9/20_2006_Larkhall.pdf
Derailment at Blackpool Pleasure Beach	18/2006	06/07/2006	18/2006/01	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/547c904c40f0b602440001a1/18_2006_Blackpool_Pleasure_Beach.pdf
Derailment at Blackpool Pleasure Beach	18/2006	06/07/2006	18/2006/02	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/547c904c40f0b602440001a1/18_2006_Blackpool_Pleasure_Beach.pdf
Derailment of a Ballast Plough Brake Van at Carlisle	17/2006	06/02/2006	17/2006/01	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/547c905840f0b602440001a7/17_2006_Carlisle.pdf
Derailment of a Ballast Plough Brake Van at Carlisle	17/2006	06/02/2006	17/2006/02	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/547c905840f0b602440001a7/17_2006_Carlisle.pdf
Derailment of a Ballast Plough Brake Van at Carlisle	17/2006	06/02/2006	17/2006/03	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/547c905840f0b602440001a7/17_2006_Carlisle.pdf
Derailment of a Ballast Plough Brake Van at Carlisle	17/2006	06/02/2006	17/2006/04	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/547c905840f0b602440001a7/17_2006_Carlisle.pdf
Derailment of a Ballast Plough Brake Van at Carlisle	17/2006	06/02/2006	17/2006/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905840f0b602440001a7/17_2006_Carlisle.pdf
Derailment of a Ballast Plough Brake Van at Carlisle	17/2006	06/02/2006	17/2006/06	Closed - I	None	First Engineering	https://assets.publishing.service.gov.uk/media/547c905840f0b602440001a7/17_2006_Carlisle.pdf
Derailment of a Ballast Plough Brake Van at Carlisle	17/2006	06/02/2006	17/2006/06	Closed - I	None	WA Developments	https://assets.publishing.service.gov.uk/media/547c905840f0b602440001a7/17_2006_Carlisle.pdf
Trackworker fatality at Trafford Park	16/2006	26/10/2005	16/2006/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c907140f0b602440001b1/16_2006_Trafford_Park.pdf

Trackworker fatality at Trafford Park	16/2006	26/10/2005	16/2006/02	Closed - I	None	Schweizer UK	https://assets.publishing.service.gov.uk/media/547c907140f0b602440001b1/16_2006_Trafford_Park.pdf
Trackworker fatality at Trafford Park	16/2006	26/10/2005	16/2006/03	Closed - I	None	Schweizer UK	https://assets.publishing.service.gov.uk/media/547c907140f0b602440001b1/16_2006_Trafford_Park.pdf
Trackworker fatality at Trafford Park	16/2006	26/10/2005	16/2006/04	Closed - I	Blue	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/547c907140f0b602440001b1/16_2006_Trafford_Park.pdf
Trackworker fatality at Trafford Park	16/2006	26/10/2005	16/2006/05	Closed - I	Blue	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/547c907140f0b602440001b1/16_2006_Trafford_Park.pdf
Trackworker fatality at Trafford Park	16/2006	26/10/2005	16/2006/06	Closed - I	Blue	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/547c907140f0b602440001b1/16_2006_Trafford_Park.pdf
Trackworker fatality at Trafford Park	16/2006	26/10/2005	16/2006/07	Closed - I	None	Carillion Construction Limited	https://assets.publishing.service.gov.uk/media/547c907140f0b602440001b1/16_2006_Trafford_Park.pdf
Trackworker fatality at Trafford Park	16/2006	26/10/2005	16/2006/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c907140f0b602440001b1/16_2006_Trafford_Park.pdf
Trackworker fatality at Trafford Park	16/2006	26/10/2005	16/2006/09	Closed - I	Blue	Network Rail	https://assets.publishing.service.gov.uk/media/547c907140f0b602440001b1/16_2006_Trafford_Park.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/01	Closed - I	None	RSSB	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/02	Closed - I	None	Railway Contractors	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/03	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Cutting of rail from a line that was still open to traffic, near Thirsk station, East Coast Main Line	15/2006	11/01/2006	15/2006/08	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c905f40f0b602410001af/15_2006_Thirsk.pdf
Derailment near Liverpool Central underground station	14/2006	26/10/2005	14/2006/01	Closed - I	None	Merseyrail	https://assets.publishing.service.gov.uk/media/547c9072e5274a428d00019b/14_2006_Liverpool_Central.pdf

Derailment near Liverpool Central underground station	14/2006	26/10/2005	14/2006/01	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9072e5274a428d00019b/14_2006_Liverpool_Central.pdf
Derailment near Liverpool Central underground station	14/2006	26/10/2005	14/2006/02	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9072e5274a428d00019b/14_2006_Liverpool_Central.pdf
Derailment near Liverpool Central underground station	14/2006	26/10/2005	14/2006/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9072e5274a428d00019b/14_2006_Liverpool_Central.pdf
Derailment near Liverpool Central underground station	14/2006	26/10/2005	14/2006/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9072e5274a428d00019b/14_2006_Liverpool_Central.pdf
Derailment near Liverpool Central underground station	14/2006	26/10/2005	14/2006/05	Closed - NI	Red	Network Rail	https://assets.publishing.service.gov.uk/media/547c9072e5274a428d00019b/14_2006_Liverpool_Central.pdf
Derailment near Liverpool Central underground station	14/2006	26/10/2005	14/2006/06	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9072e5274a428d00019b/14_2006_Liverpool_Central.pdf
Derailment near Liverpool Central underground station	14/2006	26/10/2005	14/2006/07	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9072e5274a428d00019b/14_2006_Liverpool_Central.pdf
Derailment near Liverpool Central underground station	14/2006	26/10/2005	14/2006/08	Closed - I	None	Merseyrail	https://assets.publishing.service.gov.uk/media/547c9072e5274a428d00019b/14_2006_Liverpool_Central.pdf
Collision at Black Horse Drove Crossing, near Littleport, Cambridgeshire	12/2006	19/10/2005	12/2006/01	Closed - NI	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9075ed915d4c100001a3/12_2006_Black_Horse_Drove.pdf
Collision at Black Horse Drove Crossing, near Littleport, Cambridgeshire	12/2006	19/10/2005	12/2006/02	Closed - I	None	Department for Transport	https://assets.publishing.service.gov.uk/media/547c9075ed915d4c100001a3/12_2006_Black_Horse_Drove.pdf
Collision at Black Horse Drove Crossing, near Littleport, Cambridgeshire	12/2006	19/10/2005	12/2006/02	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/547c9075ed915d4c100001a3/12_2006_Black_Horse_Drove.pdf
Collision at Black Horse Drove Crossing, near Littleport, Cambridgeshire	12/2006	19/10/2005	12/2006/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9075ed915d4c100001a3/12_2006_Black_Horse_Drove.pdf
Collision at Black Horse Drove Crossing, near Littleport, Cambridgeshire	12/2006	19/10/2005	12/2006/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9075ed915d4c100001a3/12_2006_Black_Horse_Drove.pdf
Station over-run at Haywards Heath	10/2006	12/01/2006	10/2006/01	Closed - I	None	First Capital Connect	https://assets.publishing.service.gov.uk/media/547c905fed915d4c0d0001af/10_2006_Haywards_Heath.pdf
Station over-run at Haywards Heath	10/2006	12/01/2006	10/2006/02	Closed - I	None	Alstom	https://assets.publishing.service.gov.uk/media/547c905fed915d4c0d0001af/10_2006_Haywards_Heath.pdf
Collision at New Addington on Croydon Tramlink	11/2006	23/11/2005	11/2006/01	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/547c9069ed915d4c1000019b/11_2006_New_Addington.pdf
Collision at New Addington on Croydon Tramlink	11/2006	23/11/2005	11/2006/02	Closed - I	Blue	Tramtrack Croydon Ltd	https://assets.publishing.service.gov.uk/media/547c9069ed915d4c1000019b/11_2006_New_Addington.pdf
Collision at New Addington on Croydon Tramlink	11/2006	23/11/2005	11/2006/03	Closed - I	Blue	Tramtrack Croydon Ltd	https://assets.publishing.service.gov.uk/media/547c9069ed915d4c1000019b/11_2006_New_Addington.pdf
Collision at New Addington on Croydon Tramlink	11/2006	23/11/2005	11/2006/04	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/547c9069ed915d4c1000019b/11_2006_New_Addington.pdf

Collision at New Addington on Croydon Tramlink	11/2006	23/11/2005	11/2006/05	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/547c9069ed915d4c1000019b/11_2006_New_Addington.pdf
Near miss of two track persons by a tram on the Manchester Metrolink, Radcliffe	09/2006	08/11/2005	09/2006/01	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/547c906ce5274a428d000195/09_2006_Manchester_Metrolink.pdf
Near miss of two track persons by a tram on the Manchester Metrolink, Radcliffe	09/2006	08/11/2005	09/2006/02	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/547c906ce5274a428d000195/09_2006_Manchester_Metrolink.pdf
Near miss of two track persons by a tram on the Manchester Metrolink, Radcliffe	09/2006	08/11/2005	09/2006/03	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/547c906ce5274a428d000195/09_2006_Manchester_Metrolink.pdf
Near miss of two track persons by a tram on the Manchester Metrolink, Radcliffe	09/2006	08/11/2005	09/2006/04	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/547c906ce5274a428d000195/09_2006_Manchester_Metrolink.pdf
Near miss of two track persons by a tram on the Manchester Metrolink, Radcliffe	09/2006	08/11/2005	09/2006/05	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/547c906ce5274a428d000195/09_2006_Manchester_Metrolink.pdf
Near miss of two track persons by a tram on the Manchester Metrolink, Radcliffe	09/2006	08/11/2005	09/2006/06	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/547c906ce5274a428d000195/09_2006_Manchester_Metrolink.pdf
Near miss of two track persons by a tram on the Manchester Metrolink, Radcliffe	09/2006	08/11/2005	09/2006/07	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/547c906ce5274a428d000195/09_2006_Manchester_Metrolink.pdf
Near miss of two track persons by a tram on the Manchester Metrolink, Radcliffe	09/2006	08/11/2005	09/2006/08	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/547c906ce5274a428d000195/09_2006_Manchester_Metrolink.pdf
Near miss of two track persons by a tram on the Manchester Metrolink, Radcliffe	09/2006	08/11/2005	09/2006/09	Closed - I	None	Keolis Amey Metrolink	https://assets.publishing.service.gov.uk/media/547c906ce5274a428d000195/09_2006_Manchester_Metrolink.pdf
Freight train derailment at Hatherley, near Cheltenham Spa	08/2006	18/10/2005	08/2006/01	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/547c9076e5274a428d00019d/08_2006_Hatherley.pdf
Freight train derailment at Hatherley, near Cheltenham Spa	08/2006	18/10/2005	08/2006/02	Closed - I	None	EWS	https://assets.publishing.service.gov.uk/media/547c9076e5274a428d00019d/08_2006_Hatherley.pdf
Freight train derailment at Hatherley, near Cheltenham Spa	08/2006	18/10/2005	08/2006/03	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/547c9076e5274a428d00019d/08_2006_Hatherley.pdf
Freight train derailment at Hatherley, near Cheltenham Spa	08/2006	18/10/2005	08/2006/04	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/547c9076e5274a428d00019d/08_2006_Hatherley.pdf
Freight train derailment at Hatherley, near Cheltenham Spa	08/2006	18/10/2005	08/2006/05	Closed - I	None	Freight Operating Companies	https://assets.publishing.service.gov.uk/media/547c9076e5274a428d00019d/08_2006_Hatherley.pdf
Freight train derailment at Hatherley, near Cheltenham Spa	08/2006	18/10/2005	08/2006/05	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c9076e5274a428d00019d/08_2006_Hatherley.pdf
The collision of a locomotive with carriages at Great Central Railway's Loughborough Central station	07/2006	04/02/2006	07/2006/01	Closed - I	None	Great Central Railway	https://assets.publishing.service.gov.uk/media/547c9059ed915d4c10000191/07_2006_Loughborough_Central_Station.pdf
The collision of a locomotive with carriages at Great Central Railway's Loughborough Central station	07/2006	04/02/2006	07/2006/02	Closed - I	None	Great Central Railway	https://assets.publishing.service.gov.uk/media/547c9059ed915d4c10000191/07_2006_Loughborough_Central_Station.pdf
The collision of a locomotive with carriages at Great Central Railway's Loughborough Central station	07/2006	04/02/2006	07/2006/03	Closed - I	None	Great Central Railway	https://assets.publishing.service.gov.uk/media/547c9059ed915d4c10000191/07_2006_Loughborough_Central_Station.pdf

The collision of a locomotive with carriages at Great Central Railway's Loughborough Central station	07/2006	04/02/2006	07/2006/04	Closed - I	None	Great Central Railway	https://assets.publishing.service.gov.uk/media/547c9059ed915d4c10000191/07_2006_Loughborough_Central_Station.pdf
Runaway incidents on Blackpool Transport Services Tramway	05/2006	03/12/2005	05/2006/01	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/547c906aed915d4c0d0001b7/05_2006_Runaway_incidents_Blackpool_Transport.pdf
Runaway incidents on Blackpool Transport Services Tramway	05/2006	03/12/2005	05/2006/02	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/547c906aed915d4c0d0001b7/05_2006_Runaway_incidents_Blackpool_Transport.pdf
Runaway incidents on Blackpool Transport Services Tramway	05/2006	03/12/2005	05/2006/03	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/547c906aed915d4c0d0001b7/05_2006_Runaway_incidents_Blackpool_Transport.pdf
Runaway incidents on Blackpool Transport Services Tramway	05/2006	03/12/2005	05/2006/04	Closed - I	None	Blackpool Transport Services	https://assets.publishing.service.gov.uk/media/547c906aed915d4c0d0001b7/05_2006_Runaway_incidents_Blackpool_Transport.pdf
Derailment at Phipps Bridge, Croydon Tramlink	04/2006	21/10/2005	04/2006/01	Closed - I	None	Tramtrack Croydon Ltd	https://assets.publishing.service.gov.uk/media/547c907340f0b602410001bd/04_2006_Phipps_Bridge.pdf
Derailment at Phipps Bridge, Croydon Tramlink	04/2006	21/10/2005	04/2006/02	Closed - I	None	Light Rail Tram (LTR) Infrastructure	https://assets.publishing.service.gov.uk/media/547c907340f0b602410001bd/04_2006_Phipps_Bridge.pdf
Derailment at Phipps Bridge, Croydon Tramlink	04/2006	21/10/2005	04/2006/02	Closed - I	None	Railway Contractors	https://assets.publishing.service.gov.uk/media/547c907340f0b602410001bd/04_2006_Phipps_Bridge.pdf
Derailment at Phipps Bridge, Croydon Tramlink	04/2006	21/10/2005	04/2006/03	Closed - I	None	Croydon Tramlink	https://assets.publishing.service.gov.uk/media/547c907340f0b602410001bd/04_2006_Phipps_Bridge.pdf
Derailment at Phipps Bridge, Croydon Tramlink	04/2006	21/10/2005	04/2006/03	Closed - I	None	Tramtrack Croydon Ltd	https://assets.publishing.service.gov.uk/media/547c907340f0b602410001bd/04_2006_Phipps_Bridge.pdf
Derailment at Phipps Bridge, Croydon Tramlink	04/2006	21/10/2005	04/2006/04	Closed - I	None	First Tram Operations	https://assets.publishing.service.gov.uk/media/547c907340f0b602410001bd/04_2006_Phipps_Bridge.pdf
Derailment at Watford Junction Yard	02/2006	28/10/2005	02/2006/01	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/547c906fe5274a42900001d9/02_2006_Watford_Junction_yard.pdf
Derailment at Watford Junction Yard	02/2006	28/10/2005	02/2006/02	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/547c906fe5274a42900001d9/02_2006_Watford_Junction_yard.pdf
Derailment at Watford Junction Yard	02/2006	28/10/2005	02/2006/03	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906fe5274a42900001d9/02_2006_Watford_Junction_yard.pdf
Derailment at Watford Junction Yard	02/2006	28/10/2005	02/2006/03	Closed - I	None	Passenger Train Operating Companies	https://assets.publishing.service.gov.uk/media/547c906fe5274a42900001d9/02_2006_Watford_Junction_yard.pdf
Derailment at Watford Junction Yard	02/2006	28/10/2005	02/2006/04	Closed - I	None	Network Rail	https://assets.publishing.service.gov.uk/media/547c906fe5274a42900001d9/02_2006_Watford_Junction_yard.pdf
Tram, Pedestrian Collision at Staniforth Road, Sheffield	01/2006	27/10/2005	01/2006/01	Closed - I	None	Stagecoach Supertram	https://assets.publishing.service.gov.uk/media/547c9070e5274a42900001db/01_2006_Staniforth_Road.pdf
Tram, Pedestrian Collision at Staniforth Road, Sheffield	01/2006	27/10/2005	01/2006/02	Closed - I	None	Stagecoach Supertram	https://assets.publishing.service.gov.uk/media/547c9070e5274a42900001db/01_2006_Staniforth_Road.pdf
Tram, Pedestrian Collision at Staniforth Road, Sheffield	01/2006	27/10/2005	01/2006/03	Closed - I	None	Office of Rail and Road	https://assets.publishing.service.gov.uk/media/547c9070e5274a42900001db/01_2006_Staniforth_Road.pdf