

ABOUT INSPECTA	03-05
MISSION	
VISION	
STRATEGIC DIRECTION	
CORE VALUE	
QUALITY POLICY	
ORGANIZATIONAL CHART	06
OUR SERVICES	07-09
CONVENTIONAL NDT SERVICES	
ADVANCED NDT SERVICES	
OTHER SERVICES	
RENTAL/SUPPLY OF NDT EQUIPMENT	
EQUIPMENT & CONSUMABLES	10-18
MANPOWER CERTIFICATION	19-39
CORPORATE DOCUMENTS	40-44
PROJECTS HANDLED	45-65
SUPPLIERS	66
BANK ACCOUNT	67
CONTACT US	68



# **ABOUT INSPECTA**

**Inspecta Inspection Services Corporation** is a 100% Filipino owned company specialized in the consulting services for Engineering Inspection, Non-Destructive Testing (NDT), and all other industrial inspections.

Headed by its founder, President and General Manager - Antonio B.C De Castro, who is a certified NDT Level III by the *American Society for Non-Destructive Testing (ASNT)*, Inspecta Inspection Services Corp. values integrity by conducting Engineering and NDT inspections with safety, accuracy, efficiency and honesty.

In our attitude towards quality and customer service, we are dedicated to being very competitive, that's why we are ranked excellent in our business. Quality is not just another objective; it is our fundamental strategy for our company's continuous growth.

#### **OUR MISSION**

Our pledge is to establish lasting relationships with our customers by exceeding their expectations and gaining their trust through exceptional performance by every member of the INSPECTA team. In doing this, we will deliver operational excellence in every corner of the company and meet or exceed our commitments to the many constituencies we serve — including ourselves.

#### **OUR VISION**

We at INSPECTA are striving to provide our customers with the highest standard of quality and integrity possible. With dedication to our principles, commitment to our customers and acknowledgement of our limitations, INSPECTA will ultimately achieve this goal.

### **OUR MISSION AND VISION ARE ACHIEVED THROUGH:**

- Innovations in all areas of business.
- Partnerships with our customers, subsidiaries, representatives, distributors, and suppliers.
- Dedicated well trained employees working together in a competitive environment.

#### STRATEGIC DIRECTION

- We will provide the infrastructure, organizational alignments and work environment to effectively support our business.
- We will grow our business through market-driven approach to provide the most advance and innovative inspection/testing protocols and services.
- We will achieve the highest standards in each area of our business to optimally satisfy our customer's needs and be recognized as the industry leader.



#### **CORE VALUES**

These values guide our daily decisions to promote achievement of our vision.

1. Focus on Customers

Build relationships with internal and external customers. Be honest and timely with our commitments and actions.

2. Respect

Be open-minded. Appreciate other points of view. Recognize each other contributions. Encourage individual and organizational development.

3. Be Accountable

Step up to issues with honesty and personal courage. Take responsibility and lead by example.

4. Work Together

Achieve better results through collaborative efforts and collective intelligence.


#### **QUALITY POLICY**

"INSPECTA is committed to provide its customers with excellence in service through continual improvement that focuses on accurate and timely reporting of results"

This policy has been formulated and approved by company's executive team. The policy is explained and discussed at general orientation training given to all employees. The policy is also posted in conspicuous locations throughout the company.

In the implementation of this policy, all employees of the company share the responsibility to ensure the highest quality. Quality system and program requirements are established to ensure that all company personnel follow appropriate procedures throughout entire life cycles of our services.







# OUR SERVICES CONVENTIONAL NON-DESTRUCTIVE TESTING



#### **ULTRASONIC TESTING (UT)**

is a method of characterizing the thickness or internal structure of a test piece through the use of high frequency sound waves Ultrasonic testing is very sensitive test method for detection of embedded discontinuities / imperfections either on welds or material. It is fast, economical and results are highly repeatable and reliable.



#### **RADIOGRAPHIC TESTING (RT)**

is an important part of the inspection and development process within non-destructive testing industry. The technique is commonly used on welded parts, castings, forgings, composites and is also used for corrosion mapping and the measurement of wall thickness.



#### **MAGNETIC PARTICLE TESTING (MT)**

is a non-destructive testing (NDT) method for detecting surface and subsurface discontinuities in ferromagnetic materials such as iron, nickel, and cobalt or some of their alloys, Magnetic Particle Testing is a fast, simple, inexpensive and highly portable NDT technique for detecting fine or shallow surface cracks in pipes and fixtures made of ferromagnetic material. It is a versatile evaluation technique that can be used to detect imperfections on test specimens of widely varying shapes and sizes.




#### **DYE PENETRANT TESTING (PT)**

is a simple, inexpensive and reliable non-destructive inspection method for detecting discontinuities which are open to the surface of the item to be inspected. It can be used on metals and other nonporous materials. With the proper technique, it will detect a wide variety of discontinuities ranging in size from those readily visible down to the microscopic level, as long as the discontinuities are open to the surface and are sufficiently free of foreign material.



# OUR SERVICES ADVANCED NON-DESTRUCTIVE TESTING



# TELETEST FOCUS PLISES



#### PHASED ARRAY ULTRASONIC TESTING (PAUT)

Is an advanced method of ultrasonic testing (UT) and is widely used for non-destructive testing (NDT) in several industrial sectors, such as construction, pipelines, and power generation. This method is an advanced NDT method that is used to detect discontinuities i.e. cracks or flaws and thereby determine component quality.

#### **TIME-OF-FLIGHT DIFFRACTION (TOFD)**

can be used for a variety of applications, its primary use is rapid weld testing of circumferential and axial weld seams, also known as perpendicular TOFD scanning. Since the introduction of TOFD in the 1970s, the use of this reputed reliable nondestructive testing technique has steadily increased.

#### **LONG RANGE ULTRASONIC TESTING (LRUT)**

is an advanced non-destructive examination technique that was developed for testing large volumes of material from a single test point. What differentiates this from more traditional methods of ultrasonic testing is that, with LRUT, a liquid couplant between transducers and the surface is not required. For this reason LRUT is one of the fastest inspection tools for carrying out pipeline surveys for corrosion and other damage mechanisms.

#### **EDDY CURRENT TESTING (ECT)**

is one of several non-destructive testing methods that uses the electromagnetism principle for flaw detection in conductive materials. A specially designed coil energized with an alternating-current is placed in proximity to the test surface, generating a changing magnetic field that interacts with the test-part and produces eddy currents in the vicinity. Variations in the changing phases and magnitude of these eddy currents are then monitored through the use of a receiver-coil or by measuring changes to the alternate current flowing in the primary excitation-coil.

#### **INTERNTAL ROTATING INSPECTION SYSTEM (IRIS)**

is an effective nondestructive examination technique used to detect and size internal and external erosion, corrosion, pitting, denting, and fretting in pipes and tubing. It can also detect bulges, restrictions, remaining wall thickness, channeling, and tube sheet defects. IRIS is used to inspect many types of process equipment, including feed water heaters, air fin coolers, condensers, boilers, heat exchangers, process piping, loading lines, and product flow lines.



# OTHER SERVICES WE OFFER

- Welder Qualification Test (WQT)
- Visual / Welding Inspection
- Tank Requalification
- Third Party Inspection
- On Stream Inspection (OSI)
- Out of Service Inspection (OOSI)
- Sandblasting & Painting Inspection
- Vacuum / Leak Testing
- NDT Level II Training and Qualification
- ASNT Level III Services
- Civil Works Inspection
- Post Weld Heat Treatment (PWHT)
- Hardness Testing
- Rope Access
- Calibration of NDT instruments & issuance of Calibration Certificates

# RENTAL / SUPPLY OF NDT EQUIPMENT

- UT Machines / Probes / Calibration Block (Flaw Detection / Thickness Gauging)
- Wet Fluorescent Magnetic Particle (WFMT) Testing Equipment (Magnetic Yoke & Ultraviolet Light)
- Radiographic Testing Projector and
- Accessories
- Liquid Penetrant Testing Chemicals & Consumables
- Magnetic Particle Testing Chemicals &
- Consumables
- Radiographic Film Processing Chemicals (Developer & Fixer) & Consumables













# **NDT EQUIPMENT & CONSUMABLES**





# **NDT EQUIPMENT & CONSUMABLES**





## **NDT CONSUMABLES**

MR85 – REMOVER MR62 – RED PENETRANT MR70I - DEVELOPER



**MR CHEMIE** 

**S76 – SOLVENT CLEANER** 

NQ1 – NON AQUEOUS DEVELOPER

DYE
PENETRANT
TESTING
CHEMICALS

S190 – SOLVENT CLEANER P139 – RED PENETRANT R175 – NON-AQUEOUS DEVELOPER



**FLUXO** 

SKD-S2 – CLEANER SKL-SP1 – PENETRANT SKC-S – DEVELOPER



MAGNAFLUX






## **NDT CONSUMABLES**











ADVANCED ULTRASONIC TESTING PHASED ARRAY & TOFD

**PROBES** 







ADVANCED ULTRASONIC TESTING
LONG RANGE (LRUT)













Address: 156 San Agustin, Ibaan, Batangas 4230 PH Landline: (043) 727 5527 / (043) 786 1738 Mobile: +639171741948 / +639171042131

+639214855283 / +639499558951 Email: inspecta.engineering@gmail.com Website: inspectaeis.com.ph

INSPECTA
INSPECTION SERVICES CORP. TIN No.: 747-896-222-000

#### PERSONAL DATA

Name: Antonio Bonifacio C. De Castro Provincial Address: 156 San Agustin, Ibaan, Batangas, 4230

City Address: B1 L5, Guijo Street, San Bartolome, Novaliches, Quezon City, Metro Manila Contact Number: 0928 987 4110 / 0917 104 2131 / 0939 147 6299 / 0917 204 2292 E-mail Address: inspecta.ndtservices@gmail.com / tonyd.inspecta@gmail.com

Date of Birth: 10 May 1960 Filipino Citizenship:

#### OCCUPATION

Position: President & General Manager of INSPECTA Inspection Services Corp. Other Occupation: General Manager of Villa Gracia Piggery Farm & Villa Gracia Private Resort

#### **EDUCATIONAL ATTAINMENT**

Bachelor of Science in Civil Engineering Education:

(Manuel L. Quezon University)

QUALIFICATION

ASNT NDT Level III (American Society for Non-Destructive Testing, Inc.)

SPECIAL SKILLS

Quality Assurance | Quality Control | Non-Destructive Testing Inspection

**WORK EXPERIENCE** 

Forty-one (41) years in the field of QA/QC & Non-Destructive Testing Inspections

Familiarity with Codes & Standards:

ASME Boiler & Pressure Vessel Code (Sections I, II, V, VIII, IX) ASME Piping Code (B31.1, B31.2, B31.8) API Standards (1104, 650, RP2A, RP2X) ASNT Standards (SNT-TC-1A, CP-189)

AWS D1.1

#### EMPLOYMENT HISTORY

Date:

Company:

Position:

Position: Date:

Date:

INSPECTA Inspection Services Corporation Company: Position:

President & General Manager November 2018 - Present

Bilfal / Bellleli Heavy Inds. (Saudi Arabia) Dept. Head - NDT INSPECTION DIVISION

January 1993 - November 2018 Senior NDT INSPECTION SUPERVISOR May 1990 - December 1992

Position: Date:

Welltrade / Saudi Aramco (Saudi Arabia) Company: NDT Field Inspector June 1986 - January 1990

Company: Position: Date:

Asiatic Corrosion Control Co. (ACCCO) Corrosion / Inspection Engineer January 1983 - May 1986







# ASNT CERTIFICATION SERVICES LLC.

# BE IT KNOWN THAT Antonio Bonifacio De Castro

has met the established and published Requirements for Certification by ASNT Certification Services LLC. in the following Nondestructive Testing Method:

#### **NDT Level III Ultrasonic Testing**

313306 Certificate Number October 19, 2023

March 31, 2029 Expiration Date

ASNT Certification Services LLC. President

Yel Q Certification Management

ATTASHT NOT Level III exams are drive oped and maintained in accordance with SSOIEC ROZA guidelines for certification of persons. The following exams are currently accredited by The Ansa National Rozalization Board LANGE I SSISIC EL MIT PLACED and VI. This certificials in the property of ASM Certification Services LLC, is not official without ASM Certification Services LLC, is not official without ASM Certification Services LLC. I should be a subject to revenue in prior to the exemption deals in the certification Salthe exertion on an exemption into confidence in ASM Certification SAM Certification ASM Certification ASM Certification SAM Certification ASM Certification SAM Certification ASM Certification SAM Certification
















NMYC-WORLD BANK VOCATIONAL TRAINING PROJECT OFFICE OF THE PRESIDENT [] REPUBLIC OF THE PHILIPPINES NATIONAL MANPOWER AND YOUTH COUNCIL

#### CERTIFICATE OF PROFICIENCY

#### This certifies that ANTONIO C. DE CASTRO PROFICIENCY TEST ARC WELDING INSPECTION AND QUALITY CONTROL administered by the National Manpower and Youth Council under the Training Contract with WIPWELD WELDING SCIENCE AND SKILLS DEVELOPMENT CENTER 111 Baesa Road, Caloocan City ACCURATE A. 1203

HANGER Vetco

NMYC-WORLD BANK VOCATIONAL TRAINING PROJECT OFFICE OF THE PRESIDENT [] REPUBLIC OF THE PHILIPPINES NATIONAL MANPOWER AND YOUTH COUNCIL

#### Certificate of Training

This certifies that ANTONIO C. DE CASTRO has successfully completed training in ASC WELDING INSPECTION AND QUALITY CONTROL under the Training Contract with WIFWELD WELDING SCIENCE AND SKILLS DEVELOPMENT CENTER 111 Baesa Road, Caloocan City for the period

BAIGE Vetco BELLELI BAUDI HEAVY IND.CO. A.S.N.T. EXAMINATIONS

FILE REF: 366/90 TS 111 3/11/90

Examinations conducted by : D.M. Apps Report Compiled by : D.M. Amos



NMYCWORLD BANK VOCATIONAL TRAINING PROJECT OFFICE OF THE PRESIDENT OF REPUBLIC OF THE PHILIPPINES
NATIONAL MANPOWER AND YOUTH COUNCIL

COURSE FOLLOWED BY:

#### ANTONIO C. DE CASTRO

SKILLS AND KNOWLEDGE ACQUIRED

ARC RELIDING INSPECTION AND QUALITY CONTROL

1. Welding Safety

Welding Managem

Estimating Welding Cout

6. Communicating Welding Jefo

Electrode Classification, their Applications, Characteristics and Proper Selection

Weldment Defects: Dimensional and Structural Defects 9. Welding Metallurgy

10. Heat Treatment Operations

11. Essentials of Welding Inspection and Quality Control

12. Choice and Use of Materials

14. Malding Programmy Shortfunktion/Seathfunktion 15. Qualification of Weldors/Welding Operators - Plate and Structural Welding - Pipe Welding - Re-Test

POTENTIAL POP

15. Servicing on are and manning backs in First and Ministerion Desiration.
2. Maintenance of the first and Desiration of Manning Servicing Company of the C This emplifies certificate of training number

BELLELI SAUDI HEAVY IND.CO. A.S.N.T. EXAMINATIONS FILE REF: 356/90 TS 111 3/11/90

INTRODUCTION

VETCO SALDI ARABIA LTD were requested by BELLELI SALDI HEAVY (MD.CO. to conduct A.S.W.T. examinations on their behalf using Vetco's appointed Level III owneriner Mr D.M. Assoc. The Totloving Betieli personnel were put forward for

NAME		LEVEL		DISCIPLINE
Mr A.B.	C.De Castro	Level	11	RT/MT/PT/UT
	as Kutty K.K.	Level	11	MT/PT/UT
0.00	nd Khumfangkrua	Level	1	RT/MT/PT
	i Franciscotuk	Level	1	RT/MT/PT

The required evanitations were communed on daturday the 3/11/50 at the Ballett main workshops in Juball. Typical 4.5.N.T. quade the used for the vitten tests and the practical to were supplemented by an oral examination to fully dature the conditions the conditions of the property of the property of the control of the examinations are included overleaf.









Republic of the Philippines Department of Science and Technology Philippine Nuclear Research Institute Quezon City

# Certificate

awarded to

Albert C. de Vera

for having successfully completed the

**Radiation Safety Course** for Industrial Radiographers

(8th Session)

August 5 - 16, 2013

The training course was organized by the Nuclear Training Center (NTC) of the Philippine Nuclear Research Institute (PNRI) for Radiation Safety Officers and Assistant Radiation Safety Officers. It comprises of 80 hours of training on radiation protection aspects and practices in industrial radiography.

The final grade is given on the reverse side of this certificate.

Red a. Foleriga ROEL A. LOTERIÑA OIC. Nuclear Training Center

13/RSC-3R-008/18-06





Republic of the Philippines Department of Science and Technology Philippine Nuclear Research Institute Commonwealth Ave. Diliman. Quezon City

# Certificate

is awarded to

## ALBERT C. DE VERA

for having allended the

5th Radiation Safety Refresher Course April 4 - 8, 2022

The training course was organized by the Nuclear Training Center (NTC) of the Philippine Nuclear Research Institute (PNRI) for Radiation Protection Officers and Assistant Radiation Protection Officers. It comprises of 24 hours training on radiation protection, safety and security principles, new regulations, licensing requirements, and improvement of company's procedures and policies.

ROEL A. LOTERIÑA, M.Sc.

Head, Nuclear Training Center



22/RSRC-OL 005/14-32



INSPECTION	ECTA SERVICES CORP.	Personnel Training, Certificat	ion & Experience	
Name	DIONISIO D. CLARIN			
Badge No.	007			
Date of Joining	NOV. 25, 2018		00	
Date of Birth	FEBRUARY 8, 1959		1/45	
Address	Batangas City, Philippines			
Education	B.S MECHANIC	CAL ENGINEERING		
Acquired E	xperience	COMPANY	YEAR	
SR. MECHANIC	CAL INSPECTOR	SAUDI ARAMCO (KSA)	JAN-1991 to JAN-2018	
SR. NDT TE	CHNICIAN VI	ETCO SAUDI ARABIA LTD. (KSA)	JAN- 1989 to JAN-1990	
SR. NDT TE	CHNICIAN WEL	LTRADE SAUDI ARABIA LTD (KSA)	FEB-1985 to FEB-1988	
NDT TEC	INDUST	TRIAL INSPECTION INT'L. INC (Phils)	MAR-1981 to MAR-1984	
>POWEI	ID GAS INDUSTRIES (REFINERY) R GENERATION.			
and the second s	URE VESSELS FABRICATION CERTIFICATIONS:			
	METHODS	INSTITUTE	CERTIFICATE NO.	
	API 510 Pressure Ves Inspector	API-Individual Certification Pro	gram 45681	
API	API 570 Piping Inspec	tor API-Individual Certification Pro	gram 43193	
WEI	API 577 Welding Inspection and Metallurgy	API-Individual Certification Pro	gram 50494	
	API 653 Abovegrour Storage Tank Inspec		gram 42577	
CSWIP	CSWIP 3.1 LEVEL I	I TWI	N8418242	
BGAS				
	Painting Inspector G	r. 1 TWI/CL	94865	
	Painting Inspector G	SAUDI ARABIAN OIL COMPA SAUDI ARAMCO (KSA)		
NDT		SAUDI ARABIAN OIL COMPA	NY/	
NDT	PT LEVEL II	SAUDI ARABIAN OIL COMPA SAUDI ARAMCO (KSA) SAUDI ARABIAN OIL COMPA	NY/	





#### SAUDI ARABIAN OIL COMPANY

D.D. CLARIN # 327213

HAS MET THE REQUIREMENTS ESTABLISHED BY SAUDI ARAMCO GENERAL INSTRUCTION 448,001, "QUALIFICATION AND CERTIFICATION OF NON-DESTRUCTIVE EXAMINATION PERSONNEL", FOR CERTIFICATION AS


#### LEVEL II IN PENETRANT TESTING

LEVEL III EXAMINER 07/06/97 A MANAGER, INSP. DEPT.

EXPIRY DATE







Expiration Date December 31, 2020










# Certificate


Management Systems




# **MANPOWER CERTIFICATION**

EINSFECTION	ECT SERVICES C	ORP. Pe	ersonnel Training, Certification	on & Experience
Name Badge No.	ANTONIO H.			
Date of Joining Date of Birth Address	Philippines	.8		
Education _	Diploma in E	lectronics Technolog	y / Mecahnical Technology	
Acquired I	xperience		COMPANY	YEAR
QA Ma	nager	н	APCO (Saudi Arabia)	2013 to 2018
QA/QC	4anager	LCB	Corporation (Thailand)	2012 to 2013
COO as	nd QMR	Pacific Engineer	ring & NDT Co., Limited (Thailand)	2009 to 2011
Senior Vend	or Inspector	Moody I	nternational (Saudi Arabia)	2008 to 2009
QA/QC	Manage <del>r</del>	Ishikawajima	-Harima Heavy Industries (IHI) (Thailand)	2006 to 2008
Head of Inspe	ection Division	AP-	SYCO (Saudi Arabia)	1996 to 2006
		Total Expe	rience = 21 years	
>POWE				
TRAININGS AND	CERTIFICATI	ONS:		
		METHODS	INSTITUTE	CERTIFICATE NO.
150 9000:20	oo Ser	ies Auditor/ Lead Auditor	(BSI Management System)	24311-74985
AWS	-	AWS WELDING INSPECTOR	AWS	121391
NDT		UT LEVEL II ASNT -		










Engr. Liberato B. Sadaran

ASNT LEVEL III UT / RT / MT / PT / VISUAL & OPTICAL





Ashish Kumar Singh

ASNT LEVEL III UT / RT / MT / PT / VT





# BE IT KNOWN THAT Ashish Kumar Singh

has met the established and published Requirements for Certification by ASNT Certification Services LLC. in the following Nondestructive Testing Method:

#### **NDT Level III Ultrasonic Testing**

282365

Certificate Number

October 31, 2023

Issue Date

December 31, 2028

Expiration Date

John 9 Juney

ASNT Certification Services LLC. Presiden Certification Managemen

All ASRT NOT Level III exams are developed and mointained in accordance with SQUECTIO24 guidelines for certification of persons. The following exams are currently accredited by The ANSI National Accreditation Board (ANAB) - BASIC, ET MI, PT, RT, UT, and VT, This sertification Services LEC, is not official without ASRT Certification Services LEC, shop and is subject to revocation prior to the excitation date. This certificate shall be verified on wink assisted life allowing hearty or by contacting ASRT Certification Services LEC.





# BE IT KNOWN THAT Ashish Kumar Singh

has met the established and published Requirements for Certification by ASNT Certification Services LLC. in the following Nondestructive Testing Method:

## **NDT Level III Radiographic Testing**

282365

Certificate Number

October 31, 2023 Issue Date December 31, 2028

Expiration Date



John 9 Jinney

ASNT Certification Services LLC. President Certification Management

All ANT NOT Level II exams are developed and maintained in accordance with SQUECTION guidelines for certification of persons. The following exams are correlatly accredited by The ANSI National Accreditation Board (ANAI) - BASIC, CT. NT. PT. RT. UT, and VT. This certificate is the property of ASRT Certification Services LLC. Is not official without ASRT Certification Services LLC. In part of subject to revocation prior to the expiration date. This certificate shall be verified on www.asrtcertification.org/verify or by confacting ASRT Certification Services LLC.



Ashish Kumar Singh

ASNT LEVEL III UT / RT / MT / PT / VT



# ASNT CERTIFICATION SERVICES LLC.



# BEIT KNOWN THAT Ashish Kumar Singh

has met the established and published Requirements for Certification by ASNT Certification Services LLC. in the following Nondestructive Testing Method:

## **NDT Level III Magnetic Particle Testing**

282365 Certificate Number October 31, 2023

December 31, 2028

Issue Date

Expiration Date



John 9 Juney

ASNT Certification Services LLC. President Cel offication Management Committee Chair

ALASH TOLEWILL learn are developed and mixinaised in accordance with SQLECTION quildelines for certification of persons. The Soliconing exams, currently accredited by The AKSI National Accreditation Board ANNAD - BASIC, ET. NT. P. B. IV., and VT. This certificate is the property of ASIT Certification riverses LLC. In not official without ASIT Certification prior to the expiration data. This certificate shall be verified on www.asstcentlit.cation.org/entity or by conductive, ASIT Certification Services LLC.



# ASNT CERTIFICATION SERVICES LLC.

# BEIT KNOWN THAT Ashish Kumar Singh

has met the established and published Requirements for Certification by ASNT Certification Services LLC. in the following Nondestructive Testing Method:

## **NDT Level III Liquid Penetrant Testing**

282365

Certificate Number

October 31, 2023

Issue Date

December 31, 2028

Expiration Date



ASNT Certification

Certification Management Committee Chair

ALASTIND Event It earns are developed and martination in accordance with SOUTE (TOUS quidelines for certification of persons. The following earns are currently accredited by The AKSI National. Accreditation Board (ANAI) - BASIC, ET, MIT, PR. IV VI, and VIT, this certificate is the property of AKSI Certification services LLC, is not difficial without ASSIT Certification services LLC is not difficial without ASSIT Certification services LLC.

Solve to provide the provided property of the property of ASSIT Certification and the provided provided by the AKSI National ASSIT Certification SASTIC CERTIFICATION SASTIC



Ashish Kumar Singh

ASNT LEVEL III UT / RT / MT / PT / VT







# BE IT KNOWN THAT Ashish Kumar Singh

has met the established and published Requirements for Certification by ASNT Certification Services LLC. in the following Nondestructive Testing Method:

## **NDT Level III Visual Testing**

282365

Certificate Number

June 01, 2023

Issue Date

May 31, 2028

Expiration Date

Committee Chair



Gohn 9 Junney
ASNT Certification

ASNT Certification Ce Services LLC. President

All ASMT NOT Level III exams are developed and maintained in accordance with ISQ/EC 17024 guidelines for certification of persons, the following exams are currently accredited by the ANSI National Accreditation Board (ANAB) - BASIC, ET, MT, PT, RT, UT, and VT, This certificate is the property of ASMT Certification Services LLC, is not official without ASMT Certification Services LLC, is upon and is subject to revocation prior to the expiration date. This certificate shall be verified on www.asmtcertification.org/verify or by contacting ASMT Certification Services LLC.



Warlito I. Juganas

ASNT LEVEL III MT / PT





The American Society for Nondestructive Testing, Inc.

Be it known that

# Warlito I Juganas

Has met the established and published Requirements for Certification by ASNT as

#### NDT Level III

In the following Nondestructive Testing Methods:



Method	Issue Date	Expiration Date
Liquid Penetrant Testing	5/21	5/26
Magnetic Particle Testing	5/21	5/26

239246


Certificate Number

Certification Management Council Chair


Note: All ASNT NDT Level III exams are developed and maintained in accordance with ISO/IEC 17024 guidelines for certification of persons. The following exams are currently accredited by the American National Standards Institute (ANSI) - BASIC, ET, MT, PT, RT, UT, and VT. This certificate is the property of ASNT, is not official without ASNT's raised gold seal and is subject to revocation prior to the listed expiration date. This certificate shall be verified on the ASNT website or by contacting ASNT.















Corporate Parine
deciBel NDE TRAINING INSTITUTE
DECIBEL NDE TRAINING INSTITUTE
NDE CERTIFICATION
as per
AMERICAN SOCIETY FOR NON-DESTRUCTIVE TESTING
This is to certify that Mr RAMON A AGUDA IR. No. DB/101/RT/2116160 has complied with the requirements of
American Society For Non Destructive testing, recommended practice No: ANT-FG-101 2011 addition, and has demendented professionery by
successfully completing theoretical and proclical examinations for Level II in the method RADIOGRAPHY TESTING & RT FILM INTERPRETATION
Hold in AUGUST 2013
This condificate is valid for a period of From Joans from the date of issue.
The Control of the Co


VERIFICATION CODE: 197833
deciBel
METRAINING INSTITUTE
THE THE PROPERTY OF THE PROPER
DECIBEL NDE TRAINING INSTITUTE
NDE CERTIFICATION
as per
AMERICAN SOCIETY FOR NON-DESTRUCTIVE TESTING
This is to certify that Mr RAMON A AGUDA JR. No: DB/101/UT/2116161 has complied with the requirements of
American Society For Non Destructive testing, recommended practice No. ANT-FE-101 2011 edition and has demonstrated profesionery by
increasfully completing theoretical and practical examinations for Level II in the method ULTRASONIC TESTING
Held in AUGUST 2013
This cortificate is valid for a period of Five Hears from the date of issue.
Late of Chine : 26-06-2013
Fraining House: 115 mars
Surveyed 70.00 Select
10 Ne 1740   15
Control of the View of
While Mr. 2: 15-08-1018 Surgerith Knell P. Sangerith Knell P. Sangerit
Week Experience 127 YEAKS Death Note Training Institute  All Contract backs Well Training Institute
Plainfield, New Civil Cream, Basambs, Palakkad (dast), Krasla, India. pin-679303 Phane ; 0091938/074153, 00919895027721.  Email: info@decblride.com, info@decblride.com. info@decblride.com. Website: www.docblride.com.








INSFECTION !	ECTA SERVICES CORP.		Personnel Training, Certifica	tion & E	xperience	
Badge No.  Date of Joining  Date of Birth	10000	it. Novalid	hes Quezon city, Philippines ER ENGINEERING			
Acquired Ex		COFFOR	COMPANY		YEAR	
SAFETY OFFICER, Q			ELIJAH JUN CORPUZ INC	MAI	R-2014 to MAR-2018	
INSPECTOR (QA/QC, NDT)			FAHSS/TÜV JUBAIL, K.S.A		AUG-2008 to MAR-2014	
NDT TECHNICIAN We		Weld	elders Testing Laboratory Phils. Inc.		MAY-2002 to JUNE-2006	
			16			
>POWER		REFINERY)	nce =13 years and 7 months			
RAININGS AND C	ERTIFICATIONS	:				
	MET	HODS	INSTITUTE		CERTIFICATE NO.	
	(UT) LE	VEL II	Philippines Nuclear Research Institute		1.	
	(MT/PT) LE	VEL II	Philippines Nuclear Research In	stitute	AE-08018/17-17	
NDT Our life - 11			Philippines Nuclear Research Institute			
NDT Qualification	(RT) LI	EVEL II	Philippines Nuclear Research In	sutute	-	
NDT Qualification	(RT) LI	VEL II	Philippines Nuclear Research In Philippines Nuclear Research In		- AI-11002/05-05	








































Personnel Training, Certification SERVICES CORP.					Experience
Badge No. 004  Date of Joining DEC	YD D. AGUIRR EMBER 03, 20 IL 17, 1988 Rosario Apali BS IN	18 t Pampanga,	Philippines		130
Acquired Exper	ence		COMPANY		YEAR
CSWIP 3.1 WELDING II		GS ENGIN	HEERING AND CONSTRUCTION, CAIRO, EGYPT	F	EB-2018 to DEC-2018
CSWIP 3.1 WELDING II	ISPECTOR		D TRADING AND CONTRACTING INY, RIYADH, SAUDI ARABIA	AR-2015 to MAY-2017	
QC INSPECTOR FTV			PROCLAD DUBAI L.L.C, UAE	М	AR-2011 to JUNE-2014
QC Welding Inspector J and			M ENGINEERING SERVICES		MAY-2008 to NOV-2010
NDT TECHNICIAN CIFRA INDU			STRIAL SERVICES CORPORATION, PHILIPPINES	P4	IAY-2007 to FEB-2008
		Experienc	e =9 years and 4 months		
EXPERTISE: > PETRO CHEM	IICAL				
>OIL AND GAS	INDUSTRIES				
>POWER GENI	RATION.				
	SSELS FABRICA	TION			
>SHIPPING IN					
TRAININGS AND CERT			THE TAXABLE PARTY OF THE PARTY		OFFITTION TO 112
	(UT) LEVEL	HODS	INSTITUTE		CERTIFICATE NO.
	(MT) LEVEL		Philippines Nuclear Research Institut Philippines Nuclear Research Institut		AH-10030/19-01
NDT Qualification	(PT) LEVEL		Philippines Nuclear Research In		AH-08025/21-01
	(RT) LEVEL		Philippines Nuclear Research In		AH-08025/21-01 AH-10055/20-01
	(ET) LEVEL	п	Philippines Nuclear Research In	stitute	
WELDING INSPECTOR	CSWIP LEVE	L II (3.1)	TWI DUBAI, UAE		86026




















REPUBLIC OF THE PHILIPPINES SECURITIES AND EXCHANGE COMMISSION Ground Floor, Secretariat Building, PICC City of Pasay, Metro Manila

COMPANY REG. NO. CS201953642

CERTIFICATE OF FILING OF

AMENDED ARTICLES OF INCORPORATION

KNOW ALL PERSONS BY THESE PRESENTS:

THIS IS TO CERTIFY that the amended articles of incorporation of the

#### INSPECTA INSPECTION SERVICES CORP.

(Amending Article II by adding Secondary Purpose thereof)

copy annexed, adopted on July 1, 2020 by a majority vote of the Board of Directors and by the vote of the stockholders owning or representing at least two-thirds of the outstanding capital stock, and certified under oath by the Secretary and a majority of the Board of Directors of the corporation was approved by the Commission on this date pursuant to the provision of Section 15 of the Revised Corporation Code of the Philippines, Republic Act No. 11232, which took effect on February 25, 2019, and copies thereof are filed with the Commission.

Unless this corporation obtains or already has obtained the appropriate Secondary License from this Commission, this Certificate does not authorize it to undertake business activities requiring a Secondary License from this Commission such as, but not limited to acting as: broker or dealer in securities, government securities eligible dealer (GSED), investment adviser of an investment company, close-end or open-end investment company, investment house, transfer agent, commodity/financial futures exchange/broker/merchant, financing company, preneed plan issuer, general agent in pre-need plans and time shares/club shares/membership certificates issuers or selling agents thereof. Neither does this Certificate constitute as permit to undertake activities for which other government agencies require a license or permit.

IN WITNESS WHEREOF, I have hereanto set my hand and caused the seal of this Commission to be affixed to this Certificate at Passy City, Metro Manila, Philippines, this D. day of September, Twenty Twenty.

Assistant Ofrector

STATES



Republic of the Philippines Municipality of Ibaan Office of the Mayor **BUSINESS PERMIT & LICENSING OFFICE** 



BAN NO: 19000252

Tel. No. (043) 414-1124

Date Issued: 2025-01-24 Plate No: 0003 Sticker No. : 2111

Owner's Name: INSPECTA INSPECTION SERVICES CORP

Owner's Address : IBAAN

Tel. No.: 0917-2042292/0928-9874110

Business Name: INSPECTA INSPECTION SERVICES CORP.

Ownership Type : Corporation

Business Flr. Area:

Kind of Business	Place of Business	Capitalization (NEW)	Gross Receipts (RENEWAL)
Engineering & NDT Inspections	SAN AGUSTIN IBAAN, BATANGAS		26,489,600.24

PERMIT GRANTED PURSUANT TO THE MUNICIPAL ORDINANCE NO. 2020-003 SUBJECT TO PERTINENT RULES AND REGULATIONS. THIS PERMIT IS NOT TRANSFERABLE AND VALID ONLY WITH THE CORRESPONDING OFFICIAL RECEIPT AND OFFICIAL SEAL OF THE MUNICIPALITY. IT SHALL BE POSTED CONSPICUOSLY AT THE PLACE OF BUSINESS.

THIS PERMIT IS ONLY A PRIVILEGE AND NOT A RIGHT, SUBJECT TO REVOCATION FOR ANY VIOLATION OF EXISTING LAWS AND ORDINANCE FAILURE TO SURRENDER THIS PERMIT UPON TERMINATION OF THE BUSINESS SHALL BE DEEMED

OPERATIONAL AND SHOULD BE RENEWED EVERY YEAR THEREAFTER. SUBJECT TO FINAL INSPECTION AND ASSESSMENT. NON TRANSFERABLE.




APPROVED BY

OFFICE OF THE MAYOR RELEASED DATE: 01- 24-25 TIME: XX TUNOWA

Official Receipt No.: 36216264 Payment Date : 01/24/2025 Total Amount Paid: P152,298.70 Permit Valid Until. : December 31, 2025









303 SED: APRIL 2019 REVENUE R	EGION NO. 'ENUE DIS	KAGAWARAN KAWANHAN NG 89A - CABANIRD	NG PILIPINAS NG PANANALAPI RENTAS INTERNAS (GAVITE-BATANGA: 029 - LIPA CITY, EA	S-MINDORO-ROMBLON)	BIR FORM 2303 REVISED: APRIL 2019 REVEN	IUE REGION I REVENUE I	REPUBLIKA NG PRIP KAGAWARAN NG PANA KAWANHAN NG RENTAS KO, 89A - CAILAMRD (CAVITE- SISTRICT OFF GE NO. 1999 - LIP STRICT OFF GE NO. 1999 - LIP	NALAPI INTERNAS BATANGAS MIN A CITY, EAST BA	DORO-ROMBLON) TANGAS OCN: 059RC29230030912414 OCN Generated: July 17, 2023	BIR FORM 2303 REVISED: APRIL 2019 REVENUE RE REVI	REPUBLIKA NG PRIPINAS KAGAMARAH NG PANASALAH KAMAMBAN NG SENTAS BITERNA CICIO NO. 1834 - CAJAMING (CAUTH- 54TANGA NUE DISTRICT OPPEC NO: 595 - LIPA CITY, EJ	S-MINDORO-ROMBLON)
	CE	RTIFICATE	OF REGISTE	RATION		(	CERTIFICATE OF RE	GISTRAT	ION:		CERTIFICATE OF REGIST	RATION
IN & BRANCH CODE 747-896-222-00000	2 11 11 12	IAME OF TAXPAYE INSPECTA INSPEC CORP.		TIN ISSUANCE DATE July 24, 2019	TIN & BRANCH CO 747-896-222-0000		NAME OF TAXPAYER INSPECTA INSPECTION SER	RVICES	TIN ISSUANCE DATE July 24, 2019	TIN & BRANCH CODE 747-896-222-00000	NAME OF TAXPAYER INSPECTA INSPECTION SERVICES	TIN ISSUANCE DATE July 24, 2019
EGISTERING OFFICE EGISTERED ADDRESS 156 SAN AGUSTIN 423	21111	Head Office ATANGAS PHILIPP	1	ransh	REGISTERING OFF REGISTERED ADD 156 SAN AGUST	RESS	CORP.  X Head Office  BATANGAS PHLIPPINES	Branch		REGISTERING OFFICE REGISTERED ADDRESS 106 SAN AGUSTIN 4230	CORP.  X Head Office B  BAAN BATANGAS PHILIPPINES	ranch
TAX TYPES	FORM TYPES	FILING START DATE	FILING FREQUENCY	FILING DUE DATE	TAXPAYER TYPES	DOME	STIC CORPORATION		payment and other income syments were paid or account.	-		med person is registered as indicate National Internal Revenue Code,
CORPORATE INCOME TAX	1702	August 5, 2019	ANNUALLY	On or before the 15th day of the 4th month following the close of the taxpayer's taxable year.	BUSINESS INFORM	BUSINESS INFORMATION DETAILS			29457343	JOHN CHRIS OF HER C. ILAO		
CORPORATE INCOME TAX	17020	August 5, 2019	QUARTERLY	Within sixty (60) days following the close of each of the first three (3) guarters of the taxable year.	TRADE NAME 1 (PSIC)	43309-OTH	INSPECTION SERVICES CORP. ER BUILDING COMPLETION		Auly 24, 2019	No.	REVENUE DE	N P. CUREG STRICT OFFICER ser Printed Name)
REGISTRATION FEE	0605	December 31, 2019	ANNUALLY	On or before the last day of January.	Line of Business (PSIC)	BUILDING (	HING ACTIVITIES COMPLETION AND FINISHING HITECTURAL AND OTHER	Secondary		THIS CERTIFICA	TE MUST BE EXHIBITED CONSPICUOUSLY IN T	
VALUE ADDED TAX	2550Q	August 5, 2019	QUARTERLY	Not later than the 25th day following the close of each taxable quarter.	Line of Business	ARCHITECT	ING ACTIVITIES FURAL AND ENGINEERING AND RELATED TECHNICAL	Primary				
VALUE ADDED TAX	2550M	August 5, 2019	MONTHLY.	Not later than the 20th day following the close of the month.	(PSIC)	CONSULTA						
WITHHOLDING TAX - EXPANDED/OTHERS	0619E	July 17, 2023	MONTHLY	On or before the 10th day of the month following the month in which withholding was made.	Line of Business	SERVICE A	CTIVITIES, N.E.C. SUPPORT SERVICES	Secondary				
WITHHOLDING TAX - EXPANDED/OTHERS	1601EQ	July 17, 2023	QUARTERLY	Not later than the last day of the month following the close of the quarter during which withholding was made.	REMINDERS:	gistration fee	shall be paid upon registration an	d every year then	eafter on or before the test day			
WITHHOLDING TAX - EXPANDED/OTHERS	1604E	January 1, 2024	ANNUALLY	On or before March 1 of the year following the calendar year in which the income payments subject to expanded withholding taxes or exempt from withholding tax were gaid or secreted.	of Jenuary, t 2. Filing of rec operation, to 3. For new bus the deadline earlier, from	ning BIR Form juited tax retu- avoid penaltie iness registran for filing of the the date of reg	No. 0605, im's to conform with the above 6, ts, application for registration of m s initial quarterly income tax return struction. Registration of new set of	tax types, whe namusi Books of A n or annual incor of manual B/As sh	ther with or without business scounts (BiAs) shall be before no tax robum withchavor comes nall be before its use.			
WITHHOLDING TAX - COMPENSATION	1601C	August 19, 2019	MONTHLY	On or before the 10th day of the month listowing the mosth when the withholding was made except for taxes withheld for December which shall be filed and paid/vertited on or before January 15 of the succeeding year.	registration is 5. For Self-Em does not are (PT) shall in year, such 8 percentage t	nformation by I ployed Individual sed P3,000,00 of be reflected El shall be au ax return (BIR	istrict office in case of transfer ling BIR Form No. 1905, 1895 (\$EI) whose gross sales at 10 and who opticd to avail of the 8 in the Certificate of Registration tomatically subjected to graduate Form No. 2551QI and option to a 5 troome tax rate annually.	ndfor receipts an % Income tax rat (COR). Howeve d income tax rate	d other non-operating income e, the tax type Percentage Tax ir. at the start of each taxable is and required to file quarterly			
WITHHOLDING TAX -	1604C	January 1, 2023	ANNUALLY	On or before January 31 of the year following the calendar year in which the compensation								


government. It will be used for the developmen 2 to 4 YEARS IMPRISONMENT FOR NON-ISSUANCE OF RECEIPT

 BIR CONTACT CENTER (02)981-8888 commissioner@bir.gov.ph

. ANY BIR OFFICE

(Name of Business Establishment) 747-896-222-000









Republic of the Philippines
SOCIAL SECURITY SYSTEM

2019

#### CERTIFICATE OF REGISTRATION

This is to certify that

#### INSPECTA INSPECTION SERVICES CORP.

156 SAN AGUSTIN, IBAAN, BATANGAS 4230

has been duly registered with the Social Security System (SSS) as employer on 27 August 2019 with Employer Number 80-0117960-2-000.

Pursuant to the Social Security Law the employer has the responsibility to report to the SSS for coverage, deduct from their morthly salaries their as and respective shares of the SSS contributions and, with the corresponding employer's share, security to deduct from the salaries to the SSS. It also has the responsibility to deduct from the salaries and the security of its employees their monthly loan emortization; if any, and remit them to the SSS.

Assess the This certification is issued this 27th day of August, 2019.

AURORA C. IGNACIO President and CEO







Certificate Number 25-6847350-A Issue Date 14-February-2025 Expiry Date 13-February-2028 ABS Port Office Manila, Philippines Company's Website www.inspectaeis.com.ph

CERTIFICATE OF

#### Recognized Service Supplier

This is to certify that

#### INSPECTA INSPECTION SERVICES CORP.

located at

156 San Agustin, Ibaan, Batangas, Philippines

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as Service Supplier to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

#### **Nondestructive Inspection**

Attached Certificate Appendix provides specific scope of approval, authorized personnel, manufacturer authorizations, and subcontractors.

It is the responsibility of the Service Supplier to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the Service Supplier is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. Where required by the category of service, the Service Supplier shall provide valid evidence that it is authorized or licensed by the equipment manufacturer to service the makes and models of equipment for which approval is sought. If approval from the manufacturer is not attained, a surveyor must be present at time of survey to continue work. Alternatively, current written instructions from the flag state are to be obtained to continue work without the surveyor present. Service Suppliers must present photo identification, evidence of qualification and authorizations from manufacturers, as applicable, at the time of service.

The ABS office issuing this certificate is to be kept updated with changes to the management of the company, employees, equipment and models on the authorization list and any changes made.

Saturnino S. Babao, Surveyor

CLS-SFM-00040 Rev.30

Page 1 of 3











#### **NDT END USERS**

















GREENPOWER TECHNOLOGY SERVICES













#### **NDT END USERS**



























#### **NDT END USERS**









KGB Schneiden, Corp.















PMENT CORP

RATION NANCE

ENANCE

**ES INC** 

ES OPC

ORATION PANY LIMITED

KENMATT CONSTRUCTION CORP.



ENERGY DEVELOPMENT CORPORATION (EDC)

MAISOON METAL WORKING LTD

ATLANTIC, GULF AND PACIFIC COMPANY (AG&P)

SOUTH LUZON THERMAL ENERGY CORPORATION (SLTEC)

#### **CLIENTS**

PHILIPPINE GEOTHERMAL PRODUCTION COMPANY INC.

	ENERGY DEVELOR MENT CONTROL (EDG)		THE THE GEOTHERWINE TROBUGION COMMITMENT		REMOVED CONTROL OF THE CONTROL OF TH
•	SAN MIGUEL CORPORATION GLOBAL POWER	•	KIMJA TRADING AND CONSTRUCTION CORP.	•	CA ARCHITECTS, DESIGNERS & BUILDERS
•	SAN MIGUEL BREWERY INC.	•	FLOWTORK TECHNOLOGIES CORPORATION	•	E.H. SISON ENGINEERS, CO.
•	PETRON CORPORATION	•	KEPPEL PHILIPPINES MARINE INC.	•	NC ABRAHAN BUILDERS
•	SN ABOITIZ POWER-BENGUET, INC.	•	AC ENERGY PHILPPINES INC.	•	BGS ADVANCE TESTING SERVICES CORP.
•	TÜV SÜD PSB PHILIPPINES INC.	•	PHINMA POWER GENERATION CORPORATION	•	ECO ACCESS SYSTEMS AND SOLUTIONS INC
•	CAST LABORATORIES PTE LTD	•	YUO PIN CONSTRUCTION PHILIPPINES INC.	•	PETER BENA CONSTRUCTION AND DEVELO
•	SY3 ENERGY MAINTENANCE SERVICES CORPORATION	•	J.E. MANALO CO., INC.	•	ALPHALITE FREIGHT ELEVATOR SERVICES
•	GREENPOWER TECHNOLOGY SERVICES	•	BALANCED ENGINEERING & CONSTRUCTION	•	NTSCC CONSTRUCTION
•	RJS INDUSTRIAL CONSTRUCTION AND DEVELOPMENT CORF	P. •	SM BLOOMING PHIL. INC.	•	ACCIONA EEI JV MALOLO\$ CLARK CPN04
•	CHEVRON PHILIPPINES INC.	•	HOTWORK INTERNATIONAL INC.	•	ULTRA INSULATED PAREL SERVICES CORP.
•	SEAOIL PHILIPPINES	•	JKFRJK INSULATION SALES AND SERVICES	•	OLYMPIC ENGINEERING AND SALES CORPOR
•	PHOENIX PETROLEUM PHILIPPINES INC.	•	ANTRAK LOGISTICS	•	JOEL CHAVEZ CONSTRUCTION AND MAINTEN
•	FLYING V INC.	•	JEN JEH / HEYUANG	•	INFINITE LOOP TECHNOLOGY CORP.
•	YOKOHAMA TIRE PHILIPPINES, INC.	•	ASSISTCO ENERGY & INDUSTRIAL CORPORATION	•	BCME INDUSTRIAL SERVICES
•	X5 MARKETING	•	RR BUILDERS	•	JOEL CHAVEZ CONSTRUCTION AND MAINTEN
•	BOC LIMITED	•	MTP MARINE SERVICES	•	EC STRUCTURAL COMPOSITE INC.
•	REGASCO	•	FRONTKEN PHILIPPINES INCORPORATED	•	POWERONE CONSTRUCTION LMD CORP.
•	SPEED VELOCITY	•	CIFRA INDUSTRIAL SERVICES CORPORATION	•	HERMA SHIPYARD INC.
•	CJI GENERAL SERVICES CORPORATION	•	ROTECC MOVERS INC.	•	SOUTHERN METAL AND SALES INCORPORAT
•	LINDE GROUP	•	REGASCO GAS CORP.	•	SUBIC DRYDOCK CORPORATION
•	CRYOWORKS MAINTENANCE AND CONSTRUCTION SERVICE	S•	MJL INDUSTRIAL ENGINEERING SERVICES	•	TAIHEI ALLTECH CONSTRUCTION PHILIPPINE
•	EXE ENGINEERING	•	TOSUNG CONSTRUCTION PHILS. INC.	•	BOSKALIS PHILIPPINES INC.
•	BIO 8 ENERGY CORPORATION	•	CGP METAL WORKS AND STAINLESS FABRICATION	•	PRIME METRO BMB
•	FCF MINERALS CORPORATION	•	D.M. CONSUNJI, INC.	•	RON INTEGRATED CONSTRUCTION SERVICE
•	HAYAMA INDUSTRIAL CORPORATION	•	DCCON ENGINEERING SERVICES	•	WHESSOE PHILIPPINES CONSTRUCTION INC
•	UNITED SIEGEN PHILIPPINES CORP.	•	K AND F CONSTRUCTION DEVELOPMENT CORP.	•	CBK POWER COMPANY LIMITED
•	SUAL PANGASINAN COAL FIRED THERMAL POWER PLANT	•	MAGITEK INDUSTRIAL INSPECTION SERVICES	•	NEW TRISTAR ELECTRICAL FABRICATION
•	ONE SUBIC POWER GENERATOR CORPORATION	•	BASED INDUSTRIAL INSPECTION SERVICES CORP.	•	SERVICIO FILIPINO INC.
•	KGB SCHNEIDEN CORPORATION	•	YSD & CS	•	NEWTON ELECTRICAL EQUIPMENT
•	TOREJAS CONSTRUCTION SUPPLY CORPORATION	•	APIC INSPECTION AND TESTING SERVICES INC.	•	PETROWIND ENERGY INC.
•	FEDCON CONSTRUCTION COMPANY INC.	•	CJI GENERAL SERVICES INC.	•	AMSTEEL STRUCTURES INC.
•	JD AMANCIO ENTERPRISES	•	CHANG TSAI CONST. & TRADING	•	GAUDIA ENGINEERING SERVICES
•	SPECRELIA INDUSTRIAL SERVICES	•	MITSUBISHI POWER (PHILIPPINES) INC.	•	STEEL STRUCTURE WORK
•	TRUE NORTH MANUFACTURING SERVICES CORPORATION	•	GLOBAL BUSINESS POWER (TOLEDO CEBU	•	TIGER MACHINARY AND INDUSTRIAL CORPO
•	JERTEC'S CONSTRUCTION	•	MHI POWER (PHILIPPINES) PLANT SERVICES CORPORATION	•	INSUPHIL INDUSTRIAL CORP.
•	BOYI CONSTRUCTION PHILIPPINES INC.	•	RGG CONSTRUCTION & SERVICES	•	ITALIAN-THAI DEVELOPMENT PUBLIC COMPA
•	JG SUMMIT PETROCHEMICAL CORPORATION	•	COSTAR FABRICATION CORP.		
•	GENTHINK INTERNATION CONSTRUCTION CORPORATION	•	GREEN INNOVATIONS, INC.		

SUMMA WATER RESOURCES INC.

BALDO CONSTRUCTION AND DEVELOPMENT CORP.

UNIVERSAL NDT INC.



CLIENT	PROJECT
ENERGY DEVELOPMENT CORPORATION - TONGONAN	NDT (PAUT, WFMT, PT, UT) OF TURBINE ROTOR XSOODOO N-1119 AT TONGONAN GEOTHERMAL POWER PLANT, LEYTE
ENERGY DEVELOPMENT CORPORATION - MAHANAGDONG	NDT (UT, WFMT, PT) OF TURBINE ROTOR XPL01 SPR AT MAHANAGDONG GEOTHERMAL POWER PLANT, LEYTE
ENERGY DEVELOPMENT CORPORATION - TONGONAN	NDT (UT, WFMT, PT) OF TURBINE ROTOR XSOOROO AT TONGONAN GEOTHERMAL POWER PLANT, LEYTE
ENERGY DEVELOPMENT CORPORATION	NDT (LRUT) OF OLD PAD RG PIPELINES AT MT. APO GEOTHERMAL POWER PLANT, KIDAPAWAN CITY, NORTH COTABATO
SAN MIGUEL CORPORATION GLOBAL POWER / JERTEC'S CONSTRUCTION 4 X 150MW X 460 T/H COAL POWER PLANT	NDT (RT, PT) OF UNIT 1 BOILER TUBES; UNITS 2, 3 & 4 WAS ALREADY AWARDED TO INSPECTA; NDT (RT, PT) OF UNIT 2 BOILER TUBES ALREADY STARTED; MARIVELES, BATAAN
SAN MIGUEL CORPORATION GLOBAL POWER / BOYI CONSTRUCTION PHILIPPINES INC 4 X 150MW X 460 T/H COAL POWER PLANT	NDT (RT, PT, VBT) OF UNDERGROUND PIPING, STORAGE TANKS & STRUCTURALS OF UNIT 1  UNITS 2, 3 & 4 WAS  ALREADY AWARDED TO  INSPECTA; NDT (RT, PT)  OF UNIT 2 ALREADY  STARTED; MARIVELES,  BATAAN
PETRON CORPORATION	NDT (RT) OF RSFFB UNIT 1 BOILER AT LIMAY, BATAAN
PETRON CORPORATION	NDT (RT) OF RSFFB UNIT 2 ESD TUBE REPLACEMENT AT LIMAY, BATAAN
PETRON CORPORATION	NDT (RT) - PPCS21-0010 RSFFB UNIT 1 2021 TURNAROUND FURNACE TUBE
PETRON CORPORATION	NDT (RT) OF RSFFB UNIT 1 HS LETDOWN FLANGE WELD CONNECTION
PETRON CORPORATION / FEDCON CONSTRUCTION COMPANY INC.	NDT (RT, PT,VT) OF PIPELINE JOINTS FOR PETRON BULK DEPOT AT TAGOLOAN, MISAMIS ORIENTAL
FEDCON CONSTRUCTION COMPANY INC.	NDT (UT, PT) OF ETHANOL RECEIVING LINE INSTALLATION AT SL HARBOR BULIC TERMINAL CORP. AT TABLON, CAGAYAN DE ORO
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, WFMT, PT) OF EDC - MALITBOG MBPP 77MW SN. KIN69033G3 TURBINE ROTOR AT GENERAL TRIAS, CAVITE
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, WFMT, PT) OF EDC MAHANAGDONG 60MW TURBINE ROTOR AT GENERAL TRIAS, CAVITE
HAYAMA INDUSTRIAL CORPORATION / SAN MIGUEL BREWERY INC.	NDT (RT, PT) OF PIPING JOINTS AT CAGAYAN DE ORO
CRYOWORKS MAINTENANCE AND CONSTRUCTION SERVICES	NDT (RT, PT) AT ECOGAN AND PSA PIPING JOINTS AT JG SUMMIT SIMLONG, BATANGAS CITY



CLIENT	PROJECT
UNITED SIEGEN PHILIPPINES CORP.	NDT (RT, MT) OF STORAGE TANKS AT SUAL COAL FIRED THERMAL POWER PLANT AT SUAL PANGASINAN
GREENPOWER TECHNOLOGY SERVICES	NDT (UT, WFMT, PT) OF BEARINGS AT STA.ROSA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES	NDT (WFMT, PT) OF MGPP STAGE 1 LOWER DIAPHRAGM (GE / TE SIDE) AT STA. ROSA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES	NDT (WFMT, PT) OF MGPP STAGE 5 UPPER AND LOWER DIAPHRAGM (GE SIDE) AT STA. ROSA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES	NDT (UT, PT) OF JOURNAL BEARINGS AT STA. ROSA, LAGUNA
KGB SCHNEIDEN CORPORATION	NDT (UT, PT) OF RETROFITTED BEAMS AT LIMA, BATANGAS
FCF MINERALS CORPORATION	NDT (UT, PT, VT) OF BIOX AGITATOR SHAFT AT KEPPEL BATANGAS
SPECRELIA INDUSTRIAL SERVICES	SUPPLY OF NDT PERSONNEL & EQUIPMENT ON VARIOUS PROJECTS OF SPECRELIA
FCF MINERALS CORPORATION	NDT (UT, PT, WFMT) OF BIOX AGITATORSHAFT AT RUNRUNO, NUEVA VIZCAYA
BIO 8 ENERGY CORPORATION	NDT (RT) OF 2.40KL ABOVE GROUND CME TANKS AND 12KL ABOVE GROUND CME TANK AT BALINTAWAK, Q.C
EXE ENGINEERING	NDT (RT) OF WQT'S AT MARIVELES, BATAAN
CRYOWORKS MAINTENANCE AND CONSTRUCTION SERVICES	NDT (PT) OF WELDMENTS OF COLD BOXES AT JG SUMMIT SIMLONG, BATANGAS
CJI GENERAL SERVICES CORPORATION	NDT (RT, PT) OF INSERT PLATES ON THE STORAGE TANKS AT CHEVRON PHIPPINES AT SAN PASCUAL, BATANGAS AND SAN FERNANDO LA UNION
SPEED VELOCITY	NDT (RT, PT, VBT) OF 2 VERTICAL STORAGE TANKS W/ 2 MILLION LITERS EACH GASOLINE & DIESEL
YOKOHAMA TIRE PHILIPPINES, INCORPORATED C/O SUNTECH TECHNOLOGY CORPORATION	NDT (UT) OF STRUCTURAL FULL PENETRATION WELD AT CLLARK, PAMPANGA
REGASCO C/O SUNTECH TECHNOLOGY CORPORATION	NDT (RT) / REQUALIFICATION OF LPG LORRY TANK AT ARAYAT, PAMPANGA
BOC LIMITD C/O SUNTECH TECHNOLOGY CORPORATION	NDT (RT) / REQUALIFICATION OF LPG LORRY TANK AT MEYCUAYAN, BULACAN
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT, PT) OF PAL2 OKOY5 CV AT CALAMBA, LAGUNA



CLIENT	PROJECT
X5 MARKETING C/O SUNTECH TECHNOLOGY CORPORATION	NDT (RT) OF VERTICAL STORAGE TANKS AT BARAS, RIZAL
PHOENIX PETROLEUM PHILIPPINES INC. C/O SUNTECH TECHNOLOGY CORPORATION	NDT (RT) OF ABOVE GROUND STORAGE TANKS AT CALACA, BATANGAS
SEAOIL PHILIPPINES C/O SUNTECH TECHNOLOGY CORPORATION	NDT (RT) OF VERTICAL STORAGE TANKS GASOLINE AT MABINI, BATANGAS
FLYING V C/O RJS INDUSTRIAL CONSTRUCTION AND DEVELOPMENT CORPORATION	NDT (RT, MT, VBT) OF 2 VERTICAL STORAGE TANKS W/ 2 MILLION LITERS EACH GASOLINE & DIESEL AT PASACAO, CAMARINES SUR
BALANCED ENGINEERING & CONSTRUCTION	NDT (RT-WQT) AT SMC-MPGC BIAAN, MARIVELES, BATAAN
YUO PIN CONSTRUCTION PHILIPPINES INC.	NDT (PT) OF CRANE BOOM PARTS AT BIAAN, MARIVELES, BATAAN
J.E. MANALO CO., INC.	NDT (RT-WQT) 7 SETS AT SMC-MPGC BIAAN, MARIVELES, BATAAN
GENTHINK INTERNATIONAL CONSTRUCTION CORPORATION	NDT (RT-WQT) 7 SETS AT SMC-MPGC BIAAN, MARIVELES, BATAAN
SM BLOOMING PHIL. INC.	NDT (RT-WQT) AT SMC-MPGC BIAAN, MARIVELES, BATAAN
HOTWORK INTERNATIONAL INC.	NDT (PT-WQT) AT SMC-MPGC BIAAN, MARIVELES, BATAAN
JKFRJK INSULATION SALES AND SERVICES	NDT (PT-WQT) 4 SETS SMAW AT SMC-MPGC BIAAN, MARIVELES, BATAAN
ANTRAK LOGISTICS	SUPERVISION OF HANDLING AND TRANSPORT OF RADIOACTIVE MATERIAL FOR ANTRAK LOGISTICS FROM METRO MANILA, PARAÑAQUE TO OCEANAGOLD, DIDIPIO, NUEVA VIZCAYA.
J.E. MANALO & CO., INC.	NDT (UT) OF MPGCPIER (SPLICE SPP) AT BIAAN, MARIVELES, BATAAN
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (PT) OF 2 UNITS MSV SHAFT AT GENERAL TRIAS, CAVITE
GENTHINK INTERNATIONAL CONSTRUCTION CORPORATION	NDT (RT-WQT) 8 SETS A36 AT SMC-MPGC BIAAN, MARIVELES, BATAAN
EXE ENGINEERING	NDT (PT-WQT) 6 SETS SMAW AT SMC-MPGC BIAAN, MARIVELES, BATAAN
TÜV SÜD PSB PHILIPPINES INC	ASNT NDT LEVEL III SERVICES FOR NDT (UT, MT, PT) LEVEL II RE-CERTIFICATION
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (PT) OF SHAFT - INT-EDC6-JO016-21053 AT GENERAL TRIAS, CAVITE



CLIENT	PROJECT
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, PT) OF UMPP GENERATOR ROTOR JOURNAL 3 & 4 AT GENERAL TRIAS, CAVITE
HOTWORK INTERNATIONAL INC.	NDT (PT-WQT) 4 SETS AT SMC-MPGC BIAAN, MARIVELES, BATAAN
EXE ENGINEERING	NDT (PT-WQT) 3 SETS X2 AT SMC-MPGC BIAAN, MARIVELES, BATAAN
GREENPOWER TECHNOLOGY SERVICES	NDT (UT, PT) OF UMPP BEARING 3 & 4 AT STA. ROSA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF MT. APO TURBINE ROTOR DOUBLE FLOW AT GENERAL TRIAS, CAVITE
SM BLOOMING PHILIPPINES INC.	NDT (RT-WQT) 12 SETS AT SMC-MPGC BIAAN, MARIVELES, BATAAN
JEN JEH / HEYUANG	NDT (RT-WQT) 2 SETS AT SMC-MPGC BIAAN, MARIVELES, BATAAN
YUO PIN CONSTRUCTION PHILIPPINES INC.	NDT (PT) OF STEEL TUBE WELDMENTS AT BIAAN, MARIVELES, BATAAN
GREENPOWER TECHNOLOGY SERVICES	NDT (UT, PT) OF UMPP OEC JOURNAL BEARING AT STA. ROSA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (MT, PT) OF PAL2 OKOY 5 HP AND LP DIAPHRAGM AT GENERAL TRIAS, CAVITE
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (MT, PT) OF PAL2 EX OKOY 5 GLAND PACKING (DE) SEAL AT GENERAL TRIAS, CAVITE
ASSISTCO ENERGY & INDUSTRIAL CORPORATION / PETRON CORPORATION	NDT PHASED ARRAY ULTRASONIC TESTING OF REFINERY HEATER TUBES AT LIMAY, BATAN
ASSISTCO ENERGY & INDUSTRIAL CORPORATION / PETRON CORPORATION	LOCALIZED POST WELD HEAT TREATMENT OF REFINERY HEATER TUBES AT LIMAY, BATAAN
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (PT) OF INTEGRA SHAFT AT GENERAL TRIAS, CAVITE
GREENPOWER TECHNOLOGY SERVICES	NDT (UT, PT) OF TGPP & BGI PALAYAN JOURNAL BEARINGS AT STA. RØSA, LAGUNA
TÜV SÜD PSB PHILIPPINES INC.	NDT (UTG) PERSONNEL AND EQUIPMENT AT CAGAYAN DE ORO
J.E. MANALO & CO., INC.	NDT (UT) ON STEEL PIPE PILES (SPLICE) AT BIAAN, MARIVELES, BATAAN
S.A.E. / RR BUILDERS	NDT (RT) OF AMMONIA CHARGING LINE B.I. PIPE JOINTS AT TANZA, CAVITE



CLIENT	PROJECT
MTP MARINE SERVICES	NDT (RT) OF PIPE JOINTS 2 PIPE JOINTS - 10" Ø SCH.40 AND 7 PIPE JOINTS - 8" Ø SCH.40 AT BAY, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, PT) OF UMPP OEC THRUST COLLAR AT GENERAL TRIAS, CAVITE
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF STEAM FLOW GUIDE AT CALAMBA, LAGUNA
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF PALINPINON LP3 DIAPHRAGM AT CALAMBA, LAGUNA
MTP MARINE SERVICES	NDT (RT) OF ADDITIONAL PIPE JOINTS 3 PIPE JOINTS - 10" Ø SCH.40 AND 3 PIPE JOINTS - 8" Ø SCH.40 AT BAY, LAGUNA
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF PALINPINON LP3 DIAPHRAGM (AFTER REPAIR) AT CALAMBA, LAGUNA
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF MAIN STOP VALVE (LEFT & RIGHT) AT CALAMBA, LAGUNA
CIFRA INDUSTRIAL SERVICES CORPORATION	SUPPLY OF UT / MT / PT LEVEL II INSPECTORS AT CALACA, BATANGAS
ROTECC MOVERS INC.	NDT (PT) OF BEAM SPLICE JOINTS AT STO. TOMAS, BATANGAS
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF STEAM FLOW GUIDE 2 AT CALAMBA, LAGUNA
ENERGY DEVELOPMENT CORPORATION	NDT (ECT) OF MLPP UNIT 1 GENERATOR AIR COOLERS AT MALITBOG, LEYTE
PETRON CORPORATION	UTG & PT - PPEGE21-002: PPP POWER PIPING NON-DESTRUCTIVE EXAMINATION AT BATAAN
REGASCO GAS CORP.	NDT (RT, UTG, MT) OF BULLET TANK AT AMWELD, PAMPANGA
MJL INDUSTRIAL ENGINEERING SERVICES	HARDNESS TESTING & MOCK-UP FOR PWHT TECHNICIAN QUALIFICATION AT LIBJO, BATANGAS CITY
TÜV SÜD PSB PHILIPPINES INC.	HARDNESS TESTING OF EXISTING TUBE WELDS AT BATAAN
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF PALINPINON LP3 DIAPHRAGM (AFTER REPAIR 2) AT CALAMBA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES	NDT (MT, PT) OF MAGPP STAGE 3 BLADE HOLDER AT STA. ROSA, LAGUNA
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF PALINPINON LP3 DIAPHRAGM (AFTER REPAIR 3) AT CALAMBA, LAGUNA



CLIENT	PROJECT
K AND F CONSTRUCTION DEVELOPMENT CORP.	VACUUM BOX TESTING (VBT) OF BOTTOM PLATE AT BAUAN, BATANGAS
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF CAWAYAN MSV (L/R) & CV (R) AT CALAMBA, LAGUNA
MJL INDUSTRIAL ENGINEERING SERVICES	HARDNESS TESTING AT SHELL TABANGAO, BATANGAS CITY
TOSUNG CONSTRUCTION PHILS. INC.	NDT (PT) OF REBAR HANGER WELD CONNECTION AT STO. TOMAS, PAMPANGA
GREENPOWER TECHNOLOGY SERVICES	NDT (MT, PT) OF PAL 2 OKOY GLAND PACKING SEAL AT STA. ROSA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF PAL2 OKOY5 20MW TURBINE ROTOR AT GENERAL TRIAS. CAVITE
CGP METAL WORKS AND STAINLESS FABRICATION	NDT (PT) OF ECOLAB TANK AT CARMONA, CAVITE
DCCON ENGINEERING SERVICES	NDT (UTG, RT) OF TUBE PIPE & STEEL PLATE AT LAGUNA
ENERGY DEVELOPMENT CORPORATION / NEWTON ELECTRICAL EQUIPMENT CO., INC.	NDT (UT, PT) OF UMPP OEC 11 GENERATOR SLEEVE BEARING AT VALENZUELA
TÜV SÜD PSB PHILIPPINES INC.	NDT (MT) PERSONNEL AND EQUIPMENT AT BATAAN
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF EDC NASUJI CV (L/R) & MSV (L/R) AT CALAMBA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (MT, PT) OF PAL2 OKOY5 OIL DEFLECTOR & GLAND PACKING SEALS AT GENERAL TRIAS, CAVITE
D.M. CONSUNJI, INC.	NDT (UT, MT) FOR DMCI STEEL FABRICATION TDJV-NSCR CP01 AT CALACA, BATANGAS
TOSUNG CONSTRUCTION PHILS. INC.	NDT (PT) OF REBAR HANGER AT STO. TOMAS, PAMPANGA
ASSISTCO ENERGY & INDUSTRIAL CORPORATION	NDT (PAUT) OF PETRON PPP DE-ETHANIZER (DOME CUTTING) AT LIMAY, BATAAN
TOSUNG CONSTRUCTION PHILS. INC.	NDT (MT) OF CRANE BOOM BRACES AT STO. TOMAS, PAMPANGA
MAGITEK INDUSTRIAL INSPECTION SERVICES	RT CAMERA w/ 10 Ci SOURCE RENTAL & SUPPLY OF RTLEVEL II INSPECTOR
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF PALAYAN DOUBLE FLOW TURBINE ROTOR (AS FOUND) AT GEN. TRIAS, CAVITE



CLIENT	PROJECT
BASED INDUSTRIAL INSPECTION SERVICES CORP.	NDT (UT) EQUIPMENT RENTAL
PETRON CORPORATION	NDT (RT) OF HEADER JOINT AT LIMAY, BATAAN
SIEGEN PHILIPPINES, CORP.	NDT (RT, MT/VBT) OF 1.5 MT STORAGE TANK AT SAN PASCUAL, BATANGAS
KGB SCHNEIDEN, CORP.	NDT (PT) ON SMC TINGA BRIDGE-RETROFITTING WORKS
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF PALAYAN DOUBLE FLOW TURBINE ROTOR (AS LEFT) AT GENERAL TRIAS, CAVITE
TOSUNG CONSTRUCTION PHILS. INC.	NDT (MT, PT) OF 100 TONS CRANE BOOM AT STO. TOMAS, PAMPANGA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (PT) OF 4 UNITS 28" SHAFT AND VALVE HOUSING (MSV & CV) AT GENERAL TRIAS, CAVITE
YSD & CS	NDT (UT) OF WELDING JOINTS AT MARIVELES, BATAAN
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF MGPP STAGE 1-6 DIAPHRAGM (DE & NDE SIDE) AT CALAMBA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (MT, PT) OF GLAND PACKING SEAL (PALAYAN) AT GENERAL TRIAS, CAVITE
SN ABOITIZ POWER-BENGUET, INC.	NDT (UT, MT, PT) OF BINGA PLANT TURBINE RUNNER BLADES AT BINGA, BENGUET
GENTHINK INTERNATIONAL CONSTRUCTION CORPORATION	NDT (RT-WQT) OF 16 SETS A36 AT SMC-MPGC BIAAN, MARIVELES, BATAAN
BASED INDUSTRIAL INSPECTION SERVICES CORP.	NDT (UT) EQUIPMENT RENTAL
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF MGPP STAGE 1-6 DIAPHRAGM (ADDITIONAL ENGAGEMENT) AT CALAMBA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES	NDT (MT, PT) OF LABYRINTH RING AT STA. ROSA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	CALIBRATION OF ELCOMETER 456 COATING THICKNESS GAUGE & PARKER MT AC YOKE
MJL INDUSTRIAL ENGINEERING SERVICES	ASNT NDT LEVEL III SERVICES - NDT (MT, PT) LEVEL II & PWHT CERTIFICATION
PETRON CORPORATION	NDT (RT) - PPCS22-0005 RSFFB UNITS 1, 2, 3 & 4 2022 TURNAROUND FURNACE TUBE AT BATAAN



CLIENT	PROJECT		
PETRON CORPORATION	NDT (RT) - PPM22-002-MEC MLA BYPASS LINE AT MARIVELES, BATAAN		
ASSISTCO ENERGY & INDUSTRIAL CORPORATION / PETRON CORPORATION	NDT (PAUT) OF REFINERY HEATER TUBES AT LIMAY, BATAAN		
ASSISTCO ENERGY & INDUSTRIAL CORPORATION / PETRON CORPORATION	POST WELD HEAT TREATMENT OF REFINERY HEATER TUBES AT LIMAY, BATAAN		
UNITED SIEGEN PHILLIPINES CORP.	NDT (VBT) OF 2.5 MT STORAGE TANK AT SAN PASCUAL, BATANGAS		
TÜV SÜD PSB PHILIPPINES INC.	ASNT NDT LEVEL III SERVICES - NDT (UT, MT, PT) LEVEL II RECERTIFICATION		
KGB SCHNEIDEN, CORP.	NDT (PT) ON SMC TINGA BRIDGE-RETROFITTING WORKS		
BASED INDUSTRIAL INSPECTION SERVICES CORP.	NDT (UT) EQUIPMENT RENTAL		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	CALIBRATION OF PARKER ELECTRIC MAGNETIC YOKE		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF MLPP 77.5MW DOUBLE FLOW TURBINE ROTOR (AS FOUND) AT CAVITE		
APIC INSPECTION AND TESTING SERVICES INC.	NDT (RT) EQUIPMENT RENTAL - IR-100 PROJECTOR & ACCESSORIES		
HOTWORK INTERNATIONAL INC.	NDT (PT-WQT) OF 2 SETS SA-240 PLATE AT MARIVELES BATAAN		
CJI GENERAL SERVICES INC.	ASNT NDT LEVEL III SERVICES - NDT (PT) LEVEL II CERTIFICATION		
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF BOX SUPPORT (BEFORE & AFTER LOAD TESTING) AT CALAMBA, LAGUNA		
D.M. CONSUNJI, INC.	NDT (RT-WQT) OF 25MM THK. PLATES AT IBAAN, BATANGAS		
GREENPOWER TECHNOLOGY SERVICES	NDT (UT, PT) MAPP JOURNAL BEARING #2 (U&L) AT STA. ROSA, LAGUNA		
CHANG TSAI CONST. & TRADING	NDT (RT) OF RAW WATER TRANSFER PUMP AT MARIVELES, BATAAN		
BASED INDUSTRIAL INSPECTION SERVICES CORP.	NDT (UT) EQUIPMENT RENTAL		
YUO PIN CONSTRUCTION PHILIPPINES INC.	NDT (PT) OF CRANE BOOM (STEEL TUBE) AT MARIVELES, BATAAN		



CLIENT	PROJECT
MAGITEK INDUSTRIAL INSPECTION SERVICES	RENTAL OF RADIOGRAPHIC TESTING (RT) CAMERA & ACCESSORIES
GREENPOWER TECHNOLOGY SERVICES	NDT (UT, PT) OF MAPP THRUST PAD (GENERATOR & TURBINE SIDE) AT STA. ROSA, LAGUNA
ENERGY DEVELOPMENT CORPORATION	ASNT NDT LEVEL III SERVICES - BASIC NDT TRAINING & LEVEL II CERTIFICATION OF CM PERSONNEL
EXE ENGINEERING SERVICES AND SOLUTIONS	NDT (PT-WQT) OF 10 SETS A36 PLATE AT MARIVELES, BATAAN
UNITED SIEGEN PHILIPPINES CORP.	NDT (VI, UTG, RT, MT, VBT) OF 12K CU.M. STORAGE TANK AT BACOLOD
CJI GENERAL SERVICES INC.	NDT (RTFI, VBT) LEVEL II CERTIFICATION
MITSUBISHI POWER (PHILIPPINES) INC.	NDT (PAUT) LEVEL II RECERTIFICATION
GREENPOWER TECHNOLOGY SERVICES	NDT (MT) OF EX-UNIT 3 STAGE 1 DIAPHRAGM AT STA. ROSA, LAGUNA
APIC INSPECTION AND TESTING SERVICES INC.	RENTAL OF IR-100 PROJECTOR & ACCESSORIES
K AND F CONSTRUCTION DEV'T. CORP.	NDT (RT, VBT) OF T121 AT SAN PASCUAL, BATANGAS
GREENPOWER TECHNOLOGY SERVICES	NDT (MT) OF TGPP2 TURBINE ROTOR AT STA. ROSA, LAGUNA
YSD & CS	NDT (UT) OF WELD JOINTS AT MARIVELES, BATAAN
ASSISTCO ENERGY & INDUSTRIAL CORPORATION	NDT (PAUT) OF H-105 RADIANT TUBES AT LIMAY. BATAAN
K AND F CONSTRUCTION DEV'T. CORP.	NDT (RT, VBT) OF T121 (ADD'L. ENGAGEMENT) AT SAN PASCUAL, BATANGAS
GREENPOWER TECHNOLOGY SERVICES	NDT (UT, MT, PT) OF MAPP S5 ROTOR WHEEL & OEC JOURNAL BEARING AT STA. ROSA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (PT) OF 28" FLANGE & SHAFT (MSV2 & CV2) AT GEN. TRIAS, CAVITE
TOLEDO POWER COMPANY	NDT (ECT/RFT) OF TPC 1A AT TOLEDO, CEBU
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF MGPP STAGE 1-6 DIAPHRAGM (DE & NDE; AS LEFT) AT CALAMBA, LAGUNA



CLIENT	PROJECT
MHI POWER (PHILIPPINES) PLANT SERVICES CORPORATION	NDT EQUIPMENT RENTAL & MANPOWER PROVISION AT LIMAY, BATAAN
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF PAL2 OKOY5 20MW TURBINE ROTOR (AS FOUND) AT GEN. TRIAS, CAVITE
MHI POWER (PHILIPPINES) PLANT SERVICES CORPORATION	RENTAL OF UT MACHINE & PROBE CABLES AT LIMAY, BATAAN
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) MALITBOG POWER PLANT CONTROL VALVE (RIGHT) AT CALAMBA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (PT) OF 28" FLANGE & SHAFT (MSV2 & CV2; 2ND) AT GEN. TRIAS, CAVITE
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (PT) OF MALITBOG POWER PLANT MAIN STOP VALVE (L&R) AT GEN. TRIAS, CAVITE
RGG CONSTRUCTION & SERVICES	NDT (PT-WQT) AT MARIVELES, BATAAN
JDAMANCIO ENTERPRISE	NDT (RT) OF SHIP BOTTOM HULL AT NAVOTAS
COSTAR FABRICATION CORP.	NDT (MT) OF DAMAGED SHELL & HEAD PLATE (CRUDE TANK) AT VALENZUELA
GREENPOWER TECHNOLOGY SERVICES	NDT OF TGPP STAGE 1 DIAPHRAGM (DE & NDE) AT STA. ROSA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	ASNT NDT LEVEL III SERVICES - NDT (UT, MT, PT, VT) LEVEL II CERTIFICATION
COSTAR FABRICATION CORP.	HYDROTEST WITNESSING AT VALENZUELA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF MALTIBOG BOTTOMING 20MW TURBINE ROTOR AT GEN TRIAS, CAVITE
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) MALITBOG POWER PLANT CONTROL VALVE (RIGHT; 2ND) AT CALAMBA, LAGUNA
D.M. CONSUNJI, INC.	PROVISION OF QC ENGINEER AT DMCI STEEL FABRICATION
TÜV SÜD PSB PHILIPPINES INC.	RENTAL OF UT MACHINE, CABLE AND PROBE
TÜV SÜD PSB PHILIPPINES INC.	SUPPLY OF NDT (UT) LEVEL II INSPECTORS AT DAVAO
TÜV SÜD PSB PHILIPPINES INC.	RENTAL OF DRY FILM THICKNESS GAUGE



CLIENT	PROJECT		
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (UT, PT) OF UMPP JOURNAL BEARING PAD 2 AT STA. ROSA LAGUNA		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF UMPP STG40 JOURNAL SHAFT AT GEN. TRIAS, CAVITE		
YSD & CS	NDT (UT) OF WELD JOINTS AT MARIVELES, BATAAN		
TÜV SÜD PSB PHILIPPINES INC.	RENTAL OF ULTRASONIC THICKNESS GAUGE AT DAVAO		
TÜV SÜD PSB PHILIPPINES INC.	PERSONNEL PROVISION AT BATANGAS		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	DEMAGNETIZATION OF GENERATOR ROTOR AT GEN. TRIAS, CAVITE		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF UMPP STG40 JOURNAL SHAFT (AFTER BALANCING) AT GEN TRIAS, CAVITE		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (MT, PT) OF PAL 2 OKOY 5 HP DIAPHRAGM AT GEN. TRIAS, CAVITE		
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (UT, PT) OF UMPP JOURNAL BEARING 2, 3 & 4 AT STA. ROSA, LAGUNA		
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (UT, PT) OF 63MW GLAND SEAL (DE/NDE) AT STA. ROSA, LAGUNA		
GREEN INNOVATIONS, INC.	NDT (RT-WQT) OF 4" B.I. PIPE AT MARIVELES, BATAAN		
SUMMA WATER RESOURCES INC.	NDT (RT-WQT) OF 4" B.I. PIPE AT MARIVELES, BATAAN		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF TGPP TURBINE ROTOR (AS FOUND) AT GEN. TRIAS, CAVITE		
MAGITEK INDUSTRIAL INSPECTION SERVICES	RENTAL OF RT EQUIPMENT & CONSUMABLES		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	RENTAL OF UT EQUIPMENT		
MAGITEK INDUSTRIAL INSPECTION SERVICES	NDT (RT) EQUIPMENT RENTAL		
UNIVERSAL NDT INC.	SUPPLY OF USM GO COAXIAL CABLE		
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT, PT) OF PAL2 OKOY5 MSV AT CALAMBA, LAGUNA		



CLIENT	PROJECT
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT, PT) OF PAL2 OKOY5 CV AT CALAMBA, LAGUNA
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT, PT) OF MBPP CV AT CALAMBA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (UT, PT) OF UMPP JOURNAL BEARING 3 & 4 AT STA. ROSA, LAGUNA
BALDO CONSTRUCTION AND DEVELOPMENT CORP.	NDT (PT) OF I-BEAM WELD CONNECTION AT MABINI, BATANGAS
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (PAUT, MT) ON APRI-MAKBAN TURBINE ROTOR AT STA. ROSA, LAGUNA
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF PAL2 OKOY5 20MW TURBINE ROTOR (AS FOUND) AT GEN. TRIAS, CAVITE
MAGITEK INDUSTRIAL INSPECTION SERVICES	NDT (RT) EQUIPMENT RENTAL
D.M. CONSUJI FABRICATION SHOP	TDJV-NSCR CP01 – MALANDAY DEPOT AT CALACA, BATANGAS
ACCIONA CONSTRUCTION PHILIPPINES INC.	MALOLOS CLARK RAILWAY PROJECT- SHEET PILES INSTALLED AT CIA STATION
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT,MT,PT) OF 77.5MW MLPP TURBINE ROTOR (AS LEFT) AT GEN. TRIAS,CAVITE
GREENPOWER MAINTENANCE SERVICES, INC.	NDT (UT,PT) OF TVI BEARING NO. 5 AT STA. ROSA, LAGUNA
NC ABRAHAN BUILDERS	NDT (PT) OF SAMPLE PLATES AT BATANGAS
HOTWORK INTERNATIONAL INC.	NDT (PT-WQT) OF 2 SETS PLATE AT MARIVELES BATAAN
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT , MT , PT) OF PAL2 OKOY5 TURBINE ROTOR AT GEN. TRIAS, CANTE
BGS ADVANCE TESTING SERVICES CO.	POST WELD HEAT TREATMENT OF REPAIRED WELDMENT AT TACLOBAN
ECO ACCESS SYSTEMS AND SOLUTIONS INC.	NDT (UTG) AT GNPOWER, MARIVELES, BATAAN
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT, PT) OF PAL2 OKOY5 CV AT CALAMBA, LAGUNA
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT, PT) OF MBPP CV AT CALAMBA, LAGUNA



CLIENT	PROJECT
SY3 ENERGY MAINTENNCE SERVICES CORPORATION	NDT (MT, PT) OF 60MW APRI TURBINE ROTOR (AS LEST) AT GEN. TRIAS, CAVITE
PETER BENA CONSTRUCTION AND DEVELOPMENT CORP.	NDT (UT, MT, PT) ON WAREHOUSE BUILDING AT TAGUIG
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF TGPP TURBINE ROTOR (AS FOUND) AT GEN. TRIAS, CAVITE
ENERGY DEVELOPMENT CORPORATION	NDT (PAUT) OF UMPP STG40 TURBINE ROTOR AT LEYTE
ALPHALITE FREIGHT ELEVATOR SERVICES	NDT (MT) OF 10T OVERHEAD CRANE AT QUEZON CITY
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (MT, PT) OF PAL2 OKOY5 HP DIAPHRAGM (AS LEFT) AT GEN. TRIAS, CAVITE
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (MT) OF 77.5MW MLPP BLADE ROOT AT GEN.TRIAS, CAVITE
KGB SCHNEIDEN, CORP.	DRY FILM THICKNESS TESTING (DFT) – FF CRUZ CAVITE MANHOLE AT LAS PINAS
KENMATT CONSTRUCTION CORP.	NDT (VBT) ON LEMERY OIL TERMINAL (TANKS) AT LEMERY, BATANGAS
TÜV SÜD PSB PHILIPPINES INC.	PERSONNEL PROVISION AT DAVAO
MAGITEK INDUSTRIAL INSPECTION SERVICES	NDT (RT) EQUIPMENT RENTAL
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (MT , PT) 60MW APRI TURBINE ROTOR (AS LEFT) AT GEN. TRIAS, CAVITE
PETER BENA CONSTRUCTION AND DEVELOPMENT CORP.	NDT (UT , MT , PT) ON WAREHOUSE BUILDING AT TAGUIG
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT , MT, PT) OF TGPP TURBINE ROTOR (AS FOUND) AT GEN. TRIAS, CAVITE
ENERGY DEVELOPMENT CORPORATION	NDT (PAUT) OF UMPP STG40 TURBINE ROTOR AT LEYTE
ALPHALITE FREIGHT ELEVATOR SERVICES	NDT (MT) OF 10T OVERHEAD CRANE AT QUEZON CITY
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (MT , PT) OF PAL2 OKOY5 HP DIAPHGRAM (AS LEFT) AT GEN. TRIAS, CAVITE



CLIENT	PROJECT		
SY3 ENERGY MAITENANCE SERVICES CORPORATION	NDT (MT) OF 77.5MW MLPP BLADE ROOT AT GEN. TRIAS, CAVITE		
KGB SCHNEIDEN, CORP.	DRY FILM THICKNESS TESTING (DFT) – FF CRUZ CAVITE, MANHOLE AT LAS PINAS		
TÜV SÜD PSB PHILIPPINES INC.	PERSONNEL PROVISION AT DAVAO		
MAGITEK INDUSTRIAL INSPECTION SERVICES	NDT (RT) EQUIPMENT RENTAL		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF 77.5MW MLPP TURBINE ROTOR (AS LEFT) AT GEN. TRIAS, CAVITE		
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (UT, PT) OF TVI BEARING NO. 5 AT STA. ROSA, LAGUNA		
NC ABRAHAN BUILDERS	NDT (PT) OF SAMPLE PLATES AT BATANGAS		
HOTWORK INTERNATIONAL INC.	NDT (PT-WQT) OF SETS PLATE AT MARIVELES BATAAN		
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF PAL2 OKOY5 TURBINE ROTOR AT GEN. TRIAS, CAVITE		
BGS ADVANCE TESTING SERVICES CO.	POST WELD HEAT TREATMENT OF REPAIRED WELDMENT AT TACLOBAN		
ECO ACCESS SYSTEMS AND SOLUTION INC.	NDT (UTG) AT GNPOWER, MARIVELES, BATAAN		
INFINITE LOOP TECHNOLOGY CORPORATION	NDT(MT,RT) GAS OIL STORAGE TANK AT PAKIL LAGUMA		
BCME INDUSTRIAL SERVICES	NDT(RT) RENTAL OF EQUIPMENT AT BATANGAS CITY		
POWER ONE CONSTRUCTORS LMTD CORP.	MT OF ACP. SUB FRAME AT VALENZUELA CITY		
EC STRUCTURAL COMPOSITE INC	NDT (WQT/UT) MANDALUYONG		
HERMA SHIPYARD INC.	PROVISION OF NDT LEVEL III AT MARIVELES, BATAAN		
JOEL CHAVEZ CONSTRUCTION AND MAINTENANCE	NDT (PT LEVEL II CERTIFICATE TRAINING) AT BATANGAS CITY		
CA -ARCHITECTS BUILDERS AND DESIGN	NDT (UT) AT PARANAQUE		
D. M. CONSUNJI INC.	VISUAL&UT LRS AND WORKSHOP OF NSCR LINE 1		
PETRON	RSFFB TURNAROUND UNIT 14		
PETRON CORPORATION	NDT 2023 TURNAROUND PMS		



CLIENT	PROJECT
ENERGY DEVELOPMENT CORPORATION	LRUT FOR JAGUAR TO PAD RG CONDENSATE AT KIDAPAWAN CITY
PETER BENA CONSTRUCTION AND DEVELOPMENT CORP	NDT (UT,MT) DOÑA AMPARO BUILDING AT TONDO MA <mark>NILA</mark>
PETER BENA CONSTRUCTION AND DEVELOPMENT CORP	NDT (UT,MT) OF CERRADA PROJECT AT MAKATI CITY
SUBIC DRYDOCK CORPORATION	NDT (RT) OF WQT PLATES
SY3 ENERGY MAINTENANCE SERVICES CORPORATION	NDT (UT, MT, PT) OF PAL 2 OKOY 5 TURBINE ROTOR (AS FOUND & AS LEFT) AT GEN. TRIAS, CAVITE
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (UT, PT,MT) OF BGI-PALAYAN TURBINE ROTOR AT STA. ROSA, LAGUNA
HERMA SHIPYARD INC.	RT OF WPQR AT MARIVELES, BATAAN
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (UT, PT,MT) OF MLPP TURBINE ROTOR AT STA. ROSA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (PT,MT) OF UMPP TURBINE ROTOR CAPSULE AT STA. ROSA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (PT,MT) OF GLAND PACKING GENERATOR AND TURBINE SIDE AT STA. ROSA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (UT, PT,) OF BGI-PALAYAN TURBINE BEARING AT STA. ROSA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (UT, PT,MT) OF APRI-MAKBAN TURBINE ROTOR AT STA. ROSA, LAGUNA
SUBIC DRYDOCK CORPORATION	RT OF ABS ALUMINUM TEST PLATE AT SUBIC, ZAMBALES
INFINITE LOOP TECHNOLOGY CORPORATION	NDT (UTG) OF 15 UNITS OF PRESSURE VESSEL
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (MT) OF MLPP HP ROTOR BLADE GROOVE AT STA. ROSA, LAGUNA
GREENPOWER TECHNOLOGY SERVICES, INC.	NDT (RT) OF WQT PLATES AND WPS AT STA ROSA LAGUNA
PETRON CORPORATION	NDT (RT) OF RFSSB 2023 TURNAROUND 1-4 AT LIMAY BATAAN
ENERGY DEVELOPMENT CORPORATION	NDT (MT,PT) OF MBPP UNIT 3 AT ORMOC CITY
NEWTON ELECTRICAL EQUIPMENT	NDT (UT,HT,MT,PT) OF PAL 1 UNIT 2 GENERATOR ROTOR AT VALENZUELA
NEW TRISTAR ELECTRICAL FABRICATION AND TRADING CO	NDT (PT,MT,VI) OF TOWER WELDMENTS AT PADRE GARCIA BATANGAS
HERMA SHIPYARD INC.	RT OF PLATES AT MARIVELES, BATAAN
NEW TRISTAR ELECTRICAL FABRICATION AND TRADING CO	NDT (PT,VI) OF TOWER WELDMENTS AT GENERAL TRIAS
SOUTHERN METAL AND INDUSTRIAL SALES CORPORATION	NDT (PT) OF STEEL TRUSSES AND STRUCTURES AT ALABANG
BOSKALIS PHILIPPINES INC	NDT (HT,WI,MT,UT) OF PIPE PILE AT PARAÑAQUE
TAIHEI ALLTECH CONST. (PHIL) INC	NDT (RT) OF SHOP WELD BAGO BINARY GEOTHERMAL AT STA. ROSA, LAGUNA
KENMATT CONSTRUCTION CORP	NDT (RT) OF LEMERY OIL TERMINAL CORP PHASE 2 TANK 9-12,14-15 AT LEMERY BATANGAS
PETROGREEN ENERGY CORPORATION	NDT (UT,MT & QA/QC) OF WTG #14 TOWER AT AKLAN



CLIENT	PROJECT			
HERMA SHIPYARD INC.	RT OF 6" DIA PIPE AT MARIVELES, BATAAN			
TAIHEI ALLTECH CONST. (PHIL) INC	NDT (RT) OF FIELD WELD BAGO BINARY GEOTHERMAL AT BAGO, NEGROS OCCIDENTAL			
KENMATT CONSTRUCTION CORP	NDT (VBT) OF LEMERY OIL TERMINAL CORP PHASE 2 TANK 9-12,14-15 AT LEMERY BATANGAS			
METALITE BUILDERS DEVELOPMENT COMPANY INC	PROVISION OF WPS			
MHI POWER (PHILIPPINES) PLANT SERVICE CORPORATION	NDT (UT,PT,MT) STEAM TURBINE (MAJOR VALVES) AT MALITA DAVAO			
TAIHEI ALLTECH CONST. (PHIL) INC	NDT (RT) OF FIELD WELD BAGO BINARY GEOTHERMAL AT BAGO, NEGROS OCCIDENTAL			
PETRON CORPORATION	NDT (RT) PHASE 2 H2SO4 TANK AT LIMAY, BATAAN			
PRIME METRO BMB	WELDING INSPECTION (VI) PIPE PILE AT PARAÑAQUE			
TAIHEI ALLTECH CONST. (PHIL) INC.	NDT (PAUT) OF FIELD WELD BAGO BINARY GEOTHERMAL AT BAGO, NEGROS OCCIDENTAL			
HERMA SHIPYARD	NDT (MT, PT) OF MV LORCON ILOILO AT MARIVELES, BATAAN			
YOU PIN CONSTRUCTION PHILIPPINES INC.	NDT (PT) OF CRANE BOOM (STEEL TUBES)			
NEWTON ELECTRICAL EQUIPMENT	NDT (UT, PT) OF PALINPINON RETAINING RING			
ENERGY DEVELOPMENT CORPORATION	NDT (PT, UT, MT) UNIT 3 CAWAYAN PMS SHUTDOWN			
TAIHEI ALLTECH CONST. (PHIL) INC.	NDT (MT) OF TOSHIBA BOLTS AT CALACA, BATANGAS			
SERVICIO FILIPINO INC.	NDT (RT, PWHT, PT) OF PIPING AND VALVE AT LIMAY, BATAAN			
COSTAR FABRICATION CORP.	NDT (MT, PT, UT) OR TURBINE RUNNER AT LAGUNA			
COSTAR FABRICATION CORP.	NDT (PT) OF BABBIT BEARING AT MARILAO, BULACAN			
HERMA SHIPYARD INC.	RT OF PLATE AT MARIVELES, BATAAN			
COSTAR FABRICATION CORP.	NDT (PT) ALUMINUM HULL AT BASCO, BATANES			
MJL INDUSTRIAL ENGINEERING SERVICES	NDT (RT) OF MCA SHELL ANIBONG PIPING AT TACLOBAN, LEYTE			
TAIHEI ALLTECH CONST. (PHIL) INC.	NDT (PAUT) OF MAHANAGDONG BINARY OPTIMIZATION POWER PLANT AT ORMOC, LEYTE			
TAIHEI ALLTECH CONST. (PHIL) INC.	NDT (RT) SHOPWELD OF MAHANAGDONG BINARY OPTIMIZATION POWER PLANT AT STA.ROSA, LAGUNA			
PETRON CORPORATION	NDT (RT) OF PHASE 2 H2SO4 AT LIMAY, BATAAN			
SAN MIGUEL CORPORATION GLOBAL POWER	NDT (RT) OF BOILER TUBES DURING UMO-06 AT LIMAY, BATAAN			
SUBIC DRYDOCK CORPORATION	BASIC NDT TRAINING (VISUAL) AT IBAAN, BATANGAS			
ENERGY DEVELOPMENT CORPORATION	NDT (PT, UT) OF MLPP-3 MINOR SHUTDOWN			
PETRON CORPORATION	NDT (RT) OF RFSSB UNIT 4 AT LIMAY, BATAAN			
RON INTEGRATED CONSTRUCTION SERVICES OPC.	NDT (RT) OF SS PIPING AT STO.TOMAS, BATANGAS			
FRONTKEN PHILIPPINES INCORPORATED	NDT (PT, MT) DIAPHRAGM STAGE 5-6			
FRONTKEN PHILIPPINES INCORPORATED	NDT (PT, MT) DIAPHRAGM STAGE 1 TGPP			



CLIENT	PROJECT
CBK POWER COMPANY LIMITED	NDT (UT) OF THRUST BEARING AT KALAYAAN, L <mark>AGUNA</mark>
FRONTKEN PHILIPPINES INCORPORATED	NDT (MT) OF MLPP (EX-UNIT) MAIN STOP VALVE
RON INTEGRATED CONSTRUCTION SERVICES OPC.	NDT (RT) SAMSUNG BATINO SITE AT CALAMBA, LAGUNA
ITALIAN-THAI DEVELOPMENT PUBLIC COMPANY LIMITED	NDT (UT, RT, MT) OF STRUCTURAL WELDS FOR NSCR EXTENSION PROJECT
ITALIAN-THAI DEVELOPMENT PUBLIC COMPANY LIMITED	WELDING INSPECTION (USING AWS/CSWIP 3.1 INSPECTOR) OF COMPLETED WELDS FOR NSCR EXTENSION PROJECT



#### **NDT SUPPLIERS**





















#### **NDT SUPPLIERS**





















# **BANK ACCOUNTS**

Account Name	Bank Name	Account Type	Branch	Account Number
INSPECTA Inspection Services Corp.	BDO	Peso	Rosario,Batangas 4225	007588004836
INSPECTA Inspection Services Corp.	BDO	Dollar	Rosario,Batangas 4225	107580220366
INSPECTA Inspection Services Corp.	China Bank	Peso	Rosario,Batangas 4225	157300002605




# **CONTACT US**









156 San Agustin, Ibaan, Batangas 4230



#### **SATELLITE OFFICE**

B1 L5, Guijo St. Rainbow Homes 2, San Bartolome, Novaliches, Quezon City 1116



#### SATELLITE OFFICE

Brgy. Batangas II, Mariveles, Bataan, Philippines



(043) 727 5527 / (043) 786 1738 Landline: Mobile: +639107948248/+639289874110/

+639171042131



**Landline:** (02) 8 937 9229 / (02) 7 799 5619 Mobile:

+639107948248/+639289874110/

+639171042131



Landline: (02) 8 937 9229 / (02) 7 799 5619

+639107948248/+639289874110/

+639171042131



Email: Website: inspecta.ndtservices@gmail.com

inspectaeis.com.ph



https://www.linkedin.com/company/inspectaeis/



#### Facebook URL:

https://www.facebook.com/inspectainspectionservicescorp

https://www.facebook.com/profile.php