



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520
 PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

N361CR

PAGE NO: 1

GENERAL DETAILS

Aircraft Type: AW 109SP	Fuel:	Engine Type: Pratt & Whitney	
Aircraft Fleet: Helicopters	Fuel Burn: 0.00 L/Hr	Engine PN: PW207C	
Registration: N361CR	Empty Weight: 2381.67 kgs	Engine SN: BH0538	
Callsign: Seahawk	Mauw Weight: 3175.00 kgs	Engine 2 PN: PW207C	
Serial No: 22243	Company: Columbia River Bar Pilot's Assoc.	Engine 2 SN: BH0553	

MAINTENANCE DETAILS DATE OF VALUES: 03-25-2023

Airframe	6498.60 hours	8339.00 Airframe Lifts	405.00 Hoist Lifts	119.10 Hoist Hobbs	17669.00 landings
Engine 1	2304.50 hours	5565.00 starts			
Engine 2	2304.50 hours	5565.00 starts			



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **2**

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
Inspection						
Type	Inspection	Reference	Period	Last Done	Next Due	Remaining
Scheduled Inspections	BT 109SP-100 Hoist Clutch Slip Check (Part III)	BT 109SP-100, 0B-B-25-91-00-00A-340A-A, 0B-B-04-30-00-00A-000C-A.	400 Hoist Lifts	375.00	775.00	370.00 Cycles
Airworthiness Directive						
Special Inspections	AD 2022-05-10 Goodrich Externally Mounted Hoist Assembly	AD 2022-05-10	400 Hoist Lifts	375.00	775.00	370.00 Cycles
Scheduled Inspections	Rescue Hoist Cable Replacement	Hoist MM	1500 Hoist Lifts	0.00	1500.00	1095.00 Cycles
Limitation Note: Based on Hoist Lifts.						
Engine Calendar Inspection	End of Month Pratt and Whitney Service Plan/ CAMP Reports.		1 Months	02-28-2023	03-28-2023	1 Day
30 Day Inspection/Service						
Calendar Inspection	End of Month Agusta Service Plan Report		1 Months	02-28-2023	03-28-2023	1 Day
Surface Protections						
General	7 Day Main Rotor Blade Surface Protection	0B-A-12-20-11-00A-259A-A	7 Days	03-23-2023	03-30-2023	3 Days
General	28 Day Jeppesen NAV Data; Genesys/EFB Updates.		28 Days	03-22-2023	04-19-2023	23 Days
Scheduled Inspections	30 Day Cabin Portable Fire Extinguisher	0B-A-26-23-01-00A-281A-B	30 Days	03-23-2023	04-22-2023	26 Days
General	Tail Boom Corrosion Treatment	Company Requirement	90 Days	01-22-2023	04-22-2023	26 Days
General	30 Day VOR Check	FAR 91.171	30 Days	03-23-2023	04-22-2023	26 Days
General	30 Day Hoist Cable Inspection and Clean - First 100 Ft	Goodrich Maintenance Manual 25-00-36-1 pg. 503	30 Days	03-25-2023	04-24-2023	28 Days
General	60 Day Hoist Cable Clean and Lubrication	Goodrich Maintenance Manual 25-00-36-1 pg. 503. Cable conditioning pg.718-719	60 Days	02-26-2023	04-27-2023	31 Days
General	400HR/12 Month ELT Case And Antenna Insp	AMPI 0B-B-05-70-04-00A-000A-A	12 Months	05-03-2022	05-03-2023	37 Days
General	50HR/60 Day Hoist Mount Fitting And Adjacent Fuselage	AMPI 0B-B-05-70-06-00A-000A	60 Days	03-23-2023	05-22-2023	56 Days
General	50HR/60 Day Hoist Support Frame Assembly and Back-up Structure	AMPI 0B-B-05-70-06-00A-000A-A	60 Days	03-23-2023	05-22-2023	56 Days
General	50HR/60 Day Rescue Hoist Boom	AMPI 0B-B-05-70-06-00A-000A-A	60 Days	03-23-2023	05-22-2023	56 Days
General	50HR/60 Day Step Bar Teflon Protection	AMPI 0B-B-05-70-06-00A-000A-A	60 Days	03-23-2023	05-22-2023	56 Days
50HR/60 Day Inspections/Service						
General	50HR/60 Day Airframe Insp.	AMPI 0B-B-05-44-00-01A-000A-A	60 Days	03-25-2023	05-24-2023	58 Days



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **3**

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
General	400HR/12 Month Utility Hyd Sys Accum Service	AMPI 0B-B-05-46-00-00A-000A-A	12 Months	06-02-2022	06-02-2023	67 Days
Airframe Inspection	400HR/12 Month Main Landing Gear Struts Nitrogen Service (DO CONCURRENTLY W 400/12 SHOCK ABSORBER INSP)	0B-A-12-20-05-00A-214A-A	12 Months	06-02-2022	06-02-2023	67 Days
General	50HR/90 Day M/R Floating Ring/Droop Stop Lube	AMP 0B-A-12-20-13-00A-242A-A	90 Days	03-25-2023	06-23-2023	88 Days
General	50HR/90 Day Swashplate Lube	AMP 0B-A-12-20-14-00A-242A-A	90 Days	03-25-2023	06-23-2023	88 Days
Airframe Inspection	400HR/12 Month Main Landing Gear Shock Absorber (DO THIS INSP CONCURRENTLY WITH MLG STRUT NIT. SRVC.)	0B-A-32-10-00-00A-361A-A, (0B-A-12-20-05-00A-214A-A)	12 Months	07-02-2022	07-02-2023	97 Days
Special Inspections	DVI Hot Air Delivery Tubes (P/N 109-0691-26-101/-105/-109)	0B-B-21-41-16-00A-281B-A	24 Months	07-08-2021	07-08-2023	103 Days
General	200HR/6 Month Non-rotating Scissors Insp	AMP 0B-A-62-31-03-00A-281A-A	6 Months	01-22-2023	07-22-2023	117 Days
General	200HR/6 Month Rotating Scissors Insp	AMP 0B-A-62-31-02-00A-281A-A	6 Months	01-22-2023	07-22-2023	117 Days
General	100HR/6 Month Tail Rotor 90 Deg. Gearbox Oil Change	AMP 0B-A-12-13-02-00A-292A-A	6 Months	01-22-2023	07-22-2023	117 Days
General	100HR/6 Month Tail Rotor Duplex Bearing Lube	AMP 0B-B-12-20-17-00A-242A-A	6 Months	01-22-2023	07-22-2023	117 Days
General	200HR/12 Month Main Rotor Servo Actuator Service	AMP 0B-A-12-20-16-00A-242A-A	12 Months	07-26-2022	07-26-2023	121 Days
Special Inspections	AD 2022-06-19 Hoist Support Assy Inspection	ASB 109SP-143	12 Months	07-26-2022	07-26-2023	121 Days
General	6 Month HEEL's Ops Check	Northern Avionics HEEL System ICA-NAV434 HEEL System Inspections Section A	6 Months	02-05-2023	08-05-2023	131 Days
General	200HR/12 Month #1 and #2 Main Hydraulic System Accumulator Nitrogen Service - (Flight Controls)	0B-A-12-20-01-00A-214A-A, 0B-A-12-20-02-00A-214A-A	12 Months	08-14-2022	08-09-2023	135 Days
Special Inspections	AD 2022-05-10 Goodrich Externally Mounted Hoist Assembly	AD 2022-05-10	6 Months	02-26-2023	08-26-2023	152 Days
Scheduled Inspections	BT 109SP-100 Hoist Clutch Slip Check (Part III)	BT 109SP-100, 0B-B-25-91-00-00A-340A-A, 0B-B-04-30-00-00A-000C-A.	6 Months	02-26-2023	08-26-2023	152 Days
Limitation Note: 6 Month Requirement for load clutch slip check.						
General	900HR/12 Month Battery Reconditioning Service	AMP 0B-B-24-32-01-00A-200A-A	12 Months	09-12-2022	09-12-2023	169 Days
General	12 Month ELT Antenna Check	AMP 0B-A-25-61-00-00A-340A-A	12 Months	09-30-2022	09-30-2023	187 Days
General	12 Month ELT Control and Crash Sensor Op. Test	AMP 0B-A-25-61-00-00A-320A-A and AMP 0B-B-25-61-01-00A-320A-A	12 Months	09-30-2022	09-30-2023	187 Days
General	12 Month ELT Inspection per FAR 91.207(d)	FAR 91.207(d)	12 Months	09-30-2022	09-30-2023	187 Days
General	200HR/12 Month Main Transmission Chip Detector Ops Test	AMP 0B-A-63-41-00-00A-320A-A	12 Months	01-22-2023	01-22-2024	301 Days



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION:

N361CR

DATE:

03-25-2023

PAGE NO:

4

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
General	200HR/12Month 90-Deg. Gearbox Chip Detector Test	AMP 0B-A-65-41-01-00A-320A-A	12 Months	01-22-2023	01-22-2024	301 Days
Special Inspections	200HR/12 Month FWD and AFT MGB fittings, LH/RH	AMP 0B-A-53-10-00-00A-281D-A	12 Months	01-22-2023	01-22-2024	301 Days
General	400HR/12 Month Main Trans. Oil and Filter Change	AMP 0B-A-12-13-01-00A-292A-A	12 Months	01-22-2023	01-22-2024	301 Days
General	400HR/12 Month Fan Belts Check	AMP 0B-A-63-23-00-00A-369A-A	12 Months	01-22-2023	01-22-2024	301 Days
General	400HR/12 Month Tail Boom Ext Surfaces Insp	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	01-22-2023	01-22-2024	301 Days
General	400HR/12 Month Oil Cooler Fan Attachment Flange Insp	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	01-22-2023	01-22-2024	301 Days
General	400HR/24 Month Swashplate Duplex Bearing Insp	AMP 0B-A-62-32-00-00A-283A-A	12 Months	01-22-2023	01-22-2024	301 Days
General	400HR/12 Month MLG Compartments/Extension Actuators Check	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	01-22-2023	01-22-2024	301 Days
Airframe Inspection	12 Month Wheel Bearing Grease	0B-A-12-20-09-00A-242A-B and 0B-A-12-20-10-00A-242A-B	12 Months	01-22-2023	01-22-2024	301 Days
General	12 Month MLG Wheel Tire Nitrogen Service	AMP 0B-A-12-20-07-00A-214A-A	12 Months	01-22-2023	01-22-2024	301 Days
General	12 Month NLG Strut Torque Link Lube	AMP 0B-A-12-20-06-00A-242A-A	12 Months	01-22-2023	01-22-2024	301 Days
General	400HR/12 Month MLG Strut Torque Links Grease	AMP 0B-A-12-20-05-00A-242A-A	12 Months	01-22-2023	01-22-2024	301 Days
General	12 Month NLG Strut Service Nitrogen	AMP 0B-A-12-20-06-00A-214A-A	12 Months	01-22-2023	01-22-2024	301 Days
Servicing	1600HR/36 Month RH Main Landing Gear Strut Fluid Service	0B-A-12-20-05-00A-218A-A	36 Months	01-29-2021	01-29-2024	308 Days
General	400HR/12 Month Tail Boom-Scheduled Inspection // Internal Area and Related Brackets Insp	AMP 0B-A-53-40-00-00A-281A-A, AMPI 0B-B015-45-00-00A-000A-A	12 Months	01-31-2023	01-31-2024	310 Days
General	400HR/12 Month Cockpit Door Emergency Release Mech.Insp.	AMP 0B-B-52-13-00-00A-320A-A	12 Months	02-02-2023	02-02-2024	312 Days
General	400HR/12 Month Tail Rotor Drive Shaft Support Insp.	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	02-02-2023	02-02-2024	312 Days
General	400HR/12 Month Maintenance Steps and Restraint Cables Insp.	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	02-02-2023	02-02-2024	312 Days
General	400HR/12 Month Fuselage Internal Surfaces Inspection	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	02-02-2023	02-02-2024	312 Days
General	12 Month Engine #1 Inspection	AMPI 0B-B-05-44-00-06A-000A-A	12 Months	02-03-2023	02-03-2024	313 Days
General	12 Month Engine #2 Inspection	AMPI 0B-B-05-44-00-06A-000A-A	12 Months	02-03-2023	02-03-2024	313 Days
General	Wires of the Electrical Wiring Harness - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
Engine	Chip Detector - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
Engine	Ignition Cables - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **5**

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining
General	Connectors of the Electrical Wiring Harness - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
General	T6/T1 Wiring Harness - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
P&W Scheduled Maintenance Checks - Eng#1		Reference	Period	Last Done	Next Due	Remaining
Engine Scheduled	Engines General Visual Inspection - Eng. 1.	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
Engine	Engines - General Visual Inspection - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
Engine	T6/T1 Wiring Harness - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
Engine	Wires of the Electrical Wiring Harness - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
P&W Scheduled Maintenance Checks - Eng#2		Reference	Period	Last Done	Next Due	Remaining
General	Ignition Cables - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month Main Rotor Servo Actuator Lever (3 off) Surface Protection	AMP 0B-A-12-20-18-00A-259A-A	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month Tail Boom - Scheduled Inspection // Internal Area, Stab Attachment Area and Related Locking System Insp.	0B-A-53-40-00-00A-281B-A, AMPI 0B-B-05-45-00-00A-000A-A.	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month Fuselage Structure Inspection at STA 4327	AMP 0B-B-53-10-00-00A-281C-A	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month Fuselage Struc Insp At STA 4460	AMP 0B-B-53-10-00-00A-281C-A	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month Fuselage Struc Insp At STA 2164.8	AMP 0B-B-53-10-00-00A-281C-A	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month Internal Surface Struc Below Eng Mounts	AMP 0B-A-53-10-00-00A-281A-A	12 Months	02-03-2023	02-03-2024	313 Days
Special Inspections	400HR/12 Month Fuel And Oil Hoses Insp	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month Fuselage External Surfaces Insp	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	02-03-2023	02-03-2024	313 Days
Special Inspections	400HR/12 Month Tubes And Electrical Wiring Insp	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month stabilizers Insp	AMPI 0B-B-05-45-00-00A-000A-A	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month T/R Servo Actuator Lever Lube	AMP 0B-A-12-20-19-00A-259A-A	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month Fuel Filter Element Replacement / #1 Side Airframe	AMP 0B-A-28-21-10-01A-921A-A	12 Months	02-03-2023	02-03-2024	313 Days



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **6**

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
General	400HR/12 Month Fuel Filter Element Replacement/ #2 Side Airframe	AMP 0B-A-28-21-10-01A-921A-A	12 Months	02-03-2023	02-03-2024	313 Days
Airframe Inspection	Donaldson 12 Month/Annual Inspection	Donaldson IBF ICA Manual	12 Months	02-03-2023	02-03-2024	313 Days
Airframe Inspection	400HR/12 Month Main Landing Gear Inspection	0B-A-32-11-00-00A-281A-A	12 Months	02-03-2023	02-03-2024	313 Days
12 Month Inspections/Service		Reference	Period	Last Done	Next Due	Remaining
General	12 Month Airframe Scheduled Inspection	AMPI 0B-B-05-44-00-06A-000A-A	12 Months	02-03-2023	02-03-2024	313 Days
General	12 Month/Annual Aero LED Search Light Inspection	AERO LEDs Document 0010-004 pg 1	12 Months	02-03-2023	02-03-2024	313 Days
Engine	Chip Detector - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
Engine	Connectors of the Electrical Wiring Harness - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	12 Months	02-03-2023	02-03-2024	313 Days
General	400HR/12 Month Rescue Hoist Cable Cutter Electrical Connections	AMP 0B-B-25-91-01-00A-281B-A	12 Months	02-05-2023	02-05-2024	315 Days
Airframe Calendar Inspections	ELT Beacon NOAA Reregistration	beaconregistration.gov	24 Months	02-16-2022	02-16-2024	326 Days
Limitation Note: Beacon Registration ID is 2DC87 E2788 FFBFF account email is astoria@brimaviation.com						
Special Inspections	36 Month Part 135 Aircraft Weighing	Part 135 Requirement	36 Months	05-14-2021	05-14-2024	414 Days
Servicing	1600HR/36 Month LH Main Landing Gear Strut Fluid Service	0B-A-12-20-05-00A-218A-A	36 Months	06-04-2021	06-04-2024	435 Days
Scheduled Inspections	24 Month FAR 91.411/91.413 IFR Certification	FAR 91.411, FAR 91.413	24 Months	07-27-2022	07-27-2024	488 Days
General	800HR/2 Year Tooth Belt Replacement - RH	AMP 0B-A-63-23-01-00A-720A-A	24 Months	02-03-2023	02-03-2025	679 Days
Scheduled Inspections	800HR/2 Year Tooth Belt Replacement - LH	AMP 0B-A-63-23-01-00A-720A-A	24 Months	02-03-2023	02-03-2025	679 Days
Special Inspections	AD 2015-11-08 Tail Rotor Lockwire	AD 2015-11-08	25 Airframe Hours	6498.60	6523.60	25.00 Hours
Servicing	Engine Oil & Filter Change (Oil Sample) After Overhaul	0B-A-12-13-03-00A-292A-A	400 Airframe Hours	6135.80	6535.80	37.20 Hours
Scheduled Inspection	50HR Engine DCU Download for #1 and #2 Engines	PW&C 3043322 77-41-01	50 Airframe Hours	6490.70	6540.70	42.10 Hours
Engine	Engine Power Assurance - Eng. 1	Pratt & Whitney Maintenance Manual 71-00-00	150 Airframe Hours	6396.10	6546.10	47.50 Hours
Engine	Engine Power Assurance - Eng. 2	Pratt & Whitney Maintenance Manual 71-00-00	150 Airframe Hours	6396.10	6546.10	47.50 Hours
General	50HR/60 Day Hoist Mount Fitting And Adjacent Fuselage	AMPI 0B-B-05-70-06-00A-000A	50 Airframe Hours	6496.90	6546.90	48.30 Hours
General	50HR/60 Day Hoist Support Frame Assembly and Back-up Structure	AMPI 0B-B-05-70-06-00A-000A-A	50 Airframe Hours	6496.90	6546.90	48.30 Hours
General	50HR/60 Day Rescue Hoist Boom	AMPI 0B-B-05-70-06-00A-000A-A	50 Airframe Hours	6496.90	6546.90	48.30 Hours



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **7**

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining
General	50HR/60 Day Step Bar Teflon Protection	AMPI 0B-B-05-70-06-00A-000A-A	50 Airframe Hours	6496.90	6546.90	48.30 Hours
Scheduled Inspection	50HR Aero LED Search Light Inspection	AERO LED Part 27 ICA Document 0027-0001, STC SR02704SE.	50 Airframe Hours	6498.60	6548.60	50.00 Hours
Special Inspections And Service		Reference	Period	Last Done	Next Due	Remaining
Special Inspections	#2 Engine - # 6 Fuel Nozzle Nut Torque Check.	PWC EMM 73-11-40 Para G.	50 Airframe Hours	6498.60	6548.60	50.00 Hours
Limitation Note: See Pratt Whitney Deviation Letter DAA2022-0622-PW207C-BH0553 Dated 28 Jan 2022.						
General	50HR/60 Day Airframe Insp.	AMPI 0B-B-05-44-00-01A-000A-A	50 Airframe Hours	6498.60	6548.60	50.00 Hours
General	50HR/90 Day M/R Floating Ring/Droop Stop Lube	AMP 0B-A-12-20-13-00A-242A-A	50 Airframe Hours	6498.60	6548.60	50.00 Hours
General	50HR/90 Day Swashplate Lube	AMP 0B-A-12-20-14-00A-242A-A	50 Airframe Hours	6498.60	6548.60	50.00 Hours
Scheduled Inspection	100HR Aero LED Search Light Inspection	AERO LEDs Part 27 ICA 0027-0001. STC SR027404SE.	100 Airframe Hours	6456.20	6556.20	57.60 Hours
Special Inspections	AD 2021-17-10 Rotor Brake Control	AD 2021-17-10	100 Airframe Hours	6456.20	6556.20	57.60 Hours
Limitation Note: Complied With action Item (g) and EASA AD 2021-0067 Inspection Item 1, and IAW Agusta Service Bulletin BT 109SP-146. Accomplishment Instructions 3(1-7). No Defected Noted at this time. Ongoing inspection requirement every 100 Hours TIS. C/W 10/01/2021 ACTT 5839.6 admtd 39-21675.						
100HR/6 Month Inspections/Service		Reference	Period	Last Done	Next Due	Remaining
General	100HR/6 Month Tail Rotor 90 Deg. Gearbox Oil Change	AMP 0B-A-12-13-02-00A-292A-A	100 Airframe Hours	6456.20	6556.20	57.60 Hours
General	100HR/6 Month Tail Rotor Duplex Bearing Lube	AMP 0B-B-12-20-17-00A-242A-A	100 Airframe Hours	6456.20	6556.20	57.60 Hours
General	100HR Tail Rotor Dynamic Bal Check	AMP 0B-A-18-10-02-00A-37BA-A	100 Airframe Hours	6456.20	6556.20	57.60 Hours
60HR Inspection		Reference	Period	Last Done	Next Due	Remaining
Airframe Inspection	* MANDATORY -- 60HR Insp Elastomeric Bearing (4) - Main Rotor	AMP 0B-A-62-21-00-00A-281A-A	60 Airframe Hours	6498.60	6558.60	60.00 Hours
Limitation Note: Mandatory Inspection. Inspect for cracking, separation of shims, blowing, rubber cracking or crumbs.						
General	200HR/12 Month Main Rotor Servo Actuator Service	AMP 0B-A-12-20-16-00A-242A-A	200 Airframe Hours	6377.00	6577.00	78.40 Hours
Special Inspections	AD 2020-20-02 Fire Extinguisher Bottle Inspection	AD 2020-20-02	200 Airframe Hours	6402.60	6602.60	104.00 Hours
Limitation Note: Orig. Compliance 10/01/2021 ACTT 5839.6 admtd 39-21258. Complied with by visual inspection per action item (e)(1). Not defects noted at this time. Ongoing inspections requirement every 200 Hours.						
Service Bulletins		Reference	Period	Last Done	Next Due	Remaining
Scheduled Inspections	BT 109SP-108 Fire Extinguisher Bottle Inspection	BT 109SP-108	200 Airframe Hours	6402.60	6602.60	104.00 Hours
General	200HR/12 Month #1 and #2 Main Hydraulic System Accumulator Nitrogen Service - (Flight Controls)	0B-A-12-20-01-00A-214A-A, 0B-A-12-20-02-00A-214A-A	200 Airframe Hours	6402.60	6602.60	104.00 Hours
300HR Inspection/Service		Reference	Period	Last Done	Next Due	Remaining



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **8**

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
Special Inspections	300HR Tail Rotor Drive Shaft Bearing Inspection	AMPI 0B-B-05-45-00-00A-000A-A	300 Airframe Hours	6311.80	6611.80	113.20 Hours
General	400HR/12 Month ELT Case And Antenna Insp	AMPI 0B-B-05-70-04-00A-000A-A	400 Airframe Hours	6228.70	6628.70	130.10 Hours
General	* 400HR Elect Power Sys Bus Feeder Circuit Breakers Ops Check	AMP 0B-B-24-61-00-00A-320J-A	400 Airframe Hours	6228.70	6628.70	130.10 Hours
General	* 400HR Elect Power Sys - Essential and Emergency Busses - Operation Test.	AMP 0B-B-24-61-00-00A-320E-A	400 Airframe Hours	6228.70	6628.70	130.10 Hours
Airframe Inspection	300HR Donaldson Electrical Inspection and Filter Cleaning	Donaldson IBF ICA Manual	300 Airframe Hours	6330.60	6630.60	132.00 Hours
Engine	EEC/Fuel Management Module Mode Response Check - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	800 Airframe Hours	5839.60	6639.60	141.00 Hours
Engine	EEC/Fuel Management Module Mode Response Check - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	800 Airframe Hours	5839.60	6639.60	141.00 Hours
Engine	Air Inlet Screen - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	800 Airframe Hours	5839.90	6639.90	141.30 Hours
Engine	Fuel Filter - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	800 Airframe Hours	5839.90	6639.90	141.30 Hours
Engine	Igniter Plug - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	800 Airframe Hours	5839.90	6639.90	141.30 Hours
Engine	Air Inlet Screen - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	800 Airframe Hours	5839.90	6639.90	141.30 Hours
General	Fuel Filter - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	800 Airframe Hours	5839.90	6639.90	141.30 Hours
General	Igniter Plug - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	800 Airframe Hours	5839.90	6639.90	141.30 Hours
Engine	800HR #1 Engine Inspection	Pratt & Whitney Maintenance Manual	800 Airframe Hours	5839.90	6639.90	141.30 Hours
Engine	800HR #2 Engine Inspection	Pratt & Whitney Maintenance Manual	800 Airframe Hours	5839.90	6639.90	141.30 Hours
General	200HR Airframe Insp	AMPI 0B-B-05-44-00-02A-000A-A	200 Airframe Hours	6456.20	6656.20	157.60 Hours
General	200 HR Rear Searchlight Inspection	AWPC-ENG-11-106 Rev. A Date 4/13/12 5.6.1 pg. 15	200 Airframe Hours	6456.20	6656.20	157.60 Hours
200HR/12 Month Inspections/Service		Reference	Period	Last Done	Next Due	Remaining
Airframe Inspection	* MANDATORY -- Elastomeric Bushing Insp (Tail Rotor)	0B-A-64-11-01-00A-281A-B	200 Airframe Hours	6456.20	6656.20	157.60 Hours
Limitation Note: Mandatory Inspections.						
General	200HR/6 Month Non-rotating Scissors Insp	AMP 0B-A-62-31-03-00A-281A-A	200 Airframe Hours	6456.20	6656.20	157.60 Hours
General	200HR/6 Month Rotating Scissors Insp	AMP 0B-A-62-31-02-00A-281A-A	200 Airframe Hours	6456.20	6656.20	157.60 Hours



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **9**

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
General	200HR/12 Month Main Transmission Chip Detector Ops Test	AMP 0B-A-63-41-00-00A-320A-A	200 Airframe Hours	6456.20	6656.20	157.60 Hours
General	200HR/12Month 90-Deg. Gearbox Chip Detector Test	AMP 0B-A-65-41-01-00A-320A-A	200 Airframe Hours	6456.20	6656.20	157.60 Hours
Special Inspections	200HR/12 Month FWD and AFT MGB fittings, LH/RH	AMP 0B-A-53-10-00-00A-281D-A	200 Airframe Hours	6456.20	6656.20	157.60 Hours
Airframe Inspection	Swashplate Support (Tube) Bolt - Torque Check	0B-A-62-32-00-00A-720A-A	200 Airframe Hours	6456.20	6656.20	157.60 Hours
General	400HR/12 Month Utility Hyd Sys Accum Service	AMPI 0B-B-05-46-00-00A-000A-A	400 Airframe Hours	6277.30	6677.30	178.70 Hours
General	*400HR Environmental Control Auto Shut Off Valve Sys Ops Check	AMP 0B-B-21-91-00-00A-320C-A and AMP 0B-A-21-91-00-00A-320B-A	400 Airframe Hours	6277.30	6677.30	178.70 Hours
Special Inspections	* 400HR Comms Sys RTU1 Radio Tuning Capability Ops Check	AMP 0B-B-23-81-00-00A-320B-A	400 Airframe Hours	6277.30	6677.30	178.70 Hours
Special Inspections	* 400HR Auto FLT Sys WOW Input Mismatch FM FCC Ops Check	AMP 0B-B-22-11-01-00A-320A-A	400 Airframe Hours	6318.70	6718.70	220.10 Hours
General	300HR Tail Rotor Drive Shaft Bearing Lubrication	AMP 0B-A-12-20-15-00A-242A-A	300 Airframe Hours	6428.90	6728.90	230.30 Hours
Airframe Inspection	400HR/12 Month Main Landing Gear Struts Nitrogen Service (DO CONCURRENTLY W 400/12 SHOCK ABSORBER INSP)	0B-A-12-20-05-00A-214A-A	400 Airframe Hours	6338.30	6738.30	239.70 Hours
Airframe Inspection	400HR/12 Month Main Landing Gear Shock Absorber (DO THIS INSP CONCURRENTLY WITH MLG STRUT NIT. SRVC.)	0B-A-32-10-00-00A-361A-A, (0B-A-12-20-05-00A-214A-A)	400 Airframe Hours	6342.10	6742.10	243.50 Hours
Special Inspections	90 Degree Gearbox Inspection	0B-B-05-45-00-00A-000A-A	1600 Airframe Hours	5219.90	6819.90	321.30 Hours
450HR Critical Area Inspection		Reference	Period	Last Done	Next Due	Remaining
Airframe Inspection	* MANDATORY -- 450HR Fuselage - Critical Area Inspection	AMP 0B-B-53-10-00-00A-283A-A	450 Airframe Hours	6377.00	6827.00	328.40 Hours
Limitation Note: Inspect for delamination and disbond on critical areas. Mandatory Inspection.						
General	400HR/12 Month Cockpit Door Emergency Release Mech.Insp.	AMP 0B-B-52-13-00-00A-320A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Tail Rotor Drive Shaft Support Insp.	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Maintenance Steps and Restraint Cables Insp.	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Main Rotor Servo Actuator Lever (3 off) Surface Protection	AMP 0B-A-12-20-18-00A-259A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Tail Boom-Scheduled Inspection // Internal Area and Related Brackets Insp	AMP 0B-A-53-40-00-00A-281A-A, AMPI 0B-B015-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Fuselage Internal Surfaces Inspection	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION:

N361CR

DATE:

03-25-2023

PAGE NO:

10

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
General	400HR/12 Month Tail Boom - Scheduled Inspection // Internal Area, Stab Attachment Area and Related Locking System Insp.	0B-A-53-40-00-00A-281B-A, AMPI 0B-B-05-45-00-00A-000A-A.	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Main Trans. Oil and Filter Change	AMP 0B-A-12-13-01-00A-292A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Fuselage Structure Inspection at STA 4327	AMP 0B-B-53-10-00-00A-281C-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Fuselage Struc Insp At STA 4460	AMP 0B-B-53-10-00-00A-281C-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Fuselage Struc Insp At STA 2164.8	AMP 0B-B-53-10-00-00A-281C-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Internal Surface Struc Below Eng Mounts	AMP 0B-A-53-10-00-00A-281A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Fan Belts Check	AMP 0B-A-63-23-00-00A-369A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
Special Inspections	400HR/12 Month Fuel And Oil Hoses Insp	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Fuselage External Surfaces Insp	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
Special Inspections	400HR/12 Month Tubes And Electrical Wiring Insp	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month stabilizers Insp	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month T/R Servo Actuator Lever Lube	AMP 0B-A-12-20-19-00A-259A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Tail Boom Ext Surfaces Insp	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Oil Cooler Fan Attachment Flange Insp	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/24 Month Swashplate Duplex Bearing Insp	AMP 0B-A-62-32-00-00A-283A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month MLG Compartments/Extension Actuators Check	AMPI 0B-B-05-45-00-00A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Fuel Filter Element Replacement / #1 Side Airframe	AMP 0B-A-28-21-10-01A-921A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Fuel Filter Element Replacement/ #2 Side Airframe	AMP 0B-A-28-21-10-01A-921A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month Rescue Hoist Cable Cutter Electrical Connections	AMP 0B-B-25-91-01-00A-281B-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
400HR/12 Month Inspection/Service		Reference	Period	Last Done	Next Due	Remaining
Airframe Inspection	400HR Airframe Inspection	AMPI 0B-B-05-44-00-03A-000A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR Landing Gear System Emergency Extension Operational Check	AMP 0B-B-32-31-00-00A-320B-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
Special Inspections	AD 2022-07-11 Tail Rotor Mast Crack	AD 2021-17-18	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	400HR/12 Month MLG Strut Torque Links Grease	AMP 0B-A-12-20-05-00A-242A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION:

N361CR

DATE:

03-25-2023

PAGE NO:

11

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining	
Airframe Inspection	400HR/12 Month Main Landing Gear Inspection	0B-A-32-11-00-00A-281A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
General	Rotor Brake GVI Damage/Condition	0B-A-63-51-03-00A-282A-A	400 Airframe Hours	6456.20	6856.20	357.60 Hours
Special Inspections	Hoist Cable Foul Detection OC.	0B-B-25-91-00-00A-320A-A	500 Airframe Hours	6363.10	6863.10	364.50 Days
Special Inspections	Hoist Cable Full Out Inspection, and Limit (Travel) Ops Check.	0B-B-25-91-00-00A-320C-A	500 Airframe Hours	6363.10	6863.10	364.50 Hours
General	800HR Hoist Pushbutton Contacts	AMP 0B-B-25-91-00-00A-320F-A	800 Airframe Hours	6093.90	6893.90	395.30 Hours
Special Inspections	Main Rotor Blade	0B-A-62-11-01-00A-283A-B	2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Special Inspections	Main Rotor Head Control Levers	0B-A-62-21-02-03A-283A-B	2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Special Inspections	Main Rotor Blade Grip	0B-A-62-21-02-07A-283A-B	2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Special Inspections	Main Rotor Flapping and Droop Stop Restraint	0B-A-62-21-02-23A-283A-B	2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Special Inspections	Main Rotor Head and Installation Components.	0B-A-62-21-00-00A-283D-B	2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Special Inspections	Main Rotor Hub Floating Ring		2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Special Inspections	Swash Plate	0B-A-623-32-00A-283B-B	2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Special Inspections	Main Rotor Floating Ring		2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Special Inspections	Pitch Change Llinks	0B-A-62-33-01-00A-283A-B	2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Special Inspections	Main Rotor Hub		2400 Airframe Hours	4555.40	6955.40	456.80 Hours
2400 Hour Inspections		Reference	Period	Last Done	Next Due	Remaining
Special Inspections	Main Rotor Elastomeric Bearing Inspection (Disassembly Required)		2400 Airframe Hours	4555.40	6955.40	456.80 Hours
Engine	Fuel Nozzles - Eng. 1	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	900 Airframe Hours	6062.90	6962.90	464.30 Hours
General	Fuel Nozzles - Eng. 2	Pratt & Whitney Maintenance Manual 05-20-00 (4)(C)(1) Table 2	900 Airframe Hours	6062.90	6962.90	464.30 Hours
Servicing	1600HR/36 Month RH Main Landing Gear Strut Fluid Service	0B-A-12-20-05-00A-218A-A	1600 Airframe Hours	5423.40	7023.40	524.80 Hours
General	* 1200HR Fire Protect. Sys Pressure Transducer Alarm Sw Ops Check	AMP 0B-A-26-11-01-00A-340A-A	1200 Airframe Hours	5839.60	7039.60	541.00 Hours
General	1200HR MFD Sensor Reconfig/RCP Manual Reconfig Ops Check	AMP 0B-A-31-64-00-00A-320C-A	1200 Airframe Hours	5839.60	7039.60	541.00 Hours
General	1200HR PFD Watchdog Function Ops Check	AMP 0B-A-31-64-00-00A-320B-A	1200 Airframe Hours	5839.60	7039.60	541.00 Hours
General	1200HR MFD Auto Reconfig To PFD ops Check	AMP 0B-A-31-64-00-00A-320F-A	1200 Airframe Hours	5839.60	7039.60	541.00 Hours



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **12**

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining
General	* 800HR GCU1 And GCU2 Field Relay Ops Check	AMP 0B-B-24-31-00-00A-320B-A	800 Airframe Hours	6277.30	7077.30	578.70 Hours
Special Inspections	* 800HR Comm Sys VHF2 Guarded Emerg Switch Ops Check	AMP 0B-B-23-12-00-00A-320B-A	800 Airframe Hours	6318.70	7118.70	620.10 Hours
800HR/12 Month Inspections/Service		Reference	Period	Last Done	Next Due	Remaining
General	800HR Airframe Inspection	AMPI 0B-B-05-44-00-04A-000A-A	800 Airframe Hours	6456.20	7256.20	757.60 Hours
General	800HR/2 Year Tooth Belt Replacement - RH	AMP 0B-A-63-23-01-00A-720A-A	800 Airframe Hours	6456.20	7256.20	757.60 Hours
Scheduled Inspections	800HR/2 Year Tooth Belt Replacement - LH	AMP 0B-A-63-23-01-00A-720A-A	800 Airframe Hours	6456.20	7256.20	757.60 Hours
General	1200HR Freewheel Unit Inspection	AMP 0B-A-63-21-03-00A-281A-B	1200 Airframe Hours	6062.90	7262.90	764.30 Hours
Servicing	1600HR/36 Month LH Main Landing Gear Strut Fluid Service	0B-A-12-20-05-00A-218A-A	1600 Airframe Hours	5670.10	7270.10	771.50 Hours
Servicing	1600HR Nose Landing Gear Strut Fluid Service	0B-A-12-20-06-00A-218A-A	1600 Airframe Hours	5711.50	7311.50	812.90 Hours
General	900HR/12 Month Battery Reconditioning Service	AMP 0B-B-24-32-01-00A-200A-A	900 Airframe Hours	6446.40	7346.40	847.80 Hours
General	* 1200HR Elect Conn Between Gen Bus 2 And Emerg Bus 2 Ops Check	AMP 0B-B-24-61-00-00A-320F-A	1200 Airframe Hours	6416.00	7616.00	1117.40 Hours
General	1200HR/3 Year Landing Gear Actuators Insp (Corrosion and Damage) (Over Sea.)	AMP 0B-A-32-00-00-00A-283A-A	1200 Airframe Hours	6456.20	7656.20	1157.60 Hours
1200HR/3 Year Inspection and Service		Reference	Period	Last Done	Next Due	Remaining
General	1200HR Oil Cooler Fan Inspection	AMP 0B-A-63-23-05-00A-281A-A	1200 Airframe Hours	6456.20	7656.20	1157.60 Hours
Limitation Note: For P/N 109-0455-01-103 Only						
Airframe Inspection	3000HR OC of GCU1 and GCU2 Circuits (MUST SEND TO AGUSTA)	0B-B-24-31-00-00A-320A-A	3000 Airframe Hours	4725.10	7725.10	1226.50 Hours
Certification Maintenance Requirements		Reference	Period	Last Done	Next Due	Remaining
Airframe Inspection	* MANDATORY - Blade (Composite Material) P/N 709-0104 -01-119)	0B-A-62-11-00-00A-281?A-A	100 Airframe Hours	0.00	8800.00	2301.40 Hours
Limitation Note: Mandatory Inspection. 8800 Hour Initial Period. Every 100 Hours after 8800 hours.						
Special Inspections	Hoist Cable Limit Switches Ops Check	0B-B-25-91-00-00A-320C-A	5000 Airframe Hours	4523.60	9523.60	3025.00 Hours
Special Inspections	Fire Bottle Discharge Ops Check	0B-A-26-21-01-00A-369A-B	4000 Airframe Hours	5633.10	9633.10	3134.50 Hours
Special Inspections	Fire Protection CB205, CB206 Ops Check	0B-B-26-21-00-00A-320A-A	4000 Airframe Hours	5633.10	9633.10	3134.50 Hours
Special Inspections	Fire Protection BTL1/2, ENG 1/2 Fire Extinguisher Control Panel Ops Check	0B-B-26-21-00-00A-320A-A	4000 Airframe Hours	5633.10	9633.10	3134.50 Hours
3200 Hour Inspections		Reference	Period	Last Done	Next Due	Remaining
Airframe Inspection	3200 Hour Inspection - General	0B-B-05-44-00-05A-000A-A	3200 Airframe Hours	6456.20	9656.20	3157.60 Hours



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **13**

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
Special Inspections	AHRS 1 /2 Circuit Breaker	10000 Airframe Hours	0.00	10000.00	3501.40 Hours
Special Inspections	Pilot Pedal FTR	10000 Airframe Hours	0.00	10000.00	3501.40 Hours
Special Inspections	RTU 1/2 Circuit Breaker	10000 Airframe Hours	0.00	10000.00	3501.40 Hours
Special Inspections	ICS AMU Circuit Breaker	10000 Airframe Hours	0.00	10000.00	3501.40 Hours
Special Inspections	Pilot Pedal - PTT ops test	10000 Airframe Hours	0.00	10000.00	3501.40 Hours
Special Inspections	Fuel Qty Gauging System (FQGS)	10000 Airframe Hours	0.00	10000.00	3501.40 Hours
Special Inspections	PFD MFD Cooling Fan	10000 Airframe Hours	0.00	10000.00	3501.40 Hours
Special Inspections	EFIS/IDU CPU Thermal Diode	10000 Airframe Hours	0.00	10000.00	3501.40 Hours
Special Inspections	Rotor Brake Microswitch OC	10000 Airframe Hours	0.00	10000.00	3501.40 Hours

Components

Part No.	Description	Serial No.	Life At Install	Period	Last Done	Next Due	Remaining
5833C000-005 (OC)	Environmental Assy	1717	0.00	0 Airframe Hours	0.00	0.00	N/A OC
ATA 26	FIRE PROTECTION (ATA 26)	ATA 26	0.00	0	0.00	0.00	N/A
8585C000-001 (OC)	Heat Exchanger Assy.	3963	0.00	0 Airframe Hours	3000.00	3000.00	N/A OC
109-0740V13-103 (OC)	DC Relay Box	N342	0.00	0 Airframe Hours	4015.60	4015.60	N/A OC
ATA 31	INDICATING AND RECORDING (ATA 31)	ATA 31	0.00	0	0.00	0.00	N/A
ATA 28	FUEL (ATA 28)	ATA 28	0.00	0	0.00	0.00	N/A
ATA 29	HYDRAULIC (ATA 29)	ATA 29	0.00	0	0.00	0.00	N/A
ATA 18	VIBRATION AND NOISE (ATA 18)	ATA 18	0.00	0	0.00	0.00	N/A
709-0160V01-101	ELASTOMERIC BUSHING - TAIL ROTOR [Position: Position 1]	N/A	0.00	Untracked	N/A	Untracked	N/A
			-	0	-	-	-
ATA 77	ENGINE (ATA 77)	ATA 77	0.00	0	0.00	0.00	N/A
3059779-01	filter	N/A	0.00	On Condition	N/A	On Condition	N/A
C406-N HM	406 Mhz ELT	10203	0.00	Untracked	N/A	Untracked	N/A
40612-004 (OC)	Airframe Battery	Brim 01	0.00	0 Airframe Hours	2355.20	2355.20	N/A OC
709-0160V01-101	ELASTOMERIC BUSHING - TAIL ROTOR	N/A	0.00	On Condition	N/A	On Condition	N/A
306001 (OC)	Fuel Filter Housing	D6102	0.00	On Condition	N/A	On Condition	N/A OC
306001 (OC)	Fuel Filter Housing	D6093	0.00	On Condition	N/A	On Condition	N/A OC



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **14**

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
109-0760-42-105 (OC)	Hydraulic Pump [Position: Position 1]	DA942	0.00	On Condition	N/A On Condition N/A OC
109-0760-42-105 (OC)	Hydraulic Pump [Position: Position 2]	DA934	0.00	On Condition	N/A On Condition N/A OC
109-0900-76-6A05 (OC)	Data Acquisition Unit	19050677	0.00	On Condition	N/A On Condition N/A OC
109-8131-35-101	T/R TRUNNION	AW937	0.00	On Condition	N/A On Condition N/A
109-0503-45-102 (OC)	Main Landing Gear Strut Assy RH [Position: right]	0343	0.00	0 Airframe Landings	14724.00 14724.00 N/A OC
109-0503-45-101 (OH)	Main Landing Gear Strut Assy LH	0219	0.00	0 Airframe Landings	8927.00 8927.00 N/A OH
44316-12-104 (N/A)	Rescue Hoist Core	4003	0.00	0 Airframe Hours	5870.40 5870.40 N/A N/A
44316-12-104 (OC)	Rescue Hoist Core	4003	0.00	0 Hoist Lifts	5939.00 5939.00 N/A OC
109-0300-21-101 (OC)	Fuselage Assy	AWPZ216	0.00	On Condition	N/A On Condition N/A OC
3HRL4ASSY49500-739 (OH)	Hoist Pendant Assy	00046	0.00	On Condition	N/A On Condition N/A OH
ATA 62	MAIN ROTOR 62	ATA 62	0.00	0	0.00 0.00 N/A
ATA 25	EQUIPMENT / FURSHISHING 25	ATA 25	0.00	0	0.00 0.00 N/A
ATA 63	MAIN ROTOR DRIVE 63	ATA 63	0.00	0	0.00 0.00 N/A
109-0112-02-107 (OC)	Main Rotor Assy	V5	0.00	0 Airframe Hours	4555.40 4555.40 N/A OC
ATA 64	TAIL ROTOR 64	ATA 64	0.00	0	0.00 0.00 N/A
ATA 65	TAIL ROTOR DRIVE 65	ATA 65	0.00	0	0.00 0.00 N/A
ATA 67	ROTOR FLIGHT CONTROL 67	ATA 67	0.00	0	0.00 0.00 N/A
ATA 32	LANDING GEAR 32	ATA 32	0.00	0	0.00 0.00 N/A
ATA 53	FUSELAGE 53	ATA 53	0.00	0	0.00 0.00 N/A
ATA 55	STABILIZER 55	ATA 55	0.00	0	0.00 0.00 N/A
ATA 21	ENVIRONMENTAL CONTROL 21	ATA 21	0.00	0	0.00 0.00 N/A
ATA 24	ELECTRICAL POWER 24	ATA 24	0.00	0	0.00 0.00 N/A
109-0111-49-101	Rotating Swashplate Support Ring	AW362	0.00	On Condition	N/A On Condition N/A
109-0512-70-109	Hyd. Accumulator	1813	0.00	Untracked	N/A Untracked N/A
109-0512-70-109 (OC)	Hyd. Accumulator	1813.	0.00	0 Airframe Hours	0.00 0.00 N/A OC
44316-12-104	Rescue Hoist Core		-	0	- - -
44316-12-104 (OH)	Rescue Hoist Core	4003	6.10	111 Airframe Hoist Hours	117.10 222.00 102.90 Hours OH
42325-298 (R)	Hoist Cable	S98-239	288.00	1500 Hoist Lifts	288.00 1500.00 1095.00 Cycles R



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION:

N361CR

DATE:

03-25-2023

PAGE NO:

15

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining			
109-8131-07-1 (R)	Retention Strap Assy [Position: Position 2]	AW111235	0.00		7200 Airframe Landings	13455.00	20655.00	2986.00 Landings R
109-8131-07-1 (R)	Retention Strap Assy [Position: Position 1]	AW110178	0.00		7200 Airframe Landings	15859.00	23059.00	5390.00 Landings R
709-0160-47-101 (R)	Retention Strap Bolt (Special bolt) [Position: Position 1]	AW2920	0.00		22000 Airframe Landings	5219.90	27219.90	9550.90 Landings R
109-0131-06-101 (R)	Hub Assy	AW924	0.00		12000 Airframe Landings	15859.00	27859.00	10190.00 Landings R
109-8131-06-1 (R)	Strap Plug	AW1877	0.00		20000 Airframe Landings	15859.00	35859.00	18190.00 Landings R
109-8131-06-1 (R)	Strap Plug	AW1879	0.00		20000 Airframe Landings	15859.00	35859.00	18190.00 Landings R
109-8131-08-1_ (R)	T/R hub retaining pin (Spring Pin)	AW8229	0.00		20000 Airframe Landings	15859.00	35859.00	18190.00 Landings R
109-8131-08-1_ (R)	T/R hub retaining pin (Spring Pin)	AW8241	0.00		20000 Airframe Landings	15859.00	35859.00	18190.00 Landings R
709-0160-47-101 (R)	Retention Strap Bolt (Special bolt) [Position: Position 2]	AW2853	0.00		22000 Airframe Landings	15859.00	37859.00	20190.00 Landings R
109-0425-01-3 (R)	Flange Adpt. [Position: Position 1]	V102	0.00		40000 Airframe Landings	0.00	40000.00	22331.00 Landings R
109-0425-01-3 (R)	Flange Adpt. [Position: Position 2]	V103	0.00		40000 Airframe Landings	0.00	40000.00	22331.00 Landings R
109-0425-01-3 (R)	Flange Adpt. [Position: Position 3]	MCR0645	0.00		40000 Airframe Landings	0.00	40000.00	22331.00 Landings R
109-0425-01-3 (R)	Flange Adpt. [Position: Position 4]	R1520	0.00		40000 Airframe Landings	0.00	40000.00	22331.00 Landings R
109-0500-10-109 (R)	Nose Landing Gear Servoactuator [Position: front]	0061	0.00		40000 Airframe Landings	7114.00	47114.00	29445.00 Landings R
109-0111-04-101 (R)	Elastomeric Bearing	LK3385	0.00		46000 Airframe Landings	4555.40	50555.40	32886.40 Landings R
42277-118 (R)	Rescue Hoist Ball-Spline Assy	N/A	0.00		29000 Hoist Lifts	5939.00	34939.00	34534.00 Cycles R
109-0503-44-103 (R)	Nose Landing Gear Strut [Position: front]	0251B	0.00		40000 Airframe Landings	15501.00	55501.00	37832.00 R



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **16**

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining		
109G3230V01-101 (R)	Main Landing Gear Servo Actuator [Position: left]	N/A-1	0.00	78000 Airframe Landings	0.00	78000.00	60331.00 Landings R
109G3230V01-101	Main Landing Gear Servo Actuator [Position: right]	N/A-2	0.00	78000 Airframe Landings	0.00	78000.00	60331.00 Landings
109-8412-02-3 (R)	Tall Rotor Shaft Segment [Position: Position 2]	V133	0.00	78000 Airframe Landings	0.00	78000.00	60331.00 Landings R
109-8412-02-3 (R)	Tall Rotor Shaft Segment [Position: Position 3]	V146	0.00	78000 Airframe Landings	0.00	78000.00	60331.00 Landings R
109-0111-03-113 (R)	Hub/Yoke	R862	0.00	89000 Airframe Landings	0.00	89000.00	71331.00 Landings R
42325-213	Rescue Hoist Cable Drum	N/A	0.00	70000 Hoist Lifts	5939.00	75939.00	75534.00 Cycles
109G3210V01-05 (R)	Main Landing Gear LH [Position: left]	N/A	0.00	101000 Airframe Landings	0.00	101000.00	83331.00 Landings R
109G3210V01-106 (R)	Main Landing Gear RH [Position: right]	N/A	0.00	101000 Airframe Landings	0.00	101000.00	83331.00 Landings R
109-0405-10-105 (R)	Planetary Carrier	V27	0.00	100000 Airframe Landings	4555.40	104555.40	86886.40 Landings R
42315-46	Rescue Hoist Output Pinion	N/A	0.00	109000 Hoist Lifts	5939.00	114939.00	114534.00 Cycles
109-0425-41-1 (R)	T/R Drive Shaft Assy N#1	V151	0.00	134000 Airframe Landings	0.00	134000.00	116331.00 Landings R
42315-48 (R)	Rescue Hoist Output Gear	N/A	0.00	185000 Hoist Lifts	5939.00	190939.00	190534.00 Cycles R
44314-398-101 (R)	Hoist Clutch	L90-133	0.00	36 Months	08-07-2020	07-23-2023	118 Days R
109-0740L42-101 (LL)	Digital Clock - AAA Battery Replacement (BOTH SIDE)	N/A	0.00	24 Months	08-18-2021	08-08-2023	134 Days LL
644.0506 (OH)	R/H Aft Float Assy	-	0.00	18 Months	02-24-2022	08-18-2023	144 Days OH
644.0505 (OH)	L/H Aft Float Assy	-	0.00	18 Months	02-24-2022	08-18-2023	144 Days OH
644.0504 (OH)	R/H Fwd Float Assy	-	0.00	18 Months	02-24-2022	08-18-2023	144 Days OH
644.0503 (OH)	L/H Fwd Float Assy	-	0.00	18 Months	02-24-2022	08-18-2023	144 Days OH
8162-2 (R)	HEELS battery replacement [Position: Position 1]	034275	0.00	24 Months	02-05-2023	02-05-2025	681 Days R
8162-2	HEELS battery replacement [Position: Position 2]	034265	0.00	24 Months	02-05-2023	02-05-2025	681 Days
8162-2 (R)	HEELS battery replacement [Position: Position 3]	034279	0.00	24 Months	02-05-2023	02-05-2025	681 Days R
8162-2 (R)	HEELS battery replacement [Position: Position 4]	034257	0.00	24 Months	02-05-2023	02-05-2025	681 Days R



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION:

N361CR

DATE:

03-25-2023

PAGE NO:

17

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining		
452-0133 (R)	ELT Battery [Position: Position 1]	386222-022	0.00	59 Months	09-18-2020	08-18-2025	875 Days R
27300-1 (OH)	Fire Extinguisher Bottle [Position: Position 2]	2841	0.00	5 Years	10-05-2020	10-05-2025	923 Days OH
27300-1 (LL)	Fire Extinguisher Bottle [Position: Position 1]	3143	40150.00	5 Years	07-06-2021	02-21-2026	1062 Days LL
P01202-201 (LL)	Under Seat Life Vest [Position: Position 2]	21040250032	0.00	5 Years	05-20-2021	05-19-2026	1149 Days LL
P01202-201 (LL)	Under Seat Life Vest [Position: Position 1]	21040250008	0.00	5 Years	05-20-2021	05-19-2026	1149 Days LL
P01202-201 (LL)	Under Seat Life Vest [Position: Position 3]	21040250004	0.00	5 Years	05-20-2021	05-19-2026	1149 Days LL
42315-281 (R)	CABLE CUTTER CARTRIDGE	N/A	0.00	5 Years	05-24-2021	05-24-2026	1154 Days R
30600-22	Fire Bottle Cartridges	Lot 120	0.00	12 Years	05-21-2021	05-21-2033	3708 Days
30600-22 (R)	Fire Bottle Cartridges	Lot 115	0.00	12 Years	10-05-2020	05-21-2033	3708 Days R
44314-398-101 (R)	Hoist Clutch	L90-133	0.00	2600 Airframe Lifts	5939.00	8539.00	200.00 Cycles R
1743645-02 (S)	Filter - Airframe Filter	NA	0.00	400 Airframe Hours	6346.00	6746.00	247.40 Hours S
28007GR90 (LL)	M/R Servo Actuator Base [Position: yellow]	9583	0.00	1000 Airframe Hours	5802.30	6802.30	303.70 Hours LL
109-0112-39-105 (OH)	MAIN ROTOR LAG DAMPER [Position: yellow]	2162	0.00	1200 Airframe Hours	5748.50	6948.50	449.90 Hours OH
28007GR90 (LL)	M/R Servo Actuator Base [Position: red]	10285	0.00	1000 Airframe Hours	5949.20	6949.20	450.60 Hours LL
28007GR90 (LL)	M/R Servo Actuator Base [Position: blue]	10401	0.00	1000 Airframe Hours	6157.30	7157.30	658.70 Hours LL
200SGL147Q-3-1 (OH)	Starter Generator [Position: Position 1]	S00115XL2	0.00	1000 Airframe Hours	6215.70	7215.70	717.10 Hours OH
109-0200-02-807 (R)	Left Stabilizer [Position: left]	CHA0083	0.00	3000 Airframe Hours	5980.30	8980.30	744.50 Hours R
109-0455-09-103 (R)	Cooling Fan Belt Drive [Position: Position 1]	74287	0.00	800 Airframe Hours	6456.20	7256.20	757.60 Hours R
109-0455-09-103 (R)	Cooling Fan Belt Drive [Position: Position 2]	78344	0.00	800 Airframe Hours	6456.20	7256.20	757.60 Hours R
109-0110-38-1 (R)	Upper Fixed Half Scissor Attachment Fitting	CCB0081	0.00	1600 Airframe Hours	5667.80	7267.80	769.20 Hours R
200SGL147Q-3-1 (OH)	Starter Generator [Position: Position 2]	S00149XL2	0.00	1000 Airframe Hours	6338.30	7338.30	839.70 Hours OH
109-0325-03-113 (R)	Aft Rod Assy [Position: left]	MOR1418	5630.50	13000 Airframe Hours	0.00	7369.50	870.90 Hours R
109-0325-03-113 (R)	Aft Rod Assy [Position: right]	MOR1417	5630.50	13000 Airframe Hours	0.00	7369.50	870.90 Hours R
109-0110-42-135 (OH)	M/R Servo Actuator (Yellow) [Position: yellow]	6250	195.10	1800 Airframe Hours	5802.30	7407.20	908.60 Hours OH
109-0112-39-105 (OH)	MAIN ROTOR LAG DAMPER [Position: blue]	0348	0.00	1200 Airframe Hours	6219.90	7419.90	921.30 Hours OH
109-0112-39-105 (OH)	MAIN ROTOR LAG DAMPER [Position: red]	0328	0.00	1200 Airframe Hours	6219.90	7419.90	921.30 Hours OH
109-0112-39-105 (OH)	MAIN ROTOR LAG DAMPER [Position: white]	2304	0.00	1200 Airframe Hours	6291.50	7491.50	992.90 Hours OH
GCSG505-28-1 (OH)	Generator Control Box [Position: Position 2]	2799D	0.00	3000 Airframe Hours	4725.10	7725.10	1226.50 Hours OH



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION:

N361CR

DATE:

03-25-2023

PAGE NO:

18

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining		
109-0110-42-134 (OH)	M/R Servo Actuator (Red) [Position: red]	4081	0.00	1800 Airframe Hours	5949.20	7749.20	1250.60 Hours OH
1538D000-003 (OH)	Turbine - Blower E.C.S.	1760	0.00	5000 Airframe Hours	3000.00	8000.00	1501.40 Hours OH
109-0210-03-13 (R)	Torque Tube Clamp (Bracket) Assy. [Position: right]	AV12247	0.00	4000 Airframe Hours	4062.20	8062.20	1563.60 Hours R
109-0110-42-136 (OH)	M/R Servo Actuator (Blue) [Position: blue]	8092	0.00	1800 Airframe Hours	6349.10	8149.10	1650.50 Hours OH
109-0440-01-123 (OH)	Tail (90 Deg) Gearbox Assy	TUR00543	0.00	3000 Airframe Hours	5219.90	8219.90	1721.30 Hours OH
109-0040-47-1 (R)	LINK ASSY (T/R) [Position: top]	N/A	0.00	11000 Airframe Hours	4652.50	15652.50	1769.50 Hours R
109-0040-47-1 (R)	LINK ASSY (T/R) [Position: bottom]	N/A	0.00	11000 Airframe Hours	4655.20	15655.20	1783.00 Hours R
109-0040-49-5 (LL)	Tail Rotor Servo Support	N/A	0.00	11000 Airframe Hours	4655.20	15655.20	1783.00 Hours LL
109-0134-11-103	Rotating Swashplate Locking Ring	V10	0.00	8300 Airframe Hours	0.00	8300.00	1801.40 Hours
GCSG505-28-1 (OH)	Generator Control Box [Position: Position 1]	65163	0.00	3000 Airframe Hours	5307.20	8307.20	1808.60 Hours OH
109-0435-31-1 (R)	Sleeve Mounting	TUR521	0.00	3300 Airframe Hours	5219.90	8519.90	2021.30 Hours R
109-0442-01-139 (R)	Case Assy	TUR00045	0.00	3300 Airframe Hours	5219.90	8519.90	2021.30 Hours R
109-0130-60-3 (R)	Lever	N/A	0.00	8600 Airframe Hours	0.00	8600.00	2101.40 Hours R
109-0130-21-103 (R)	Lever	MOR0676	0.00	8600 Airframe Hours	0.00	8600.00	2101.40 Hours R
109-0130-43-113 (R)	Lever Assy	22243	0.00	8600 Airframe Hours	0.00	8600.00	2101.40 Hours R
109-0716V03-101 (R)	Cooling Fan [Position: Position 3]	16357	0.00	6000 Airframe Hours	2997.40	8997.40	2498.80 Hours R
109-0716V03-101 (R)	Cooling Fan [Position: Position 2]	16353	0.00	6000 Airframe Hours	2997.40	8997.40	2498.80 Hours R
109-0716V03-101 (R)	Cooling Fan [Position: Position 1]	16349	0.00	6000 Airframe Hours	2997.40	8997.40	2498.80 Hours R
109-0134-03-105 (R)	Rotating Swashplate	R706	0.00	9100 Airframe Hours	0.00	9100.00	2601.40 Hours R
45888 (R)	HYD PUMP VESPEL SPLINE ADAPTER	N/A-	0.00	4800 Airframe Hours	4555.50	9355.50	2856.90 Hours R
109-0400-03-119 (OH)	Main Gearbox Assy	V171	1336.17	4800 Airframe Hours	6062.90	9526.73	3028.13 Hours OH
109-0405-76-107 (R)	M/R Shaft Assy.	V87	0.00	10000 Airframe Hours	4555.40	14555.40	3198.80 Hours R
109-0130-60-109	T/R rocker arm assy	FUC0040	0.00	10000 Airframe Hours	0.00	10000.00	3501.40 Hours
109-0210-03-13 (R)	Torque Tube Clamp Assy. [Position: left]	PZ607	0.00	4000 Airframe Hours	6013.60	10013.60	3515.00 Hours R
109-0325-02-107 (R)	Forward Rod Assy	ILS5856L	5630.50	16000 Airframe Hours	0.00	10369.50	3870.90 Hours R



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: N361CR DATE: 03-25-2023 PAGE NO: 19

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining		
45888 (R)	HYD PUMP VESPEL SPLINE ADAPTER	N/A	0.00	4800 Airframe Hours	5839.50	10639.50	4140.90 Hours R
3HRL4ASSY44316-505 (LL)	Hoist Mount	0052	0.00	7600 Airframe Lifts	5607.00	13207.00	4868.00 Cycles LL
109-0130-62-1 (R)	Walking Beam	MOR0887_	0.00	8600 Airframe Hours	3062.30	11662.30	5163.70 Hours R
109-0200-02-808 (R)	Right Stabilizer [Position: right]	CHA0026	0.00	6900 Airframe Hours	5219.90	12119.90	5621.30 Hours R
109-0344-23-101 (R)	Aft Interface Fitting	n/a	0.00	13000 Airframe Hours	0.00	13000.00	6501.40 Hours R
109-0344-23-102 (R)	Aft Interface Fitting	n/a	0.00	13000 Airframe Hours	0.00	13000.00	6501.40 Hours R
109-0332-34-101 (R)	Forward Interface Fitting	n/a	0.00	13000 Airframe Hours	0.00	13000.00	6501.40 Hours R
109-0332-34-102 (R)	Forward Interface Fitting	n/a	0.00	13000 Airframe Hours	0.00	13000.00	6501.40 Hours R
709-0104-01-111 (R)	M/R Blade [Position: red]	R2241	0.00	8800 Airframe Hours	4262.10	13062.10	6563.50 Hours R
709-0104-01-111	M/R Blade [Position: yellow]	AW1707	0.00	8800 Airframe Hours	4262.10	13062.10	6563.50 Months
709-0104-01-111 (R)	M/R Blade [Position: white]	V284	0.00	8800 Airframe Hours	4795.40	13595.40	7096.80 Hours R
709-0104-01-111 (R)	M/R Blade [Position: blue]	1212	0.00	8800 Airframe Hours	4795.40	13595.40	7096.80 Hours R
109-0130-33-1 (R)	Torsion Tube - Shaft	MOR1217	0.00	8600 Airframe Hours	5219.90	13819.90	7321.30 Hours R
109-0130-43-115 (R)	Forked lever assy	MOR2191	0.00	8600 Airframe Hours	6228.70	14828.70	7342.80 Hours R
109-0402-45-101 (R)	Upper Case Assy	V86	0.00	9800 Airframe Hours	4555.40	14355.40	7856.80 Hours R
109-0133-04-109 (R)	Tail Rotor Stick Assy	MOR8812	0.00	8600 Airframe Hours	6024.00	14624.00	8125.40 Hours R
109-0133-04-109 (R)	Tail Rotor Stick Assy	MOR9239	0.00	8600 Airframe Hours	6024.00	14624.00	8125.40 Hours R
109-0325-02-107 (R)	Forward Rod Assy	ILS8167G	3466.70	16000 Airframe Hours	2163.80	14697.10	8198.50 Hours R
109-0110-21-103 (R)	Stationary Scissor Sleeve	MCR1538	0.00	15000 Airframe Hours	0.00	15000.00	8501.40 Hours R
109-0040-48-117 (OH)	T/R Control Lever- Bell Crank	N/A	0.00	11000 Airframe Hours	4015.60	15015.60	8517.00 Hours OH
709-0160-48-101 (R)	Tail Rotor Blade Assy [Position: Position 2]	AW104077	0.00	10000 Airframe Hours	5839.60	15839.60	9341.00 Hours R
709-0160-48-101 (R)	Tail Rotor Blade Assy [Position: Position 1]	AW104079	0.00	10000 Airframe Hours	5839.60	15839.60	9341.00 Hours R
109-0110-53-1 (R)	Lower Fixed Half Scissor Support	N/A	0.00	17000 Airframe Hours	0.00	17000.00	10501.40 Hours R
109-0110-21-103 (R)	Stationary Scissor Sleeve	MCR02150	0.00	15000 Airframe Hours	2160.20	17160.20	10661.60 Hours R
109-0040-51-103 (OH)	TAIL ROTOR SERVO ACTUATOR	702	0.00	11000 Airframe Hours	6225.80	17225.80	10727.20 Hours OH
109-0110-04-1 (R)	Spherical Sleeve	AW31586	0.00	12000 Airframe Hours	6062.90	18062.90	11564.30 Hours R
109-0110-63-5	Fixed Swashplate Assy.	Q710	0.00	19000 Airframe Hours	0.00	19000.00	12501.40 Hours



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: N361CR DATE: 03-25-2023 PAGE NO: 20

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining		
109-0110-53-1	Lower Fixed Half Scissor Support	OSU525	0.00	17000 Airframe Hours	2908.00	19908.00	13409.40 Hours
109-0110-60-1 (R)	Lower Fixed Half-Scissor	MCR01547	0.00	20000 Airframe Hours	4555.40	24555.40	18056.80 Hours R
109-0134-29-101. (R)	Swashplate Support Tube.	AW217	0.00	24000 Airframe Hours	6062.90	30062.90	23564.30 Hours R
109-0433-01-107 (R)	90-Deg. Gearbox Pinion Gear	TUR00796	0.00	30000 Airframe Hours	5219.90	35219.90	28721.30 Hours R
109-0325-08-109 (R)	Brackett Assy [Position: Position 4]	604/PZL	5630.50	41000 Airframe Hours	0.00	35369.50	28870.90 Hours R
109-0325-08-109 (R)	Brackett Assy [Position: Position 1]	601/PZL	5630.50	41000 Airframe Hours	5630.50	41000.00	34501.40 Hours R
109-0325-08-109 (R)	Brackett Assy [Position: Position 2]	602/PZL	5630.50	41000 Airframe Hours	5630.50	41000.00	34501.40 Hours R
109-0325-08-109 (R)	Brackett Assy [Position: Position 3]	603/PZL	5630.50	41000 Airframe Hours	5630.50	41000.00	34501.40 Hours R
109-0110-90-107 (R)	Rotating Swashplate Grease Bolt	V53	0.00	42000 Airframe Hours	0.00	42000.00	35501.40 Hours R
109-0110-90-107 (R)	Rotating Swashplate Grease Bolt	V52	0.00	42000 Airframe Hours	0.00	42000.00	35501.40 Hours R
109-0440-01-103 (R)	90 DEG Gearbox Gear	TUR00543	0.00	41000 Airframe Hours	5219.90	46219.90	38611.10 Hours R
109-0111-04-101	Elastomeric Bearing	LK3390	0.00	46000 Airframe Hours	4555.40	50555.40	44056.80 Hours
109-0111-04-101	Elastomeric Bearing	LK3391	0.00	46000 Airframe Hours	4555.40	50555.40	44056.80 Hours
109-0111-04-101	Elastomeric Bearing	LK3395	0.00	46000 Airframe Hours	4555.40	50555.40	44056.80 Hours
109-0445-08-117 (R)	T/R Shaft Assy [Position: Position 1]	TUR00325	0.00	50000 Airframe Hours	3191.50	53191.50	45582.70 Hours R
109-0110-54-111	Upper Fixed Half-Scissor	MCR01455	0.00	48000 Airframe Hours	4555.40	52555.40	46056.80 Hours

Engine 1 Lifer Components

Part No.	Description	Serial No.	Life At Install	Period	Last Done	Next Due	Remaining
			-	0	-	-	-
PW207C (OH)	Engine [Position: Position 1]	BH0538	0.00	4000 Engine1 Hours	0.00	4000.00	1695.50 Hours OH

Engine 2 Lifer Components

Part No.	Description	Serial No.	Life At Install	Period	Last Done	Next Due	Remaining
			-	0	-	-	-
PW207C (OH)	Engine [Position: Position 2]	BH0553	0.00	4000 Engine2 Hours	0.00	4000.00	1695.50 Hours OH

ADs

Types	Subject	AD Number	Based On	Period	Warning	Last Done	Next Due	Remaining/Status
Standard ADs	TDR-94 Mode S Failure	1993-04-02		-	0	-	-	Not Applicable



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **21**

Maintenance Required	Reference	Period	Last Done	Next Due	Remaining
Limitation Note: Not Applicable by Part Number					
Standard ADs	Tail Rotor Mast Crack	2021-17-18	-	-	Superseded
Limitation Note: C/W 06/15/2021 ACTT 5695.5 ADMT 39-21701. C/W Part II and Part III by installation of a non affected sleeve. Part IV Applicable every 400FH. AD 2021-17-18 super-ceded by AD 2022-07-11.					
Standard ADs	Protective Sheath FOD	2022-11-06	-	-	Not Applicable
Limitation Note: Not Applicable by Aircraft Serial Number.					
Standard ADs	MLG Strut Inspection	AD#2021-24-11	Untracked	-	Complied With
Limitation Note: C/W by visual inspection per action item 1 of EASA AD#2019-0182. AD does not apply due to effected parts not installed on aircraft. P/N not installed.					
Standard ADs	Radio Altimeter 5G Interference	AD# 2021-23-13	On Condition	-	Complied With
Limitation Note: Complied With 01/10/22 ACTT 6053.1.					
Standard ADs	Hydraulic Pump P/N# 109-0760-42-103	AD#2021-23-10	Airframe Hours	25 Hours	5839.60 7439.60 Complied With
Limitation Note: C/W by EASA AD 2019-0213. Pump splines where replaced at 1600 TIS per overhaul requirements. Work was completed under W.O.#50, item #60 of the Annual inspection for 2021.					
Standard ADs	Rigid Connecting Link	AD#21-21-03	Date (Months)	0 Months	- - Complied With
Limitation Note: C/W per service bulletin SP109-128 on 12/17/2018 Reinspected per AD#21-21-03 on 12/10/2021 - Terminating action.					
Standard ADs	Tail Fin Vibration Damper.	2021-16-13	-	-	Complied With
Limitation Note: Not Applicable by P/N. Part not Installed. C/W 10/01/2021 ACTT 5839.5 admt 39-21675.					
Standard ADs	Chafing of Elect Wires	2021-05-04	-	-	Complied With
Limitation Note: C/W 06/18/2018 ACTT 3890.6. C/W by performing action items (e)(1)(i-ii),(2)(i-ii),(5). admt 39-21294.					
Standard ADs	MR Floating Ring	2020-21-21	-	-	Complied With
Limitation Note: N/A by Part Number. P/N 109-0134-29-101(R) Installed at 2400 Hours Service. See log entry dated 5/27/2019. C/W 05/27/209 ACTT 4555.4. admt 39-21294					
Standard ADs	ELT Transmitter Inspection	2017-16-01	-	-	Not Applicable
Limitation Note: Not Applicable. Not Installed on Aircraft.					
Standard ADs	T/R Retension Bolt	2020-15-16	-	-	Complied With
Limitation Note: Complied With by replacement of affected P/N with New P/N 709-0160-47-101. C/W 9/18/2020 ACTT 5219.9 14195 Landings. admt39-21179.					
Standard ADs	Hoist Cable Chafing	2019-09-04	-	-	Complied With
Limitation Note: C/W 02/14/2017 ACTT 3053.4, admt 39-19638. C/W by action items (e)(1)(i-III)and Action Item 2. No Defects noted at this time.					
Standard ADs	Oil Cooler Fan Pulley	2018-16-08	-	-	Not Applicable
Limitation Note: Not Applicable by P/N. Aircraft has P/N 109-0455-01-101 Oil Cooler Fans installed on #1 and #2 Positions. No further action Required.					
Standard ADs	T/R Blade Retention Bolt	2018-07-08	-	-	Superseded
Limitation Note: Superseded by AD 2015-15-16., admt 39-19239.					



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: **N361CR** DATE: **03-25-2023** PAGE NO: **22**

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining
Standard ADs	MRB Tip Cap Disbond	2018-07-02	-	-	-	Complied With
Limitation Note: C/W 12/31/2019 ACTT 4254.5, admt 39-19233. N/A by Serial Number.						
Standard ADs	Swashplate Support	2018-06-51	-	-	-	Not Applicable
Limitation Note: Not Applicable by Part Number. Aircraft was inspected Per Agusta Emergency Service Bulletin EASB 109SP-119 Dated March 7, 2018, and was found that P/N 109-0110-05-101 was not installed on this aircraft. EASB 109SP--119 Complied With on March 07, 2018, ACTT 3726.5, Log Card B2541.						
Standard ADs	Elevator Structure	2017-25-17	-	-	-	Complied With
Limitation Note: N/A by Part Number, P/N 109-0200-02-808 Installed at this time. C/W 09/18/2020 ACTT 5219.9, admt 39-19131.						
Standard ADs	Tail Rotor Drive Shaft	2016-18-18	-	-	-	Complied With
Limitation Note: C/W AD2016-18-18 IAW Agusta Service Bulletin BT 109SP-094 Action 1-8. No Defects Noted. C/W 06/07/2019, ACTT 4555.4, admt 39-18649.						
Standard ADs	Tail Rotor Pitch Link	2015-05-52	-	-	-	Complied With
Limitation Note: Complied With 03/05/2015 ACTT 1909.9, admt 39-18136.						
Standard ADs	Rod End Replacement	2015-05-05	-	-	-	Not Applicable
Limitation Note: N/A by Serial Number, admt 39-18115.						
Standard ADs	TDR 94 Mode S	2014-18-01	-	-	-	Not Applicable
Limitation Note: Not Applicable by P/N.						
Standard ADs	Swashplate Support Nuts	2014-11-07	Airframe Hours	-	0 Hours	Complied With
Limitation Note: Complied With 06/18/2014, ACTT 1440.0, admt 39-17857.						
Standard ADs	Rod End Replacement	2014-4-14	-	-	-	Superseded
Limitation Note: Superseded by AD 2015-05-05, dated 4/23/2015.						
Standard ADs	T/R Drive Thomas Couplings	2013-20-51	Untracked	-	0	Complied With
Limitation Note: Complied With 10/08/2013 ACTT 961.4.						
Standard ADs	Hoist Load Slip Check	2013-06-51	-	-	-	Complied With
Limitation Note: Complied With 03-26/2013 ACTT 605.4. Previously complied with. See log book entry. admt 39-17486.						
Standard ADs	PT Disk Reidentification	ENGINE AD 2013-03-02	-	-	-	Not Applicable
Standard ADs	Elevator Fatigue Cracks	2011-27-08	Untracked	-	0	Superseded
Limitation Note: Superseded by AD 2017-25-17						
Standard ADs	Halon 1211 Fire Extinguisher Replacement	2010-01-03	-	-	-	Not Applicable
Limitation Note: Not applicable by Part Number.						
Standard ADs	Compressor Turbine Disk Retaining Nut.	ENGINE AD 2009-03-05	-	-	-	Not Applicable



BRIM AVIATION
 P O BOX 3009
 ASHLAND, OREGON 97520
 445 DEAD INDIAN MEMORIAL RD
 ASHLAND, OREGON 97520

PH: 541-482-1008
 EMAIL: INFO@BRIMAVIATION.COM
 WWW.BRIMAVIATION.COM

Maintenance Tracking Report

AIRCRAFT REGISTRATION: N361CR DATE: 03-25-2023 PAGE NO: 23

Maintenance Required		Reference	Period	Last Done	Next Due	Remaining
Standard ADs	TDR 94 Mode S.	2002-06-06	0	-	-	Not Applicable

Limitation Note: Not Applicable per Section III.