

- Cont. From Previous Page -

Page No. \_\_\_\_\_

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED - SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTAL brought forward from previous page			
4-3-19	5889.4	3832.4	AD 15-19-07 External Fuel Injector Lines c/w Visual Inspect next due after any maintenance on engine done. OR EVERY 110 hrs. FAR 91.207 ELT c/w (d) (1-4) Next due +100 hrs / +12 mths ELT Battery Pack Good till March 2021.
Date <u>4-3-19</u> total time <u>5889.4</u>		Date <u>4/3/2019</u> <u>5889.4</u>	
I certify this <u>Aircraft</u> has been inspected in accordance with a <u>100 hr.</u> inspection and was determined to be in airworthy condition.		I certify this <u>Aircraft</u> has been inspected in accordance with an <u>Annual</u> inspection and found to be in airworthy condition	
Signature <u>[Signature]</u> ASP No. <u>446428169</u>		Signature <u>[Signature]</u> A. 1221137	

SUB-TOTAL this page

TOTAL—Carry forward to next page

