

N421 MY
RIGHT.



The Standard

PROPELLER LOG

ASA-SP-L

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>1996</u>	Total Time in Service	Description <u>Complete S/H at A257.25 A/F hrs. 99691</u>
Date: <u>9 Feb</u>		<u>Now Zero Time at 2061.20 A/F hrs.</u>
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: <u>2005</u>	Total Time in Service	Description
Date: <u>9/6</u>	<u>516:05</u>	<u>100 HRS INSPECTION CARRIED OUT. DETAILS OF WORK CARRIED OUT</u>
Next Inspection Due:	Time Since Overhaul	<u>@ SKY ENGINEERING LTD (UK) IS HELD UNDER FILE REF SELO264.</u>
	<u>119:10</u>	Mech. Cert. # or Repair Station # <u>A & P 2590424 IA.</u>

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Date: 15-Apr-06 Tach: 4833.5 TSOH: 180.3 Total Time: Unknown

F.A.S.T Aviation Inc.

4015 N. Santa Anita Ave. El Monte, CA 91731

(626)575.3278



I certify this PROPELLER has been inspected IAW 100hr. Inspection procedures and has been determined to be in airworthy condition. Dressed several small nicks in blades. Serviced unfeathering accumulator IAW Cessna 421B Service Manual.

END

Make: McCauley Model: 3AF34C.92/90 SN: 900328 Brandon Weil A&P 2837076 for FAST Aviation

Date: PROP MODEL (R): 3AF34C92
Next Ins Due: PROP S/N (R): 900328
REG. NO: 421MY
WORK ORDER: 17079-09-2006



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 10/6/2006
A/C TSN: 4872.5
PROP TT (R): 2811.3
TSPOH (R): 615.25
HOBBS: 4845.5

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.... Blended several large nicks from leading edges of right propeller blades and painted aft faces flat black.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 10/6/2006

SIGNED:

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 17079-09-2006

Printed by EBis 3 (datcomedia.com)



Year

Date

Next

Due:

Year

Date

Next

Due:

PROP MODEL (R):
3AF34C92
PROP S/N (R): 900328
REG. NO: 421MY
WORK ORDER:
17931-05-2007

**Howard Aviation, Inc.**

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 8/31/2007
A/C TSN: 4993 2
PROP TT (R): 2932
TSPOH (R): 735.95
HOBBS: 4966 2

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 8/31/2007

SIGNED:

Work Order: 17931-05-2007

Robin Howard
Certified Repair Station No. TO3R874L

Printed by EBis 3 (datcomedia.com)

Overhaul**Mech. Cert. # or Repair Station #****Total Time
in Service****Description****Time Since
Overhaul****Mech. Cert. # or Repair Station #**

HARTZELL

N421MY-Right

PROPELLER OWNER'S MANUAL



HARTZELL PROPELLER INC

INSPECTION

Item Number: C3D00050

Date: 7/16/2008

Work Order #: M780950

Model Number											
PHC-C3YD-2UF/FC9587DB-7											
Ass'y Ser No. MJ38B		Hydr Unit No. NA		Bulkhead No. NA		Valve No. NA					
Blade 1: K76911		Blade 2: K76914		Blade 3: K76910		Blade 4:		Blade 5:		Blade 6:	
Clamp 1:		Clamp 2:		Clamp 3:		Clamp 4:		Clamp 5:			
Reverse NA	Start Lock NA	Low Pitch 15.8	High Pitch 21.0	Feather 86.2	Position	Orient.	Qty:AI	St	Scrw	A-2424-1	Washer
					2	L	2	0	0	0	0
Ref Radius (inches) for angles: 30					3	L	1	0	0	0	1
Comments: Deice Kit: 5E2967-1 Included but not inst.											
Packing Certified By:			Date:								
Inspected By: John Martin											

The approved design data for this propeller incorporates all changes required by applicable Airworthiness Directives.

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-C34D-24 F

PROPELLER S/N MJ38B

LOGBOOK # _____

Date

Propeller
TSN TSOA/C
HrsDescription of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

PROP MODEL (R)
PHC-C3YD-2UF
PROP S/N (R) MJ38B
REG. NO 421MY
WORK ORDER:
19558-09-2008



Howard Aviation, Inc.

Repair Station No. T03R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 10/17/2008
A/C TSN: 5062 1
PROP TT (R): 0
HOBBS: 5035 1

Right Prop Entries

Inspected propeller, spinner and bulkhead I/AW service manual.... Installed new Hartzell PHC-C3YD -2UF propeller I/AW STC SA10361SC.... Removed right propeller #2 blade de-ice boot. Removed adhesive, cleaned with M.E.K. Applied two coats of 1300L to blade and new boot. Installed boot and connected wiring. Ops check ok.

I certify this propeller has been inspected I/AW a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 10/17/2008

SIGNED: 

Robin Howard
Certified Repair Station No. T03R874L

Work Order: 19558-09-2008

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R):
PHC-C3YD-2UF
PROP S/N (R): MJ38B
REG NO: 421MY
WORK ORDER:
20801-10-2009



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 11/20/2009
A/C TSN 5109 8
PROP TT (R): 47.7
HOBBS: 5082 8

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 11/20/2009

SIGNED: 

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 20801-10-2009

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R):
PHC-C3YD-2UF
PROP S/N (R): MJ38B
REG NO: 421MY
WORK ORDER:
21841-12-2010



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 12/22/2010
A/C TSN 5172 5
PROP TT (R): 110 4
HOBBS: 5145 5

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 12/22/2010

SIGNED: 

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 21841-12-2010

Printed by EBis 3 (datcomedia.com)

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		

PROP MODEL (R):
PHC-C3YD-2UF
PROP S/N (R): MJ388
REG NO: 421MY
WORK ORDER:
22811-12-2011



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 1/13/2012
A/C TSN: 5268.5
PROP TT (R): 206.4
HOBBS: 5241.5

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 1/13/2012

SIGNED:

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 22811-12-2011

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R):
PHC-C3YD-2UF
PROP S/N (R): MJ388
REG NO: 421MY
WORK ORDER:
23768-01-2013



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 1/29/2013
A/C TSN: 5310.8
PROP TT (R): 248.7
HOBBS: 5248.8

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 1/29/2013

SIGNED:

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 23768-01-2013

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R):
PHC-C3YD-2UF
PROP S/N (R): MJ38B
REG. NO. 421MY
WORK ORDER:
24820-02-2014



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 2/14/2014
A/C TSN: 5375.7
PROP TT (R): 313.6
HOBBS: 5.8

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 2/14/2014

SIGNED:

Work Order: 24820-02-2014

Robin Howard
Certified Repair Station No. TO3R874L

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R):
PHC-C3YD-2UF
PROP S/N (R): MJ38B
REG. NO. 421MY
WORK ORDER:
25791-02-2015



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 3/19/2015
A/C TSN: 5429.3
PROP TT (R): 367.2
HOBBS: 59.4

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 3/19/2015

SIGNED:

Work Order: 25791-02-2015

Robin Howard
Certified Repair Station No. TO3R874L

Printed by EBis 3 (datcomedia.com)

Date

T:

PROP MODEL (R):
PHC-C3YD-2UF
PROP S/N (R): MJ38B
REG. NO. 421MY
WORK ORDER:
26699-03-2016

**Howard Aviation, Inc.**

Repair Station No. T03R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 4/1/2016
A/C TSN: 5489.5
PROP TT (R): 427.4
HOBBS: 119.6

S,
tions.**Right Prop Entries**

Inspected propeller, spinner and bulkhead I/A/W service manual...Profiled leading edge of prop and touch up painted aft facing side.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 4/1/2016

SIGNED:

Work Order: 26699-03-2016

Robin Howard
Certified Repair Station No. T03R874L

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R):
PHC-C3YD-2UF
PROP S/N (R): MJ38B
REG. NO. 421MY
WORK ORDER:
27630-04-2017

**Howard Aviation, Inc.**

Repair Station No. T03R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 5/10/2017
A/C TSN: 5541.4
PROP TT (R): 479.3
HOBBS: 171.5

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 5/10/2017

SIGNED:

Work Order: 27630-04-2017

Robin Howard
Certified Repair Station No. T03R874L

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R):
PHC-C3YD-2UF
PROP S/N (R): MJ38B
REG NO: 421MY
WORK ORDER:
28247-05-2018



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 5/29/2018
A/C TSN: 5588.6
PROP TT (R): 526.5
HOBS: 218.7

Right Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 5/29/2018

SIGNED:

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 28247-05-2018

Printed by EBis 3 (datcomedia.com)



2650 W Shamrell Blvd
Flagstaff Pulliam Airport
Flagstaff, AZ 86001
928.779.9585 Phone
928.779.9586 Fax

N421MY

Hobbs: 261.2

SMOH: 569.0

Right Propeller

TTAF: 5631.1

WO-354

June 19, 2019

Completed annual inspection in accordance with Cessna 421 series manual.

→ Removed spinner, inspected hub, blades, and bulkhead.

AD's

→ AD's checked through cycle 2019-12.

I certify this propeller has been inspected in accordance with FAR 43 appendix D and is approved for return to service.

Rory T. Goforth 2736122 IA

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Date	Propeller		A/C Hrs
	TSN	TSO	



2650 W Shamrell Blvd
Flagstaff Pulliam Airport
Flagstaff, AZ 86001
928.779.9585 Phone
928.779.9586 Fax

N421MY

RH PR / MJ38B

Hobbs: 297.2

TTAF: 5667.1

SMOH: 605

WO-658

August 13, 2020

Completed annual inspection in accordance with Cessna 421 series manual.

→ Removed spinner, inspected hub, blades, and bulkhead.

AD's

→ AD's checked through cycle 2020-16.

I certify this propeller has been inspected in accordance with CFR 43 appendix D and is approved for return to service.

Randall T Hamilton 2740756 IA