

N 421 MY
LEFT

 The Standard
PROPELLER LOG

ASA-SP-L

798941.

Propeller Record General InformationPropeller Manufacturer MCCAULEYModel BAF 31C 92 APR.

Hub Series # _____

Blade #

590 LF-0

Date of Manufacture

1977.

Make/Model

Aircraft Installed On:

CESSNA 421B.

Serial #

123 0356(N421MY)LEFT.

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>1996</u>	Total Time in Service	Description <u>COMPLETE O/H AT 4257.25 AFHRS 9-28-96</u>
Date: <u>9 FEB</u>		<u>NOW ZERO TIME AT 2061.20 AFHRS.</u>
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: <u>2005</u>	Total Time in Service	Description
Date: <u>9/6</u>	<u>516:05</u>	<u>100 HRS INSPECTION CARRIED OUT. Details of work held</u>
Next Inspection Due:	Time Since Overhaul	<u>@ SKY Engineering Ltd. (UK) under file Ref SEL 0264.</u>
	<u>119:10</u>	Mech. Cert. # or Repair Station # <u>A&P 2590424 IA.</u>

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Date: 15-Apr-06 Tach: 4833.5 TSOH: 180.3 Total Time: Unknown

F.A.S.T. Aviation Inc.

4015 N. Santa Anita Ave. El Monte, CA 91731

(626)575.3278



I certify this PROPELLER has been inspected IAW 100hr. Inspection procedures and has been determined to be in airworthy condition. Dressed several small nicks in blades. Serviced unfeathering accumulator IAW Cessna 421B Service Manual.

END

Make: McCauley Model: 3AF34C.92/90 SN: 798941 Brandon Weil A&P 2837076 for FAST Aviation

Year: Description

Date:

PROP MODEL (L):

3AF34C92

Next Insp:

PROP S/N (L): 798941

Due:

REG. NO: 421MY

WORK ORDER

17079-09-2006



Howard Aviation, Inc.

Repair Station No. TO3R874L

1401 Fairplex Drive

La Verne, CA 91750

Phone: 909-593-2596

DATE: 10/6/2006

A/C TSN: 4872 5

PROP TT (L): 2811 3

TSPCH (L): 615 25

HOBBS: 4845 5

Left Prop Entries

Inspected propeller, spinner and bulkhead IAW service manual.... Blended several large nicks from leading edges of left propeller blades and painted aft faces flat black.

Date:

I certify this propeller has been inspected IAW a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

Next Insp:

Due:

DATE: 10/6/2006

SIGNED:

Work Order: 17079-09-2006

Robin Howard

Certified Repair Station No. TO3R874L

Printed by EBIS 3 (datcomedia.com)

☐ HUB

PROP MODEL (L):
3AF34C92
PROP S/N (L): 798941
REG NO 421MY
WORK ORDER
17931-05-2007

**Howard Aviation, Inc.**

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 8/31/2007
A/C TSN: 4993 2
PROP TT (L): 2932
TSPCH (L): 735 95
HOBBS: 4966 2

Year: _____

Date: _____

Next Insp
Due: _____**Left Prop Entries**

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

Year: _____

Date: _____

Next Insp
Due: _____

DATE: 8/31/2007

SIGNED: _____

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 17931-05-2007

Printed by EBis 3 (datcomedia.com)

Overhaul

Mech. Cert. # or Repair Station # _____

Year: _____

Date: _____

Next Inspection
Due: _____Total Time
in ServiceTime Since
Overhaul

Description

Mech. Cert. # or Repair Station # _____

HARTZELL

N421MY-Left

PROPELLER OWNER'S MANUAL



HARTZELL PROPELLER INC

Item Number: C3D00050

Date: 7/16/2008

INSPECTION

Work Order #: M780950

Model Number PHC-C3YD-2UF/FC9587DB-7									
Ass'y Ser No. MJ37B		Hydr Unit No. NA		Bulkhead No. NA		Valve No. NA			
Blade 1: K76912		Blade 2: K76913		Blade 3: K76915		Blade 4:		Blade 5:	
Blade 6:		Clamp 1:		Clamp 2:		Clamp 3:		Clamp 4:	
Clamp 5:									
Reverse NA	Start Lock NA	Low Pitch 15.8	High Pitch 21.0	Feather 86.2	Position	Orient.	Qty:AI	St	Scrw
					A-2424-1	Washer			
Ref Radius (inches) for angles: 30					1	L	0	0	0
					2	L	0	0	0
Comments: Deice Kit: 5E2967-1 Included but not inst.									
Packing Certified By:					Date:				
Inspected By: John Martin									

The approved design data for this propeller incorporates all changes required by applicable Airworthiness Directives.

Name _____
 Company _____
 Address _____
 City _____
 State _____
 Zip _____
 Telephone _____
 E-mail _____
 Propeller _____
 Blade _____
 Airframe _____
 Registration _____
 Date _____
 Is this _____

IMPORTANT
 Please use call
 Unreadable o
 Hartzell Prop

Y U MUS
 to receive up
 information,

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-C34D-24F

PROPELLER S/N MJ37B

LOGBOOK # _____

Date

Propeller
TSN TSOA/C
HrsDescription of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.PROP MODEL (L)
PHC-C3YD-2UF
PROP S/N (L) MU37B
REG NO 421MY
WORK ORDER
19558-09-2008

Howard Aviation, Inc.

Repair Station No TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596DATE: 10/17/2008
A/C TSN 5062 1
PROP TT (L) 0
HOBBS 5035.1

Left Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.... Installed new Hartzell PHC-C3YD -2UF propeller I/A/W STC
SA10361SC.I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was
determined to be in an airworthy condition

DATE: 10/17/2008

SIGNED:

Robin Howard
Certified Repair Station No TO3R874L

Work Order: 19558-09-2008

Printed by EBis 3 (datcomedia.com)

PROP MODEL (L):
PHC-C3YD-2UF
PROP S/N (L): MJ37B
REG NO. 421MY
WORK ORDER:
20801-10-2009



Howard Aviation, Inc.

Repair Station No. T03R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 11/20/2009
A/C TSN 5109 8
PROP TT (L): 47.7
HOBBS: 5082 8

Left Prop Entries

Inspected propeller, spinner and bulkhead I/AW service manual.

I certify this propeller has been inspected I/AW a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 11/20/2009

SIGNED:

Work Order: 20801-10-2009

Robin Howard
Certified Repair Station No. T03R874L

Printed by EBis 3 (datcomedia.com)

PROP MODEL (L):
PHC-C3YD-2UF
PROP S/N (L): MJ37B
REG NO. 421MY
WORK ORDER:
21841-12-2010



Howard Aviation, Inc.

Repair Station No. T03R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 12/22/2010
A/C TSN 5172.5
PROP TT (L): 110.4
HOBBS: 5145.5

Left Prop Entries

Inspected propeller, spinner and bulkhead I/AW service manual.

I certify this propeller has been inspected I/AW a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 12/22/2010

SIGNED:

Work Order: 21841-12-2010

Robin Howard
Certified Repair Station No. T03R874L

Printed by EBis 3 (datcomedia.com)

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		

PROP MODEL (L)
PHC-C3YD-2UF
PROP S/N (L) MJ37B
REG NO 421MY
WORK ORDER:
22811-12-2011



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 1/13/2012
A/C TSN: 5268 5
PROP TT (L): 206 4
HOBBS: 5241 5

Left Prop Entries

Inspected propeller, spinner and bulkhead I/AW service manual.

I certify this propeller has been inspected I/AW a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 1/13/2012

SIGNED:

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 22811-12-2011

Printed by EBis 3 (datcomedia.com)

PROP MODEL (L):
PHC-C3YD-2UF
PROP S/N (L) MJ37B
REG. NO. 421MY
WORK ORDER:
23768-01-2013



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 1/29/2013
A/C TSN: 5310 8
PROP TT (L): 248.7
HOBBS: 5248.8

Left Prop Entries

Inspected propeller, spinner and bulkhead I/AW service manual.

I certify this propeller has been inspected I/AW a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 1/29/2013

SIGNED:

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 23768-01-2013

Printed by EBis 3 (datcomedia.com)

PROP MODEL (L):
PHC-C3YD-2UF
PROP S/N (L) MJ37B
REG. NO. 421MY
WORK ORDER:
24820-02-2014



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 2/14/2014
A/C TSN: 5375.7
PROP TT (L): 313.6
HOBBS: 5.8

Left Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 2/14/2014

SIGNED:

A handwritten signature in black ink, appearing to read 'Robin Howard'.

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 24820-02-2014

Printed by EBis 3 (datcomedia.com)

PROP MODEL (L):
PHC-C3YD-2UF
PROP S/N (L) MJ37B
REG. NO. 421MY
WORK ORDER:
25791-02-2015



Howard Aviation, Inc.

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 3/19/2015
A/C TSN: 5429.3
PROP TT (L): 367.2
HOBBS: 59.4

Left Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 3/19/2015

SIGNED:

A handwritten signature in black ink, appearing to read 'Robin Howard'.

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 25791-02-2015

Printed by EBis 3 (datcomedia.com)

Date

Pi
TSN

PROP MODEL (L):
PHC-C3YD-2UF
PROP S/N (L): MJ37B
REG. NO: 421MY
WORK ORDER:
26699-03-2016

**Howard Aviation, Inc.**

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 4/1/2016
A/C TSN: 5489 5
PROP TT (L): 427.4
HOBBS: 119.6

TS.

Left Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 4/1/2016

SIGNED:

Work Order: 26699-03-2016

Robin Howard
Certified Repair Station No. TO3R874L

Printed by EBis 3 (datcomedia.com)

PROP MODEL (L):
PHC-C3YD-2UF
PROP S/N (L): MJ37B
REG. NO: 421MY
WORK ORDER:
27630-04-2017

**Howard Aviation, Inc.**

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 5/10/2017
A/C TSN: 5541.4
PROP TT (L): 479.3
HOBBS: 171.5

Left Prop Entries

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 5/10/2017

SIGNED:

Work Order: 27630-04-2017

Robin Howard
Certified Repair Station No. TO3R874L

Printed by EBis 3 (datcomedia.com)

PROP MODEL (L)
PHC-C3YD-2UF
PROP S/N (L) MJ37B
REG NO 421MY
WORK ORDER:
28247-05-2018



Howard Aviation, Inc.

Repair Station No. T03R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone 909-593-2596


DATE: 5/29/2018
A/C TSN: 5588.6
PROP TT (L): 528.5
HOBBS: 218.7

Left Prop Entries

Inspected propeller, spinner and bulkhead VAW service manual.

I certify this propeller has been inspected VAW a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 5/29/2018

SIGNED: 

Robin Howard
Certified Repair Station No. T03R874L

Work Order: 28247-05-2018

Printed by EBis 3 (datcomedia.com)



2650 W Shamrell Blvd
Flagstaff Pulliam Airport
Flagstaff, AZ 86001
928.779.9585 Phone
928.779.9586 Fax

N421MY

Hobbs: 261.2

SMOH: 569.0

Left Propeller

TTAF: 5631.1

WO-354

June 19, 2019


Completed annual inspection in accordance with Cessna 421 series manual.

→ Removed spinner, inspected hub, blades, and bulkhead.

AD's

→ AD's checked through cycle 2019-12.

I certify this propeller has been inspected in accordance with FAR 43 appendix D and is approved for return to service.

Rory T. Goforth 2736122 IA 

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	-------------------------	------------	---



2650 W Shamrell Blvd
Flagstaff Pulliam Airport
Flagstaff, AZ 86001
928.779.9585 Phone
928.779.9586 Fax

N421MY

LH PR / MJ37B

Hobbs: 297.2

TTAF: 5667.1

SMOH: 605

WO-658

August 13, 2020

Completed annual inspection in accordance with Cessna 421 series manual.

→ Removed spinner, inspected hub, blades, and bulkhead.

AD's

→ AD's checked through cycle 2020-16.

I certify this propeller has been inspected in accordance with CFR 43 appendix D and is approved for return to service.

Randall T Hamilton 2740756 IA