

**HORTON AVIATION LLC.**



**LEFT**

**PROPELLER  
MAINTENANCE  
RECORDS**



# PROPELLER MAINTENANCE RECORDS

(Including transponder biennial checks)

Log No. \_\_\_\_\_

Aircraft Registration No. N4542T

Propeller Manufacturer Hartzell

Hub Model \_\_\_\_\_

Blade Design No. \_\_\_\_\_

Hub Serial No. \_\_\_\_\_

Blade Serial No.s \_\_\_\_\_

1. \_\_\_\_\_

2. \_\_\_\_\_

3. \_\_\_\_\_

4. \_\_\_\_\_

Pitch Range:

High \_\_\_\_\_ Low \_\_\_\_\_

Feather \_\_\_\_\_ Reverse \_\_\_\_\_

Governor Manufacturer \_\_\_\_\_

Model No. \_\_\_\_\_

Serial No. \_\_\_\_\_

Date installed on aircraft \_\_\_\_\_

Time Between Overhauls (TBO) \_\_\_\_\_ Hours \_\_\_\_\_

If used on multi engine aircraft:

☐ Right

☐ Left

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 09-151 DATE 08/15/09 HOBBS  
111.0 TACH 3007.52 SMOH 451.88

LEFT PROPELLER, HC-C2YK-2CGUF/FC7666A, S/N AU6571E, H02214, H02221  
AD 2008-13-28 AND AD 2006-18-15, EDDY CURRENT INSPECTION COMPLIED WITH. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 11-038 DATE 2/12/2011 HOBBS  
176.8 LEFT TACH: 3053.31 SMOH: 497.87 LEFT PROPELLER, HC-C2YK-2CGUF/FC7666A, S/N AU6571E, H02214, H02221

AD 2009-22-03, EDDY CURRENT INSPECTION COMPLIED WITH. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 12-067 DATE 2/27/2012 HOBBS  
214.3 LEFT TACH: 3081.54 SMOH: 526.1 LEFT PROPELLER, HC-C2YK-2CGUF/FC7666A, S/N AU6571E, H02214, H02221

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

MAY 2013	N#	N4542T Piper PA34-200T, S/N 34-7250128
	HOBBS	343.3
	Left propeller	HC-C2YK-2CGUF/FC7666A S/N AU6571E
	AD 2008-13-28 AND AD 2006-18-15	Eddy current inspection complied with. I certify that the propeller has been inspected in accordance with an annual inspection and determined to be in airworthy condition.
	J. Lamburn	A+P 3363040
	SUB TOTALS	this page
	TOTALS-	carry forward

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128  
W.O.# 13-121 DATE 5/16/2013 HOBBS 342.9 LEFT TACH:  
3116.23 SMOH: 554.7 LEFT PROPELLER, HC-C2YK-  
2CGUF/FC7666A, S/N AU6571E, H02214, H02221

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*Chris*

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128  
W.O.# 17-059 DATE 3/17/2017 HOBBS 400.1 LEFT TACH: 3161.22  
SMOH: 599.69 LEFT PROPELLER, HC-C2YK-2CGUF/FC7666A,  
S/N AU6571E, H02214, H02221

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*Chris*

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128  
W.O.# 18-148 DATE 6/1/2018 HOBBS 428.4 LEFT TACH: 3185.3  
SMOH: 623.77 LEFT PROPELLER, HC-C2YK-2CGUF/FC7666A,  
S/N AU6571E, H02214, H02221

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*Chris*

DESCRIPTION OF WORK PERFORMED \_\_\_\_\_  
SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK \_\_\_\_\_

forward from previous page

SUB TOTALS this page

TOTALS- carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page

**HORTON AVIATION SERVICES LLC**  
**2732 PERIMETER ROAD, SUITE 101**  
**NORTH LAS VEGAS, NEVADA 89032**  
**REPAIR STATION # YHSR284L**

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 07-231 DATE 08/03/08 HOBBS 2378.4

LEFT PROPELLER, HC-C2YK-2CGUF/FC7666A, S/N AU6571E, H02214, H02221  
 I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. DYNAMIC BALANCE OF PROPELLER COMPLIED WITH AD 2006-18-15 AND 2008-13-28 REFERENCE AD COMPLIANCE LOG THIS DATE.

*[Signature]*

**HORTON AVIATION SERVICES LLC**  
**2732 PERIMETER ROAD, SUITE 101**  
**NORTH LAS VEGAS, NEVADA 89032**  
**REPAIR STATION # YHSR284L**

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 16-008 DATE 2/19/2016 HOBBS 347.9 LEFT TACH: 3117.89 SMOH: 356.36 LEFT PROPELLER, HC-C2YK-2CGUF/FC7666A, S/N AU6571E, H02214, H02221

certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*[Signature]*

**HORTON AVIATION SERVICES LLC 2732 PERIMETER RD 101 N LAS VEGAS, NV 89032 RS# YHSR284L N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 20-127 DATE 0/22/2020 HOBBS 518.2 LEFT TACH: 3257.83 SMOH: 696.3 LEFT PROPELLER, HC-C2YK-2CGUF/FC7666A, S/N AU6571E, H02214, H02221 NDT INSPECTION C/W BY NEXTANT AEROSPACE WO# CAS-N12573 I certify that this propeller has been inspected as required by FAR 91.409(a), and IAW FAR 43 appendix D, an annual/100 inspection and found to be in an airworthy condition. The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.**

*[Signature]*

**HORTON AVIATION SERVICES LLC 2732 PERIMETER RD 101 N LAS VEGAS, NV 89032 REPAIR STATION # YHSR284L N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 19-190 DATE 9/9/2019 HOBBS 477.3 LEFT TACH: 3228.16 SMOH: 666.63 LEFT PROPELLER, HC-C2YK-2CGUF/FC7666A, S/N AU6571E, H02214, H02221 NDT INSPECTION C/W BY NEXTANT AEROSPACE WO# CAS-N12573 I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.**

*[Signature]*  
 3378156114

SUB TOTALS this page

TOTALS- carry forward to next page



## AD NOTES COMPLIANCE RE

Engine - Textron Lycoming - LIO-360-C1E6  
Magnetos - Bendix-S-1200

S/N: L-230-67A Western Skyways, Inc.  
S/N: F02DA016R BL-349305-1  
S/N: F02DA221R BL-349365-3  
S/N: 17357 2524590-8  
S/N: AA14155 R00253-501  
S/N: C031676 MZ4222

Bendix-Fuel injectors

Fuel Pump

Starter - Electrosystems

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method
66-20-04	Oil filter adaptor gasket	7/02/2002 4897.3	N/A by engine serial nu
71-05-02 R4	Crankshaft main bearings	7/02/2002 4897.3	Engine overhauled.
71-11-02	Hydraulic tappet plunger	7/02/2002 4897.3	N/A installed 78290 plu
73-07-04	Bendix Magnetos		Superseded by 94-01-C
73-10-02	Bendix fuel injection systems	7/02/2002 4897.3	Verified compliance wit
73-23-01 R4	Piston pin failures	7/02/2002 4897.3	N/A by installation of pi
74-26-09	Bendix magnetos	7/02/2002 4897.3	Verified compliance wit
75-08-09 R3	Oil pump	7/02/2002 4897.3	Complied with Lycomin
75-09-15	Fuel flow divider gasket	7/02/2002 4897.3	Complied with at overh per Lycoming SB 382.
78-09-07 R3	Bendix magnetos		Superseded by 96-12-f
78-23-10	Center body bellows seal assembly	7/02/2002 4897.3	N/A by parts list numb
79-04-05	Fuel diaphragm	7/02/2002 4897.3	N/A by parts list numb
79-21-08	Bendix fuel injection systems	7/02/2002 4897.3	Verified compliance wit
79-26-03	Bendix fuel injection systems	7/02/2002 4897.3	N/A by parts list numb
81-18-04 R2	Oil pump		Superseded by 96-09-
82-13-01	Bendix magnetos	7/02/2002 4897.3	N/A no green blocks us

**HORTON AVIATION LLC.**



**RIGHT**

**PROPELLER  
MAINTENANCE  
RECORDS**



# PROPELLER MAINTENANCE RECORDS

(When filled in, this record should be retained permanently)

Page No.

Airport Registration No.

10-10-10-10-10

Propeller Registration No.

10-10-10-10-10

Year of Birth

Year of Death

Year of Birth

Year of Death

1

2

3

4

Birth Range

High

Low

Front

Rear

Government Manufacturer

Model No.

Serial No.

Date installed on aircraft

Time Between Overhauls (TBO) Hours

If used on multi engine aircraft:

☒ Right

☐ Left

☐ Front

☐ Rear

(All applicable information must be filled in)



DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTALS brought forward from previous page				

**HORTON AVIATION SERVICES LLC**  
**2732 PERIMETER ROAD, SUITE 101**  
**NORTH LAS VEGAS, NEVADA 89032**  
**REPAIR STATION # YHSR284L**

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 09-151 DATE 08/15/09 HOBBS  
111.0 R/TACH 2998.35 SMOH 448.62

RIGHT PROPELLER, HC-C2YK-2CLGUF/FJC7666A, S/N AU7398E, H05581, H05584  
 AD 2006-18-15 EDDY CURRENT INSPECTION COMPLIED WITH. I certify that this propeller has been  
 inspected in accordance with an annual inspection and was determined to be in airworthy condition.

*[Signature]*

SUB TOTALS this page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED
				SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page

**HORTON AVIATION SERVICES LLC**  
**2732 PERIMETER ROAD, SUITE 101**  
**NORTH LAS VEGAS, NEVADA 89032**  
**REPAIR STATION # YHSR284L**

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 07-231 DATE 08/03/08 HOBBS  
2378.4

RIGHT PROPELLER, HC-C2YK-2CLGUF/FJC7666A, S/N AU7398E, H05581, H05584  
I certify that this propeller has been inspected in accordance with an annual inspection and was  
determined to be in airworthy condition. DYNAMIC BALANCE OF PROPELLER COMPLIED WITH  
AD 2006-18-15 AND 2008-13-28 REFERENCE AD COMPLIANCE LOG THIS DATE.

*Charlie*

**HORTON AVIATION SERVICES LLC**  
**2732 PERIMETER ROAD, SUITE 101**  
**NORTH LAS VEGAS, NEVADA 89032**  
**REPAIR STATION # YHSR284L**

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 11-038 DATE 2/12/2011 HOBBS  
176.8 RIGHT TACH: 3047.26 SMOH: 497.53 RIGHT PROPELLER, HC-C2YK-2CLGUF/FJC7666A, S/N  
AU7398E, H05581, H05584

AD 2008-13-28, AD2009-22-03, EDDY CURRENT INSPECTION COMPLIED WITH. I certify that this  
propeller has been inspected in accordance with an annual inspection and was determined to be in  
airworthy condition.

*Charlie*

7 Feb 2012

ACT 5447.48

Complied with AD 2008-13-28

GDPY Current inspection propeller-

Hub. J. Lamb AIP 3363040

EC-5000

**HORTON AVIATION SERVICES LLC**  
**2732 PERIMETER ROAD, SUITE 101**  
**NORTH LAS VEGAS, NEVADA 89032**  
**REPAIR STATION # YHSR284L**

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 12-067 DATE 2/27/2012 HOBBS  
214.3 RIGHT TACH: 3075.40 SMOH: 525.67 RIGHT PROPELLER, HC-C2YK-2CLGUF/FJC7666A, S/N  
AU7398E, H05581, H05584

I certify that this propeller has been inspected in accordance with an annual  
determined to be in airworthy condition.

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 07-231 DATE 08/03/08 HOBBS  
2378.4

RIGHT PROPELLER, HC-C2YK-2CLGUF/FJC7666A, S/N AU7398E, H05581, H05584  
I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. DYNAMIC BALANCE OF PROPELLER COMPLIED WITH AD 2006-18-15 AND 2008-13-28 REFERENCE AD COMPLIANCE LOG THIS DATE.

*Charlie*

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 11-038 DATE 2/12/2011 HOBBS  
176.8 RIGHT TACH: 3047.26 SMOH: 497.53 RIGHT PROPELLER, HC-C2YK-2CLGUF/FJC7666A, S/N  
AU7398E, H05581, H05584

AD 2008-13-28, AD2009-22-03, EDDY CURRENT INSPECTION COMPLIED WITH. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

*Charlie*

27 Feb 2012

ACTT 5447.48

Complied with AD 2008-13-28

EDDY Current inspection propeller-

Hub. *J. Lamb* AIP 3363040

EC-5000

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128 W.O.# 12-067 DATE 2/27/2012 HOBBS  
214.3 RIGHT TACH: 3075.40 SMOH: 525.67 RIGHT PROPELLER, HC-C2YK-2CLGUF/FJC7666A, S/N  
AU7398E, H05581, H05584

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

*Charlie*

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
13MAY2013				TOTALS brought forward from previous page
				N# N4542T Model PA34-200T S/N 34-7250128
				HOBBS 343.3
				Right Propeller, HC-C2YK-2CLGUF/FJC7666A,
				S/N AU7398E
				I certify that AD 2008-13-28 AND AD 2006-18-15
				Eddy current inspection complied with. I certify
				that the propeller has been inspected in accordance
				with an annual inspection and determined to be
				in airworthy condition. Jambour Att 3363040

**HORTON AVIATION SERVICES LLC**  
 2732 PERIMETER ROAD, SUITE 101  
 NORTH LAS VEGAS, NEVADA 89032  
 REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128  
 W.O. # 13-121 DATE 5/16/2013 HOBBS 342.9 RIGHT TACH:  
 3109.67 SMOH:554.27 RIGHT PROPELLER, HC-C2YK-  
 2CLGUF/FJC7666A, S/N AU7398E, H05581, H05584

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*Chute*

**HORTON AVIATION SERVICES LLC**  
 2732 PERIMETER ROAD, SUITE 101  
 NORTH LAS VEGAS, NEVADA 89032  
 REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128  
 W.O. # 16-008 DATE 2/19/2016 HOBBS 347.9 RIGHT TACH:  
 3111.29 SMOH:555.89 RIGHT PROPELLER, HC-C2YK-  
 2CLGUF/FJC7666A, S/N AU7398E, H05581, H05584

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*Chute*

SU

TO

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128  
W.O.# 17-059 DATE 3/17/2017 HOBBS 400.1 RIGHT TACH:  
3154.19 SMOH:598.79 RIGHT PROPELLER, HC-C2YK-  
2CLGUF/FJC7666A, S/N AU7398E, H05581, H05584

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*[Signature]*

HORTON AVIATION SERVICES LLC  
2732 PERIMETER ROAD, SUITE 101  
NORTH LAS VEGAS, NEVADA 89032  
REPAIR STATION # YHSR284L

N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128  
W.O.# 18-148 DATE 6/1/2018 HOBBS 428.4 RIGHT TACH: 3178.0  
SMOH:622.6 RIGHT PROPELLER, HC-C2YK-2CLGUF/FJC7666A,  
S/N AU7398E, H05581, H05584

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*[Signature]*

HORTON AVIATION SERVICES LLC 2732 PERIMETER RD 101  
N LAS VEGAS, NV 89032 REPAIR STATION # YHSR284L  
N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128  
W.O.# 19-190 DATE 9/09/2019 HOBBS 477.3 RIGHT TACH:  
3220.59 SMOH:665.19 RIGHT PROPELLER, HC-C2YK-  
2CLGUF/FJC7666A, S/N AU7398E, H05581, H05584  
NDT INSPECTION C/W BY NEXTANT AEROSPACE WO# CAS-  
N12573 I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*[Signature]* 33785214

HORTON AVIATION SERVICES LLC 2732 PERIMETER RD 101  
N LAS VEGAS, NV 89032 REPAIR STATION # YHSR284L  
N# N4542T MFG. PIPER MODEL PA34-200T S/N 34-7250128  
W.O.# 20-127 DATE 10/22/2020 HOBBS 477.3 RIGHT TACH:  
3250.03 SMOH:694.63 RIGHT PROPELLER, HC-C2YK-  
2CLGUF/FJC7666A, S/N AU7398E, H05581, H05584  
NDT INSPECTION C/W BY NEXTANT AEROSPACE WO# CAS-  
N12573 I certify that this propeller has been inspected as required by FAR 91.409(a), and IAW FAR 43 appendix D, an annual/100 inspection and found to be in an airworthy condition. The aircraft and/or components above was repaired and inspected in accordance with Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this agency under above work order number.

*[Signature]*


SUB TOTALS this page

TOTALS- carry forward to next page

DESCRIPTION OF WORK  
NATURE & CERTIFICATE NO.

ht forward from previous p