

The day the modules were being set. Notice the large gap between the bottom left module and the foundation wall. This is a good visual indication of how far out of level the foundation wall is. Liscott testified in arbitration that they were aware of problems at this time. Instead of telling us of the problem and unstacking the modules to repair the foundation wall, Liscott simply plowed forward hoping nobody would notice.

