

Furnace intake & exhaust installed under an operating bedroom window. This will allow carbon monoxide to enter the home!

Poorly compacted soil sunk and is putting great amounts of stress on the gas line feeding the home

Electrical feed installed with non-code conduit

