

This image is an interior shot showing just how far apart and out of square the modules are from one another. Instead of properly solving this issue, Liscott just had their drywall crew cover this up. This image also demonstrates why the walls running down the centerline of the home are fully 1.5" wider at the bottom than they are at the top.

