

Foundation being backfilled. Notice that the walls are not supported from movement. Also notice the lack of compaction and native soils and large rocks in the fill.







