

Footings for the patio and patio roof being poured. Notice the native soils and large rocks in the fill zone. All of this concrete ended up sinking and breaking away from the house and had to be dug out by crews we hired to fix Liscotts defective work.



