

DATE 19__	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)



BlūSky Avionics, LLC

1000 N Beeline Hwy 311

Payson, AZ 85541

CRS# 8BUR043C

Date: 9-26-25

N# 92680

Hobbs: 2021.9 T: 7819.1 WO# 2845

I certify that the altimeter and static system have been inspected as required by FAR 91.411. The altimeter and static system were tested to 20,000 feet and found to meet the specs of FAR 43

Appendix E. The transponder was inspected in accordance with FAR 91.413 and found to conform to FAR 43 Appendix F. *cas#*

Ronald E. Opfergelt

Red ^{ca8#} 86020430