

EPDM/Weatherproof Membrane Report 03.10.22

Created: 10-07-2022
Creator: Peter Mazur (@PMA)
Status:
Dates: 08-30-2022 - 10-07-2022

Recipients

piotr@facadestc.co.uk

Description

Cavity Inspection for EPDM/Membrane Lev 0.

Support Documents:
Drawings A-21_01 , A21_50
Architects Guidance, Scope of Work
BS 8000-4 and Code of Practice for Weatherproofing
Subcontractors own Design drawings and details
CWCT Specs

Specifications and Manual:
FixFast(Cortex)
ARBO

Author: P.Mazur

Hashtags

#langdaleassociates




Table of contents


#	Description	Category	Plan	Assignee	Status	Page
38	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	5
39	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	5
40	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	6
41	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	6
42	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	7
43	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	7
44	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	8
48	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	8
49	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	9
50	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	9
51	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	10
55	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	11
56	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	11

58	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	12
59	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	13
60	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	14
61	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	15
62	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	16
63	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	16
64	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	17
65	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	18
66	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	19
67	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	20
69	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	22
70	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	22
71	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	24
72	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	25

73	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	26
74	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	27
75	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	28
76	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	28
77	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	29
78	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	29
79	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	30
80	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	30
81	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	31
82	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	31
83	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	32
84	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	33
85	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	33
86	EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.	Snagging	EPDM Blockwork _ Gabion Wall Plan	@PMA	EPDM/Weatherproof Membrane - 10-03- 2022	34

● **#38 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)
Peter Mazur



28 Sep 11:16 AM

● **#39 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur




28 Sep 11:18 AM

● **#40 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022

Task messages (time in BST)
Peter Mazur





28 Sep 11:20 AM

● **#41 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022


Task messages (time in BST)
Peter Mazur



28 Sep 11:23 AM

● **#42 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)
Peter Mazur



28 Sep 11:26 AM

● **#43 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)
Peter Mazur



28 Sep 11:27 AM

● **#44 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)
Peter Mazur



28 Sep 11:28 AM

● **#48 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur




28 Sep 11:45 AM



● **#49 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)
Peter Mazur

28 Sep 11:49 AM



● **#50 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)



● **#51 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur

28 Sep 11:59 AM




Peter Mazur

28 Sep 11:59 AM



● **#55 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur

28 Sep 12:53 PM




Peter Mazur

28 Sep 12:53 PM



● **#56 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)

Peter Mazur

28 Sep 01:45 PM



Peter Mazur

28 Sep 01:46 PM




Peter Mazur

28 Sep 01:46 PM



● **#58 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)



● **#59 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork_ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)





● **#60 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)





● **#61 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur

28 Sep 02:09 PM




Peter Mazur

28 Sep 02:09 PM



● **#62 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur



28 Sep 02:19 PM


Peter Mazur



28 Sep 02:19 PM

● **#63 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-28-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)



● **#64 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)





● **#65 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur

29 Sep 08:40 AM



Peter Mazur

29 Sep 08:40 AM




● **#66 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging

Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External

Tags: #langdaleassociates

Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)

Peter Mazur



29 Sep 08:44 AM

Peter Mazur



29 Sep 08:44 AM


Peter Mazur



29 Sep 08:44 AM

● **#67 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork_ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur

29 Sep 08:49 AM



Peter Mazur

29 Sep 08:49 AM



Peter Mazur

29 Sep 08:49 AM



Peter Mazur

29 Sep 08:49 AM



Peter Mazur

29 Sep 08:49 AM



Peter Mazur

29 Sep 08:50 AM




Peter Mazur

29 Sep 08:51 AM



● **#69 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur



29 Sep 09:12 AM


Peter Mazur



29 Sep 09:12 AM

● **#70 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)

Peter Mazur

29 Sep 09:17 AM




Peter Mazur

29 Sep 09:17 AM



Peter Mazur

29 Sep 09:18 AM



Peter Mazur


29 Sep 09:18 AM





● **#71 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)



Peter Mazur

29 Sep 09:24 AM



Peter Mazur

29 Sep 09:24 AM




Peter Mazur

29 Sep 09:25 AM



● **#72 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)



● **#73 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)





● **#74 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur

29 Sep 11:00 AM




Peter Mazur

29 Sep 11:01 AM



● **#75 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)
Peter Mazur



29 Sep 11:11 AM

● **#76 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)
Peter Mazur



29 Sep 11:17 AM

● **#77 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)


Peter Mazur



29 Sep 11:28 AM

● **#78 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)


Peter Mazur



29 Sep 01:45 PM

● **#79 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)
Peter Mazur



29 Sep 01:47 PM

● **#80 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)
Peter Mazur



29 Sep 02:01 PM

● **#81 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur

29 Sep 02:15 PM




Peter Mazur

29 Sep 02:15 PM



● **#82 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)



● **#83 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022




Task messages (time in BST)



● **#84 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
 Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
 Tags: #langdaleassociates
 Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)


Peter Mazur



29 Sep 02:37 PM

● **#85 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
 Plan: EPDM Blockwork _ Gabion Wall Plan | Location: Lev 0 External
 Tags: #langdaleassociates
 Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)


Peter Mazur



29 Sep 02:54 PM

● **#86 - EPDM / Weatherproof barriers poor installed, not as per specs, manual installation guidance and as per drawings.**

EPDM/Weatherproof Membrane | Peter Mazur | Snagging
Plan: EPDM Blockwork_ Gabion Wall Plan | Location: Lev 0 Externall
Tags: #langdaleassociates
Created 09-29-2022 | EPDM/Weatherproof Membrane 10-03-2022



Task messages (time in BST)
Peter Mazur

29 Sep 03:00 PM



Peter Mazur

29 Sep 03:00 PM



Peter Mazur

29 Sep 03:07 PM



