



Date: 02nd July, 2025

To Whom It May Concern

I had visited the existing School Building on GLR No. 126, No. 1, Church Road, Mumbai-Pune Highway, Khadki, Pune - 411003., for All Saints' School. The Existing structure is Ground Floor + 2 above floors & Roof is constructed in fabrication structure (i.e. Ground +3 floor structure).

The structure is Constructed in around year 1982, so the age of structure is around 43 Years.

It is observed on site that the whole structure is in good condition as on same date and is structurally fit.

As per my observation the whole structure is constructed in RCC framed structure and Last roof is constructed in fabrication work.

No damage or no structural cracks are observed on site.

On basis of this I hereby certify that to the best of my knowledge and belief the said structure is **structurally fit for the intended purpose.**

** This certificate is issued on request of Client / Owner / Trust.

** If any structural changes are made after our conclusion/certification, then we are not responsible for that.

** This Certificate is valid for 4 Years only.

** It is suggested to conduct structural stability inspection after 4 years.

Yours truly,

Shankar D. Bade.

Structural Consultant

P. M. C. Lic. No. – 471

Grade- A

