

JSJ & Company, Inc.

Home Inspection Service Since 1996



HOME INSPECTION AGREEMENT

This is an Agreement between you, the undersigned Client, and us, the Inspector, pertaining to our inspection of the Property listed below.

The terms below govern this Agreement.

	2224
1. The inspection fee and address is: \$ Address: Your Address, Coral Springs,	<u>33065</u>
2. We will perform a <u>visual inspection</u> of the home/building and provide you with a written report identifying the defects that we (material. The report is only supplementary to the seller's disclosure.	1) observed and (2) deemed
3. Unless otherwise indicated in writing, we will NOT test for the presence of radon, a harmful gas. Unless otherwise indicated in We will not test for compliance with applicable building codes or for the presence of or for any potential dangers arising from the soil contamination, or other environmental hazards or violations. If any part of the structure you want us to inspect is inaccessible, y are impossible for us to inspect and evaluate. Therefore, the scope of our inspection will NOT include inaccessible areas in their ent is inside walls, underground, or covered with attic insulation cannot be seen. Polybutylene piping was used from 1978 to 1995 an inspector visually looks for Polybutylene but it is not always possible to definitively determine its presence. This report does not dis not present.	e presence of asbestos, lead paint you understand that such structures tirety. Plumbing pipe material that d is known to leak over time. The
4. Our inspection and report are for your use only. You give us permission to discuss our observations with real estate agents interested parties. You will be the sole owner of the report and all rights to it. We are not responsible for use or misinterpretation who rely on it in any way do so at their own risk and release us (including employees and business entities) from any liability whats on your behalf provide the report to a third party who then sues you and/or us, you release us from any liability and agree to pay ou any action naming us. Our inspection and report are in no way a guarantee or warranty, express or implied, regarding the future suitability of the home/building or its components. We disclaim all warranties, express or implied, to the fullest extent allowed by	n by third parties, and third parties soever. If you or any person acting or costs and legal fees in defending re use, operability, habitability or
5. We assume no liability for the cost of repair or replacement of unreported defects, either current or arising in the fut	
limited to liquidated damages in an amount not greater than the fee you paid us. You waive any claim for consequential damages or for the loss of the use of the home/building. You acknowledge that this liquidated damages is not a penalty, but that that actual damages may be difficult or impractical to ascertain; (ii) allocate risk between us; and (iii) enable us to perform the insp	we intend it to: (i) reflect the fac
6. We do not perform engineering, architectural, plumbing, or any other job function requiring an occupational license in the jurisdictif you request a re-inspection, the re-inspection is subject to the terms of this Agreement.	ction where the property is located
7. It is agreed and understood that you will have no cause of action against the Home Inspector(s) after the date and time that the agreed and understood that Home Inspector(s) will not be held liable for any errors and omissions in the entirety of this Home Inspector.	
8. You agree that the exclusive venue for any litigation arising out of this Agreement shall be in the county where we have our print to prove any claim against us, you agree to pay all our legal costs, expenses and attorney's fees incurred in defending that claim. You	
9. If a court declares any provision of this Agreement invalid, the remaining provisions remain in effect. This Agreement represent no terms other than those set forth herein. All prior discussions are merged into this Agreement. No statement or promise by us should writing and signed by one of our authorized officers. Any modification of this Agreement must be in writing and signed by you are officers. This Agreement shall be binding upon and enforceable by the parties and their heirs, executors, administrators, successors any term of this Agreement ambiguous or requiring judicial interpretation, the court shall not construe that term against us by reason in a document is construed against the party drafting it. You had the opportunity to consult qualified counsel before signing this.	hall be binding unless reduced to nd by one of our authorized s and assignees. If a court finds
10. If there is more than one Client, you are signing on behalf of all of them, and you represent that you are authorized to do so.	
BY MAKING PAYMENT FOR THIS SERVICE, BUYER ACKNOWLEDGES THAT THEY HAVE CAREFULLY REAGREE TO IT. THE BUYER FULLY UNDERSTANDS THAT THEIR PAYMENT ACTS AS THEIR WRITTEN SIGN	
Client: Your Name Inspector: Jerome Strano	License #HI4757

JSJ & Company, Inc.

561 665 0201 JSJcompanyinc@gmail.com Date: 6/28/2024 www.JSJcompanyinc.com

HOME INSPECTION REPORT

Inspection Time: 9:30
Description of Home:
Single FamilyX
Town House
Villa
Condo
Duplex
Configuration: 4 Bed, 2 bath, 2 car garage
Home occupied at time of inspection: Yes X No No
Year Built: 1992
Total Square Feet: 2,263
Evident of Renovations: Yes No _ X _ (if "Yes", building permits should be checked)
Date of Last Significant Rainfall: >1 week < 1 week
Comments:




	Home Inspection Report	N	S	U	R	S
1		0	A	N	E	A
Т		T	Т	S	Р	F
E			ı	Α	Α	E
М		Α	S	Т	ı	Т
	<u>GROUNDS</u>	P	F	I	R	Y
		P	A C	S F	N	ı
		ì	T	A	E	S
		C	0	C	E	S
		Α	R	Т	D	U
	Note: This inspection is not a warrantee and/or guarantee. Building codes are not checked in this inspection	В	Υ	0	E	E
	report.	L		R	D	
		Е	~	Υ		
	Walkways		X			
	Driveways		Х			
-	Porch	Х				
	Patio		X			
	Stoops /Steps	X				
	Deck / Balcony	X				
	Fence / Wall		X			
8	Overhanging Trees		X			
9	Landscaping Effecting Foundation		X			
10	Low Spots / Standing Water		X			
11	Storm Water Runoff		X			
12	Hose Bibs		X			
13	Pool	X				

	Home Inspection Report	N	s	U	R	s
1		0	A	N	E	A
Т		T	T	S	P	F
E			ı	Α	Α	E
М		Α	S	T	ı	Т
	EXTERIOR & PLUMBING	Р	F	ı	R	Υ
		P	A	S	N.	.
		L	C T	F A	N E	S
		C	0	Ċ	E	S
		A	R	T	D	Ü
	Note: This inspection is not a warrantee and/or guarantee. Building codes are not checked in this inspection	В	Υ	0	Ε	E
	report.	L		R	D	
	Note: Aluminum windows have a usable life of approximately 20 years, soals will degrade at this point	Ε		Y		
	Note: Aluminum windows have a usable life of approximately 20 years, seals will degrade at this point.					
1	Siding Material & Condition: Concrete _X Wood Vinyl Other		X			
2	Caulking Around Doors / Windows		X			
3	Ground Clearance With Siding	X				
4	Trim	X				
5	Doors		X			
6	Walls		X			
7	Windows / Screens		X			
8	Electrical Receptacles, GFI installed: Yes NoX		X			
9	Lighting		X			
10	Foundation Type: Slab on GradeX Wood Visible: Yes NoX		X			
11	Main Water Supply Shut-Off Valve		X			
12	Evidence of Main Water Supply Leak		Х			
13	Water Supply Piping Material installed CopperX PVC Polybutylene Other		X			
14						

I T E M	Home Inspection Report BATHROOMS	N O T A P P L I C	S A T I S F A C T	U N S A T I S F A C	R E P A I R N E	S A F E T Y I S S
		Α	R	T	D	Ü
	<u>Note</u> : This inspection is not a warrantee and/or guarantee. If the home is occupied at the time of the inspection not all walls may be accessible for inspection.	B L E	Υ	O R Y	E D	E
1	Sinks / Cabinet				Х	
2	Toilets		X			
3	Bathtubs		X			
4	Showers		X			
5	Evidence of Water leaks		X			
6	Ventilation Fans		X			
7	Electrical Receptacles		Χ			
	Lighting		Χ			
	Water Temperature Adequate (hot)		X			
	Water Pressure Adequate		Χ			
	Drain Piping Size / Material		Χ			
_	Drain Rate Adequate		X			
13	Drain Traps in Place		X			
14	Ceiling		Х			
15	Tile / Caulking / Grout				X	
16	Water Hammering Issue		Х			
17	Walls / Floor				X	

- 1. The right side sink cabinet, in the master bathroom, is cracked at the top section behind the doors.
- 14. The back-splash on the left side of the master bathroom sink needs to be caulked.
- 17. Several floor tiles near the entryway are cracked, no sharp edges are exposed.









I T E M	Home Inspection Report KITCHEN	N O T A P P L I C A B	S A T I S F A C T O R Y	U N S A T I S F A C T O	R E P A I R N E E D E	S A F E T Y I S S U E
	Note: This inspection is not a warrantee and/or guarantee. If the home is occupied at the time of the inspection not all walls may be accessible for inspection.	L E	•	R Y	D	
1	Cabinets		Х			
2	Countertops		Х			
3	Sink		Χ			
	Drain Piping		Χ			
	Drain Rate		Χ			
	Drain Traps in Place		Χ			
	Garbage Disposal		Χ			
	Evidence of Water Leakage		Χ			
	Water Supply Pressure		X		\longmapsto	
	Stove / Range		X		\longmapsto	\vdash
	Range Hood / Vent Refrigerator		Х		$\vdash \vdash \vdash$	
	Dishwasher		X		\vdash	
	Microwave				Х	
15	Lighting		Х			
16	Electrical Receptacles / Switches		Х			
17	Ceiling		Х			
18	Wall		Х			
19	Floor			X		

- 14. The microwave display is faulty; the decimals are both dim and some are over bright.
- 19. The kitchen floor has a small chip in one tile, no sharp edges are exposed.



JSJ & Company, Inc.


Page 7 of 12

	Home Inspection Report	N	S	U	R	S
1		0	Α	N	Ε	Α
Т		Т	Т	S	Р	F
Ε			ı	Α	Α	E
M		Α	S	Т	ı	Т
	INTERIOR ROOMS	Р	F	I	R	Υ
		P .	A	S		.
		L	C T	F A	N E	S
		C	0	C	E	S
		Α	R	T	D	Ü
		В	Υ	0	E	E
	Note: This inspection is not a warrantee and/or guarantee. If the home is occupied at the time of the	L		R	D	
	inspection not all walls may be accessible for inspection.	Ε		Υ		
1	Wall		Х			
2	Ceiling		Χ			
3	Ceiling Fans		Χ			
4	Floor		X			
5	Molding / Trim		Χ			
6	Doors		X			
7	Lighting		Χ			
8	Electrical Receptacles		Χ			
9	Smoke Detectors			Χ		
10	Steps / Stair Rails	Χ				
11	A/C Vents / Grills		Χ			
12	Window Sills		X			

a	The cme	ka datactar	c are very ale	l thoso	should bo	roplaced	every 10 years	
ч.	The smo	ke detector	s are verv oid	i, these s	snoula ne	replaced	every 10 years	

	Home Inspection Report					
١,		N O	S A	U N	R E	S
'		T	T	S	P	A
E		•	i	A	A	E
М		Α	S	Т	1	Т
	GARAGE / LAUNDRY ROOM	P	F	ı	R	Υ
	GARAGE / LACINDINI ROCIVI	Р	Α	S		
		L	C T	F A	N E	S
		C	0	C	E	S
		Α	R	T	D	Ü
		В	Υ	0	Ε	E
	Note: This inspection is not a warrantee and/or guarantee. If the home is occupied at the time of the	L		R	D	
	inspection not all walls may be accessible for inspection.	Ε		Υ		
1	Automatic Opener		Х			
	Garage Door		X			
-	Wash Tub	Х	^			
-	Washer	^	Х			
	Dryer Dryer Venting Preparts		X			
	Dryer Venting Properly Interior Service Door		X			
						
	Lighting		X			-
	Ceiling		Х			\vdash
-	Floor			X		-
	Wall		X			
12	Electrical Receptacles		Х			

10. Two floor tiles in the laundry room are cracked, no sharp edges are exposed.



HEATING & COOLING A S T I T P F I R Y P A S L C F N I I T A E S be accessible for inspection. Building codes are not checked in this inspection report.							
HEATING & COOLING HEATING & COOLING A N E A S T I I T S P F I I A A A E S T I I T I T A E S T I I T I T A E S T I I T I T A E S T I I T I T A E S T I I T I T A E S T I I T I T A E S T I I T I T A E S T I I T I T A E S T I I T I T A E S T I I T I T A E S T I I T I T I T I T I T I T I T I T I		Home Inspection Report				_	
HEATING & COOLING HEATING & COOLING HEATING & COOLING A A S T I I T A A A E A S T I I T T B S P F I I R S S P F I I R S S T I I R S S T I I R S S T I I R S S T I I R S S T I I T A A A E I I T A A A E I I T A A S S T I I T A A A E I I T A A S S T I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I T A A E I I I T A A E I I T A A E I I T A A E I I I T A A E I I I T A A E I I T A A E I I I T A A E I I I T A A E I I I T A A E I I I T A A E I I I T A A E I I I I T A A E I I I I T A A E I I I I I I I I I A A E I I I I I	١.				_		_
HEATING & COOLING A S T I I R P F I I R P A S I I I T A E S I I I T A E S I I I I I T A E S I I I I T A E S I I I I I T A E S I I I I I T A E S I I I I I T A E S I I I I I T A E S I I I I I T A E S I I I I I T A E S I I I I I T A E S I I I I I T A E S I I I I I I T A E S I I I I I I T A E S I I I I I I I I I I I I I I I I I I	1 -		_			_	F
Note: This inspection is not a warrantee and/or guarantee. Due to shallow attic clearance not all areas may be accessible for inspection. Building codes are not checked in this inspection report. Note: Central A/C systems and Water Heater have a typical life expectancy of approximately 15 years. 1 HVAC System Type: Wall mount Central A/C _X System Age: 2015			·	-		A	E
Note: This inspection is not a warrantee and/or guarantee. Due to shallow attic clearance not all areas may be accessible for inspection. Building codes are not checked in this inspection report. Note: Central A/C systems and Water Heater have a typical life expectancy of approximately 15 years. 1 HVAC System Type: Wall mount Central A/C _X System Age: 2015	М	HEATING & COOLING	Α	S	Т	ı	Т
Note: This inspection is not a warrantee and/or guarantee. Due to shallow attic clearance not all areas may be accessible for inspection. Building codes are not checked in this inspection report. Note: Central A/C systems and Water Heater have a typical life expectancy of approximately 15 years. 1 HVAC System Type: Wall mount Central A/C _X System Age: 2015			Ρ	F	ı	R	Υ
Note: This inspection is not a warrantee and/or guarantee. Due to shallow attic clearance not all areas may be accessible for inspection. Building codes are not checked in this inspection report. Note: Central A/C systems and Water Heater have a typical life expectancy of approximately 15 years. 1 HVAC System Type: Wall mount Central A/C _X System Age: 2015			P		_		
Note: This inspection is not a warrantee and/or guarantee. Due to shallow attic clearance not all areas may be accessible for inspection. Building codes are not checked in this inspection report. Note: Central A/C systems and Water Heater have a typical life expectancy of approximately 15 years. 1 HVAC System Type: Wall mount Central A/C _X _ System Age: 2015			L	_	_		ı
be accessible for inspection. Building codes are not checked in this inspection report. Note: Central A/C systems and Water Heater have a typical life expectancy of approximately 15 years. 1 HVAC System Type: Wall mount Central A/C _X System Age: 2015		Note: This inspection is not a warrantee and/or guarantee. Due to shallow attic clearance not all areas may	•	-			S
Note: Central A/C systems and Water Heater have a typical life expectancy of approximately 15 years. 1 HVAC System Type: Wall mount Central A/C _X System Age: 2015				_	_		U
Note: Central A/C systems and Water Heater have a typical life expectancy of approximately 15 years. 1 HVAC System Type: Wall mount Central A/C _X System Age: 2015		be accessible for inspection. Building codes are not checked in this inspection report.					E
1 HVAC System Type: Wall mount Central A/C _X System Age: 2015		Note: Central A/C systems and Water Heater have a typical life expectancy of approximately 15 years	L		R	D	
2 Cooling Ability: 3 HVAC Compressor 4 HVAC Compressed Freon Line Insulation 5 HVAC Compressor Ventilation (clear of bushes etc.) 6 HVAC Air Handler 7 HVAC Air Handler Drain Clear 8 HVAC Ductwork 9 Thermostat 10 Water Heater Relief Valve Venting Properly 11 Water Heater Condition X		<u>note.</u> Central Ay 6 systems and water fleater have a typical me expectancy of approximately 15 years.	Ε		Υ		
2 Cooling Ability: 3 HVAC Compressor 4 HVAC Compressed Freon Line Insulation 5 HVAC Compressor Ventilation (clear of bushes etc.) 6 HVAC Air Handler 7 HVAC Air Handler Drain Clear 8 HVAC Ductwork 9 Thermostat 10 Water Heater Relief Valve Venting Properly 11 Water Heater Condition X							
3 HVAC Compressor 4 HVAC Compressed Freon Line Insulation 5 HVAC Compressor Ventilation (clear of bushes etc.) 6 HVAC Air Handler 7 HVAC Air Handler Drain Clear 8 HVAC Ductwork 9 Thermostat 10 Water Heater Relief Valve Venting Properly 11 Water Heater Condition (if accessible) X (if accessible) X (if accessible) X X System Age: 2016 X							
4 HVAC Compressed Freon Line Insulation (if accessible) X 5 HVAC Compressor Ventilation (clear of bushes etc.) (if accessible) X 6 HVAC Air Handler (if accessible) X 7 HVAC Air Handler Drain Clear (if accessible) X 8 HVAC Ductwork (if accessible) X 9 Thermostat X 10 Water Heater Relief Valve Venting Properly 11 Water Heater Condition System Age: 2016 X				Х			
5 HVAC Compressor Ventilation (clear of bushes etc.) 6 HVAC Air Handler 7 HVAC Air Handler Drain Clear 8 HVAC Ductwork 9 Thermostat 10 Water Heater Relief Valve Venting Properly 11 Water Heater Condition (if accessible) X (if accessible) X (if accessible) X System Age: 2016 X	3	HVAC Compressor (if accessible)		X			
6 HVAC Air Handler (if accessible) X 7 HVAC Air Handler Drain Clear (if accessible) X 8 HVAC Ductwork (if accessible) X 9 Thermostat X 10 Water Heater Relief Valve Venting Properly 11 Water Heater Condition System Age: 2016 X		' '		X			
7 HVAC Air Handler Drain Clear (if accessible) X 8 HVAC Ductwork (if accessible) X 9 Thermostat X 10 Water Heater Relief Valve Venting Properly 11 Water Heater Condition System Age: 2016 X	5	HVAC Compressor Ventilation (clear of bushes etc.) (if accessible)		X			
8 HVAC Ductwork (if accessible) X 9 Thermostat X 10 Water Heater Relief Valve Venting Properly 11 Water Heater Condition System Age: 2016 X	6	HVAC Air Handler (if accessible)		X			
9 Thermostat 10 Water Heater Relief Valve Venting Properly 11 Water Heater Condition X X System Age: 2016 X	7	HVAC Air Handler Drain Clear (if accessible)		X			
10 Water Heater Relief Valve Venting Properly X 11 Water Heater Condition System Age: 2016 X	8	HVAC Ductwork (if accessible)		X			
11 Water Heater Condition System Age: 2016 X	9	Thermostat		X			
	10	Water Heater Relief Valve Venting Properly		X			
12	11	Water Heater Condition System Age: 2016		X			
	12						

	Home Inspection Report	N	S	U	R	s
lт		0	A	N	E	Ă
т		Т	Т	S	Р	F
E			ı	Α	Α	Е
М		Α	S	Т	- 1	Т
	ELECTRICAL	Р	F	1	R	Υ
		P	A	S		.
		ı	C T	F A	N E	S
	Note: This inspection is not a warrantee and/or guarantee. Building codes are not checked in this	C	0	c	E	S
	inspection report.	Α	R	T	D	Ŭ
		В	Υ	0	Ε	E
	Note: If a hazardous Electrical Panel is installed, it will have to be evaluated by a Licensed Electrician.	L		R	D	
		E		Υ		
<u> </u>	A					
-	Main Power Amperage & Voltage: 200 Amp 120v X 120v/240v		X			
2	Circuits Clearly Labeled		X			
-	GFCI Breakers	X				
-	AFCI Breakers	X				
5	Circuit Panel Accessible		X			
	Appears Grounded to Earth		X			
7	Overhead Wiring Clearances	X				
8	Overhead Supply Line Mast	X				
9	Main Circuit Panel Condition		X			
10	Exterior Service Condition		X			
11	Hazardous Panel Installed Yes NoX		X			
12	Exposed Wiring		X			

Circuit box

Wiring



JSJ & Company, Inc.

Date: 6/28/2024 www.JSJcompanyinc.com

I T E M	Note: This is not a code inspection. It is an inspection for water- tightness only. Due to shallow attic clearance not all areas may be accessible for inspection. Note: Concrete roofs have a typical life expectancy of 25 to 30 years. Note: Shingle roofs have a typical life expectancy of 15 to 20 years.	N O T A P P L I C A B L E	S A T I S F A C T O R Y	U N S A T I S F A C T O R Y	R E P A I R N E E D E D	S A F E T Y I S S U E
1	Roof Material: Cement Tile Barrel Tile Tar & Gravel Cedar Shake Strip Shingle Other <u>Metal</u>		X			
	Roof Properly Installed		X			
	Missing Shingles and/or Tiles	X				
	Shingle Blisters or Curled	X				
	Cracked Tiles	X				
	Moss or Mildew		X			
	Flashing		X			
	Fascia		X			
	Soffits and Vent Screens		Х			
	Ventilation Clear and adequate		X			
	Cracks or Gaps In Roofing Evidence of Leaks		X			
			X			
<u> </u>	Skylights		Х			
	Gutters & Downspouts		X			
15	Vent Pipes		X			
16	Low Spots on Roof		Х			
17	Roof Sheathing		Х			
18	Roof Condition		Х			
19	Attic Insulation				X	

19. One section of insulation in the attic, above the laundry room, has fallen out of place.

