



EDUCATION DEPARTMENT
GOVERNMENT OF SIKKIM
GANGTOK

Memo No. - 195/ED/EW/Edu.

Date - 21/07/2021

BUILDING SAFETY CERTIFICATE

This is to Certify that a physical inspection of **Rolep Sr. Sec. School East Sikkim**, was conducted on 21th July 2021 by the field engineer of Education Department, East II.


1. R.C.C Building:


- 3 Storied- 12 Rooms. (Classroom.)
- 1 Storied- 2 Rooms. (Classroom.)
- 3 Storied- 6 Rooms. (Including Principal Office, Staff room, Lab and IT Room.)

2. Low Cost Structure:

- 1 Storied- 3 Rooms. (Classroom.)
- 1 Storied- 2 Rooms. (Classroom.)

The visual inspection revealed that the columns, beams, and slab had no cracks or shear stress of any kind. The partitions were also found to be free from cracks, till date the school structures have no significant damages and defects. Hence, the structure can be certified to be fairly safe.


Assistant Engineer (East-II)
Education Deptt.
Govt. of Sikkim
Asstt. Engineer, East II
Education Department
Govt. of Sikkim


Divisional Engineer (East-II)
Education Deptt.
Govt. of Sikkim
Divisional Engineer, East II
Education Department
Govt. of Sikkim