Bond Home Repairs



SUMMARY OF SCOPE:

Buildings 542 and 543

- A. Renovations to restrooms
- B. Electrical and plumbing repairs/modifications
- C. Flooring
- D. Interior and exterior painting
- E. Roof repairs
- F. Demo of various concrete elements and construction of new concrete walks/ramps and foundation repair

Photo Index




- Small restrooms
- Large restrooms
- Kitchen and dining areas
- Family room
- Home exterior

Small Restrooms

Rooms 111/211









Small Restrooms

Rooms 112/212







Pics of small restroom in one home. Other home has same floorplan.

Large Restrooms

Rooms 107/207







Pics of large restroom in one home. Other home has same floorplan.

Large Restrooms

Rooms 107/207



Pic of large restroom in one home. Other home has same floorplan.



Kitchen & Dining

Rooms 102/202







Pics of dining area in one home. Other home has same floorplan.

Kitchen & Dining

Rooms 103/203

TEXAS

Health and Human Services



Pics of kitchen space in one home. Other home has same floorplan.






Family Room

Room 101/201







Building 542 (Castle River)





Building 542 (Castle River)









TEXAS

Health and Human Services

Building 543 (River Forest)







Views from front yard.

Building 543 (River Forest)







Backyard walkway area.

Building 543 (River Forest)



