



1

.

,





"ESTANCIA"

property of

JOSEPH F. DEMPSEY

situate

Great River Road, Great River, Suffolk County, N. Y.

THORSEN & RITCHIE INCORPORAȚED

One Park Avenue, New York
January 15, 1942

DESCRIPTION

BLDG. #1 - MAIN DWELLING

CONSTRUCTION:

Height - one and three stories and basement. Foundations - brick. Walls - brick on first; frame, stuccoed, on second and third. Roof - wood shingle on wood rafters. Floors - basement, concrete; first, second and third, double 1" wood boards on wood joists; hardwood finish on first; tile in baths. Interior Finish - basement, wood lath and plaster ceiling, open walls; first, wood lath and plaster with part oak wainscoting, and archaic plaster in dining room; second and third, wood lath and plaster. Floor Openings - one wood stair, basement to first, wood door at first; one wood stair, first to second, wood door at first; one wood stair, first to third, open. Lighting - electricity. Heating - fireplaces throughout; hot air, coal fired, furnace. Chimneys - brick. Cooking - coal range. Area - ground floor approximately 5,150 sq. ft.

OCCUPANCY:

Basement - Heating Apparatus, Cellar Purposes.

lst Floor - Living Room, Reception Hall, Dining
Room, Den, Pantry (safe), Kitchen, Laundry.

2nd Floor - Six Bedrooms, Four Baths, Five Helps' Bedrooms and one Bath.

3rd Floor - Four Bedrooms, Play Room, Bath, Attic Space.

PUBLIC PROTECTION:

Yes.

REMARKS:

Age - About forty years.

Condition - Good.

BLDG. #2 - FARM COTTAGE

CONSTRUCTION:

Height - one and two stories and part basement. Foundations - brick. Walls - frame, wood shingle. Roof - wood shingle on wood rafters. Floors - basement, concrete; first, single 1" wood boards on wood sleepers in concrete, part single 1" wood boards on wood joists; second, part double and part single 1" wood boards. Interior Finish - basement, open, first, part rock lath and plaster, part wood lath and plaster with tongued and grooved board ceiling; second, part open and part wood lath and plaster. Floor Openings - two stairs, first to second, open; one wood stair, basement to first, wood door at first. Righting - electricity. Heating - low pressure steam, coal fired, boiler. Chimneys - brick. Cooking - gas range. Area - ground floor approximately 3,550 sq. ft.

OCCUPANCY:

1st Floor - Tower Room, Book Stall, Living Room, Dining-Living Room, Kitchen, Pantry, Two Sun Porches, Two Lavatories, Two-car Garage and Stable.

2nd Floor - Eight Bedrooms, Two Baths, Storage Loft, Tower Room.

PUBLIC PROTECTION:

None.

REMARKS:

Age - Built about 50 years ago; renovated in the Summer of 1941.

Condition - Very good.

BLDG. #3 - BOAT HOUSE

CONSTRUCTION:

Height - two stories and no basement.

Foundations - brick.

Walls - brick on first, frame, stuccoed on second.

Floors - single 1" wood boards on wood joists.

Roof - wood shingle on wood rafters.

Interior Finish - tongued and grooved boards.

Floor Openings - one wood stair, first to second, open.

Lighting - electricity.

Heating - fireplace.

Chimney - brick.

Area - ground floor approximately 1,200 sq. ft.

OCCUPANCY:

lst Floor - Boat Dock, Two Dressing Rooms, Shower
Room.

2nd Floor - Recreation Room.

PUBLIC PROTECTION:

Yes.

REMARKS:

Age - About forty years.

Condition - Good.

BLDG. #4 - EARN & TOOL HOUSE

CONSTRUCTION:

Height - one and two stories.

Walls - frame, clapboard finish.

Roof - wood shingle on wood rafters.

Floors - first, part concrete and part wood plank;
second, single 1" wood boards on wood joists.

Interior Finish - part tongued and grooved boards,
part open and part plasterboard on first; second,
open.

Floor openings - one wood stair, first to second,
Lighting - electricity.

Area - ground floor approximately 2,000 sq. ft.

OCCUPANCY:

lst Floor - Horse stalls, garage, tool shed,
wagon shed.

2nd Floor - Loft.

PUBLIC PROTECTION:

None.

REMARKS:

Age - About 40 years.

Condition - Fair to good.

BLDG. #5 - CHICKEN HOUSE NO. 1

Height - one story. Foundations - wood post.

Walls - frame, clapboard finish. Roof - wood
shingle on wood rafters. Floors - single 1"
wood boards on wood joists. Interior Finish open. Area - ground floor area approximately
500.

Occupancy - Old chicken house.

Public Protection - None
Age - About 40 years.

Condition - Fair to good.

BLDG. #6 - CHICKEN HOUSE NO. 2

Height - one story. Foundations - cement block piers. Walls - frame, vertical siding. Roof - composition on wood boards on wood rafters. Floors - single 1" wood boards on wood joists. Interior Finish - open. Area - ground floor approximately 90 sq. ft.

Occupancy - Chicken coop.

Public Protection - No.

Age - About 1 year.

Condition - Good.

BLDG. #7 - OLD PUMP HOUSE

Height - one story. Foundations - wood posts.

Walls - frame, vertical siding. Roof - wood
shingle on wood rafters. Floors - single 1" wood
boards on wood joists. Interior Finish - open.

Area - ground floor approximately 120 sq. ft.

Occupancy - Miscellaneous storage <u>Public Protection</u> - No. <u>Age - About 40 years.</u> <u>Condition</u> - Fair.

BLDG. #8 - DUCK HOUSE

Height - one story. Foundations - brick.

Walls - frame, wood shingle. Roof - wood shingle
on wood rafters. Floors - single 1" wood boards
on wood joists. Interior Finish - open. Area ground floor approximately 375 sq. ft.

Occupancy - Duck House.

Public Protection - No.

Age - About 40 years.

Condition - Fair.

BLDG. #9 - GOAT HOUSE

Height - one story. Foundations - brick.

Walls - frame, wood shingle. Roof - wood shingle
on wood rafters. Floors - single 1" wood boards
on wood joists. Interior Finish - open. Area ground floor approximately 375 sq. ft.

Occupancy - Goat House and Pigeon Cote.

Public Protection - No.

Age - About 40 years.

Condition - Fair.

BLDG. #10 - ICE HOUSE

Height - one story. Foundations - brick.

Walls - brick. Roof - wood shingle on wood

rafters. Floors - earth. Interior Finish open. Area - ground floor approximately 72

sq. ft.

Occupancy - Unused ice house.

Public Protection - Yes.

Age - About 40 years.

Condition - Good.

SOUND VALUE

Sound Value is replacement cost less depreciation and should be the basis of the amount of insurance to be carried in order to properly protect your interests. The estimate as given herein is the personal opinion of the Engineer who made the inspection, checked by building cost charts and tables which are believed to be fairly reliable.


The estimates of sound value exclude the cost of excavations; also foundations below the level of the lowest floor and architects' fees.

The estimates for determining the amounts of insurance to be carried are approximate and as of this date and cannot be considered as binding on either you or any insurance company as to the actual value of the property.

Estimated Prese	nt
ound Value Insura	nce
	<i>y</i> .
\$65,000. \$70,0	00.
17,000. 15,0	00.
5,500. 4,0	00.
2,200. 2,5	00.
500.	00.
125. n	il
75. n	11
200. n	11
	11
190. n	11
	\$65,000. \$70,0 17,000. 15,0 5,500. 4,0 2,200. 2,5 500. 5 125. n. 75. n. 200. n.

RATES PER \$100. - Fire and Lightning

Item	One Year	Three Years	Five Years
1 Dwelling	•18	•45	.72
2 Farm Cottage	.40	1.00	1.60
3 Boat House	.18	•45	.72
4 Barn & Tool House	• 50	1.25	2.00
5 Chicken House #1	• 50	1.25	2.00
6 11	•50	1.25	2.00
7 Old Pump House	• 50	1.25	2.00
8 Duck House	•50	1.25	2.00
9 Goat House	• 50	1.25	2.00
10 Ice House	.18	.45	72



GREAT RIVER ROAD

• D.H

L - ILLIAMIN W NQ 2 FARN COTTAGE

"ESTANCIA" PROPERTY OF JOSEPH F. DEMPSEY GREAT RIVER, NEW YORK

GREAT RIVER ROAD

. D.H NO. 10 ICE HO. NO. 1 BRICK IST FRAME 2 NO MAIN DWELLING

SUBMITTED BY THORSEN & RITCHIE

NEW YORK CITY, N.Y.

DISTANCES BETWEEN BLDGS NOT TO SCALE

F.R.S.

JAK


NQ 3 BOAT HO.



BLDG. #1 - MAIN DWELLING




BLDG. #2 - FARM COTTAGE



BLDG. #3 - BOAT HOUSE



BLDG. #4 - BARN & TOOL HOUSE



BIDG. #5 - CHICKEN HOUSE NO. 1