

BUILDING SAFETY CERTIFICATE

No.

Dated: 02.09.2024

It is certified that the existing building **MILESTONE INTERNATIONAL SCHOOL** (name of the building or premises) at **Village – Podar, SH22- Khamariya Gramin Pradhan mantri Marg, Block – Saikheda, Salichouka Road, 487881, District- Narsinghpur, M.P.** (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G + 1	G + 1				


The building is owned/occupied by **MILESTONE INTERNATIONAL SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Government PWD Engineer** (Name of Department/ Govt.) on **30.08.2024** (date of inspection) in the presence of **S. S. RAJPUT** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **02.09.2024** for a period of **03 YEARS** in accordance with rule and subject to compliance of the specific conditions as appended.

1. The work has been completed to my best satisfaction.
2. The building is structurally sound, safe and hygienic.
3. Hence it is fit for use how in with **MILESTONE INTERNATIONAL SCHOOL** is running.

Issued on 02.09.2024 at JAN. PANCHYAT SAIKHEDA, GADARWARA by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: 

Name: **S.S. RAJPUT** 

Designation: **SUB ENGINEER**

Name & Address of Department/ Office: JAN. PANCHYAT SAIKHEDA

BUILDING SAFETY CERTIFICATE

No.

Dated: 02.09.2024

It is certified that the existing building **MILESTONE INTERNATIONAL SCHOOL** (name of the building or premises) at **Village – Podar, SH22- Khamariya Gramin Pradhan mantri Marg, Block – Saikheda, Salichouka Road, 487881, District- Narsinghpur, M.P.** (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G + 1	G + 1				

The building is owned/occupied by **MILESTONE INTERNATIONAL SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Government PWD Engineer** (Name of Department/ Govt.) on **30.08.2024** (date of inspection) in the presence of **S. S. RAJPUT** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **02.09.2024** for a period of **03 YEARS** in accordance with rule and subject to compliance of the specific conditions as appended.

1. The work has been completed to my best satisfaction.
2. The building is structurally sound, safe and hygienic.
3. Hence it is fit for use how in with **MILESTONE INTERNATIONAL SCHOOL** is running.

Issued on 02.09.2024 at JAN. PANCHYAT SAIKHEDA, GADARWARA by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal  **उपयंत्री**
 Name: **S.S. RAJPUT** **पंचायत साईखेडा**
 Designation: **SUB ENGINEER**

Name & Address of Department/ Office: JAN. PANCHYAT SAIKHEDA