FORM - A

(Form of application under sub-section (1)/ sub – section (2) of section 4 of the Madras Public buildings (licensing) act, 1965 madras 13 of 1965) referred to rule 3 of the madras public buildings (licensing) rules, 1966).

From

SRI SABARI NATIONAL SCHOOL,
Door No.9-8-9, Kazhuvancheri Road,
Kattukuthagai Karisalkulam Village,
Kariapatti Taluk, Virudhunagar District.

To

THE THASILDAR,
Taluk office,
Kariapatti.

Sir,

I Intend / continue to use the buildings which is situated at **SRI SABARI NATIONAL SCHOOL,** Door No.9-8-9, S.Nos.66/8C1, 66/16B2, 66/16C2 & 66/17, Kazhuvancheri Road, Kattukuthagai Karisalkulam Village, Kariapatti Taluk, Virudhunagar District and specified in the statement enclosed as a public buildings for a period of three years from **21 - 05 – 2024 to 20 - 05 - 2027.**

The year of construction and the present approximate cost of construction and the purpose for which is to be used or being used as public building are also furnished in the statement accompanying this application.

I enclose a challon for Rs.

I also enclose a certificate of structural soundness in the prescribed form furnished by the engineer P.Ganesan, B.E., M.I.E., F.I.V.

DATE:25.04.2024

SIGNATURE OF THE OWNER
OF THE BUILDING

ENCL:
1. Statement,
2. Challon for Rs. towards the application fees.
3. Certificate of structural soundness.
4. Declaration of *ENGINEER.*

SRI SABARI NATIONAL SCHOOL

STATEMENT ACCOMPANYING FORM –A

1.	Door No, of the building	: Door No.9-8-9
2.	Location of {street no., Ward no. Name of the place, Corporation/municipality/ Township}	: Door No.9-8-9, S.Nos.66/8C1, 66/16B2, 66/16C2 & 66/17, Kazhuvancheri Road, Kattukuthagai Karisalkulam Village, Kariapatti Taluk, Virudhunagar District
3.	Year of Construction	: Ground Floor – 2018 First Floor – 2024
4.	Approximate cost of Construction as per current rates.	: Rs.3,50,00,000.00
5.	Purpose for which the building has been used or proposed to be used.	: School Building Ground Floor – Reception Hall, Chairman Room, Correspondent Room, Principal Room, Class Room, Computer Lab, Composite Lab, Staff Room and Toilet (Boys and Girls) First Floor – Library, Class Room and Toilets.

SHANTHA CONSULTANCY
Chartered Engineer
Approved Valuer
RAJAPALAYAM

6.	Purpose for which the building has hither to been used.	: School Building Ground Floor – Reception Hall, Chairman Room, Correspondent Room, Principal Room, Class Room, Computer Lab, Composite Lab, Staff Room and Toilet (Boys and Girls) First Floor – Library, Class Room and Toilets.
7.	Details of construction of the building (Particulars of the foundation sold, specification of the various parts under) :-	
	(1) Foundation	: Reinforced cement concrete Columns.
	(2) Basement	: Reinforced cement concrete Columns and Brick Masonry Wall in C.M.1:5
	(3) Superstructrue	: Reinforced cement concrete Columns and Brick Masonry Wall in C.M.1:5
	(4) Floor and Roof	: Flooring – Marbonite tiles Flooring. Roofing - Reinforced cement concrete roofing

SHANTHA CONSULTANCY
Chartered Engineer
Approved Valuer
RAJAPALAYAM

8	Period for which licence is required	: 3 Years (From **21-05–2024 to 20-05-2027)**
9.	Number of persons to be accommodated	: 800 Nos.

Date : 25.04.2024

SHANTHA CONSULTANCY ★ Chartered Engineer Approved Valuer ★ RAJAPALAYAM

P.G-17

SIGNATURE OF THE ENGINEER

Er.P.GANESAN B.E.,M.Sc.,(Agri),
MIE.,FIV.,MICI.,MICA.,MISTE.,
Chartered Engineer, Approved Valuer
SHANTHA CONSULTANCY
2,Kooraipillaiyar Kovil Street,
RAJAPALAYAM -626 117
CELL : 94862 06897

Certified that no addition or alternation has been made to the existing building or portion of the building for which this application has been made. I undertake to obtain a fresh license in case of any addition or alternation is made in the existing or portion of building. I also undertake to obtain a fresh license if the purpose for which the license was granted for the use of the building or a portion of the building originally is changed or alternated subsequently.

DATE : 25.04.2024

1SIGNATURE OF THE OWNER OF THE BUILDING

FORM - B

(Form of certificate of Structural soundness under sub section (4) of Section 4 of the Tamil Nadu Public Buildings (Licensing) Act 1965 (Tamil Nadu Act 13 of 1965) Refered to in rule 4 of the Tamil Nadu Buildings (Licensing) Rules 1966)

I Certify that I have inspected the building mentioned in the statement and furnish below its salient technical features

I) FOUNDATION :-

(i)	Depth below ground level	: 2.10 M
(ii)	Nature of soil met with at foundation level	: Sandy Gravel/Kanker
(iii)	Pressure at foundation	:18.00 T/SM
(iv)	Probable safe bearing capacity of the starata met with at foundation	: 45 T/SM

HENCE SAFE

II) SUPERSTRUCTURE :-

(i)	Maximum stress in the most critical section of masonry or concrete	: 350.00 T/SM
(ii)	Nature of masonry and concrete and its safe permissible stress	: Reinforced cement concrete columns – 850 T/SM.

SHANTHA CONSULTANCY
Chartered Engineer
Approved Valuer
RAJAPALAYAM

The structural soundness of the building has been verified by me with reference to ISI loading standard 875 (Latest version) and other relevant Indian standards code of practice and I declare that the building is structural sound to be used as a public building for the purpose noted in the statement. A license may be granted for the granted for the period from **21 - 05 – 2024 to 20 - 05 - 2027.**

DATE : 25 - 04 - 2024

SHANTHA CONSULTANCY ★ RAJAPALAYAM ★ Chartered Engineer Approved Valuer

P-G-I

SIGNATURE OF THE ENGINEER

Er.P.GANESAN B.E.,M.Sc.,(Valu,
MIE.,FIV.,MICI.,MICA.,MISTE.,
Chartered Engineer, Approved Valuer
SHANTHA CONSULTANCY
2,Kooraipillaiyar Kovil Street,
RAJAPALAYAM -626 117
CELL : 94862 06897

FORM –C

FORM OF OPINION

Under sub – section 1 of section 5 of madras public building (licensing) act 1965 (madras act XIII of 1965) referred to rule 5 of the madras public building (licensing) rules 1966.

I have inspected the buildings specified in the statement below and I have satisfied myself that the building is structurally sound to be used as public building for the purpose specified in the statement. The structural soundness of the building has been verified, taking into account, the loading as per the latest Indian standards 875. I am therefore of the portion of the opinion that and license may be granted for the period from **21 - 05 – 2024 to 20 - 05 - 2027.**

DATE : 25 - 04 - 2024.

SHANTHA CONSULTANCY ★ RAJAPALAYAM ★ Chartered Engineer Approved Valuer

S *IGNATURE OF THE ENGINEER*

Er.P.GANESAN B.E.,M.S
MIE.,FIV.,MICI.,MICA.,MIS
Chartered Engineer, Approved Valuer
SHANTHA CONSULTANCY
2,Kooraipillaiyar Kovil Street,
RAJAPALAYAM -626 117
CELL : 94862 06897

STATEMENT TO ACCOMPANY THE OPNION REGARDING STRUCTURAL SOUNDNESS

Location of the Building Door No., Street, Name of the Place	: Door No.9-8-9, S.Nos.66/8C1, 66/16B2, 66/16C2 & 66/17, Kazhuvancheri Road, Kattukuthagai Karisalkulam Village, Kariapatti Taluk, Virudhunagar District
Age of the Building	: Ground Floor – 6 Years First Floor – Just Completed.
Short description of structures Steel, R.C.C. Framed or Load bearing Masonry	: Reinforced cement concrete Framed Structure.
Purpose for which the building is certified for use	: <u>School Building</u> Ground Floor – Reception Hall, Chairman Room, Correspondent Room, Principal Room, Class Room, Computer Lab, Composite Lab, Staff Room and Toilet (Boys and Girls) First Floor – Library, Class Room and Toilets.
The period for which the building will be structurally sound	: 3 Years (From **21-05–2024 to 20-05-2027)**
Number of Persons to be accommodated	: 800 Nos.
Remarks	: Proper periodical and annual maintenance have been insisted.

DATE : 23-04-2024.

SHANTHA CONSULTANCY RAJAPALAYAM Chartered Engineer Approved Valuer

SIGNATURE OF THE ENGINEER

Er.P.GANESAN B.E.,M.Sc.,(Valu,
MIE.,FIV.,MICI.,MICA.,MISTE.,
Chartered Engineer, Approved Valuer
SHANTHA CONSULTANCY
2,Kooraipillaiyar Kovil Street,
RAJAPALAYAM -626 117
CELL : 94862 06897

DECLARATION

I , P.GANESAN, office at 2, Kooraipillaiyar Kovil Street, Rajapalayam-626117 do herby that I possess the qualification and experience specified in the table to rule II of the madras public building(licensing) rules 1966 for issuing the certificate of structural soundness of the building covered by the certificate.

Remarks :

1. This certificate does not hold or holds or ensures the responsibility for the Stability of the building structure due to Natural calamities like Earth quake, Gale cyclone and Fire.

2. The subsequent addition and alteration of the building should be done only with prior information to the certifying authority.

P.G-1

STATION : Rajapalayam.

DATE : 25 - 04 - 2024.

SHANTHA CONSULTANCY ★ RAJAPALAYAM ★ Chartered Engineer Approved Valuer

Er.P.GANESAN B.E.,
MIE, FIV, MICI, MICA,
Chartered Engineer, Approved Valuer
SHANTHA CONSULTANCY
2,Kooraipillaiyar Kovil Street,
RAJAPALAYAM -626 117
CELL : 94862 06897

SIGNATURE OF THE CERTIFYING ENGINEER.

1.	NAME OF ADDRESS (In Block Letters)	P.GANESAN,B.E., 2, Kooraipillaiyar Kovil Street, Rajapalayam-626117.
2.	ENGINNERING QUALIFICATION	B.E., M.I.E.,F.IV.,
3.	NUMBER OF YEARS OF EXPERIENCE & NATURE THERE OF	33 Years experience in civil engineering works, Chartered engineer, Approved valuer (Govt of India) Registered engineer under class I A of Virudhunagar District in collector's order No.VMJ2/6732/2016 Dt. 07 - 03 - 2017.

FORM - E

Form of respect to be made to be the competent Authority by inspecting Authorities of Officer appointed under section 28 of the Madras buildings (licensing) act, 1965 referred to in the rule 7 of the madras public buildings (licensing) rules, 1996).

1.	Name of designation of inspecting authority or officer appointed or having jurisdiction under any other Act or law.	: P.GANESAN,B.E., 2, Kooraipillaiyarkoil Street, Rajapalayam-626117
2.	Location of the building inspected (Door Number, Street Number, Name of Place ie. Municipal Corporation/Municipality/ Panchayath or Panchayath Union/Town Ship/Cantonment)	: Door No.9-8-9, S.Nos.66/8C1, 66/16B2, 66/16C2 & 66/17, Kazhuvancheri Road, Kattukuthagai Karisalkulam Village, Kariapatti Taluk, Virudhunagar District
3.	Date of Inspection	: 25.04.2024
4.	Purpose for which the building is used	: School Building Ground Floor – Reception Hall, Chairman Room, Correspondent Room, Principal Room, Class Room, Computer Lab, Composite Lab, Staff Room and Toilet (Boys and Girls) First Floor – Library, Class Room and Toilets.
5.	Nature of defects noticed	: Maintained properly
6.	Suggestions for rectifying defects	: Maintained properly
7.	If in dangerous condition, immediate steps recommended to be taken	: Not applicable

STATION : Rajapalayam.

DATE : 25.04.2024.

SHANTHA CONSULTANCY * RAJAPALAYAM * Chartered Engineer Approved Valuer


P. G-17

SIGNATURE OF THE CERTIFYING ENGINEER.

Er.P.GANESAN B.E.,M.Sc.,(Valu,
MIE.,FIV.,MICI.,MICA.,MISTE.,
Chartered Engineer, Approved Valuer
SHANTHA CONSULTANCY
2,Kooraipillaiyar Kovil Street,
RAJAPALAYAM -626 117
CELL : 94862 06897











SHANTHA CONSULTANCY
RAJAPALAYAM
Chartered Engineer
Approved Valuer









SHANTHI CONSULTANCY
Chartered Engineer
Approved Valuer
RAJAPALAYAM