

- oxidized BRASS
- old FELT
eaten up by moths

before



- ❖ polished BRASS
- ❖ New English Cashmere

after





❖ polished
Brass

❖ New
English
Cashmere








Acoustic System

- ❖ **Restored Sound Board**
(cracks are gone)
- ❖ **New Strings**
- ❖ **New Tuning Pins**
- ❖ **New English Cashmere**
- ❖ **Polished Brass**
(cover over the pin block looks like a mirror!)


*[photographer hid face
in a way to not be
recognized 😊]*



before

after





- ❖ New Candleholders
- ❖ Polished Keys
- ❖ New Rolls
- ❖ New English Cashmere
(over the keyboard)

