Activity Report 11/4/22, 1:45 PM

and needs to be closed manually to be secure.

Near the "Lux" delivery area, I found a package on the floor.

Photos attached.

Start Time

2022-11-01 00:15

Duty

FOOT PATROL OF PROPERTY

Notes While on foot patrol of the outside perimeter of both buildings, I saw 3 different dumpsters that had doors left open. I closed 2 out

of the 3. The Southside dumpster doors, next to building #2, could not be closed because the dumpsters were blocking the doors.

On the east side of building #2, I found the "Fire Sprinkler Riser Room" unlocked. This is next to the "Electrical Service

Disconnects Inside Bulding #2, 1 of 3."

On the Southside of building #2, I observed a downed tree that is covering parking spaces. Also at building #2, I note there is a

shopping cart inside the stairwell "Stair K, Level 2".

At the south, Westside entrance gates, I found the walk through gate was not closed all the way and needs to be manually closed.

On the Eastside of building #1, I note the "Electrical Service Disconnects Inside Building #1, 5 of 5", is unlocked.

In the same area of building #1, I came upon a "Target" cart on Elysian property.

While on the same foot patrol, at the northwest vehicle entrance gates, I observe the left side of the entrance is not closing. I also

observed neither vehicle exit gate closing.

Photos attached.

Start Time

2022-11-01 01:00

Duty

CLUB HOUSE AND POOL

Notes

While on patrol of the level 1 gym area, I found several weights not put away, causing a safety hazard. I also observed the gym

windows open and closed them.

While in the pool area, I note the southeast door that goes between the pool area and resident units, is not locking.

Photos attached.

Start Time

2022-11-01 01:30

Duty

PATROL OF PARKING AREAS

Notes

While on patrol of the parking areas, I observed the northwest vehicle exit gates are now closed. This leaves the left side to the

entrance, not closing.

In the Westside parking area of building #2, I found a downed tree that is laying in the driveway.

Photos attached.

Start Time

2022-11-01 02:00

Duty

CLUB HOUSE AND POOL

Notes

While on patrol of the Clubhouse and Pool areas, I did not encounter any residents or guests.

Photos attached.

Activity Report 11/4/22, 1:45 PM

Start Time 2022-11-01 02:30

Duty FOOT PATROL OF PROPERTY

Notes While on foot patrol of building #1, level 2, I note a broken latch at "Stair C, Level 2".

I observed On Level 2 of building #1, Stairwell "Stair E, Level 1", was propped open by the rug. I also note the door is not aligned

correctly, keeping it from closing.

Photos attached.

Start Time 2022-11-01 03:15

Duty PATROL OF PARKING AREAS

Notes While on patrol of all parking areas, I did not observe any residents or guests.

Photos attached.

Start Time 2022-11-01 03:45

Duty FOOT PATROL OF PROPERTY

Notes While on foot patrol of building #2, I observed items left in the hall near "S-35" on level #2.

Also in building #2, on level #4, I note other items left in the hall. The items are near units "4083-4088".

Photos attached.

Start Time 2022-11-01 04:15

Duty CLUB HOUSE AND POOL

Notes While on patrol of the Clubhouse areas, I observed a few residents or guests coming through the main lobby, watching TV in the

game area, and using the coffee machine. I also note there were 2 people using the level 1 gym area.

Photos attached.

Start Time 2022-11-01 04:45

Duty CLUBHOUSE MAILROOM

Notes While patrolling the Clubhouse Mailroom area, I did not encounter any residents or guests.

Photos attached.

Start Time 2022-11-01 05:00

Duty PATROL OF PARKING AREAS

Notes While patrolling the parking areas, I did not encounter any residents or guests.

Photos attached.

Start Time 2022-11-01 05:30

Duty CLUB HOUSE AND POOL

Notes While on patrol of Clubhouse and Pool areas, I observed several residents or guests coming and going in the main lobby. One

resident watching television in the gaming area. There was a resident in the level 1 gym area and 1 resident in the level 2 fitness