Insured/Applicant Name: Jane Doe		Application	on / Policy #:		
Address Inspected: 1234 Main Street, Any	Address Inspected: 1234 Main Street, Anytown US 12345				
Actual Year Built: 1958 Date Inspected:			- W - 20		
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scorching □ Other (explain)			
General condition of the electrical system: ✓ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel Panel age: 10 years Year last updated: 2012	Second Panel Panel age: Year last updated:		Wiring Type ☑ Copper ☑ NM, BX or Conduit		
Brand/Model: Square D	Brand/Model:				

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: 2019 est.					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ✓ No Space heater used as primary heat source? ☐ Yes ✓ No Is the source portable? ☐ Yes ✓ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ✓ No					
Supplemental Information					
Age of system: 9 years Year last updated: 2013 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Utility Closet					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home 10 years Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ✓ Copper ✓ PVC/CPVC ☐ Galvanized ✓ PEX ☐ Polybutylene ☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof			
Covering material: Ashphalt/Fiberglass Composition (Dimensional)		Covering material: Modified Bitumen			
Roof age (years): 10 years		Roof age (years): 10 years			
Remaining useful life (years): 10 years		Remaining useful life (years): 5 years			
Date of last roofing permit: 03/01/2012		Date of last roofing permit: 03/01/2012			
Date of last update: 03/01/2012		Date of last update: 03/01/2012			
If updated (check one):		If updated (check one):			
✓ Full replacement		✓ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
✓ Satisfactory		✓ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Unsatisfactory (explain below)		_ sisaasassi, (explain 2010),	Olisatistationy (explain below)		
Any visible signs of damage / deterior		Any visible signs of damage / deterioration?			
(check all that apply and explain below)		(check all that apply and explain below)			
☐ Cracking					
☐ Cupping/curling ☐ Excessive granule loss		☐ Excessive granule loss	Cupping/curling		
Exposed asphalt		Exposed asphalt			
☐ Exposed felt		Exposed distriction			
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs or tiles			
☐ Soft spots in decking		☐ Soft spots in decking			
☐ Visible hail damage		☐ Visible hail damage			
Any visible signs of leaks? ☐ Yes No		Any visible signs of leaks? ☐ Yes ✓ No			
Attic/underside of decking ☐ Yes ✓ No		Attic/underside of decking Yes No			
Interior ceilings ☐ Yes ✓ No		Interior ceilings ☐ Yes ✓ No	Interior ceilings ☐ Yes ✓ No		
Additional Comments/Observations (use additional pages if needed):					
Plumbing re-pipe in 2012 per building permit 12 106522 00 B1.					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
KOm	Owner	HI 11423			
Inspector Signature	Title	License Number	Date		
KMI Home Inspections, Inc.	Home Inspector	941-350-2927			
Company Name	License Type	Work Phone			

Special Instructions: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- . Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

House Front



House Number



Left Elevation



Rear Elevation



Right Elevation



Roof 1



Roof 2



Roof 3



Roof 4



Condenser



Condenser Data Plate



Air Handler



Air Handler Data Plate



Main Panel Cover On



Main Panel Cover Off



Water Heater



Water Heater Data Plate




Plumbing 1



Plumbing 2






Plumbing 4



Plumbing 6



Plumbing 7

