

April 22, 2016

COBURN WOODS

PARKING CLUSTERS

SNOW REMOVAL MAPS



COBURN WOODS
PARKING DIAGRAM
● Building Footprint
● Street
● Parking Spot
● Water Feature
● Boundary

- 105 - 108
- 109 - 115
- 116 - 125
- 126 - 130
- 131 - 133
- 134 - 140
- 141 - 148
- 149 - 155
- 156 - 166
- 167 - 172
- 173 - 181
- 182 - 187
- 188 - 193
- 194 - 196
- 197 - 202
- 203 - 212
- 213 - 220
- CLUBHOUSE

- 1 - 14
- 15 - 20
- 21 - 25
- 26 - 36
- 37 - 41
- 42 - 53
- 54 - 58
- 59 - 61
- 62 - 68
- 69 - 76
- 77 - 84
- 85 - 91
- 92 - 97
- 98 - 104

TABLE OF CONTENTS

SNOW 1 - 14

Car #1 - fully parked in carport.
 Car #2 - parked where shown.

- V VISITOR PARKING
- P PERMIT ISSUED
- A AMENITY PARKING
- / NO PARKING - TOW ZONE

PERMITS GRANTED
 #12 - 3RD PERMIT



TABLE OF CONTENTS

SNOW 15 - 20

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V VISITOR PARKING
- P PERMIT ISSUED
- A AMENITY PARKING
- / NO PARKING - TOW ZONE

PERMITS GRANTED
#18 - 3RD PERMIT




TABLE OF CONTENTS

Pond 1

Pool 1

Pool 1 house



SNOW 21 - 25

Car #1 - fully parked in carport.

Car #2 - parked where shown.





-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE

TABLE OF CONTENTS

SNOW 26 - 36

Pond 1



Car #1 - fully parked in carport.
 Car #2 - parked where shown.

- V VISITOR PARKING
- P PERMIT ISSUED
- A AMENITY PARKING
- / NO PARKING - TOW ZONE

PERMITS GRANTED
 #27 - 3RD PERMIT
 #32 - 3RD PERMIT

TABLE OF CONTENTS

SNOW 37 - 41

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**

PERMITS GRANTED
#39 - 3RD PERMIT








TABLE OF CONTENTS

SNOW 42 - 53

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE








TABLE OF CONTENTS

SNOW 54 - 58

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE




TABLE OF CONTENTS

SNOW 59 - 61

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**




TABLE OF CONTENTS

SNOW 62 - 68

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V VISITOR PARKING
- P PERMIT ISSUED
- A AMENITY PARKING
- / NO PARKING - TOW ZONE

PERMITS GRANTED
#63 - 3RD PERMIT








TABLE OF CONTENTS

SNOW 69 - 76

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE




TABLE OF CONTENTS

SNOW 77 - 84

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**




TABLE OF CONTENTS

SNOW 85 - 91

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**

PERMITS GRANTED
#91 - 3RD PERMIT




TABLE OF CONTENTS

SNOW 92 - 97

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**

PERMITS GRANTED
#95 - 3RD PERMIT








TABLE OF CONTENTS

SNOW 98 - 104

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE








TABLE OF CONTENTS

SNOW 105 - 108

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE




TABLE OF CONTENTS

SNOW 109 - 115

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**




TABLE OF CONTENTS

SNOW 116 - 125

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V VISITOR PARKING
- P PERMIT ISSUED
- A AMENITY PARKING
- / NO PARKING - TOW ZONE

PERMITS GRANTED
#124 - 3RD PERMIT




TABLE OF CONTENTS

SNOW 126 - 130

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**








TABLE OF CONTENTS

SNOW 131 - 133

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE




TABLE OF CONTENTS

SNOW 134 - 140

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**








TABLE OF CONTENTS

SNOW 141 - 148

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE




TABLE OF CONTENTS

SNOW 149 - 155

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**








TABLE OF CONTENTS

SNOW 156 - 166

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE




TABLE OF CONTENTS

SNOW 167 - 172

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**








TABLE OF CONTENTS

SNOW 173 - 181

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE

PERMITS GRANTED
#175 - 3RD PERMIT
#180 - 3RD PERMIT








TABLE OF CONTENTS

SNOW 182 - 187

Car #1 - fully parked in carport.

Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE




TABLE OF CONTENTS

SNOW 188 - 193

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**




TABLE OF CONTENTS

SNOW 194 - 196

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**

PERMITS GRANTED
#196 - 3RD PERMIT




TABLE OF CONTENTS

SNOW 197 - 202

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V VISITOR PARKING
- P PERMIT ISSUED
- A AMENITY PARKING
- / NO PARKING - TOW ZONE








TABLE OF CONTENTS

SNOW 203 - 212

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE




TABLE OF CONTENTS

SNOW 213 - 220

Car #1 - fully parked in carport.
Car #2 - parked where shown.

- V** VISITOR PARKING
- P** PERMIT ISSUED
- A** AMENITY PARKING
- NO PARKING - TOW ZONE**

PERMITS GRANTED
#220 - 3RD PERMIT








TABLE OF CONTENTS

SNOW CLUBHOUSE

Car #1 - fully parked in carport.
Car #2 - parked where shown.

-  VISITOR PARKING
-  PERMIT ISSUED
-  AMENITY PARKING
-  NO PARKING - TOW ZONE

