

ARCHITECTS. ENGINEERS. PLANNERS.

## FIELD REPORT

SIG PI – 2019 ROOF REPLACEMENT PROJECT 7396-19-0010 Houghton, MI

None required.


7/23/2019

Work in Progress:

Present at Site:	Jeff Peltier (J. Peltier Construction, Inc.), Louis Meyette (OHM), Terry Dahl (OHM)
Time:	1:00 p.m. – Sunny – 74 Degrees
Work Completed:	All work is complete, and jobsite is cleaned up. Lou Meyette led a general discussion questioning the methods used by the contractor for the roof installation, focusing on flashing, lapping and trim locations. Jeff gave good narrative on these methods and Terry Dahl confirmed that he witnessed those methods being used during his visits. Lou took a look into the completed attic truss reinforcing and discussed the conditions and results that the contractor attained doing this portion of the work. All work appears to be of high quality.  The Attic access enclosure box was placed off to the side of the access hole and the insulated plywood cover was set loosely on the opening. This appears to have been moved by the residents of the house after the contractors left the job, and it appears the residents have been up in the attic area.







Copies to: Owner, Lou Meyette (OHM)

Inspected by: Terry Dahl