

December 19, 2022

Chris Martin
Derby ING
PO Box 721725
McAllen, TX 78504

SATL Report No.: 2212217
RE: State
Project Number: 0820016

Dear Chris Martin

SATL received 1 Sample(s) on 12/14/2022 for analyses identified on the chain of custody. The analyses were performed using methods indicated on the laboratory report. Any deviations observed at sample receiving are notated on the Sample Receipt Checklist and/or Chain of Custody documents attached as part of this analytical report.

Sincerely,

For San Antonio Testing Laboratory, Inc.



Richard Hawk,
General Manager

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.



Derby ING
PO Box 721725
McAllen TX, 78504

Project Manager: Chris Martin
Project: State
Project Number: 0820016

Reported:
12/19/22 12:59
Received:
12/14/22 11:32

Additional Notes:

Report No. 2212217

SAMPLE SUMMARY

Total Samples received in this work order: 1

The following samples were requested for analysis as per the CoC. Any re-runs or re-analyses requested are identified as such.

<u>Sample ID</u>	<u>Laboratory ID</u>	<u>Matrix</u>	<u>Sampling Method</u>	<u>Date Sampled</u>	<u>Date Received</u>
Tank Site	2212217-01	Drinking Water	Grab	12/14/22 08:03	12/14/22 11:32

Notes

All quality control samples and checks are within acceptance limits unless otherwise indicated.
Test results pertain only to those items tested.
All samples were in good condition when received by the laboratory unless otherwise noted.

Derby ING
PO Box 721725
McAllen TX, 78504

Project Manager: Chris Martin
Project: State
Project Number: 0820016

Reported:
12/19/22 12:59
Received:
12/14/22 11:32

Additional Notes:

Report No. 2212217

Sample ID #: Tank Site

Sampling Method: Grab

Lab Sample ID #: 2212217-01

Sample Matrix: Drinking Water

Date/Time Collected: 12/14/22 08:03

Analyte	Result	Units	PQL	Prep Method	Batch	Analyzed	Method	Analyst	Notes
Microbiological Parameters									
Total Coliforms *	Absent	-				Start 12/14/22 13:13/End 12/15/22 14:36	Colilert	SG	
E. Coli *	Absent	-				Start 12/14/22 13:13/End 12/15/22 14:36	Colilert	SG	
Field Parameters									
Residual Chlorine	.88	mg/L							

Derby ING
PO Box 721725
McAllen TX, 78504

Project Manager: Chris Martin
Project: State
Project Number: 0820016

Reported:
12/19/22 12:59
Received:
12/14/22 11:32

Additional Notes:

Report No. 2212217

DEFINITIONS

*	TNI / NELAC accredited analyte
PQL	Practical Quantitation Limit
MCL	Maximum Contaminant Level
mg/Kg	Milligrams per Kilogram (Parts per Million)
mg/L	Milligrams per Liter (Parts per Million)
PPM	Parts per Million
L	LCS recovery is outside QC acceptance limits, the results may have a slight bias.
M	MS recovery is outside QC limits, the results may have a slight bias due to possible matrix interferences.
NR	Not Recovered due to source sample concentration exceeds spiked concentration.
RMCCCL	Recommended Maximum Concentration of Contaminants Level
Surr L	Surrogate recovery is low outside QC limits.
Surr H	Surrogate recovery is high outside QC limits.
HT	Sample received past holdtime
IC	Improper Container for this analyte(s)
IP	Improper preservation for this analyte(s)
IT	Improper Temperature
V	Inssufficient Volume
B	Sample collected in Bulk
S	RPD is outside QC limits.
AB	VOA Vial contained air bubbles.
OP	ortho-Phosphate was not filtered in the field within 15minutes of collection.
CCV	Continuing Calibration Verification Standard.
ICV	Initial Calibration Verification Standard.

Test Methods followed by the laboratory are referenced in the following approved methodology, unless otherwise specified.

Standard Methods for the Examination of Water and Wastewater, 23rd Edition, 2017
Methods for Chemical Analysis of Water and Wastes, EPA 600/4-79-020, Rev. March 1983
EPA SW Test Methods for the Examination of Solid Waste, SW-846, 1996



Derby ING
PO Box 721725
McAllen TX, 78504
Additional Notes:

Project Manager: Chris Martin
Project: State
Project Number: 0820016

Reported:
12/19/22 12:59
Received:
12/14/22 11:32

Report No. 2212217

Marcela Gracia Hawk, President For

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.



Richard Hawk, General Manager

Sample Receipt Checklist

Client: Derby ING	Project Manager: Marcela Gracia Hawk
Project: State	Project Number: 0820016

Report To:

Chris Martin

SATL Report Number: 2212217

Work Order Due by:	12/19/22 17:00 (3 day TAT)
Received By:	Joana Martinez
Logged In By:	Joana Martinez
Date Received:	12/14/22 11:32
Date Logged In:	12/14/22 12:35

Sample(s) Received on ICE/evidence of Ice (cooler with melted ice,etc):	Yes
Sample temperature at receipt *:	3.3°C
Custody Seals Present:	No
All containers intact:	Yes
Sample labels/COC agree:	Yes
Samples Received within Holding time :	Yes
Samples appropriately preserved **:	Yes
Containers received broken/damaged/leaking:	No
Air bubbles present in VOA vials for VOC/TPH analyses, if applicable:	Not Applicable
TRRP 13 Reporting requested?	No
BacT Sample bottles filled to volume (100mL mark), if applicable:	Not Applicable
LCR Sample bottles filled to volume (1 Liter mark), if applicable:	Not Applicable
Subcontracting required for any analyses:	No
RUSH turnaround time requested:	Yes
Requested Turnaround Time:	3 Business days
Samples delivered via :	Hand Delivered
Air bill included if Samples were shipped:	No
Other deviations not meeting SATL sample acceptance criteria notated on CoC:	None

Notes:

* Samples delivered to the laboratory on the same day that they are collected may not meet thermal preservation criteria (>0°C but <6°C) but are acceptable, if they arrive on ice.

** If improperly preserved, notate client authorization on CoC to proceed with analysis.

Checked By : Joana Martinez

Date : 12/14/22 11:32

SATL#FO001
Revised 09/15/2022